

# Test Map

Title	Case Type	Address
Case 1021662 - Application Added as of 01/29/2010	CONSTRUCT	1007 1ST AVE
Case 1019485 - Application Added as of 05/07/2010	CONSTRUCT	720 SENECA ST
Case 1007783 - Application Added as of 03/10/2006	CONSTRUCT	708 RAINIER AVE S
Case 1020368 - Application Added as of 08/24/2009	HZW	6004 12TH AVE S
Case 1015889 - Application Added as of 06/04/2008	CONSTRUCT	9019 RAINIER AVE S
Case 1011834 - Application Added as of 06/21/2007	HZW	660 W EWING ST
Case 1017563 - Application Added as of 10/20/2009	CONSTRUCT	12360 LAKE CITY WAY NE
Case 1003028 - Case Resolved as of 12/27/2004	HZW	122 19TH AVE E
Case 1011339 - Application Added as of 02/28/2008	HZW	4025 13TH AVE W

# Test Map

Description	Permit And Complaint Status URL
Occupying a hotel requires a Certificate of Occupancy (C of O). Permit 6081417 never received final approval from DPD.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021662">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021662</a>
Permit 6221206 was issued 9/14/09 for work started without a permit. This case will remain open until all required inspections are requested and approved.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019485">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019485</a>
Electrical permit required before any more electrical work is done.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1007783">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1007783</a>
8/13/09 ej- Inspection shows multiple businesses operating and appears the Use has not been establish for this property.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020368">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020368</a>
Permit 6181561 was issued 5/20/08 & Permit 6181790 was issued 6/4/08 for work originally started without permits.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015889">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015889</a>
Reapir shed owned by Diamond Painting, LLC moved from 2629 NW 54th Street to this location, still in violation (no permits).	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1011834">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1011834</a>
REPAIR THE TELEPHONES IN ELEVATORS #3450 AND #3451	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017563">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017563</a>
Emergency Order of the Director to pay relocation assistance	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1003028">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1003028</a>
No permits for 4 covered moorage sheds.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1011339">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1011339</a>

# Test Map

Longitude	Latitude
-122.33679617	47.60479796
-122.33025393	47.60953837
-122.31142688	47.59639774
-122.31701169	47.54900252
-122.27077291	47.52289798
-122.36686922	47.65401497
-122.29475267	47.71894549
-122.30713125	47.61920064
-122.37507213	47.65649388

# Test Map

Case 1011182 - Application Added as of 02/26/2007	CONSTRUCT	4000 15TH AVE NE
---	-----------	------------------

Case 1011183 - Application Added as of 02/26/2007	CONSTRUCT	4000 15TH AVE NE
---	-----------	------------------

Case 1021515 - Application Added as of 01/09/2010	CITATION	523 BROADWAY E
---	----------	----------------

Case 1016563 - Application Added as of 07/14/2008	CONSTRUCT	676 S ORCAS ST
---	-----------	----------------

Case 1005995 - Application Added as of 08/09/2005	CONSTRUCT	901 12TH AVE
---	-----------	--------------

Case 1013582 - Application Added as of 05/21/2010	HZW	13330 STONE AVE N
---	-----	-------------------

Case 1022466 - Application Added as of 05/11/2010	CITATION	4807 40TH AVE SW
---	----------	------------------

Case 1020984 - Application Added as of 04/27/2010	CITATION	2939 S MOUNT BAKER BLVD
---	----------	----------------------------

# Test Map

Violation of the Mechanical Code seen (life safety issues) in the Paul Allen Electrical Engineering Center.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1011182>

Violation of the Mechanical Code seen (life safety issues) in the William Gates Sr. Law Library.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1011183>

Int Insp 9/9/09 DG I went to the site and spoke to Kyle, gave him my card and told him of the complaint regarding early starts. The complaint has dates from the previous month, and I explained the complaint on the sheet was from August. He will have the superintendent call me.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021515>

Screen cleaning water being discharged to storm drain - must be discharged to sanitary. Permit(s) required for re-route & repairs.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016563>

Electrical Permit 606588 issued 8/8/05. Building Permit still required (see application 2504884) for photovoltaic system tied into the power system for the Student Center installed without permits or inspections (west of the intersection of 12th Ave. & E. Cherry St.).

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1005995>

Land Use Code Violation

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1013582>

Violation of Weeds & Vegetation Ord-

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022466>

10/23/09 bg - Vacant lot, debris on the property including mattress, fridge, shopping cart, stove, wood debris and misc. furniture. photos taken

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020984>

# Test Map

-122.31040965	47.65644039
---------------	-------------

-122.31040965	47.65644039
---------------	-------------

-122.32134022	47.62351258
---------------	-------------

-122.32459255	47.55167755
---------------	-------------

-122.31711211	47.61065351
---------------	-------------

-122.34132496	47.72654976
---------------	-------------

-122.383178	47.55904843
-------------	-------------

-122.29435163	47.57563705
---------------	-------------

# Test Map

Case 1010817 - Application Added as of 05/21/2008	HZW	1400 HUBBELL PL
Case 1004936 - Notice or Order Issued as of 03/29/2010	CONSTRUCT	1707 VALENTINE PL S
Case 1021730 - Notice or Order Issued as of 03/31/2010	HZW	2609 S JACKSON ST
Case 1022376 - Application Added as of 05/17/2010	HZW	300 E PINE ST
Case 1016350 - Application Added as of 01/06/2009	CONSTRUCT	611 S BRANDON ST
Case 1019153 - Application Added as of 04/30/2009	CONSTRUCT	613 S BRANDON ST
Case 1011922 - Case Opened as of 12/26/2007	CONSTRUCT	9420 RAINIER AVE S
Case 1010965 - Application Added as of 02/01/2007	CONSTRUCT	1312 N 41ST ST
Case 1010398 - Application Added as of 02/06/2007	CONSTRUCT	9701 AURORA AVE N

# Test Map

VIOLATION OF SEATTLE LAND USE AND ZONING CODE (CONDOMINIUM UNITS BEING ADVERTISED ON INTERNET AS "LODGING USES).

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010817>

Constructing a carport and digging into the hillside, mapped Steep Slope and Potential Slide Environmentally Critical Areas (ECAs), requires a permit & inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1004936>

zoning. VIOLATION ALERT. illegal unit in basement.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021730>

04/29/10 bg - A use permit for bar/nightclub will be required.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022376>

STOP WORK--PERMIT REQUIRED FOR DORMER AND DECK ADDITION (ALSO A POSSIBLE 5TH UNIT IN PROGRESS)

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016350>

Performing electrical work, covering and energizing electrical work requires permit(s), and all required inspections with final approval from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019153>

Permit 6139106 was issued 5/11/07 for work originally performed without a permit. This case will remain open until all inspections are approved.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1011922>

CONTINUATION OF PTS CASE #233732--FAILING TO CONSTRUCT GARAGE PER PLAN FOR PERMIT #735099--PROPERTY LINE MUST BE ESTABLISHED BY SURVEY

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010965>

PERMIT #723379 MUST BE REESTABLISHED--SUBMIT SPECIAL INSPECTION REPORTS AND CALL

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010398>



# Test Map

-122.32975832	47.61220443
---------------	-------------

-122.30753723	47.58817932
---------------	-------------

-122.29824486	47.59901179
---------------	-------------

-122.32756294	47.61546872
---------------	-------------

-122.32625712	47.55389711
---------------	-------------

-122.32625712	47.55389711
---------------	-------------

-122.26406656	47.52010881
---------------	-------------

-122.34153951	47.65705576
---------------	-------------

-122.3450549	47.6999602
--------------	------------

# Test Map

Case 1009679 - Notice or Order Issued as of 05/03/2010	CONSTRUCT	1767 20TH AVE S
Case 1020352 - Application Added as of 01/29/2010	HZW	2640 NW 57TH ST
Case 1022560 - Application Added as of 05/20/2010	CITATION	331 15TH AVE
Case 1001337 - Application Added as of 09/13/2006	CONSTRUCT	3038 S EDMUNDS ST
Case 1020556 - Case Resolved as of 10/02/2009	HZW	3868 16TH AVE SW
Case 1019295 - Application Added as of 05/12/2010	HZW	2315 15TH AVE S
Case 1001662 - Application Added as of 03/04/2004	CONSTRUCT	1921 5TH AVE
Case 1022233 - Application Added as of 04/16/2010	CONSTRUCT	1601 2ND AVE
Case 1022223 - Application Added as of 04/14/2010	HZW	2215 1ST AVE
Case 1019741 - Application Added as of 03/01/2010	HZW	1430 2ND AVE

# Test Map

FOR INSPECTION	1010398
Structure in rear yard requires a permit and inspections from DPD.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1009679">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1009679</a>
garage conversion w/out permit & unpermitted 2nd (basement) dwelling unit: zone now L-2	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020352">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020352</a>
Violation of the Land Use Code	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022560">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022560</a>
GRADING IN ECA--TRACKING MUD OFF SITE--STOP WORK POSTED	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1001337">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1001337</a>
Open to entry via front door, picture in file.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020556">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020556</a>
Property owner of Unit lot D is parking in the driveway access of Unit Lot C. Plat map notes driveway access, easement to ingress/egress not for parking. photo taken	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019295">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019295</a>
Violation of the Seattle Building Code found.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1001662">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1001662</a>
WALL SIGN WITH OFF-PREMISES ADVERTISING ("HOTMAIL.COM") HAS BEEN INSTALLED ON THE NORTH FACING WALL	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022233">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022233</a>
HBMC	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022223">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022223</a>
Possible Violation of the Land Use & Zoning Code.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019741">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019741</a>

# Test Map

-122.30650341	47.58721345
---------------	-------------

-122.39196043	47.67038532
---------------	-------------

-122.31315548	47.6053137
---------------	------------

-122.29239549	47.55883199
---------------	-------------

-122.35512155	47.56852117
---------------	-------------

-122.31393265	47.58240355
---------------	-------------

-122.3389258	47.61321665
--------------	-------------

-122.34036668	47.61035736
---------------	-------------

-122.34614211	47.61277489
---------------	-------------

-122.33830577	47.60911192
---------------	-------------

# Test Map

Case 1001003 - Application Added as of 11/12/2003      CONSTRUCT      418 8TH AVE S

Case 1022109 - Application Added as of 03/29/2010      CONSTRUCT      418 8TH AVE S

Case 1016888 - Application Added as of 08/20/2008      CONSTRUCT      117 12TH AVE

Case 1019764 - Notice or Order Issued as of  
12/22/2009      HZW      730 S ELMGROVE ST

Case 1019765 - Notice or Order Issued as of  
12/22/2009      HZW      730 S ELMGROVE ST

Case 1017935 - Citation Issued as of 04/23/2010      CITATION      3019 NE 120TH ST

Case 1017937 - Application Added as of 04/23/2010      HZW      3019 NE 120TH ST

# Test Map

Work performed without a permit. Stop Work Order posted 11/10/03.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1001003>

The International Special Review District Board has not approved this sign. Sign must be removed.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022109>

Application 6190587 made 8/8/08 for grading more than 100 cu.yds. (at least 1,500 cu.yds. including adjacent properties) performed w/o permit & inspections from DPD. STOP WORK ORDER posted 8/6/08. Only work allowed: stabilize site (currently 16'-17' cut 10' from west property line).

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016888>

OBSERVED VIOLATION OF THE SEATTLE HOUSING AND BUILDING MAINTENANCE CODE (RODENT UNDER NORTHEAST CORNER OF RESIDENCE REAR DOOR NAILED SHUT AND OTHER VIOLATIONS).

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019764>

"VIOLATION ALERT"OBSERVED VIOLATION OF THE SEATTLE LAND USE AND ZONING CODE (DETACHED GARAGE WAS CONVERTED TO UNAUTHORIZED DWELLING UNIT; PERMIT 687036 ISSUED 7/19/06 FOR GARAGE ADDITION EXPIRED 1/19/98).

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019765>

Land Use Code Violation

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017935>

Land Use Code Violation

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017937>

# Test Map

-122.32223647 47.59849416

-122.32223647 47.59849416

-122.31733647 47.60223267

-122.32407144 47.5307106

-122.32407144 47.5307106

-122.29528086 47.71539974

-122.29528086 47.71539974

# Test Map

Case 1022056 - Application Added as of 03/22/2010	CITATION	923 21ST AVE
Case 1015742 - Application Added as of 12/24/2009	CONSTRUCT	2122 S BAYVIEW ST
Case 1001367 - Application Added as of 01/29/2004	CONSTRUCT	8437 DALLAS AVE S
Case 1008411 - Application Added as of 07/24/2008	HZW	811 NE 73RD ST
Case 1012226 - Application Added as of 05/30/2007	CONSTRUCT	912 12TH AVE
Case 1022383 - Application Added as of 04/30/2010	HZW	912 12TH AVE
Case 1020627 - Application Added as of 03/24/2010	CITATION	8716 10TH AVE S
Case 1021719 - Notice or Order Issued as of 03/24/2010	HZW	8716 10TH AVE S
Case 1010275 - Application Added as of 11/08/2006	CONSTRUCT	1700 1ST AVE S



# Test Map

Violation of the Land Use & Zoning Code

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022056>

Rebuilding a retaining wall more than 4' tall in a Steep Slope ECA requires permit and inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015742>

Violation of the Seattle Building and Land Use Code.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1001367>

Vehicle stored in driveway.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1008411>

Remodeling & changing use in warehouse requires construction & electrical permits & ALL inspections from DPD. King Co. Health plumbing permit & inspections required. STOP WORK ORDER posted 5/29/07.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1012226>

zoning\_illegal use.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022383>

VIOLATION OF THE SEATTLE LAND USE AND ZONING CODE OBSERVED (BOAT IN SIDE YARD, VEHICLES IN FRONT YARD, SCRAP WOOD AND OTHER MATERIALS IN YARDS)

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020627>

"VIOLATION ALERT" VIOLATION OF THE SEATTLE LAND USE AND ZONING CODE CONFIRMED (2ND STORY ADDITION ON SINGLE-FAMILY RESIDENCE WITHOUT REQUIRED PERMIT.)

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021719>

Cracked roof truss has temporary repairs and shoring installed at the direction of a structural engineer. Structural evaluation and emergency permit for

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010275>

# Test Map

-122.30536271 47.61077548

-122.30455274 47.58119764

-122.31603267 47.52750027

-122.31931684 47.68139421

-122.31638159 47.61087958

-122.31638159 47.61087958

-122.3199905 47.52507557

-122.3199905 47.52507557

-122.33365376 47.58787436

# Test Map

Case 1022144 - Application Added as of 04/02/2010	CONSTRUCT	1927 5TH AVE
Case 1022557 - Application Added as of 05/20/2010	CITATION	826 19TH AVE S
Case 1022502 - Application Added as of 05/13/2010	CITATION	2321 FRANKLIN AVE E
Case 1021849 - Case Resolved as of 04/16/2010	HZW	8951 AURORA AVE N
Case 1004091 - Case Opened as of 06/04/2008	CONSTRUCT	6009 WEST MARGINAL WAY SW
Case 1004248 - License Issued as of 01/20/2005	TRAO	5204 12TH AVE NE
Case 1022242 - Notice or Order Issued as of 04/16/2010	HZW	1632 23RD AVE
Case 1012334 - Payment Processed as of 07/30/2007	TRAO	4302 7TH AVE NE
Case 1020778 - Case Resolved as of 02/18/2010	HZW	2008 3RD AVE

# Test Map

permanent repairs required.

IMMEDIATLY CLEAN UP RIGHT OF WAY--OBTAIN A STRUCTURAL ENGINEER'S REPORT--COMPLETE REPAIRS UNDER DPD PERMIT

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022144>

05/19/10 bg - Vacant lot, overgrown vegetation, fence damaged and leaning into alley, construction debris on site. photos taken

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022557>

Big outdoor storage issues. Citation sent, no warning.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022502>

salvage & junk on site , business in C1-40 zone

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021849>

Retaining wall requires permit and inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1004091>

No Displacement of Tenants

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1004248>

junk in yard includes mattress, black plastic bags, screens, metal frame, buckets; pictures in file.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022242>

Application for a Tenant Relocation License. Total units: 2; total units occupied: 2. Demolition.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1012334>

Inspection: owner has removed all of the required vegetation screening; U-Park Systems take over of lot has removed the pay station from the NE corner of the lot to the SW corner which prevents easy access for the required disabled parking slot. There are now 78 parking

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020778>

# Test Map

-122.33927235	47.61338606
---------------	-------------

-122.30697055	47.59509466
---------------	-------------

-122.32494739	47.64036032
---------------	-------------

-122.34495143	47.69388275
---------------	-------------

-122.34570899	47.54742391
---------------	-------------

-122.3149034	47.66660815
--------------	-------------

-122.3023558	47.61628218
--------------	-------------

-122.3204263	47.65973149
--------------	-------------

-122.34097844	47.61284107
---------------	-------------

# Test Map

Case 1010033 - Case Closed as of 02/10/2010	HZW	5101 RAINIER AVE S
Case 1003079 - Application Added as of 08/05/2004	CONSTRUCT	1202 S DONOVAN ST
Case 1003802 - Application Added as of 10/28/2004	CONSTRUCT	5213 12TH AVE NE
Case 1016486 - Application Added as of 12/11/2009	CONSTRUCT	6428 CARLETON AVE S
Case 1003308 - Application Accepted as of 10/12/2006	TRAO	2040 E MADISON ST
Case 1019748 - Application Added as of 03/23/2010	HZW	3611 2ND AVE NW

# Test Map

stalls, where only 35 are allowed on one portion of the lot. The curb cut on the west side of the lot, north corner is now blocked by plastic orange posts and no parking signs (City). This curb cut was allowed to remain only because the required vegetation was "permanently" positioned along with a metal fence that did not allow use of the curb cut. The lot is now using the west side (south end) as egress near the corner to jump the curb to enter and leave the lot. This lot was allowed as temporary use only-it has now merged with the lot formerly for public use on the corner of 3rd ave and Virginia St.

Inspection shows Zoning violation.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010033>

Violations found: work without permit and work not according to approved plan (Permit 630170). Stop Work Order posted 8/4/04.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1003079>

NEED BUILDING ,ELECTRICAL,PLUMBING PERMITS

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1003802>

Permit 6187658 was issued 7/16/08 for work originally started without a permit. This case will remain open until all required inspections have been requested and approved by DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016486>

Application for a Tenant Relocation License

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1003308>

LU: six illegal dwelling units in office blding, only one legal res unit allowed on 3rd floor per permits #583841 &

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019748>

# Test Map

-122.28392811	47.55598051
---------------	-------------

-122.31737224	47.52578595
---------------	-------------

-122.31548334	47.66685446
---------------	-------------

-122.3206569	47.54492408
--------------	-------------

-122.30454868	47.6180925
---------------	------------

-122.35928317	47.65366404
---------------	-------------



# Test Map

Case 1022092 - Application Added as of 03/25/2010	CONSTRUCT	5620 6TH AVE S
Case 1015388 - Application Added as of 04/04/2008	CONSTRUCT	621 S KING ST
Case 1018444 - Application Added as of 02/12/2009	CITATION	4219 INTERLAKE AVE N
Case 1018495 - Citation Issued as of 04/01/2010	CITATION	4219 INTERLAKE AVE N
Case 1022424 - Application Added as of 05/05/2010	CONSTRUCT	401 NE 45TH ST
Case 1022436 - Application Added as of 05/06/2010	CONSTRUCT	7100 42ND AVE S
Case 1022044 - Application Added as of 05/18/2010	HZW	1414 S CONCORD ST
Case 1020096 - Case Opened as of 08/05/2009	CONSTRUCT	1516 2ND AVE
Case 1013113 - Notice or Order Issued as of 03/18/2010	HZW	1723 N 45TH ST

# Test Map

585483 finaled in 1981.	1019748
Relocation of demising/partition wall & electrical work requires permits and inspections from DPD.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022092">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022092</a>
Electrical work requires permit(s) and inspections from DPD.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015388">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015388</a>
Numerous violations. Off street parking has been removed. House is unsafe. Excessive overgrowth of shrubery.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018444">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018444</a>
zoning/ HOUSE IS OWNER OCCUPIED	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018495">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018495</a>
THIS SIGN VIOLATES THE LAND USE CODE BY ADVERTISING A PRODUCT NOT FOUND ON THE PREMISES--SIGN CANNOT BE PERMITTED	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022424">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022424</a>
Remodeling a building requires permit(s) and inspections form DPD. STOP WORK ORDER posted 5/4/10.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022436">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022436</a>
VIOLATION OF THE SEATTLE LAND USE AND ZONING CODE OBSERVED)STRUCTURE AND BACKHOE IN AREA DESIGNATED FOR 2 PARKING SPACES. TOOK PHOTOS.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022044">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022044</a>
PERMIT IS REQUIRED FOR SIGN--SIGN MUST ADVERTISE GOODS OR SERVICES PROVIDED ON SITE	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020096">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020096</a>
Land Use Code Violation	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1013113">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1013113</a>

# Test Map

-122.3263517	47.55221774
--------------	-------------

-122.32543781	47.59817858
---------------	-------------

-122.34105607	47.65859655
---------------	-------------

-122.34105607	47.65859655
---------------	-------------

-122.32379543	47.66120047
---------------	-------------

-122.28026246	47.5385658
---------------	------------

-122.31409587	47.52420645
---------------	-------------

-122.33903835	47.6099491
---------------	------------

-122.33640306	47.66122959
---------------	-------------

# Test Map

Case 1020717 - Application Added as of 09/28/2009	CONSTRUCT	8300 WABASH AVE S
Case 1022245 - Application Added as of 04/16/2010	HZW	5715 15TH AVE NW
Case 1021689 - Application Added as of 02/23/2010	HZW	26 S HANFORD ST
Case 1022091 - Application Added as of 03/25/2010	CONSTRUCT	159 DENNY WAY
Case 1014345 - Payment Processed as of 03/06/2008	TRAO	416 E HARRISON ST
Case 1020470 - Case Opened as of 10/23/2009	HZW	7601 GREENWOOD AVE N
Case 1003767 - Application Added as of 10/24/2004	CONSTRUCT	927 21ST AVE
Case 1019756 - Citation Issued as of 05/10/2010	CITATION	927 21ST AVE
Case 1017636 - Notice or Order Issued as of 03/25/2010	CONSTRUCT	3200 1ST AVE S
Case 1017793 - Notice or Order Issued as of 12/22/2009	HZW	3200 1ST AVE S

# Test Map

Constructing a carport on the west side of an existing commercial structure requires a permit and inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020717>

Zoning violation.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022245>

Violation of the Land Use & Zoning Code.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021689>

Mechanical HVAC and Additional Mechanical (Kitchen hood) require permit(s) and inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022091>

Application for a Tenant Relocation License. Total units: 2; total units occupied: 2. Demolition.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014345>

LU uses not established/ ACU needed

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020470>

Violation of the Seattle Building Code found: work without a permit (large shed or garage in back yard requires renewed permit and ALL required building inspections).

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1003767>

Violation of the Land Use & Zoning Code

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019756>

Operating a business (Herban Feast) without a Certificate of Occupancy.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017636>

Land Use violation- Illegal use.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017793>

# Test Map

-122.26947816	47.52937959
---------------	-------------

-122.3767409	47.6706305
--------------	------------

-122.33863898	47.57613068
---------------	-------------

-122.35363041	47.61836699
---------------	-------------

-122.32584835	47.62218319
---------------	-------------

-122.35578011	47.68428759
---------------	-------------

-122.30531245	47.61089518
---------------	-------------

-122.30531245	47.61089518
---------------	-------------

-122.3334911	47.5750695
--------------	------------

-122.3334911	47.5750695
--------------	------------

# Test Map

Case 1003146 - Application Added as of 02/19/2010	CONSTRUCT	1724 4TH AVE S
Case 1017089 - Application Added as of 09/03/2008	CONSTRUCT	8445 RAINIER AVE S
Case 1016999 - Application Added as of 09/03/2008	CONSTRUCT	8445 RAINIER AVE S
Case 1004930 - Application Added as of 04/08/2005	HZW	5014 15TH AVE NE
Case 1013674 - Application Added as of 09/16/2009	CITATION	1300 NE 65TH ST
Case 1011632 - Application Added as of 04/10/2007	CONSTRUCT	1921 1ST AVE
Case 1010290 - Application Added as of 02/16/2007	CONSTRUCT	1921 1ST AVE

# Test Map

Permit 6207200 was issued 3/26/09 and received final approval 5/22/09 for the demolition of the fire damaged hazardous building at 1724 4th Ave S.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1003146>

Creating approximately 9,600 sq.ft. of impervious surface without drainage system review and side sewer permit & inspections. This case will remain open until permit & all required inspections have been obtained. STOP WORK ORDER issued 8/13/08.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017089>

Grading & side sewer permit required for removing soil/adding gravel (over 100 cu.yds. grading w/o permit) on north side of building. STOP WORK ORDER issued 8/13/08. Bare soil to be covered & other Temporary Erosion & Sedimentation Control (TESC) measures in place by 8/15/08.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016999>

Failure to pay emergency relocation assistance pursuant to SMC Section 22.206.260.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1004930>

LUC violation -inops

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1013674>

Replacing windows (alley & 1st Ave side); painting & removing portion of railing on top of building; and attaching banners & flags to Post Alley side of building ALL require approval from Pike Place Market Historical Commission. STOP WORK ORDER posted 4/10/07.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1011632>

Rooftop deck and interior remodel on top floor and for the Starlite Lounge require permits and all required inspections from DPD. Stop Work Order posted 11/9/06.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010290>



# Test Map

-122.32787136	47.58745683
---------------	-------------

-122.27049845	47.52678523
---------------	-------------

-122.27049845	47.52678523
---------------	-------------

-122.31163271	47.66536035
---------------	-------------

-122.31412478	47.67600323
---------------	-------------

-122.3422717	47.61050649
--------------	-------------

-122.3422717	47.61050649
--------------	-------------

# Test Map

Case 1019665 - Case Resolved as of 05/21/2010	CITATION	310 S HENDERSON ST
Case 1022116 - Application Added as of 03/31/2010	HZW	1400 S HENDERSON ST
Case 1020395 - Application Added as of 04/13/2010	CONSTRUCT	448 NE RAVENNA BLVD
Case 1021807 - Application Added as of 02/19/2010	HZW	920 ELLIOTT AVE W
Case 1016833 - Application Added as of 08/01/2008	CITATION	1318 NE 65TH ST
Case 1019321 - Citation Issued as of 05/18/2010	CITATION	3921 S HUDSON ST
Case 1003981 - Application Added as of 05/22/2006	CONSTRUCT	8661 DALLAS AVE S
Case 1012844 - Application Added as of 07/19/2007	TRAO	1902 24TH AVE S

# Test Map

6/8/09 ej -Observed outdoor junk storage such as but not limited to inoperable RV, truck and tires, appliances wood and other miscellaneous items. Parking more than the allowed three vehicles not enclosed on a single family lot. People living in the RV.

Observed van/bus in vacant lot.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019665>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022116>

PERMITS ARE REQUIRED FOR BASEMENT BUILD OUT--NEW UNITS, STORAGE ROOM AND MANAGER'S OFFICE

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020395>

Land Use violation.Operating religious and dance/yoga activities w/o the appropriate use.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021807>

Junk storage, including but not limited to, broken TV components under the front stairs, the rest of the TV components beside the house to the east, a mini trampoline in the back yard, carpet, rags, a metal book shelf, a truck canopy and bumper, plywood and tarps. Outdoor junk storage is not allowed in residential zones in the city of Seattle.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016833>

VIOLATION OF THE SEATTLE LAND USE AND ZONING CODE OBSERVED (AUTO TIRES,RIMS, AND OTHER AUTO PARTS IN FRONT AND REAR YARDS.)

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019321>

Demolition of above ground fuel tanks requires SEPA and demolition permits from DPD. Stop Work Order posted 11/18/04.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1003981>

Violation of the Tenant Relocation Assistance Ordinance

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=>

# Test Map

-122.33019527 47.52302585

-122.31465866 47.52322825

-122.32337803 47.67787646

-122.36905136 47.62739979

-122.31348377 47.67602508

-122.28252694 47.55683339

-122.31149354 47.52604209

-122.30134221 47.5861958

# Test Map

Case 1022256 - Notice or Order Issued as of 04/27/2010	HZW	1902 24TH AVE S
Case 1018378 - Application Added as of 04/27/2010	HZW	6754 M L KING JR WAY S
Case 1014960 - Application Added as of 03/05/2008	TRAO	1000 VIRGINIA ST
Case 1020808 - Case Resolved as of 05/21/2010	CITATION	3309 WETMORE AVE S
Case 1022473 - Application Added as of 05/11/2010	HZW	2014 TERRY AVE
Case 1021765 - Notice or Order Issued as of 04/30/2010	CONSTRUCT	14010 AURORA AVE N
Case 1011445 - Application Added as of 03/23/2007	HZW	1517 BOYLSTON AVE
Case 1010622 - Application Accepted as of 03/09/2010	ADVISORY	1220 BOREN AVE
Case 1014688 - Application Added as of 01/17/2008	CONSTRUCT	151 S LANDER ST
Case 1015907 - Application Added as of 12/22/2009	HZW	8600 AURORA AVE N

# Test Map

bldg. secure but outdoor storage includes mattresses, clothes, tv's, toys, suitcases, lumber, books, construction debris, child seat, shoes & carpeting.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1012844>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022256>

Violation of Land Use Code.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018378>

Application for a Tenant Relocation License. Total units: 60; total units occupied: 47. Change of use.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014960>

10/02/09 bg - Number of vehicles some inoperable in the rear yard along with an accumulation of junk and debris. photos taken

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020808>

Minor Violations of HBMC

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022473>

PERMIT REQUIRED TO REMOVE WALLS--MAY NEED CHANGE OF USE

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021765>

Law Case Conversion

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1011445>

Condo Conversion.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010622>

Installing a Type I hood and refrigeration requires permit(s) and inspections from DPD. STOP WORK ORDER posted 1/16/08.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014688>

Land Use Code Violation

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=>

# Test Map

-122.30134221	47.5861958
---------------	------------

-122.28273466	47.54097682
---------------	-------------

-122.33490717	47.6174116
---------------	------------

-122.29363428	47.5739861
---------------	------------

-122.33529423	47.61750932
---------------	-------------

-122.34451166	47.73095389
---------------	-------------

-122.32364225	47.61466349
---------------	-------------

-122.32668694	47.61136681
---------------	-------------

-122.33268935	47.5793634
---------------	------------

-122.34419912	47.69139187
---------------	-------------

# Test Map

Case 1012699 - Payment Processed as of 12/14/2009	TRAO	422 MALDEN AVE E
---	------	------------------

Case 1004900 - Application Added as of 07/21/2005	CONSTRUCT	9103 8TH AVE S
---	-----------	----------------

Case 1018095 - Application Added as of 03/24/2010	CONSTRUCT	2122 14TH AVE S
---	-----------	-----------------

Case 1022064 - Application Added as of 03/22/2010	CITATION	2506 S JACKSON ST
---	----------	-------------------

Case 1012857 - Application Added as of 07/19/2007	TRAO	2415 S HOLGATE ST
---	------	-------------------

Case 1022066 - Notice or Order Issued as of 04/19/2010	HZW	2415 S HOLGATE ST
--	-----	-------------------

Case 1014988 - Notification Issued as of 10/09/2009	VACANT	2415 S HOLGATE ST
---	--------	-------------------

Case 1020875 - Application Added as of 10/28/2009	HZW	5901 AIRPORT WAY S
---	-----	--------------------

Case 1020851 - Case Opened as of 05/14/2010	CITATION	1057 S DONOVAN ST
---	----------	-------------------



# Test Map

	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015907">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015907</a>
Application for a Tenant Relocation License. Total units: 3; total units occupied: 3. Demolition.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1012699">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1012699</a>
Violation of the Seattle Building Code found: 2nd floor deck, rear deck with new partial roof and interior alterations require permit from DPD. Stop Work Order posted 4/5/05.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1004900">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1004900</a>
Building a garage and converting it to living space and enclosing unconditioned space at the rear of a mixed use building requires permits & inspections from DPD. STOP WORK ORDER posted 12/9/08 & 7/7/09.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018095">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018095</a>
Violation of the Land Use Code	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022064">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022064</a>
Violation of the Tenant Relocation Assistance Ordinance	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1012857">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1012857</a>
Front door open to entry, picture in file.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022066">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022066</a>
Open to entry with junk stg.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014988">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014988</a>
10/15/09 ej- Inspection shows at music venue for concerts and drinking establishment.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020875">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020875</a>
<b>VIOLATION OF THE SEATTLE WEEDS AND VEGETATION ORDINANCE OBSERVED VEGETATION</b>	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020851">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020851</a>

# Test Map

-122.31336604	47.62264951
---------------	-------------

-122.32340572	47.52212114
---------------	-------------

-122.31444422	47.58383148
---------------	-------------

-122.2994621	47.59944443
--------------	-------------

-122.30090325	47.58617857
---------------	-------------

-122.30090325	47.58617857
---------------	-------------

-122.30090325	47.58617857
---------------	-------------

-122.31735691	47.54997454
---------------	-------------

-122.31780478	47.52540026
---------------	-------------

# Test Map

Case 1020852 - Case Opened as of 05/14/2010	CITATION	1057 S DONOVAN ST
---	----------	-------------------

Case 1020203 - Application Added as of 12/18/2009	HZW	915 CHERRY ST
---	-----	---------------

Case 1022566 - Application Added as of 05/20/2010	CITATION	1617 S LANE ST
---	----------	----------------

Case 1022243 - Application Added as of 04/16/2010	HZW	801 E HARRISON ST
---	-----	-------------------

Case 1009593 - Payment Processed as of 12/14/2009	TRAO	2808 FAIRVIEW AVE E
---	------	---------------------

Case 1020629 - Application Added as of 12/18/2009	CONSTRUCT	5000 EAST MARGINAL WAY S
---	-----------	-----------------------------

Case 1022026 - Application Added as of 03/17/2010	HZW	2804 NW MARKET ST
---	-----	-------------------

Case 1012558 - Findings Issued as of 03/25/2010	ADVISORY	3005 NW MARKET ST
---	----------	-------------------

Case 1022462 - Application Added as of 05/10/2010	CITATION	310 E MERCER ST
---	----------	-----------------

# Test Map

OVERGROWTH OVERHANGING AND OBSTRUCTING PUBLIC USE OF THE SIDEWALK ALONG 17TH AVE S AND ALONG S DONOVAN ST.

VIOLATION OF THE SEATTLE LAND USE AND ZONING CODE OBSERVED (MORE THAN 3 VEHICLES IN YARDS; METAL, PLASTIC AND OTHER JUNK STORAGE IN YARDS).

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020852>

Violation of the HBMC

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020203>

Violation of the Weed & Veg Ord.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022566>

The gutter system is sending water into the open stairwells during heavy rains.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022243>

Application for a Tenant Relocation License. Total units: 4; total units occupied: 4. Demolition.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1009593>

Constructing an outdoor patio requires permits & inspections from DPD. Permit 6191604 requires final approval from DPD. STOP WORK ORDER posted 9/18/09.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020629>

Zoning violation.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022026>

Condo conversion

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1012558>

outdoor storage includes man-lift, tires, wheelbarrow, lumber, chair, bench, flower pots & other items, pictures

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=>

# Test Map

-122.31780478	47.52540026
---------------	-------------

-122.32443607	47.60628751
---------------	-------------

-122.31080749	47.59642499
---------------	-------------

-122.32181924	47.62182609
---------------	-------------

-122.32650076	47.64592783
---------------	-------------

-122.3383499	47.55724237
--------------	-------------

-122.39319927	47.66889317
---------------	-------------

-122.39755898	47.66811929
---------------	-------------

-122.32734272	47.62460154
---------------	-------------

# Test Map

Case 1022385 - Notice or Order Issued as of 05/11/2010	HZW	310 E MERCER ST
--	-----	-----------------

Case 1019897 - Application Added as of 07/09/2009	CONSTRUCT	2400 E SPRUCE ST
---	-----------	------------------

Case 1013714 - Application Added as of 10/10/2007	CONSTRUCT	1917 1ST AVE
---	-----------	--------------

Case 1021063 - Application Added as of 12/18/2009	CONSTRUCT	2401 1ST AVE
---	-----------	--------------

Case 1010952 - Application Added as of 01/31/2007	CONSTRUCT	5304 1ST AVE S
---	-----------	----------------

Case 1011319 - Application Added as of 03/13/2007	HZW	1641 22ND AVE
---	-----	---------------

Case 1022517 - Notice or Order Issued as of 05/21/2010	HZW	167 20TH AVE
--	-----	--------------

# Test Map

lumber, chair, bench, flower pots & other items, pictures in file.

1022462

Open to entry via bay window on West wall & rear deck via climbing on a man-lift kept in the yard, pictures in file.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022385>

Commercial kitchen equipment requires Type I Hood. Equipment not to be used until Type I Hood is permitted & all inspections approved by DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019897>

Cutting hole for door & other work on Post Alley side of Alaska Trade Bldg. requires permits & inspections from DPD & Pike Place Market Historical Commission approval. STOP WORK ORDER posted 10/8/07.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1013714>

A SIGN ADVERTISING THE ICON GROUP HAS BEEN INSTALLED W/O PERMIT--IT IS OFF PREMISES ADVERTISING AND MUST BE REMOVED--ALSO THE REGISTRATION NUMBER FOR THE EXISTING PERMITTED SIGN MUST BE DISPLAYED ON THE FACE OF THE BILLBOARD

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021063>

Police car ran into & damaged building. Wall needs to be secured & temporary support provided. Building permit required for repairs.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010952>

VIOlation OF THE SEATTLE LAND USE AND ZONING CODE CONFIRMED (WORK ON EXPIRED PERMIT# 697127 FOR BEDROOM ADDITION IN PROGRESS).

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1011319>

Garage & adjacent shed open to entry, pictures in file.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022517>

# Test Map

-122.32734272      47.62460154

-122.30076447      47.60373947

-122.34214278      47.610413

-122.34822892      47.61409745

-122.33389887      47.55465791

-122.30384846      47.61650174

-122.30663383      47.60321438



# Test Map

Case 1011308 - Application Added as of 04/29/2009	CONSTRUCT	712 20TH AVE
Case 1021618 - Citation Issued as of 04/01/2010	CITATION	723 22ND AVE
Case 1021740 - Case Resolved as of 05/13/2010	CITATION	1727 NW 56TH ST
Case 1020234 - Case Opened as of 09/23/2009	UNFIT	925 NW 49TH ST
Case 1022533 - Application Added as of 05/19/2010	CITATION	1202 E DENNY WAY
Case 1021722 - Payment Processed as of 05/20/2010	TRAO	711 BELLEVUE AVE E
Case 1011008 - Application Added as of 09/10/2008	CONSTRUCT	110 ALASKAN WAY S
Case 1022442 - Application Added as of 05/07/2010	HZW	623 BROADWAY E
Case 1018977 - Application Added as of 04/02/2010	HZW	547 S SULLIVAN ST
Case 1019289 - Notification Issued as of 03/08/2010	VACANT	547 S SULLIVAN ST
Case 1019296 - Case Resolved as of 03/08/2010	CITATION	547 S SULLIVAN ST

# Test Map

Building, electrical and plumbing permits and inspections required for work in the basement. Duplex use needs to be established.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1011308>

Violation of the Weed & Veg Code

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021618>

Zoning violation.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021740>

Abatement request canceled - demo will be attached to building permit. Cancel application and refund log 5390

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020234>

Violation of the Weed & Veg Ord

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022533>

Application for a Tenant Relocation License. Total units:6; total units occupied:6. Demolition.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021722>

Demolishing a building requires Pioneer Square Preservation Board approval AND a valid permit from DPD. Work not per Permit 6088080.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1011008>

4/22/10 KB inspected property and LU Violation exist- Use Not Established by Permit.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022442>

2 SFR's on 1 site. rear sfr open to entry; junk on complete site; may be part of a new const. proj.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018977>

2 SFR's on 1 site. rear sfr open to entry; junk on complete site; may be part of a new const. proj.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019289>

Outdoor storage on site includes const. materials & debris, mattresses, lumber, broken concrete, tires,

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=>

# Test Map

-122.30604585	47.60848519
---------------	-------------

-122.30410957	47.60871812
---------------	-------------

-122.38015874	47.66926811
---------------	-------------

-122.36974501	47.6641943
---------------	------------

-122.3166815	47.61894656
--------------	-------------

-122.32690968	47.62542583
---------------	-------------

-122.3352109	47.6013469
--------------	------------

-122.3213113	47.62495121
--------------	-------------

-122.32625434	47.52712958
---------------	-------------

-122.32625434	47.52712958
---------------	-------------

-122.32625434	47.52712958
---------------	-------------

# Test Map

Case 1021949 - Application Added as of 04/14/2010	CITATION	547 S SULLIVAN ST
---	----------	-------------------

Case 1018006 - Application Added as of 05/14/2010	HZW	501 E PIKE ST
---	-----	---------------

Case 1014966 - Application Added as of 05/10/2010	HZW	1820 E UNION ST
---	-----	-----------------

Case 1015099 - Notification Issued as of 05/10/2010	VACANT	1820 E UNION ST
---	--------	-----------------

Case 1020479 - Application Added as of 05/10/2010	HZW	1820 E UNION ST
---	-----	-----------------

Case 1021863 - Order of Director Issued as of 05/19/2010	UNFIT	1820 E UNION ST
--	-------	-----------------

Case 1012422 - Application Added as of 03/24/2009	CONSTRUCT	8327 WOLCOTT AVE S
---	-----------	--------------------

Case 1017959 - Application Added as of 03/24/2009	CONSTRUCT	8327 WOLCOTT AVE S
---	-----------	--------------------

Case 1011289 - Application Added as of 05/23/2007	CONSTRUCT	1403 E OLIVE WAY
---	-----------	------------------

# Test Map

debris, mattresses, lumber, broken concrete, tires, couches, motors, furniture, gas tank & other items.	<a href="#">1019296</a>
New outdoor storage in rear yard. Looks like a neighbor has decided to dismantle/repair vehicles, pictures in file of mattresses, pallets, tires, lumber, auto parts, tools, gas tanks, jack, air compressor, tv, handtruck, clothes, fabric, tarps, car seats, table top & other items.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021949">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021949</a>
Parking lot not established by permit.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018006">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018006</a>
Bldg. open to entry with grafitti.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014966">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014966</a>
Bldg. open to entry with grafitti.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015099">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015099</a>
Deflected, unsound, unsafe collapsing roof assembly. Access is possible; pictures in file.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020479">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020479</a>
unfit vacant commercial structure.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021863">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021863</a>
Permit and inspections are required for alterations to stormwater disposal from DPD. STOP WORK ORDER posted 5/31/07.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1012422">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1012422</a>
Remodeling a house (including creating habitable space in the basement) & constructing a deck on the west side (rear) requires permits & inspections from DPD.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017959">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017959</a>
Retaining wall adjacent to sidewalk requires repair. Permit & inspections from DPD required. Emergency	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1011289">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1011289</a>

# Test Map

-122.32625434	47.52712958
---------------	-------------

-122.32524106	47.61387001
---------------	-------------

-122.30780512	47.61304627
---------------	-------------

-122.30780512	47.61304627
---------------	-------------

-122.30780512	47.61304627
---------------	-------------

-122.30780512	47.61304627
---------------	-------------

-122.2680076	47.52885438
--------------	-------------

-122.2680076	47.52885438
--------------	-------------

-122.32632113	47.61715302
---------------	-------------

# Test Map

Case 1016356 - Application Added as of 08/05/2009	HZW	6317 15TH AVE NE
Case 1015528 - Application Added as of 03/08/2010	HZW	4026 17TH AVE SW
Case 1015531 - Notification Issued as of 03/08/2010	VACANT	4026 17TH AVE SW
Case 1017235 - Application Added as of 11/06/2009	CONSTRUCT	4026 17TH AVE SW
Case 1016205 - Case Opened as of 05/11/2010	UNFIT	4026 17TH AVE SW
Case 1021055 - Application Added as of 11/05/2009	HZW	1551 19TH AVE S
Case 1021057 - Application Added as of 11/05/2009	HZW	1551 19TH AVE S
Case 1021058 - Application Added as of 11/05/2009	CITATION	1551 19TH AVE S
Case 1021040 - Case Resolved as of 12/23/2009	HZW	1551 19TH AVE S

# Test Map

permit for new retaining wall w/engineered design & drainage O.K. per Jim Lawton. STOP WORK ORDER posted 5/23/07.

HBMC violations

1011289

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016356>

Open to entry with deterioration & outdoor storage.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015528>

Open to entry with deterioration & outdoor storage.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015531>

Grading more than 25 cu.yds. in a Potential Slide Environmentally Critical Area requires permits and inspections from DPD. STOP WORK ORDER posted 9/3/08. Temporary Erosion & Sedimentation Control (TESC) measures required.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017235>

VIOLATION ALERT- part of property is on a slope.unfit single family residence

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016205>

Open to weather; deterioration; standing water.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021055>

outdoor storage including const. debris & supplies, lumber, computer monitors, television, furniture, 1 picture in file.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021057>

veg. overgrowth encroaching & overhanging public sidewalks on this corner lot.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021058>

Open to entry; deterioration; outdoor storage; veg. overgrowth.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=>



# Test Map

-122.3121869	47.67534253
--------------	-------------

-122.35553639	47.56752967
---------------	-------------

-122.35553639	47.56752967
---------------	-------------

-122.35553639	47.56752967
---------------	-------------

-122.35553639	47.56752967
---------------	-------------

-122.30869135	47.58857445
---------------	-------------

-122.30869135	47.58857445
---------------	-------------

-122.30869135	47.58857445
---------------	-------------

-122.30869135	47.58857445
---------------	-------------

# Test Map

Case 1013665 - Application Added as of 10/03/2007	CITATION	832 14TH AVE
---	----------	--------------

Case 1021694 - Application Added as of 02/03/2010	CITATION	612 2ND AVE
---	----------	-------------

Case 1022576 - Application Added as of 05/21/2010	HZW	2013 2ND AVE
---	-----	--------------

Case 1022122 - Case Opened as of 04/21/2010	CITATION	5700 24TH AVE NW
---	----------	------------------

Case 1012141 - Payment Processed as of 12/14/2009	TRAO	12741 30TH AVE NE
---	------	-------------------

Case 1020841 - Notice or Order Issued as of 05/21/2010	CONSTRUCT	128 24TH AVE
--	-----------	--------------

Case 1022537 - Case Opened as of 05/21/2010	HZW	128 24TH AVE
---	-----	--------------

# Test Map

overgrowth.

OBSERVED VIOLATION OF THE SEATTLE WEEDS AND VEGETATION ORDINANCE.(OVERGROWTH OBSTRUCTING PUBLIC USE OF THE SIDEWALKS)

1021040

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1013665>

Violation Maser Use Permit # 3005085

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021694>

Temporary Use permit expired 5-1-09 - there is no recent application to continue this Use and the information for project #3009360 states "no more applications will be accepted or approved" (after the May 1, 2009 date of expiration).

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022576>

1/12/09 JS noise is from rooftop condensing units installed by QFC under an over the counter STFI permit.the equipment is producing 52 dB @ 200' in the park.the park is Zoned commercial and the noise is in compliance with the objective standards of the noise ordinance.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022122>

Application for a Tenant Relocation License. Total units: 8; total units occupied: 8. Demolition.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1012141>

Replacing roof structure w/ new rafters, beams & dormers; remodeling basement into bedrooms (egress windows too small); & removing established parking all without a permit & inspections from DPD. STOP WORK ORDER posted 10/12/09.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020841>

Violations of the HBMC:drains slow in kitchen, bath, broken & missing wall & ceiling coverings, egress

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=>

# Test Map

-122.31378671      47.6102377

-122.33263138      47.60294469

-122.34252822      47.61183696

-122.38672403      47.67055197

-122.29683859      47.72226613

-122.3007112      47.60253811

-122.3007112      47.60253811

# Test Map

Case 1022183 - Application Added as of 05/11/2010      HZW      1413 QUEEN ANNE AVE N

Case 1017272 - Case Closed as of 02/20/2009      UNFIT      8727 PHINNEY AVE N

Case 1021734 - Notice or Order Issued as of 03/25/2010      HZW      10335 MIDVALE AVE N

Case 1022524 - Application Added as of 05/17/2010      CONSTRUCT      9105 RAINIER AVE S

Case 1022024 - Application Added as of 05/07/2010      CONSTRUCT      1706 RAINIER AVE S

Case 1022371 - Application Added as of 04/30/2010      HZW      10306 MERIDIAN AVE N

Case 1021536 - Notice or Order Issued as of 01/14/2010      CONSTRUCT      614 1ST AVE

# Test Map

broken & missing wall & ceiling coverings, egress window taped/repair or replace, heat intermittant, wiring for stove questionable. Covers missing for lt. fixtures & electrical outlets. Possible roach infestation. Handrail missing or in disrepair for interior bsmt stairs, exterior bsmt door & front stairs. Vegetation overgrowth & outdoor junk storage Owner storage in rental unit. deteriorated & unsecured bldg., pictures in file.

1022537

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022183>

Requested abatement- duplex

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017272>

illegal sixth dwelling unit in 5 unit blding

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021734>

OBTAIN A PERMIT TO FINAL PERMIT #6130333--  
CALL FOR FINAL INSPECTION AND OBTAIN A  
CERTIFICATE OF OCCUPANCY

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022524>

Permit 6241751 was issued 4/14/10 for work originally started without a permit. This case will remain open until all required inspections have been requested and approved by DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022024>

Housin violations in unit#623-

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022371>

THERE IS A NEW SIGN AND A NEW BUSINESS AT  
THIS ADDRESS--A NEW SIGN PERMIT IS NEEDED--  
MUST ALSO GET PIONEER SQUARE  
PRESERVATION BOARD APPROVAL

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021536>

# Test Map

-122.35690284      47.6317397

-122.35453198      47.69318184

-122.34361368      47.70425556

-122.27031339      47.52212282

-122.30536612      47.58820502

-122.33278822      47.70348967

-122.33364608      47.60236873

# Test Map

Case 1018813 - Payment Processed as of 06/19/2009    TRAO    5159 42ND AVE S

Case 1022117 - Citation Issued as of 05/06/2010    CITATION    3618 2ND AVE NW

Case 1011547 - Application Added as of 04/04/2007    CONSTRUCT    6317 39TH AVE S

Case 1021894 - Notice or Order Issued as of 05/14/2010    HZW    12011 32ND AVE NE

Case 1015225 - Application Accepted as of 05/20/2008    TRAO    12311 32ND AVE NE

Case 1020238 - Application Added as of 03/23/2010    HZW    3613 2ND AVE NW

Case 1022469 - Application Added as of 05/11/2010    CITATION    9031 14TH AVE SW

Case 1022082 - Application Added as of 05/17/2010    CITATION    8751 12TH AVE NW

Case 1022439 - Application Added as of 05/06/2010    CITATION    1521 21ST AVE S

Case 1017630 - Application Added as of 02/06/2009    HZW    8116 8TH AVE S



# Test Map

## PRESERVATION BOARD APPROVAL

Application for a Tenant Relocation License. Total units: 1; total units occupied: 1. Demolition.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018813>

Junk storage in L2 zone sfr

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022117>

Recently installed drainage requires permit and inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1011547>

HBMC Violation

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021894>

Application for a Tenant Relocation License. Total units: 24; total units occupied: 24. Demolition.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015225>

Property is a single family residence per 1906 permit #44838 but being used as four dwelling units, 1 on each floor: basement, 1st, 2nd & 3rd floors. Permits #690763, #6129100 and #6141131 were never finaled.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020238>

5/6/10 ej -Inspection shows more than the allowed 3 vehicles parked on a single family lot.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022469>

Zoning violation.furniture, mattress,bicycle and more items stored in driveway.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022082>

04/07/10 bg - Two vehicles parked in required front yard. photos taken

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022439>

10/03/08 KB inspected property and Housing Code violations exist-missing exterior stairs

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017630>

# Test Map

-122.28099361 47.55557218

-122.35870194 47.65384613

-122.28360766 47.54551712

-122.29433971 47.7159226

-122.29446194 47.71786721

-122.35918974 47.65374106

-122.35311021 47.52187741

-122.37170808 47.69358152

-122.30539057 47.58892706

-122.3226526 47.52999347

# Test Map

Case 1021848 - Application Added as of 02/26/2010	CITATION	4533 9TH AVE NE
Case 1016504 - Application Accepted as of 07/01/2009	ADVISORY	2645 NW 60TH ST
Case 1021752 - Notice or Order Issued as of 03/26/2010	CONSTRUCT	666 S HOMER ST
Case 1016309 - Application Added as of 01/21/2010	HZW	740 S ELMGROVE ST
Case 1022035 - Application Added as of 04/20/2010	CITATION	2416 E MARION ST
Case 1013622 - Findings Issued as of 04/27/2009	ADVISORY	4525 S HENDERSON ST
Case 1015333 - Application Added as of 03/31/2008	CONSTRUCT	4525 S HENDERSON ST
Case 1021646 - Case Opened as of 02/10/2010	HZW	1829 S LANE ST

# Test Map

Violations of Land Use Code observed.

Condo Conversion

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021848>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016504>

Occupying an indoor acrobat structure/facility requires a Certificate of Occupancy. All required inspections & approvals needed for Permit 6189698 or discontinue occupancy.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021752>

VIOLATION ALERT Inspection shows storage for Independent Metals, the Use has not been establish for this parcel.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016309>

outdoor storage includes boat, construction equipment, supplies & debris, appliances, garden equipment & supplies, lumber, buckets & other items; pictures in file.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022035>

10 unit 1 building condo conversion

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1013622>

Construction permit required to convert existing apartment to condos & create 11th dwelling unit per plan & EHB 1848. Work being performed also requires electrical, mechanical & plumbing permits AND inspections.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015333>

"VIOLATION ALERT" VIOLATION OF THE SEATTLE LAND USE AND ZONING CODE CONFIRMED (SHED BUILT ON VACANT SF 5000 LOT WITHOUT PRINCIPAL USE STRUCTURE.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021646>

# Test Map

-122.31866021 47.66233826

-122.39221314 47.67217391

-122.32459049 47.55240872

-122.32367797 47.53075714

-122.30069217 47.610198

-122.27533031 47.52299889

-122.27533031 47.52299889

-122.30762663 47.59645467

# Test Map

Case 1021113 - Case Resolved as of 01/04/2010	CITATION	8719 10TH AVE S
Case 1022513 - Application Added as of 05/14/2010	CITATION	8719 10TH AVE S
Case 1021817 - Application Added as of 04/21/2010	HZW	4208 37TH AVE S
Case 1020728 - Application Added as of 09/30/2009	CONSTRUCT	3423 KCLICKITAT AVE SW
Case 1022420 - Application Added as of 05/04/2010	CITATION	4204 LETITIA AVE S
Case 1021981 - Notice or Order Issued as of 03/23/2010	HZW	4733 21ST AVE NE
Case 1014584 - Application Added as of 06/29/2009	CITATION	1112 21ST AVE S
Case 1019346 - Citation Issued as of 04/01/2010	CITATION	1112 21ST AVE S
Case 1022504 - Application Added as of 05/14/2010	CITATION	1112 21ST AVE S

# Test Map

Bldg. secure; outdoor storage in yard areas, pictures in file.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021113>

VIOLATION OF THE SEATTLE LAND USE AND ZONING CODE OBSERVED (SCRAP WOOD, PROPANE TANK, GAS CONTAINER IN YARD) TOOK PHOTO.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022513>

VIOLATION OF THE SEATTLE LAND USE AND ZONING CODE OBSERVED(TUB IN SIDE YARD). TOOK PHOTOS.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021817>

See Vic S

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020728>

04/30/10 bg - Junk storage - Inoperable vehicles in the rear yard along with old carpet.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022420>

Violation of HBMC observed.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021981>

OBSERVED VIOLATIONS OF THE SEATTLE LAND USE AND ZONING CODE (PALLET BOARDS, APPLIANCES, TARP AND DEBRIS IN L1 ZONE).TOOK PHOTOS.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014584>

OBSERVED VIOLATIONS OF THE SEATTLE LAND USE AND ZONING CODE (INOPERABLE VEHICLE, MISSING TIRE, AUTO TIRES, SCRAP METAL AND PLASTIC IN YARD, L1 ZONE).

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019346>

OBSERVED VIOLATIONS OF THE SEATTLE LAND USE AND ZONING CODE (SCRAP WOOD METAL

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022504>

# Test Map

-122.32051492	47.52511455
---------------	-------------

-122.32051492	47.52511455
---------------	-------------

-122.28581021	47.56510336
---------------	-------------

-122.35321245	47.57221311
---------------	-------------

-122.28944023	47.56533006
---------------	-------------

-122.30575636	47.66406595
---------------	-------------

-122.30455999	47.5926488
---------------	------------

-122.30455999	47.5926488
---------------	------------

-122.30455999	47.5926488
---------------	------------



# Test Map

Case 1017402 - Application Added as of 10/14/2009	CONSTRUCT	6006 33RD AVE S
---	-----------	-----------------

Case 1018356 - Application Added as of 03/11/2009	CONSTRUCT	6006 33RD AVE S
---	-----------	-----------------

Case 1022356 - Application Added as of 05/11/2010	HZW	6410 9TH AVE NE
---	-----	-----------------

Case 1013129 - Application Added as of 09/08/2009	CONSTRUCT	9129 48TH AVE S
---	-----------	-----------------

Case 1019382 - Application Added as of 02/02/2010	HZW	9129 48TH AVE S
---	-----	-----------------

Case 1021574 - Payment Processed as of 05/20/2010	TRAO	1623 BELLEVUE AVE
---	------	-------------------

Case 1019789 - Notice or Order Issued as of 12/22/2009	CONSTRUCT	1623 BELLEVUE AVE
--	-----------	-------------------

Case 1020725 - Application Added as of 09/30/2009	CONSTRUCT	100 W MERCER ST
---	-----------	-----------------

# Test Map

AND DEBRIS IN L1 ZONE). TOOK PHOTOS.

Constructing a retaining wall over 4' tall & adding more than 25 cu.yds. fill in a Steep Slope ECA, constructing a 2nd story deck & establishing parking on south & east sides of house requires zoning approval, permit & inspections from DPD. STOP WORK ORDER posted 9/23/08.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017402>

Ecology block retaining wall on south side of property (built without a permit) is failing and the slope on the south and east sides of the house have de-stabilized.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018356>

HBMC violations observed.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022356>

Constructing a deck, building a shed larger than 120 sq.ft. and performing an interior remodel including creating a 2nd dwelling unit in a SFR requires permits and inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1013129>

"VIOLATION ALERT" VIOLATION OF THE SEATTLE LAND USE AND ZONING CODE CONFIRMED (UNAUTHORIZED DWELLING UNIT IN BASEMENT.)

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019382>

Application for a Tenant Relocation License. Total units:11;total units occupied:11. Demolition.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021574>

EXCEPTIONAL TREE REMOVED IN COMMERCIAL ZONE

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019789>

INSPECTOR IS WORKING WITH CONTRACTOR TO RESOLVE SCOPE OF WORK

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020725>

# Test Map

-122.28998984	47.54764064
---------------	-------------

-122.28998984	47.54764064
---------------	-------------

-122.31842601	47.67539067
---------------	-------------

-122.27314721	47.52133348
---------------	-------------

-122.27314721	47.52133348
---------------	-------------

-122.32715403	47.61593332
---------------	-------------

-122.32715403	47.61593332
---------------	-------------

-122.35823815	47.62477997
---------------	-------------

# Test Map

Case 1022512 - Application Added as of 05/14/2010	CITATION	6627 ELLIS AVE S
---	----------	------------------

Case 1014207 - Application Added as of 11/27/2007	HZW	5945 39TH AVE S
---	-----	-----------------

Case 1014365 - Notice or Order Issued as of 05/14/2010	CONSTRUCT	5945 39TH AVE S
--	-----------	-----------------

Case 1022506 - Application Added as of 05/13/2010	CITATION	3544 S HUDSON ST
---	----------	------------------

Case 1018118 - Application Accepted as of 03/03/2009	TRAO	12047 35TH AVE NE
--	------	-------------------

Case 1010812 - Application Added as of 01/16/2007	CONSTRUCT	8131 RAINIER AVE S
---	-----------	--------------------

Case 1019507 - Case Resolved as of 04/29/2010	HZW	2509 S JACKSON ST
---	-----	-------------------

Case 1010925 - Application Added as of 01/29/2007	CONSTRUCT	843 HIAWATHA PL S
---	-----------	-------------------

Case 1022562 - Application Added as of 05/20/2010	CITATION	413 11TH AVE
---	----------	--------------

# Test Map

VIOLATION OF THE WEEDS AND VEGETATION  
ORDINANCE OBSERVED (OVERGROWTH  
OBSTRUCTING SIDEWALK ALONG ELLIS AVE S

Inspection shows the Land Use has not been establish.  
zoning violation.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022512>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014207>

Additions, decks & carports and changing SFR to  
assembly occupancy, if allowed by zoning & building  
codes, requires permit & inspections by DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014365>

05/13/10 bg - Branches lower than 8' clearance over  
sidewalk.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022506>

Application for a Tenant Relocation License. Total units:  
5; total units occupied: 5. Demolition.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018118>

Adding a new door (and covering old door) with ramp to  
R-O-W and new window in an existing commercial  
building requires permit and inspections from DPD.  
Permit 727100 requires final inspection to obtain C of O.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010812>

06/02/09 - Vacant lot has 3 commercial vehicles on it, 2  
trackhoes and a commercial truck. The rear of the  
property is filled with construction debris, wood, pallets,  
plastic buckets, paint cans, tires. There are a four  
vehicles covered in plastic tarps. photos taken. bg

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019507>

Dewatering requires a permit from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010925>

Violation of the Land Use Code

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022562>

# Test Map

-122.31950153 47.54321203

-122.28369015 47.54843803

-122.28369015 47.54843803

-122.28687544 47.55721546

-122.29167027 47.7168949

-122.27019114 47.52940589

-122.29936995 47.59907635

-122.30971039 47.59490559

-122.31840856 47.60566671

# Test Map

Case 1007808 - Application Added as of 03/15/2006	CONSTRUCT	800 14TH AVE
Case 1007059 - Application Added as of 05/06/2010	CONSTRUCT	848 S CLOVERDALE ST
Case 1006000 - Case Opened as of 01/17/2006	CONSTRUCT	2508 ALKI AVE SW
Case 1012587 - Notice or Order Issued as of 05/17/2010	CONSTRUCT	1331 15TH AVE S
Case 1019327 - Application Added as of 05/20/2009	CONSTRUCT	4933 52ND AVE S
Case 1020562 - Notification Issued as of 03/08/2010	VACANT	4933 52ND AVE S
Case 1001981 - Application Added as of 07/30/2004	CONSTRUCT	4237 NE 90TH ST
Case 1007983 - Application Added as of 04/12/2007	CONSTRUCT	2324 41ST AVE SW
Case 1015854 - Application Added as of 01/27/2009	CONSTRUCT	2324 41ST AVE SW

# Test Map

Side Sewer Permit required for downspout drainage to curb through alley R-O-W, need to use approved piping & bedding materials for drain line and SDOT approval required for work in R-O-W.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1007808>

Permit from DPD required for new foundation, new pony walls, stairs on west side, roof structure and interior alterations to SF home.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1007059>

CMU wall with roof built on east side of property requires a permit from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1006000>

Addition to east side (front) of SFR requires permit(s) & inspections from DPD and appears to be in front yard setback. STOP WORK ORDER posted 6/25/07.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1012587>

Performing a side sewer repair requires a Side Sewer Permit and inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019327>

Bldg. secure. Open to weather, missing paint, open ditches, outdoor storage.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020562>

AT LEAST 25TH CUBIC YARDS GRADED IN NEW POTENTIAL SLIDE AREA ECA--FILL DEPOSITED AT THE NE SIDE OF THE ROAD LEADING TO HOUSE

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1001981>

New structure larger than 120 sq. ft. in rear yard AND structural changes to an existing garage requires permit(s) from DPD. Stop Work Order posted 4/4/06.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1007983>

Application 6199671 will be revised to address the substantial repairs (gutting interior, new walls & new windows throughout) to SF residence. This case will remain open until all required permits have been issued

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015854>



# Test Map

-122.31378113	47.60936604
---------------	-------------

-122.32082234	47.5266316
---------------	------------

-122.40578721	47.58079178
---------------	-------------

-122.31426072	47.59054249
---------------	-------------

-122.26850955	47.55724925
---------------	-------------

-122.26850955	47.55724925
---------------	-------------

-122.28101192	47.69351951
---------------	-------------

-122.38355793	47.58270581
---------------	-------------

-122.38355793	47.58270581
---------------	-------------

# Test Map

Case 1014058 - Application Added as of 07/28/2008	CONSTRUCT	7328 31ST AVE SW
---	-----------	------------------

Case 1011240 - Application Added as of 03/05/2007	TRAO	1006 N 39TH ST
---	------	----------------

Case 1017142 - Application Added as of 12/31/2009	CONSTRUCT	9622 20TH AVE NE
---	-----------	------------------

Case 1022474 - Notice or Order Issued as of 05/12/2010	HZW	7638 WINONA AVE N
--	-----	-------------------

Case 1001731 - Application Added as of 03/12/2004	CONSTRUCT	721 25TH AVE S
---	-----------	----------------

Case 1011542 - Notice or Order Issued as of 03/29/2010	CONSTRUCT	3922 SW HOLLY ST
--	-----------	------------------

Case 1007806 - Application Added as of 03/13/2006	CONSTRUCT	10111 BEACON AVE S
---	-----------	--------------------

Case 1019533 - Application Added as of 07/14/2009	HZW	2258 NE 65TH ST
---	-----	-----------------

Case 1003584 - Case Opened as of 06/30/2008	CONSTRUCT	6306 BEACH DR SW
---	-----------	------------------

# Test Map

remain open until all required permits have been issued & all required inspections have been requested and approved.

Permit req'd for 2nd story addition including engineer sealed approval for new size & location of windows. Okay to demo portion built w/o permit (no demo permit req'd per Berg). Current height allowed by code.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014058>

Issuance of an "Owner's Certification of Occupancy or No Displacement"

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1011240>

PERMIT REQUIRED FOR RETAINING WALL HIGHER THAN 4 FEET AND IN RIPARIAN CORRIDOR ECA

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017142>

Unpermitted basement ADU & eliminated garage req'd parking

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022474>

Side sewer permit required for work being performed without a permit.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1001731>

Building a deck in the required front yard, remodeling a kitchen and installing French doors requires a permits and inspections from DPD. STOP WORK ORDER posted 4/2/07.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1011542>

Building a detached garage requires a permit from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1007806>

Land Use Code Violation

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019533>

Project 3003091 was issued on 10/23/07 for tree and vegetation removal in ECA 2 (potential slide) that

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=>

# Test Map

-122.37225708	47.53648414
---------------	-------------

-122.34547826	47.65436136
---------------	-------------

-122.3066209	47.69912304
--------------	-------------

-122.34024795	47.68441578
---------------	-------------

-122.30018603	47.59612426
---------------	-------------

-122.38287852	47.54312959
---------------	-------------

-122.27197294	47.50984142
---------------	-------------

-122.30334345	47.67597459
---------------	-------------

-122.39813679	47.54660288
---------------	-------------

# Test Map

Case 1021134 - Notice or Order Issued as of 12/22/2009	CONSTRUCT	808 31ST AVE S
Case 1006723 - Application Added as of 10/28/2005	TRAO	200 N 85TH ST
Case 1014853 - Notice or Order Issued as of 03/29/2010	CONSTRUCT	8712 HAMLET AVE S
Case 1020668 - Notice or Order Issued as of 03/09/2010	HZW	151 12TH AVE
Case 1021101 - Application Added as of 11/23/2009	CONSTRUCT	151 12TH AVE
Case 1020794 - Citation Issued as of 02/03/2010	CITATION	151 12TH AVE
Case 1010994 - Application Added as of 02/06/2007	CONSTRUCT	1511 RAINIER AVE S
Case 1017651 - Application Added as of 03/11/2010	CITATION	6539 21ST AVE SW
Case 1016651 - Application Added as of 10/22/2008	TRAO	1313 CALIFORNIA AVE SW

# Test Map

vegetation removal in ECA 2 (potential slide) that originally occurred without a revegetation plan from DPD.

TREE HAS BEEN CUT ON STEEP SLOPE--  
RESTORATION REQUIRED

1003584

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021134>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1006723>

Permit 6174798 was issued 8/14/08 for work originally started without a permit. This case will remain open until all required inspections have been requested and approved by DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014853>

Violation of the Land Use Code.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020668>

Temporary Erosion & Sedimentation Control (TESC) is not per expired Permit 6167711 or the Seattle Stormwater, Grading & Drainage Control Code.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021101>

Violation of the Land Use Code.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020794>

Continuation of PTS Case BC993090: INSTALLING TRAILERS W/O PERMIT.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010994>

09/26/08 KB inspected property and Land Use violation exists-inop vehicle

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017651>

Issuance of "Owner's Certification of Occupancy or No Displacement". Total units: 1; total units occupied: 1. Demolition.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016651>

# Test Map

-122.29242121	47.59546692
---------------	-------------

-122.35641336	47.69078827
---------------	-------------

-122.26594049	47.52564714
---------------	-------------

-122.31708977	47.60282225
---------------	-------------

-122.31708977	47.60282225
---------------	-------------

-122.31708977	47.60282225
---------------	-------------

-122.30692203	47.58925461
---------------	-------------

-122.35988642	47.54368166
---------------	-------------

-122.38651344	47.59155135
---------------	-------------

# Test Map

Case 1021638 - Notice or Order Issued as of 03/10/2010	CONSTRUCT	4600 FREMONT AVE N
--	-----------	--------------------

Case 1002927 - Application Added as of 07/22/2004	CONSTRUCT	5322 S WALLACE ST
---	-----------	-------------------

Case 1022422 - Notice or Order Issued as of 05/12/2010	HZW	6727 RAINIER AVE S
--	-----	--------------------

Case 1020600 - Case Resolved as of 05/21/2010	HZW	1515 S DAWSON ST
---	-----	------------------

Case 1021423 - Notice or Order Issued as of 05/10/2010	HZW	1605 BELLEVUE AVE
--	-----	-------------------

Case 1021718 - Notification Issued as of 05/10/2010	VACANT	1605 BELLEVUE AVE
---	--------	-------------------

Case 1022511 - Application Added as of 05/14/2010	CITATION	1756 VALENTINE PL S
---	----------	---------------------

Case 1020093 - Application Added as of 08/20/2009	CITATION	4317 S MORGAN ST
---	----------	------------------

Case 1020363 - Notification Issued as of 08/21/2009	VACANT	4317 S MORGAN ST
---	--------	------------------



# Test Map

NEW SHED IS LARGER THAN 120 SQUARE FEET  
AND REQUIRES A PERMIT

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021638>

Violations found: Side Sewer work without a permit,  
retaining walls without a permit and Temporary Erosion  
& Sedimentation Control (TESC) is inadequate.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1002927>

OBSERVED HIGH INTENSITY LIGHT FIXTURES ON  
THE ROOFS ABOVE THE EAST AND WEST  
EXTERIOR WALLS DURING DAYLIGHT.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022422>

09/08/09 bg - Parking in required front yard, storage of  
junk. photos taken.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020600>

Open to weather due to fire damage.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021423>

Open to weather due to fire damage.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021718>

Concrete foundations only; junk on site includes tires,  
construction debris & equipment, lumber, tarps, pictures  
in file.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022511>

7/10/09 Ej- Inspection shows vacant and burnt house  
open to entry, piles of debris over the yard, vegetation  
overgrowth throughout the property. Inoperable vehicles  
located on the property.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020093>

7/10/09 Ej- Inspection shows vacant and burnt house  
open to entry, piles of debris over the yard, vegetation  
overgrowth throughout the property. Inoperable vehicles  
located on the property.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020363>

# Test Map

-122.34968294	47.6623887
---------------	------------

-122.26660597	47.49779587
---------------	-------------

-122.27358046	47.54162916
---------------	-------------

-122.31274936	47.55541609
---------------	-------------

-122.32703068	47.61557165
---------------	-------------

-122.32703068	47.61557165
---------------	-------------

-122.30707077	47.58742451
---------------	-------------

-122.27907267	47.54387343
---------------	-------------

-122.27907267	47.54387343
---------------	-------------

# Test Map

Case 1020362 - Application Added as of 08/21/2009      HZW      4317 S MORGAN ST

Case 1020080 - Application Added as of 08/03/2009      HZW      5145 S MORGAN ST

Case 1014580 - Application Added as of 02/10/2009      CONSTRUCT      7363 BEACON AVE S

Case 1022057 - Application Added as of 05/13/2010      CITATION      804 NW 87TH ST

Case 1020765 - Case Resolved as of 12/23/2009      HZW      6602 BEACON AVE S

Case 1022425 - Application Added as of 05/19/2010      CITATION      1738 NE 88TH ST

Case 1014653 - Application Added as of 01/14/2008      CONSTRUCT      1703 15TH AVE S

Case 1007378 - Application Added as of 01/30/2006      CONSTRUCT      424 35TH AVE S

Case 1012447 - Application Added as of 03/05/2009      HZW      8456 7TH AVE SW

# Test Map

7/10/09 Ej- Inspection shows vacant and burnt house open to entry, piles of debris over the yard, vegetation overgrowth throughout the property. Inoperable vehicles located on the property.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020362>

07/22/09 bg - Night site visit, lights on the top of the Synagogue shining into adjacent property, along with lights on construction trailers. photos taken.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020080>

Permit 6172080 was issued 2/6/09 for work originally performed without a permit. This case will remain open until all required inspections have been requested & approved by DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014580>

Zoning violation.Exceeding number of vehicles in SF zone.Outdoor junk storage including but not limited to construction and yard debris,a brown vehicle with license plate number 207-uke.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022057>

10/01/09 bg - Tenant contacted as no water at the residence at this time, meter removed.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020765>

Weeds and Vegetation Ordinance Violation

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022425>

Remodeling a garage into habitable space requires zoning approval, permits & inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014653>

ROOF OVER FRONT PORCH REQUIRES PERMIT

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1007378>

failure to comply with ADU requirements. Owner rents out both units, including the legalized ADU

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1012447>

# Test Map

-122.27907267 47.54387343

-122.26797178 47.54387409

-122.29206335 47.53556759

-122.3664576 47.6922624

-122.29915074 47.5434828

-122.30783978 47.69227093

-122.31403717 47.58828298

-122.28750844 47.59832215

-122.34393189 47.52663681

# Test Map

Case 1014350 - Application Added as of 02/22/2010	HZW	8456 7TH AVE SW
Case 1014351 - Application Added as of 02/06/2009	HZW	8456 7TH AVE SW
Case 1021161 - Notice or Order Issued as of 04/26/2010	HZW	8456 7TH AVE SW
Case 1019583 - Citation Issued as of 01/07/2010	CITATION	5405 25TH AVE SW
Case 1019200 - Application Added as of 06/15/2009	CONSTRUCT	5405 25TH AVE SW
Case 1021754 - Payment Processed as of 05/20/2010	TRAO	4301 STONE WAY N
Case 1021951 - Application Added as of 03/08/2010	CONSTRUCT	2720 FAIRMOUNT AVE SW
Case 1007718 - Application Added as of 04/12/2007	NOISE	4608 SW SEATTLE ST
Case 1002251 - Application Added as of 05/12/2004	CONSTRUCT	2703 E UNION ST
Case 1022375 - Application Added as of 04/29/2010	CITATION	7303 44TH AVE SW

# Test Map

HBMC violations. Broken window, incomplete repairs, electrical. plumbing violations

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014350>

OFF STREET PARKING HAS BEEN REMOVED

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014351>

illegal basement dwelling unit

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021161>

zoning violation- 6/10/09 CA.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019583>

Covering the front porch of a single family residence and making an addition to & remodeling/creating habitable space for a business in an accessory structure requires permits & inspections, including side sewer, from DPD. STOP WORK ORDER posted 5/5/09.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019200>

Application for a Tenant Relocation License. Total units:9; total units occupied:8. Demolition.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021754>

Tree & vegetation removal on a site mapped ECA 1 of >1500 sq.ft. requires restoration plan & replanting. Permit 6242305 was obtained on 3/4/10 for side sewer work originally started without a permit.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021951>

Powervent emits noise that exceeds objective noise standards.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1007718>

Roof drains need to be properly installed and discharge into an approved public conveyance system.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1002251>

4/27/10 EJ- Inspection shows vegetation encroaching

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=>

# Test Map

-122.34393189 47.52663681

-122.34393189 47.52663681

-122.34393189 47.52663681

-122.36458059 47.55349205

-122.36458059 47.55349205

-122.34255274 47.65941436

-122.38193935 47.57852711

-122.39074786 47.58962739

-122.29725968 47.61273857

-122.38850727 47.53804837



# Test Map

Case 1002346 - Application Added as of 05/19/2004      CONSTRUCT      3625 SW TRENTON ST

Case 1014320 - Application Added as of 08/20/2008      CONSTRUCT      4326 SW DONOVAN ST

Case 1021292 - Application Added as of 12/11/2009      CONSTRUCT      2216 SW ORCHARD ST

Case 1019736 - Application Added as of 06/23/2009      CONSTRUCT      11836 55TH AVE S

Case 1018160 - Application Added as of 09/03/2009      CONSTRUCT      3116 SW WEBSTER ST

Case 1015872 - Application Added as of 05/19/2008      CONSTRUCT      5652 37TH AVE SW

Case 1012537 - Findings Issued as of 07/01/2009      ADVISORY      840 NE 125TH ST

# Test Map

onto the sidewalk along SW Othello St.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022375>

Violation found: work without a permit and not in conformance with codes (porch).

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1002346>

Unpermitted 8'+ retaining wall is failing. Geotechnical engineer to supervise removal of backfill. Grading & building permits & inspections required from DPD. Structural & Geotechnical reports required to be submitted to DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014320>

Permit 6235108 was issued 12/8/09 for electrical work originally started without a permit. This case will remain open until all inspections have been requested and approvals have been obtained from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021292>

Constructing a 2 story addition along & the entire length of the east side of a single family residence requires permits & inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019736>

Replacing a foundation requires permit(s) and inspections from DPD. Permit 733632 renewed by 744856 requires renewal/re-establishment & all req'd inspections from DPD. STOP WORK ORDER posted 1/2/09.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018160>

Removing trees & vegetation from a Steep Slope ECA requires approval from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015872>

Condo Conversion.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1012537>

# Test Map

-122.37911304      47.52450083

-122.38879215      47.52614049

-122.36203387      47.53790673

-122.26325395      47.49612656

-122.37335855      47.53574403

-122.37859144      47.55046297

-122.31877267      47.71965257

# Test Map

Case 1022011 - Citation Issued as of 03/29/2010	CITATION	4848 DELRIDGE WAY SW
Case 1002419 - Application Added as of 01/11/2008	CONSTRUCT	2707 S FERDINAND ST
Case 1011677 - Application Added as of 04/12/2007	CONSTRUCT	2707 S FERDINAND ST
Case 1021350 - Case Resolved as of 03/29/2010	CITATION	13544 27TH AVE NE
Case 1018578 - Application Added as of 07/23/2009	CONSTRUCT	3101 W COMMODORE WAY
Case 1022107 - Application Added as of 03/29/2010	CONSTRUCT	414 8TH AVE S
Case 1018649 - Application Added as of 03/01/2010	HZW	6937 ELLIS AVE S
Case 1012009 - Application Added as of 05/10/2007	CONSTRUCT	1707 PARKSIDE DR E

# Test Map

Violation of Land Use- Outdoor junk storage

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022011>

Building Permit 6098193 was issued 7/17/07 for work originally started without a permit. This case will remain open until all required inspections have been approved by DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1002419>

Structures (some 2-stories) built without permit in required yard. PERMIT & INSPECTIONS REQUIRED FOR REMOVAL of structures. STOP WORK ORDER posted 4/12/07.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1011677>

Land Use Code Violation

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021350>

PERMIT REQUIRED FOR RETAINING WALLS IN STEEP SLOPE ECA

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018578>

The International Special Review District Board has not approved this sign. Sign must be removed.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022107>

"VIOLATION ALERT" VIOLATION OF THE SEATTLE LAND USE AND ZONING CODE OBSERVED (CHANGE OF USE PERMIT REQUIRED FOR EXISTING STRUCTURES, VEHICLE PARKING & OUTDOOR STORAGE ON "VACANT LOT"). DWELLING WAS DEMOLISHED UNDER PERMIT # 552875 8/2/74 AND VACANT LOT REMAINED.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018649>

ELECTRICAL WORK IS NOT DONE IN ACCORDANCE WITH PERMIT #6023989--THIS PERMIT IS EXPIRED

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1012009>

# Test Map

-122.36260736	47.55780405
---------------	-------------

-122.29769348	47.55823629
---------------	-------------

-122.29769348	47.55823629
---------------	-------------

-122.29891189	47.72786253
---------------	-------------

-122.39699544	47.6635439
---------------	------------

-122.32228653	47.59869858
---------------	-------------

-122.32062894	47.53970532
---------------	-------------

-122.29125859	47.63493371
---------------	-------------

# Test Map

Case 1018693 - Application Added as of 03/09/2009	TRAO	2216 11TH AVE W
Case 1014683 - Payment Processed as of 03/14/2008	TRAO	3608 COURTLAND PL S
Case 1008295 - Application Added as of 05/02/2006	CONSTRUCT	4509 50TH AVE S
Case 1010212 - Application Added as of 10/31/2006	CONSTRUCT	7321 18TH AVE SW
Case 1016670 - Application Added as of 08/08/2008	CONSTRUCT	7321 18TH AVE SW
Case 1021485 - Case Opened as of 01/12/2010	HZW	2501 FAIRVIEW AVE E
Case 1017571 - Application Added as of 11/14/2008	CONSTRUCT	6609 SW ADMIRAL WAY
Case 1022224 - Application Added as of 05/06/2010	CITATION	4804 NE 60TH ST
Case 1021959 - Application Added as of 04/21/2010	CITATION	933 NW 59TH ST
Case 1014669 - Application Added as of 02/26/2010	CONSTRUCT	1907 S BENNETT DR

# Test Map

Notice of Violation of Tenant Relocation Assistance Ordinance (Seattle Municipal Code Chapter 22.210)

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018693>

Application for a Tenant Relocation License. Total units: 4; total units occupied: 4. Demolition.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014683>

SIDE SEWER PERMIT NEEDED FOR DOWNSPOUT CONNECTION

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1008295>

Grading more than 25 cubic yards in a Steep Slope Environmentally Critical Area (ECA) requires a permit from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010212>

Grading more than 25 cubic yards in a Steep Slope Environmentally Critical Area (ECA) requires a permit and inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016670>

Float reappeared by second (December) inspection, which had been prompted by a second complaint.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021485>

Removing and replacing two antennas and other work requires permits and inspections from DPD. STOP WORK ORDER posted 10/9/08 & 10/21/08.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017571>

Violation of weeds and vegetation ordinance observed.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022224>

zoning violation

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021959>

Side sewers and stormwater drainage lines installed without all required inspections. Curb inlet catch basins require reinstallation or curbing so runoff is directed into the catch basins.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014669>



# Test Map

-122.37128485	47.63917699
---------------	-------------

-122.28676835	47.57128911
---------------	-------------

-122.27103793	47.56254192
---------------	-------------

-122.35735625	47.53633537
---------------	-------------

-122.35735625	47.53633537
---------------	-------------

-122.32931977	47.64292537
---------------	-------------

-122.41698908	47.57555687
---------------	-------------

-122.27718029	47.67313596
---------------	-------------

-122.37012798	47.67144672
---------------	-------------

-122.30803923	47.55432977
---------------	-------------

# Test Map

Case 1014790 - Case Opened as of 02/26/2010	HZW	1907 S BENNETT DR
Case 1019424 - Case Resolved as of 05/21/2010	CITATION	3727 MERIDIAN AVE N
Case 1015671 - Application Added as of 04/29/2008	CONSTRUCT	7956 46TH AVE S
Case 1019496 - Case Resolved as of 12/23/2009	HZW	2301 6TH AVE
Case 1020961 - Application Added as of 11/03/2009	CONSTRUCT	2301 6TH AVE
Case 1022434 - Application Added as of 05/06/2010	HZW	8416 RAINIER AVE S
Case 1012847 - Application Added as of 07/19/2007	TRAO	1906 24TH AVE S
Case 1022258 - Notice or Order Issued as of 04/27/2010	HZW	1906 24TH AVE S
Case 1016378 - Notification Issued as of 05/15/2009	VACANT	1906 24TH AVE S
Case 1012859 - Application Added as of 07/19/2007	TRAO	2423 S HOLGATE ST

# Test Map

the catch basins.

LU Code violations of permit conditions

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014790>

junk storage in sfzone

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019424>

Extensive additions to single family home require zoning approval, permits and inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015671>

I observed the east side of the lot full of new car with the license covers "Downtown Toyota"- there are no permits in the system for this use.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019496>

Temporary Erosion & Sedimentation Control (TESC) is not per code: a functional construction entrance with 2"-4" quarry spalls required. No dirt or runoff to leave site.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020961>

Multiple Seattle Municipal Code violations, including but not limited to, a large number of rats on the property, a cockroach infestation, multiple housing violations, graffiti, and outdoor storage.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022434>

Violation of the Tenant Relocation Assistance Ordinance.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1012847>

junk storage in rear yard includes black plastic bags & carpeting, pictures in file..

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022258>

Bldg. open to entry; outdoor storage & veg. overgrowth.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016378>

Violation of the Tenant Relocation Assistance Ordinance

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=>

# Test Map

-122.30803923 47.55432977

-122.33417488 47.65277006

-122.27417244 47.52991102

-122.34300507 47.6164148

-122.34300507 47.6164148

-122.26961364 47.52786411

-122.30111106 47.58606415

-122.30111106 47.58606415

-122.30111106 47.58606415

-122.30059223 47.58617602

# Test Map

Case 1015990 - Notification Issued as of 05/15/2009	VACANT	2423 S HOLGATE ST
Case 1021631 - Payment Processed as of 04/30/2010	TRAO	1650 E OLIVE WAY
Case 1009020 - Case Opened as of 04/05/2007	CONSTRUCT	10026 51ST AVE SW
Case 1001009 - Case Opened as of 11/25/2003	CONSTRUCT	6919 HEIGHTS PL SW
Case 1001010 - Application Added as of 11/13/2003	CONSTRUCT	6917 HEIGHTS PL SW
Case 1001992 - Application Added as of 06/17/2004	CONSTRUCT	1926 31ST AVE S
Case 1002386 - Application Added as of 05/26/2004	CONSTRUCT	1926 31ST AVE S
Case 1013126 - Application Added as of 08/14/2007	CONSTRUCT	9545 45TH AVE NE
Case 1001124 - Application Added as of 12/12/2003	CONSTRUCT	1114 31ST AVE S
Case 1007562 - Application Added as of 02/21/2006	CONSTRUCT	8122 15TH AVE SW

# Test Map

	1012859
Bldg. secure; outdoor storage & veg. overgrowth.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015990">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015990</a>
Application for a tenant relocation license. Total units:8; total units occupied:8. Demolition.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021631">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021631</a>
Repairs to building and deck and constructing a CMU retaining wall in a Steep Slope and Potential Slide ECA requires permit(s) from DPD.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1009020">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1009020</a>
Building a retaining wall in ECA 1 (steep slope) without a permit.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1001009">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1001009</a>
Drainage work without a permit.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1001010">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1001010</a>
POSTED STOP WORK--ADDITION MUST BE CUT BACK FROM DISPUTED AREA,OR OWNER MUST PROVIDE A CERTIFIED SURVEY SHOWING THE PROPERTY LINE	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1001992">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1001992</a>
*	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1002386">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1002386</a>
PERMIT REQUIRED TO BUILD RETAINING WALL ON STEEP SLOPE (ECA)	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1013126">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1013126</a>
REMODELED BASEMENT W/O PERMIT	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1001124">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1001124</a>
STOP WORK POSTED FOR CONSTRUCTION IN REAR YARD--PERMIT NEEDED	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=</a>

# Test Map

-122.30059223	47.58617602
---------------	-------------

-122.32381188	47.61994956
---------------	-------------

-122.3942461	47.51313938
--------------	-------------

-122.38565881	47.54158865
---------------	-------------

-122.38566072	47.54172745
---------------	-------------

-122.29269511	47.58545833
---------------	-------------

-122.29269511	47.58545833
---------------	-------------

-122.28029344	47.69869599
---------------	-------------

-122.2923943	47.59288499
--------------	-------------

-122.35367715	47.52930691
---------------	-------------

# Test Map

Case 1015738 - Application Added as of 08/18/2009	CONSTRUCT	3253 PERKINS LN W
---	-----------	-------------------

Case 1015896 - Application Added as of 02/18/2009	CONSTRUCT	7715 28TH AVE NW
---	-----------	------------------

Case 1018768 - Citation Issued as of 04/08/2010	CITATION	9519 4TH AVE NW
---	----------	-----------------

Case 1020885 - Application Added as of 04/06/2010	HZW	9519 4TH AVE NW
---	-----	-----------------

Case 1004068 - Application Added as of 12/06/2004	CONSTRUCT	4412 SW WILDWOOD PL
---	-----------	---------------------

Case 1001726 - Application Added as of 03/11/2004	CONSTRUCT	900 NW CULBERTSON DR
---	-----------	----------------------

Case 1020603 - Application Added as of 12/30/2009	CONSTRUCT	3426 BEACH DR SW
---	-----------	------------------

Case 1022468 - Application Added as of 05/11/2010	CITATION	9045 12TH AVE SW
---	----------	------------------



# Test Map

REAR YARD--PERMIT NNEDED	1007562
PERMIT NEEDED FOR RETAINING WALL IN ECA	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015738">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015738</a>
PERMIT REQUIRED FOR GARAGE REMODEL AND 2ND STORY ADDITION	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015896">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015896</a>
NS inspected the property on 3/16/09-Inspection shows outdoor junk storage including but not limited to tarps,piles of wood,buckets,sinks,appliances,bags of garbage,tools,ladders,tables and more misc.items stored on the roof and in all required yards.Also more than 3 vehicles parked on the property and more than 3 temp.structures in the required rear yard.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018768">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018768</a>
*VIOLATION ALERT* Multiple zoning and building violations. Please require full review of plans when the owner comes in. Please call Tom Bradrick @ 4-7689 or Clay Thompson @ 4-7794	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020885">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020885</a>
Not building per plan (Permit 744914). Stop Work Order issued 12/3/04.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1004068">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1004068</a>
Violation of tree protection regulations noted.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1001726">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1001726</a>
Permit 6236793 was issued 12/29/09 for work orignally started without a permit. This case will remain open until all required inspections are requested and approved.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020603">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020603</a>
5/6/10 ej- inspection shows outdoor junk storage such as but not limited to tires, car parts and other miscellaneous	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022468">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022468</a>

# Test Map

-122.41662956	47.65013088
---------------	-------------

-122.39332639	47.68542084
---------------	-------------

-122.3626718	47.69854844
--------------	-------------

-122.3626718	47.69854844
--------------	-------------

-122.38973172	47.52099153
---------------	-------------

-122.36829544	47.73258565
---------------	-------------

-122.41577587	47.57364956
---------------	-------------

-122.35094503	47.5214934
---------------	------------

# Test Map

Case 1001072 - License Issued as of 08/16/2004	TRAO	2411 24TH AVE E
Case 1022277 - Application Added as of 04/20/2010	CITATION	2304 SW MYRTLE ST
Case 1001300 - Application Added as of 03/11/2004	CONSTRUCT	3507 SW SEOLA LN
Case 1010700 - Application Added as of 12/29/2006	CONSTRUCT	3507 SW SEOLA LN
Case 1001093 - Application Added as of 12/04/2003	CONSTRUCT	919 25TH AVE S
Case 1005204 - License Issued as of 05/24/2005	TRAO	11743 5TH AVE NE
Case 1019299 - Application Added as of 07/02/2009	CONSTRUCT	315 25TH AVE E
Case 1020680 - Notice or Order Issued as of 02/17/2010	HZW	2600 FAIRVIEW AVE E
Case 1020681 - Notice or Order Issued as of 02/08/2010	HZW	2600 FAIRVIEW AVE E

# Test Map

items located in the driveway.	1022468
Application for Tenant Relocation License	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1001072">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1001072</a>
4/15/10 ej- Inspection shows more than the allowed 3 vehicles parked on a single family lot not in an enclosed area. Towing business violates the home occupation rules.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022277">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022277</a>
Violation of the grading ordinance and SEPA.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1001300">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1001300</a>
Temporary Erosion and Sedimentation Controls (TESC) required as directed by a certified Erosion Control Specialist or licensed Geotechnical Engineer until a building permit is obtained and work has begun for retaining wall repair/replacement.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010700">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010700</a>
CARPORT NEEDS PERMIT--OR REMOVE IT	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1001093">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1001093</a>
Issance of an "Owner's Certification of Occupancy or No Displacment"	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1005204">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1005204</a>
DRAINAGE SYSTEM SHOULD PROTECT ADJACENT PRIVATE AND PUBLIC PROPERTY FROM DAMAGE	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019299">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019299</a>
Floating homes exceeding lot coverage (unresolved PTS cases from early 1990's)	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020680">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020680</a>
Accessory float w/o authorization	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020681">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020681</a>

# Test Map

-122.3023939	47.64056572
--------------	-------------

-122.36186209	47.53927566
---------------	-------------

-122.37685146	47.49750886
---------------	-------------

-122.37685146	47.49750886
---------------	-------------

-122.30041553	47.5939612
---------------	------------

-122.3238236	47.71535214
--------------	-------------

-122.30019868	47.62183638
---------------	-------------

-122.32795792	47.64377683
---------------	-------------

-122.32795792	47.64377683
---------------	-------------

# Test Map

Case 1018018 - Case Opened as of 06/11/2009	HZW	10 E ROANOKE ST
Case 1018020 - Application Added as of 06/11/2009	HZW	10 E ROANOKE ST
Case 1017883 - Application Added as of 12/23/2009	HZW	10 E ROANOKE ST
Case 1018474 - Notice or Order Issued as of 12/23/2009	HZW	10 E ROANOKE ST
Case 1018510 - Notice or Order Issued as of 02/04/2010	HZW	10 E ROANOKE ST
Case 1011450 - Application Added as of 08/16/2007	HZW	1515 FAIRVIEW AVE E
Case 1022541 - Application Added as of 05/20/2010	CONSTRUCT	2521 27TH AVE W
Case 1017471 - Application Added as of 09/30/2008	CONSTRUCT	3615 15TH AVE S
Case 1006577 - Application Added as of 02/28/2008	CONSTRUCT	11012 56TH AVE S
Case 1021982 - Notice or Order Issued as of 03/16/2010	HZW	11008 RIVIERA PL NE

# Test Map

Unlawful accessory float on E side of floating home (see case no. 1018474, Bldg. 12)

1020681

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018018>

Float/finger pier w/o permits.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018020>

Floating home remodel w/o permits.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017883>

Unit 12 unauthorized float >396 sq. ft.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018474>

Unit 17 unauthorized float 189 sq. ft.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018510>

Law Case Referral Shoreline

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1011450>

NEW DECK NEEDS PERMIT

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022541>

Permit 6193616 was issued 9/5/08 for work originally started without a permit. This case will remain open until all required inspections have been requested and obtained.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017471>

Constructing accessory structure requires permit and inspection(s) from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1006577>

Observed pier addition w/o authorization

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021982>

# Test Map

-122.32906168 47.64336591

-122.32906168 47.64336591

-122.32906168 47.64336591

-122.32906168 47.64336591

-122.32906168 47.64336591

-122.32734037 47.63294666

-122.39200105 47.64183321

-122.31372485 47.57113554

-122.2621453 47.50209323

-122.27631009 47.71021647



# Test Map

Case 1017021 - Application Added as of 08/18/2008      CONSTRUCT      2122 S BRANDON ST

Case 1018078 - Application Added as of 12/17/2008      CONSTRUCT      3302 S BRANDON ST

Case 1021506 - Application Added as of 02/24/2010      HZW      1338 S DAWSON ST

Case 1021735 - Case Opened as of 03/25/2010      HZW      3035 S CHICAGO ST

Case 1015037 - Notice or Order Issued as of 02/04/2010      HZW      1002 W NICKERSON ST

Case 1005135 - Application Added as of 05/05/2005      CONSTRUCT      2620 ALKI AVE SW

Case 1022163 - Application Added as of 04/30/2010      CITATION      4814 COLUMBIA DR S

Case 1022180 - Application Added as of 05/07/2010      CITATION      2530 LAKE PARK DR S

Case 1014371 - Application Added as of 12/12/2007      CONSTRUCT      5941 BEACH DR SW

# Test Map

One story addition on north end of single family residence requires permits & inspections from DPD. STOP WORK ORDER posted 8/14/08.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017021>

This permit does not include approval for a 2nd dwelling unit or ADU. The 2nd electrical meter socket is not per Electrical Permit 6189280.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018078>

"VIOLATION ALERT" (VIOLATION OF THE SEATTLE LAND USE AND ZONING CODE CONFIRMED (PERMIT FOR TWO STORY ADDITION TO SFR 720765 EXPIRED 11/18/02/) TOOK PHOTOS.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021506>

"VIOLATION ALERT" VIOLATION OF THE SEATTLE LAND USE AND ZONING CODE CONFIRMED(2ND STORY ADDITION, CARPORT & OTHER ALTERATIONS TO SINGLE-FAMILY RESIDENCE, BUILT 1915, WITHOUT PERMIT).

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021735>

Designated as a duplex but changed to a fourplex.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015037>

Violation of the Seattle Building Code found: infill/enclosure under deck in rear requires permit from DPD or removal. Work is not included in Permit 748605.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1005135>

04/02/10 bg - Vegetation overgrown along sidewalk on S Columbian Way. photos taken

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022163>

04/06/10 bg - Recreational vehicle parked on through lot/ two front yards. photos taken

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022180>

Structural and non-structural interior alterations (including electrical & plumbing work) and demolishing a

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=>

# Test Map

-122.30518551 47.5542938

-122.2902507 47.55369564

-122.31430446 47.55598328

-122.29175322 47.53187362

-122.36994731 47.65407058

-122.4073049 47.5800946

-122.30544324 47.5595753

-122.28781243 47.58058112

-122.3980735 47.5490367

# Test Map

Case 1020029 - Case Opened as of 07/23/2009	HZW	5941 BEACH DR SW
Case 1006934 - Application Added as of 11/21/2005	CONSTRUCT	1115 LAKE WASHINGTON BLVD S
Case 1008765 - Payment Processed as of 10/09/2006	TRAO	12557 35TH AVE NE
Case 1018819 - Application Added as of 03/24/2009	CONSTRUCT	3006 S JUNEAU ST
Case 1020701 - Notice or Order Issued as of 12/22/2009	CONSTRUCT	9250 SAND POINT WAY NE
Case 1022219 - Notice or Order Issued as of 04/16/2010	HZW	3432 WALLINGFORD AVE N
Case 1021679 - Application Added as of 04/05/2010	HZW	3600 WALLINGFORD AVE N

# Test Map

(including electrical & plumbing work) and demolishing a chimney requires permits and inspections from DPD. STOP WORK ORDER posted 12/11/07.

1014371

Observed replaced story deck on waterward side of residence w/o DPD authorization. Addition of 2nd story stair slightly alters deck configuration from 2007 aerial photo. Stair is waterward of deck residential setback; deck is legally existing nonconformity. Compare photos from inspection to 2005-07 aerials.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020029>

Permits 6079719 & 6079307 issued 11/21/05 for remodel. Ten foot tall retaining wall with backfill in ECA 1 & 2 and second story deck in required front yard require permits from DPD. STOP WORK ORDER issued 11/16/05. See related Case 1006933.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1006934>

Application for a Tenant Relocation License

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1008765>

Occupying a religious institution without a Certificate of Occupancy & constructing structures greater than 120 sq.ft. requires permits & inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018819>

RESTORATION REQUIRED FOR 6 TREES REMOVED WITHIN THE RIPARIAN CORRIDOR ECA

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020701>

HBMC violations

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022219>

Observed violation of Land Use Code.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021679>

# Test Map



-122.3980735	47.5490367
--------------	------------



-122.28946189	47.59297448
---------------	-------------

-122.29122455	47.72092884
---------------	-------------



-122.29397247	47.55015609
---------------	-------------

-122.27588882	47.69569532
---------------	-------------



-122.33608541	47.64902085
---------------	-------------

-122.33616657	47.65066879
---------------	-------------

# Test Map

Case 1016488 - Application Added as of 07/08/2008	CONSTRUCT	1119 NEWPORT WAY
Case 1022303 - Application Added as of 04/29/2010	HZW	7014 14TH AVE NW
Case 1022463 - Application Added as of 05/10/2010	CITATION	9502 14TH AVE NW
Case 1007317 - Application Added as of 01/24/2006	CONSTRUCT	2327 HUGHES AVE SW
Case 1021595 - Notice or Order Issued as of 04/12/2010	HZW	108 NW 84TH ST
Case 1021596 - Application Added as of 03/29/2010	CITATION	108 NW 84TH ST
Case 1021989 - Notification Issued as of 04/12/2010	VACANT	108 NW 84TH ST
Case 1022095 - Application Added as of 03/25/2010	CONSTRUCT	5469 LAKE WASHINGTON BLVD S
Case 1020007 - Application Added as of 07/20/2009	CONSTRUCT	3601 60TH AVE SW
Case 1014016 - Payment Processed as of 03/04/2008	TRAO	12330 ROOSEVELT WAY NE
Case 1011446 - Application Added as of 03/23/2007	HZW	8015 MERIDIAN AVE N

# Test Map

Exterior decks and railing above garage require permit and inspections from DPD. STOP WORK ORDER posted 7/7/08.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016488>

Housing violation

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022303>

weeds and vegetation violation.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022463>

TREE LARGER THAN 6 INC CALIPER CUT W/O PERMIT IN STEEP SLOPE ECA

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1007317>

Fire damaged, unsecured SFR, outdoor storage, pictures in file.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021595>

outdoor storage, pictures in file.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021596>

Fire damaged, unsecured SFR, outdoor storage, pictures in file.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021989>

INSPECTOR UNABLE TO DETERMINE WHEN THE TREE WAS REMOVED BUT THE STUMP IS LARGE ENOUGH TO MAKE THE TREE EXCEPTIONAL

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022095>

Remodeling an existing 2nd floor bathroom, interior alterations and installing a small dormer on the north side requires permits & inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020007>

Application for a Tenant Relocation License. Total units: 21; total units occupied: 14. Substantial rehabilitation.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014016>

Law Case Conversion

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=>



# Test Map

-122.28400339	47.61231697
---------------	-------------

-122.37334395	47.68006109
---------------	-------------

-122.37370379	47.6980893
---------------	------------

-122.39913043	47.5829562
---------------	------------

-122.35849162	47.69015887
---------------	-------------

-122.35849162	47.69015887
---------------	-------------

-122.35849162	47.69015887
---------------	-------------

-122.260359	47.55131868
-------------	-------------

-122.40978715	47.5721244
---------------	------------

-122.31768494	47.71854207
---------------	-------------

-122.33342392	47.68728763
---------------	-------------

# Test Map

Case 1022301 - Notice or Order Issued as of 04/28/2010	CONSTRUCT	4514 SW GRAHAM ST
--	-----------	-------------------

Case 1022134 - Application Added as of 04/01/2010	CITATION	134 NW 59TH ST
---	----------	----------------

Case 1022113 - Application Added as of 03/29/2010	CITATION	2120 NE 54TH ST
---	----------	-----------------

Case 1004614 - Application Added as of 03/21/2005	CONSTRUCT	1610 6TH AVE W
---	-----------	----------------

Case 1010899 - Application Accepted as of 08/21/2009	ADVISORY	7701 DELRIDGE WAY SW
--	----------	----------------------

Case 1016818 - Application Added as of 12/11/2009	CONSTRUCT	7320 CALIFORNIA AVE SW
---	-----------	------------------------

Case 1010980 - Application Added as of 02/02/2007	CONSTRUCT	1428 PALM AVE SW
---	-----------	------------------

Case 1022121 - Application Added as of 05/17/2010	CITATION	5422 16TH AVE SW
---	----------	------------------

Case 1010530 - Notice or Order Issued as of 05/03/2010	CONSTRUCT	2112 31ST AVE S
--	-----------	-----------------

# Test Map

	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1011446">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1011446</a>
Constructing a deck on the south side & a ramp on the east side of an SFR more than 18" above grade requires a permit & inspections from DPD.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022301">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022301</a>
Zoning violation.Outdoor junk storage including but not limited to tarp, window screens and more misc.items stored in the driveway.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022134">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022134</a>
Violation of Land Use Code observed.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022113">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022113</a>
ROOF DECK ON GARAGE NEEDS PERMIT	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1004614">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1004614</a>
Condo Conversion.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010899">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010899</a>
Permit 6190103 was issued 12/9/08 for work origianlly started without a permit. This case will remain open until all required inspections have been obtained.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016818">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016818</a>
CONTINUATION OF PTS CASE #232004--RE-ESTABLISH PERMIT #724602 AND CALL FOR INSPECTION	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010980">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010980</a>
3/19/10 ej- Outdoor junk storage such as but not limited to, table saw, broken car shed, and other miscellaneous items.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022121">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022121</a>
Building a solid fence over 6' tall with garage door in front yard of SFR & other construction requires permits &	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010530">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010530</a>

# Test Map

-122.39069618	47.54695869
---------------	-------------

-122.35922928	47.67175637
---------------	-------------

-122.30440977	47.66823014
---------------	-------------

-122.36474271	47.63391949
---------------	-------------

-122.36081573	47.53345184
---------------	-------------

-122.38700034	47.53749428
---------------	-------------

-122.38428139	47.59109444
---------------	-------------

-122.35442691	47.55294357
---------------	-------------

-122.29273994	47.58402722
---------------	-------------

# Test Map

Case 1022412 - Application Added as of 05/04/2010	CITATION	3000 23RD AVE S
Case 1011543 - Application Added as of 12/07/2007	CONSTRUCT	3624 S SPOKANE ST
Case 1001719 - Application Added as of 03/10/2004	CONSTRUCT	4103 23RD AVE SW
Case 1021772 - Citation Issued as of 05/21/2010	CITATION	1761 STURGUS AVE S
Case 1018163 - Notification Issued as of 04/12/2010	VACANT	13524 LINDEN AVE N
Case 1016126 - Notification Issued as of 11/04/2008	VACANT	1322 NE 65TH ST
Case 1014982 - Citation Issued as of 04/29/2008	CITATION	1322 NE 65TH ST
Case 1022497 - Application Added as of 05/13/2010	CITATION	1217 FEDERAL AVE E
Case 1020091 - Application Added as of 09/04/2009	HZW	6723 DIVISION AVE NW

# Test Map

inspections from DPD. Inspections & final approval required for Permits 6138326 (renewal of 010703-013) and 6138322 (renewal of 720823).

05/04/10 bg - Storage of commercial vehicles, violation of home occupation standards. photos taken

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022412>

Permit 6134237 was issued 3/30/07 for work started without a permit. This case will remain open until all required inspections are requested & obtained from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1011543>

Violation of the Seattle Building Code and SEPA found.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1001719>

02/10/10 bg - Inoperable vehicle(s) on the property. photos taken

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021772>

Unsecured structure with evidence of transient activity; pictures in file.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018163>

unfit

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016126>

unfit and garbage accumulation.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014982>

A laurel hedge is growing over the sidewalk.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022497>

Duplex in a single family zone- permitted as an ADU- owners not living at location

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020091>

# Test Map

-122.30304124	47.57656583
---------------	-------------

-122.28678462	47.57174761
---------------	-------------

-122.36258209	47.56637761
---------------	-------------

-122.31182565	47.58734851
---------------	-------------

-122.34709361	47.72753951
---------------	-------------

-122.31336886	47.67600672
---------------	-------------

-122.31336886	47.67600672
---------------	-------------

-122.31944183	47.6310695
---------------	------------

-122.36683962	47.67845042
---------------	-------------

# Test Map

Case 1006302 - Application Added as of 09/13/2005	CONSTRUCT	1110 ALKI AVE SW
Case 1017789 - Application Added as of 04/13/2009	HZW	1218 ALKI AVE SW
Case 1020324 - Application Added as of 04/15/2010	CITATION	2464 ALKI AVE SW
Case 1021755 - Notice or Order Issued as of 05/10/2010	HZW	2464 ALKI AVE SW
Case 1020596 - Notification Issued as of 03/08/2010	VACANT	2464 ALKI AVE SW
Case 1022096 - Notice or Order Issued as of 03/31/2010	HZW	4740 DELRIDGE WAY SW
Case 1008203 - Application Added as of 03/08/2010	HZW	9833 RAINIER AVE S
Case 1008204 - Notification Issued as of 03/08/2010	VACANT	9833 RAINIER AVE S
Case 1022538 - Application Added as of 05/19/2010	CITATION	504 29TH AVE S
Case 1021267 - Case Resolved as of 05/21/2010	CITATION	5406 21ST AVE SW



# Test Map

Permit required for structure, approx. 2' retaining wall, built in area mapped ECA 8 (Known Slide), ECA 2 (Potential Slide) and ECA 5 (Liquefaction) across 1110 & 1116 Alki Ave. SW with drainage directed to shared driveway with 1118 Alki Ave. SW.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1006302>

Violation of the Just Cause Eviction Ordinance

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017789>

Blackberry vines at Northeast corner of site on the sidewalk, pictures in file.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020324>

Open to entry & weather with deterioration.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021755>

Open to weather via open or broken windows on 3 sides of the bldg. 2 delaminated entry doors on rear wall, picture in file.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020596>

Violation of Land Use-

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022096>

Access limited; appears open to entry with deterioration.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1008203>

Access limited; appears open to entry with deterioration.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1008204>

Auto repair in a residential neighborhood.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022538>

Violation of Land Use- Outdoor junk storage

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021267>

# Test Map

-122.38572142	47.59488909
---------------	-------------

-122.38875582	47.59412899
---------------	-------------

-122.40496091	47.58116901
---------------	-------------

-122.40496091	47.58116901
---------------	-------------

-122.40496091	47.58116901
---------------	-------------

-122.36254396	47.55984337
---------------	-------------

-122.25178781	47.51382266
---------------	-------------

-122.25178781	47.51382266
---------------	-------------

-122.29467401	47.59784318
---------------	-------------

-122.3597024	47.55341088
--------------	-------------

# Test Map

Case 1020780 - Notice or Order Issued as of 05/04/2010	CONSTRUCT	2717 S NORMAN ST
Case 1019674 - Citation Issued as of 05/06/2010	CITATION	8310 38TH AVE S
Case 1018999 - Case Resolved as of 05/21/2010	HZW	5638 DELRIDGE WAY SW
Case 1017354 - Application Added as of 06/02/2009	CONSTRUCT	3010 61ST AVE SW
Case 1005500 - Application Added as of 06/13/2005	HZW	6521 FREMONT AVE N
Case 1022426 - Citation Issued as of 05/21/2010	CITATION	5622 S BANGOR ST
Case 1022398 - Application Accepted as of 05/20/2010	TRAO	5802 ROOSEVELT WAY NE
Case 1014522 - Application Added as of 12/28/2007	HZW	8515 11TH AVE NW
Case 1022204 - Case Opened as of 04/16/2010	HZW	8007 BEACON AVE S

# Test Map

Permit 6236426 was issued 12/22/09 for a portion of the work originally started without a permit. THIS CASE WILL REMAIN OPEN UNTIL ALL REQUIRED PERMITS HAVE BEEN ISSUED AND ALL INSPECTIONS OBTAINED.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020780>

OBSERVED VIOLATION OF THE SEATTLE LAND USE AND ZONING CODE (AUTO TIRES, FURNITURE, MACHINERY AND OTHER MATERIALS IN YARD ABUTTING 38TH AVE S).

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019674>

HBMC violations

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018999>

Unit D: fireplace requires a mechanical permit & inspections from DPD. Flue height needs to be reduced to meet zoning code. No permit required for patio (appears to be less than 18" above grade).

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017354>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1005500>

05/05/10 bg - More than 3 vehicles on the property, truck, RV and boat parked in required front and side yards. photos taken

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022426>

Application for a Tenant Relocation License. Total units: 2; total units occupied: 2. Demolition.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022398>

Violation of Just Cause Eviction Ordinance.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014522>

"VIOLATION ALERT" VIOLATION OF THE SEATTLE

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=>

# Test Map

-122.29691998	47.59308314
---------------	-------------

-122.28510476	47.52928032
---------------	-------------

-122.36261568	47.55072883
---------------	-------------

-122.41033825	47.57730982
---------------	-------------

-122.35019452	47.6767279
---------------	------------

-122.26210649	47.5063592
---------------	------------

-122.31704047	47.67089796
---------------	-------------

-122.37066542	47.69122877
---------------	-------------

-122.28846591	47.53070954
---------------	-------------

# Test Map

Case 1019384 - Citation Issued as of 05/06/2010	CITATION	10802 BEACON AVE S
---	----------	--------------------

Case 1020625 - Application Added as of 09/18/2009	CITATION	7700 RAINIER AVE S
---	----------	--------------------

Case 1020624 - Application Added as of 09/18/2009	CITATION	7700 RAINIER AVE S
---	----------	--------------------

Case 1018865 - Payment Processed as of 04/20/2010	TRAO	4800 SAND POINT WAY NE
---	------	------------------------

Case 1018870 - Application Accepted as of 06/24/2009	TRAO	4800 SAND POINT WAY NE
--	------	------------------------

Case 1002947 - Application Added as of 07/26/2004	CONSTRUCT	5410 48TH AVE SW
---	-----------	------------------

# Test Map

LAND USE AND ZONING CODE CONFIRMED (DDITION TO GARAGE WITHOUT REQUIRED PERMIT; STRUCTURE IN REAR YARD EXCEEDS 40% OF AREA; POSSIBLE ILLEGAL CONVERSION TO HABITABLE SPACE. TOOK PHOTOS.

[1022204](#)

VIOLATION OF THE SEATTLE LAND USE AND ZONING CODE OBSERVED (AUTO TIRES, LUMBER METAL AND OTHER AND OTHER JUNK STORAGE IN YARDS.)

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019384>

OBSERVED VIOLATION OD THE SEATTLE LAND USE AND ZONING CODE (VAN MISSING FRONT TIRE AND TIRES STORED ON VACANT LOT)ACTIVE PROJ # 3009571, SITE FOR 65,000SQ. FT. REZONE FROM SF 500 TO NC240

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020625>

OBSERVED VIOLATION OD THE SEATTLE LAND USE AND ZONING CODE (VAN MISSING FRONT TIRE AND TIRES STORED ON VACANT LOT)ACTIVE PROJ # 3009571, SITE FOR 65,000SQ. FT. REZONE FROM SF 500 TO NC240

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020624>

Application for a Tenant Relocation License. Total units: 17; total units occupied: 16. Demolition. See companion Case No. 1018870.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018865>


Application for a Tenant Relocation License. See companion Case No. 1018865.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018870>

Violation of the Seattle Building Code found: work without a permit (structure in rear yard requires a permit).

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1002947>

# Test Map




-122.26964655      47.50349256




-122.26947591      47.53347148

-122.26947591      47.53347148



-122.28145789      47.66231302

-122.28145789      47.66231302



-122.39339623      47.55357712



# Test Map

Case 1022318 - Application Added as of 04/26/2010      CONSTRUCT      8026 22ND AVE NW

Case 1022234 - Application Added as of 04/20/2010      HZW      8033 20TH AVE NE

Case 1022235 - Case Opened as of 04/29/2010      HZW      8033 20TH AVE NE

Case 1020018 - Case Resolved as of 05/10/2010      HZW      7530 15TH AVE NW

Case 1022464 - Notice or Order Issued as of  
05/13/2010      HZW      7530 15TH AVE NW

Case 1016451 - Application Added as of 05/15/2009      HZW      10728 RIVIERA PL NE

Case 1017053 - Application Added as of 03/23/2010      CONSTRUCT      10728 RIVIERA PL NE

Case 1017054 - Application Added as of 08/20/2008      CONSTRUCT      10728 RIVIERA PL NE

Case 1012632 - Application Added as of 06/29/2007      CONSTRUCT      9014 39TH AVE S

# Test Map

SANITARY SEWER REPAIR TO LINE ON NORTH SIDE OF HOUSE WAS DONE W/O PERMIT--OBTAIN PERMIT, EXCAVATE REPAIR MAKE CORRECTIONS AND CALL FOR INSPECTION

Land Code Violation

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022318>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022234>

HBMC Violation

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022235>

residential use unpermitted

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020018>

LU violations in NC2-40 & present permitted use Auto Repair (permit #46587 from 1975: Currently a salvage yard & outdoor storage (both prohibited in NC) & Auto Repair shop. NOV 1020018 Closed, superceeded by 1022464.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022464>

Aerial photos show finger pier parallel to shore constructed between 1999 & 2002; no permits.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016451>

PERMIT REQUIRED FOR NEW DECK

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017053>

PERMIT REQUIRED FOR NEW DECK

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017054>

Completely remodeling and adding a dwelling unit to a single family residence requires permit(s) and inspections from DPD. STOP WORK ORDER issued 6/28/07.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1012632>

# Test Map

-122.38406075	47.68768075
---------------	-------------

-122.30709033	47.68773772
---------------	-------------

-122.30709033	47.68773772
---------------	-------------

-122.3765182	47.68405054
--------------	-------------

-122.3765182	47.68405054
--------------	-------------

-122.27575038	47.70868313
---------------	-------------

-122.27575038	47.70868313
---------------	-------------

-122.27575038	47.70868313
---------------	-------------

-122.28346868	47.52258583
---------------	-------------

# Test Map

Case 1018321 - Application Accepted as of 05/20/2010	TRAO	6924 42ND AVE S
Case 1018866 - Application Added as of 03/30/2009	TRAO	6924 42ND AVE S
Case 1022252 - Application Added as of 05/21/2010	CITATION	2145 N 133RD ST
Case 1015775 - Application Added as of 05/08/2008	CITATION	5442 45TH AVE SW
Case 1002983 - Application Added as of 07/29/2004	CONSTRUCT	10050 RAINIER AVE S
Case 1017732 - Application Added as of 05/28/2009	HZW	9057 9TH AVE SW
Case 1022228 - Application Added as of 04/15/2010	CITATION	130 NW 58TH ST
Case 1021788 - Application Added as of 03/19/2010	CITATION	4315 SW WEBSTER ST
Case 1019716 - Application Added as of 02/02/2010	HZW	10749 PALATINE AVE N
Case 1010992 - Application Added as of 02/06/2007	CONSTRUCT	800 POPLAR PL S

# Test Map

6/28/07.

Application for a Tenant Relocation License. Total units:4; Total units occupied:2. Demolition.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018321>

Issuance of Owner's Certification of Occupancy or No Displacement.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018866>

zoning

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022252>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015775>

Violation found: soldier pile wall not built per plan and portion built in right-of-way requires permit from SDOT.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1002983>

Failure to pay relocation assistance pursuant to an Emergency Order to Vacate and Close as required by SMC 22.206.260.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017732>

Outdoor junk storage including but not limited to mattress, broken down furniture and more misc. items stored in the driveway.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022228>

2/16/10 EJ-Inspection shows vegetation encroaching onto the sidewalk along 44th Ave SW.(covering about 50% of the sidewalk)

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021788>

2nd dwelling unit in basement w/out permit & hobby shop has cooktop per frequent occupant

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019716>

Continuation of PTS Case BC200724: INSTALLED TRAILER W/O PERMIT.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010992>

# Test Map

-122.2803391	47.53998256
--------------	-------------

-122.2803391	47.53998256
--------------	-------------

-122.33225602	47.72484623
---------------	-------------

-122.3895526	47.5527143
--------------	------------

-122.24633514	47.51143213
---------------	-------------

-122.34708585	47.52111794
---------------	-------------

-122.35895996	47.67119592
---------------	-------------

-122.38825662	47.53568465
---------------	-------------

-122.35712163	47.70842529
---------------	-------------

-122.31220172	47.59534369
---------------	-------------

# Test Map

Case 1010983 - Application Added as of 02/05/2007      CONSTRUCT      10019 BEACON AVE S

Case 1017269 - Notice or Order Issued as of 04/29/2010      CONSTRUCT      3645 22ND AVE SW

Case 1021992 - Application Added as of 03/11/2010      CITATION      7527 32ND AVE SW

Case 1022003 - Application Added as of 03/11/2010      HZW      7527 32ND AVE SW

Case 1019818 - Citation Issued as of 02/11/2010      CITATION      7954 30TH AVE SW

Case 1004993 - Application Added as of 04/19/2005      CONSTRUCT      5602 41ST AVE SW

Case 1019526 - Application Added as of 06/05/2009      CONSTRUCT      5602 41ST AVE SW

Case 1022445 - Application Added as of 05/10/2010      CITATION      5046 20TH AVE NE

Case 1005065 - Application Added as of 04/28/2005      CONSTRUCT      7339 40TH AVE SW

# Test Map

CONTINUATION OF PTS CASE #224437--PERMIT  
REQUIRED FOR MORE THAN 100 CUBIC YARDS OF  
FILL

Permit 6197118 was issued 8/31/09 for work originally  
performed without a permit & inspections. This case will  
remain open until all required inspections have been  
requested & approved.

Outdoor junk storage including car parts, a TV and  
furniture.

Failing roof system.

6/30/09 EJ- Inspection shows outdoor junk storage such  
as but not limited to cardboard boxes of miscellaneous  
items, pallets of miscellaneous items, inoperable  
vehicles, wood, and other miscellaneous items  
throughout the property.

Violation of the Seattle Building Code found: building a  
garage/carport in rear yard requires a permit from DPD.  
Stop Work Order posted 4/18/05.

Electrical work requires a permit & inspections from  
DPD. Additions were built under Permit 681824  
(renewed by Permit 693963).

Observed violation of Land Use Code.

Violation of the State Environmental Policy Act (SEPA)  
found: tree and vegetation removal in a Steep Slope

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010983>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017269>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021992>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022003>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019818>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1004993>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019526>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022445>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=>



# Test Map

-122.27215523 47.51044482

-122.36140122 47.57041582

-122.3742461 47.53472388

-122.3742461 47.53472388

-122.37094083 47.53025702

-122.38387313 47.5519316

-122.38387313 47.5519316

-122.30626209 47.66628389

-122.38403214 47.53637697

# Test Map

Case 1015112 - Application Added as of 03/06/2008	CONSTRUCT	3771 S PERRY ST
---	-----------	-----------------

Case 1022211 - Notice or Order Issued as of 05/17/2010	HZW	9039 12TH AVE SW
--	-----	------------------

Case 1019059 - Notice or Order Issued as of 02/02/2010	CONSTRUCT	3903 39TH AVE SW
--	-----------	------------------

Case 1022047 - Application Added as of 03/19/2010	HZW	2717 E ROY ST
---	-----	---------------

Case 1006933 - Application Added as of 11/21/2005	CONSTRUCT	1111 LAKE WASHINGTON BLVD S
---	-----------	--------------------------------

Case 1008296 - Notice or Order Issued as of 03/26/2010	CONSTRUCT	7103 SEWARD PARK AVE S
--	-----------	------------------------

Case 1009916 - Case Opened as of 10/27/2006	CONSTRUCT	3228 46TH AVE SW
---	-----------	------------------

# Test Map

found: tree and vegetation removal in a Steep Slope Environmentally Critical Area (ECA) requires a permit from DPD.

1005065

Trees not planted per Permit 743689 renewed by Permit 6105639. Permit 6105639 expired 1/13/08 without obtaining final inspection.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015112>

Front picture window broken, picture in file. site has locked gate & is fenced so access is limited.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022211>

Constructing a retaining wall over 4' tall & remodeling a garage into habitable space & removing required parking requires permits & inspections. Permit 6124624 was issued 4/27/09 for other work originally started without permits & inspections. This case will remain open until all required permits & inspections have been obtained from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019059>

A business operating out of a Single Family zone.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022047>

Performing work not according to approved plan (Permit 753110) including demolishing a house and constructing a 10' foot retaining wall with backfill in ECA 1, 2 & 8. This work requires permits from DPD and Special Inspections. STOP WORK ORDER issued 11/16/05. See related Case 1006934.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1006933>

PERMIT & INSPECTIONS REQUIRED FOR SHED LARGER THAN 120 SQUARE FEET

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1008296>

Permit 6115333 issued 10/6/06 for work originally started

# Test Map

-122.28301609	47.5146657
---------------	------------

-122.35087684	47.52168606
---------------	-------------

-122.381801	47.5691148
-------------	------------

-122.29687378	47.62489638
---------------	-------------

-122.28946091	47.59308535
---------------	-------------

-122.26756753	47.53870601
---------------	-------------

-122.39033121	47.57480592
---------------	-------------

# Test Map

Case 1013940 - Application Added as of 10/24/2007      CONSTRUCT      2318 BELVIDERE AVE SW

Case 1021944 - Application Added as of 03/09/2010      CITATION      5351 S WALLACE ST

Case 1008368 - Application Added as of 07/14/2006      CONSTRUCT      10115 MARINE VIEW DR  
SW

Case 1012680 - Application Added as of 05/07/2008      CONSTRUCT      11002 MARINE VIEW DR  
SW

Case 1022349 - Application Added as of 04/28/2010      CITATION      921 E ALLISON ST

Case 1009732 - Application Added as of 09/19/2006      CONSTRUCT      3207 POINT PL SW

Case 1018070 - Application Added as of 12/17/2008      CONSTRUCT      5766 S OAKLAWN PL

# Test Map

without a permit.

Constructing a retaining wall in Steep Slope ECA requires permits & inspections from DPD and, if located on Parks property and in the R-O-W, permission is required from DOPAR & SDOT.

VIOLATION OF THE SEATTLE LAND USE AND ZONING CODE OBSERVED (SIX VEHICLES PARKED OUTDOORS ON A SF 9600 LOT. TOOK PHOTOS.

Tennis court and retaining walls on a site mapped ECA 1 & 2 require permits (including drainage review for more than 750 sq. ft. of new impervious surface) from DPD. New drainage work requires a side sewer permit.

Converting detached garage into dwelling unit not allowed. Mechanical and building permits & inspections required. STOP WORK ORDER posted 6/28/07 & 5/7/08.

Vegetation including rose bushes over the sidewalk.

Work being done is not per approved plan for Permit 732533 (renewed by Permit 742841 renewed by Permit 6075899). A revision to the permit is required.

Demolishing a detached accessory structure & constructing a new structure requires plan review, zoning approval and permits & inspections from DPD. STOP WORK ORDER posted 12/15/08.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1009916>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1013940>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021944>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1008368>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1012680>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022349>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1009732>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018070>

# Test Map

-122.37920798      47.582746

-122.26551886      47.49660126

-122.39130878      47.51249711

-122.38013875      47.50448716

-122.31985      47.64850556

-122.41958782      47.57682471

-122.25943311      47.54375462

# Test Map

Case 1021297 - Application Added as of 04/20/2010	HZW	6526 15TH AVE NE
Case 1009677 - Application Added as of 09/13/2006	CONSTRUCT	2050 S COLUMBIAN WAY
Case 1014991 - Notice or Order Issued as of 05/04/2010	CONSTRUCT	3200 SW ANDOVER ST
Case 1007566 - Application Added as of 02/21/2006	CONSTRUCT	4540 DELRIDGE WAY SW
Case 1019470 - Application Added as of 08/04/2009	HZW	1526 LAKESIDE AVE S
Case 1014708 - Application Added as of 12/01/2009	HZW	8702 1ST AVE NW
Case 1020454 - Application Added as of 08/31/2009	CONSTRUCT	10637 RENTON AVE S
Case 1021532 - Application Added as of 05/03/2010	CONSTRUCT	722 25TH AVE S
Case 1014884 - Application Added as of 08/14/2008	CONSTRUCT	3816 SW MASSACHUSETTS ST



# Test Map

Failure to pay relocation assistance pursuant to an Emergency Order to Vacate and Close as required by SMC 22.206.260

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021297>

Temporary Tent Structure (Permit 748099) must be removed.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1009677>

Permit 6186739 was issued 9/5/08 for work originally started without a permit. This case will remain open until all required inspections have been requested, performed and approved by DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014991>

REATAINING WALL/ROCKERY IN POTENTIAL SIDE AREA (ECA) REQUIRES A BUILDING PERMIT

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1007566>

Grading & new bulkhead w/o authorization. Photos provided by WDFW fish biologist Alisa Bieber.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019470>

eliminated off st pking into habit space & addition without permit.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014708>

Permit 6220902 was issued 8/5/09 for work originally started without a permit. This case will remain open until all required inspections from DPD have been approved.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020454>

Permit 6237903 was issued 1/13/10 for work originally started without a permit. This case will remain open until all required inspections have been requested, performed and approved.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021532>

Application 6169702 was accepted for review by DPD on 8/8/08 for constructing a retaining wall & installing drainage in a Steep Slope and Potential Slide

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014884>

# Test Map

-122.31167364	47.67662279
---------------	-------------

-122.30521188	47.56003204
---------------	-------------

-122.37212776	47.56820572
---------------	-------------

-122.36264102	47.56166529
---------------	-------------

-122.28580453	47.5881251
---------------	------------

-122.35772989	47.69260327
---------------	-------------

-122.25368672	47.50528973
---------------	-------------

-122.2997064	47.59603408
--------------	-------------

-122.38182944	47.58822047
---------------	-------------

# Test Map

Case 1004316 - Application Added as of 01/19/2005	CONSTRUCT	8609 34TH AVE SW
Case 1016897 - Application Added as of 10/14/2008	CONSTRUCT	1550 N 38TH ST
Case 1012287 - Application Added as of 02/15/2008	CONSTRUCT	1977 PERKINS LN W
Case 1012829 - Application Added as of 02/15/2008	CONSTRUCT	1977 PERKINS LN W
Case 1006070 - Application Added as of 05/06/2010	CONSTRUCT	2847 MOUNT RAINIER DR S
Case 1022209 - Application Added as of 04/14/2010	HZW	4001 FAUNTLEROY WAY SW
Case 1007328 - Application Added as of 01/25/2006	CONSTRUCT	723 29TH AVE S
Case 1022481 - Notice or Order Issued as of 05/12/2010	HZW	4827 S GRAHAM ST
Case 1022482 - Application Added as of 05/12/2010	HZW	4827 S GRAHAM ST

# Test Map

Environmentally Critical Area. Work requires permit(s) and inspections from DPD. STOP WORK ORDER posted 2/7/08.

Violation of the Seattle Building Code found: work being performed requires a STFI permit from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1004316>

Deck on east facade (over 18" in height & appears to extend over the property line) and trellis require zoning approval, permit & inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016897>

REPLANTING REQUIRED FOR CLEARING IN STEEP SLOPE/LANDSLIDE PRONE AREA--PERMIT REQUIRED FOR NEW PATIO IN STEEP SLOPE ECA

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1012287>

BUILDING PERMIT IS REQUIRED FOR STAIRS,PATIO, ETC BUILT ON STEEP SLOPE ECA

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1012829>

Rebuilding enclosed porch requires either a permit from DPD or removal. Stop Work Order posted 8/15/05.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1006070>

Violation of Land Use- Over fence height limit

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022209>

ELECTRICAL WORK REQUIRES PERMIT

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1007328>

Garage open to entry; pictures in file.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022481>

outdoor storage includes bicycle, lumber, couch, table, umbrella, cooking equipment, pick-up truck tool box, shelving; pictures in file.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022482>

# Test Map

-122.37563295	47.52614463
---------------	-------------

-122.33916944	47.65287651
---------------	-------------

-122.40966065	47.63759841
---------------	-------------

-122.40966065	47.63759841
---------------	-------------

-122.28735643	47.57708958
---------------	-------------

-122.37402554	47.56768385
---------------	-------------

-122.29539802	47.5960104
---------------	------------

-122.27137697	47.54584274
---------------	-------------

-122.27137697	47.54584274
---------------	-------------

# Test Map

Case 1021586 - Notice or Order Issued as of 04/30/2010	HZW	10022 ASHWORTH AVE N
--	-----	----------------------

Case 1021587 - Notice or Order Issued as of 04/30/2010	HZW	10022 ASHWORTH AVE N
--	-----	----------------------

Case 1021896 - Application Added as of 03/03/2010	HZW	1505 13TH AVE S
---	-----	-----------------

Case 1015770 - Application Added as of 03/09/2010	CONSTRUCT	10829 42ND AVE SW
---	-----------	-------------------

Case 1016571 - Notice or Order Issued as of 05/06/2010	CONSTRUCT	10829 42ND AVE SW
--	-----------	-------------------

Case 1001282 - Application Added as of 01/04/2005	HZW	1936 HARBOR AVE SW
---	-----	--------------------

Case 1022540 - Application Added as of 05/20/2010	CITATION	2005 NE 130TH ST
---	----------	------------------

Case 1020906 - Citation Issued as of 04/28/2010	CITATION	6727 23RD AVE SW
---	----------	------------------

Case 1001342 - Application Added as of 01/04/2007	CONSTRUCT	4037 HILLCREST AVE SW
---	-----------	-----------------------

# Test Map

HBMC violations including defective plumbing & electric with no permits

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021586>

Zoning violations: eliminated parking & using basement as housing unit guest room.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021587>

10/22/09 bg - HBMC violations in Unit 1.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021896>

Permit 6177682 was issued 4/16/08 for work originally started without a permit. This case will remain open until all required inspections have been requested and approved.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015770>

Permits 6191051 & 6191050 were issued 8/13/08 for work performed w/o permits. Condenser unit not to be operated until permit(s) obtained & inspections approved. This case will remain open until all required inspections have been requested & approved.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016571>

Overwater deck area not removed as required by the Shoreline Hearings Board. Restaurant expansion complete.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1001282>

Land Use Code Violation

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022540>

10/20/09 ej- Inspection shows 5 vehicles parked on the property and outdoor junk storage such as but not limited to inoperable vehicles.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020906>

REMODELING NEEDS BLDG, ELECTRICAL, & PLUMBING PERMITS

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1001342>

# Test Map

-122.33897629	47.70213054
---------------	-------------

-122.33897629	47.70213054
---------------	-------------

-122.31635114	47.58970111
---------------	-------------

-122.38510723	47.50565551
---------------	-------------

-122.38510723	47.50565551
---------------	-------------

-122.37644382	47.58653746
---------------	-------------

-122.30678324	47.72225962
---------------	-------------

-122.36274457	47.54210424
---------------	-------------

-122.40523577	47.56743335
---------------	-------------



# Test Map

Case 1022449 - Application Added as of 05/07/2010	CITATION	8619 35TH AVE SW
Case 1008713 - Application Added as of 06/15/2006	CONSTRUCT	2920 SW AVALON WAY
Case 1021329 - Case Resolved as of 03/19/2010	CITATION	11538 FREMONT AVE N
Case 1006591 - Application Added as of 06/30/2008	CONSTRUCT	9734 31ST AVE SW
Case 1015572 - Citation Issued as of 05/13/2009	CITATION	7035 10TH AVE NW
Case 1019511 - Notice or Order Issued as of 02/17/2010	HZW	5338 15TH AVE S
Case 1020443 - Application Added as of 08/28/2009	CONSTRUCT	2904 E CHERRY ST
Case 1016427 - Application Added as of 06/30/2008	CONSTRUCT	2037 34TH AVE S
Case 1016346 - Application Added as of 06/26/2008	CONSTRUCT	801 LAKESIDE AVE S

# Test Map

5/6/10 EJ- Inspection shows vegetation encroaching onto the sidewalk along 35th Ave SW.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022449>

Constructing a 2nd story addition and creating a dwelling unit requires a permit from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1008713>

junk storage on sf prop

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021329>

Converting a garage into a single family residence requires a permit (including zoning approval) from DPD. Stop Work Order posted 6/23/05.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1006591>

junk in sf zone

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015572>

VIOLATION OF THE SEATTLE LAND USE AND ZONING CODE CONFIRMED (AREA DESIGNATED FOR PARKING IN NC1-30 ZONE BEING USED FOR OUTDOOR STORAGE OF MATERIALS)

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019511>

Grading more than 100 cu.yds. requires a permit and inspections from DPD. Temporary Erosion & Sedimentation Control (TESC) measures must be installed.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020443>

Unable to reach builder to verify that height is per Permit 6113524. STOP WORK ORDER posted 6/27/08.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016427>

ROOF DECK HAS BEEN BUILT OVER SWIMMING POOL--AND grate has been removed to allow ACCESS TO GARAGE ROOF DECK DESPITE PREVIOUS DETERMINATION THAT IT CANNOT BE USED--

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016346>

# Test Map

-122.37698446 47.52552215

-122.37091354 47.57042541

-122.34997383 47.71348831

-122.37169085 47.51571007

-122.36966076 47.68061482

-122.31307834 47.55373603

-122.29466382 47.6081215

-122.29008636 47.58403153

-122.28820191 47.59556909

# Test Map

Case 1002535 - Application Added as of 08/23/2006	CONSTRUCT	10222 57TH AVE S
---	-----------	------------------

Case 1002673 - Application Added as of 06/28/2004	CONSTRUCT	8135 4TH AVE SW
---	-----------	-----------------

Case 1007385 - Application Added as of 10/24/2006	CONSTRUCT	3032 19TH AVE S
---	-----------	-----------------

Case 1019129 - Case Opened as of 05/17/2010	HZW	4677 S WILLOW ST
---	-----	------------------

Case 1022294 - Notice or Order Issued as of 04/29/2010	HZW	5026 18TH AVE NE
--	-----	------------------

Case 1021469 - Notice or Order Issued as of 01/27/2010	CONSTRUCT	5211 21ST AVE NE
--	-----------	------------------

Case 1021260 - Application Added as of 12/04/2009	CONSTRUCT	211 31ST AVE S
---	-----------	----------------

Case 1009369 - Application Added as of 08/15/2006	CONSTRUCT	5921 24TH AVE S
---	-----------	-----------------

# Test Map

OBTAIN PERMITS and inspections OR REMOVE DECKS.

Permit 6082289 (renewal of Permit 743836) was issued during January 2006 for work that was originally done without a permit. This case to be kept open until final inspection approved for Permit 6082289. NO RENEWAL OF PERMIT 6082289 per L. Elder.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1002535>

Violation found: building a retaining wall in ECA 1 (steep slope) without a permit.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1002673>

Permit 6103889 issued July 20, 2006, for addition originally built without a permit on the back of the house in a Steep Slope Environmentally Critical Area. This case will remain open until all required inspections have been requested from and performed by DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1007385>

Bldg. secure; deterioration, outdoor storage.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019129>

Land Use violation observed.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022294>

PERMIT IS REQUIRED FOR NEW RETAINING WALL BUILT IN STEEP SLOPE ECA

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021469>

Installing a pump chamber & yard drain (discharging to the sidewalk) requires a Side Sewer Permit & inspections from DPD (for sanitary & drainage work).

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021260>

Decks and additions require a permit from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1009369>

# Test Map

-122.2605634	47.50888509
--------------	-------------

-122.34060734	47.52908246
---------------	-------------

-122.30742668	47.57598597
---------------	-------------

-122.27219797	47.54055043
---------------	-------------

-122.30804332	47.66567046
---------------	-------------

-122.30594641	47.66688609
---------------	-------------

-122.29286829	47.60044477
---------------	-------------

-122.30327346	47.54942208
---------------	-------------

# Test Map

Case 1007264 - Application Added as of 01/18/2006	CONSTRUCT	5937 49TH AVE SW
Case 1020951 - Citation Issued as of 05/20/2010	CITATION	635 NW 82ND ST
Case 1003638 - Application Added as of 10/11/2004	CONSTRUCT	3416 64TH AVE SW
Case 1016035 - Notice or Order Issued as of 04/21/2010	CONSTRUCT	1745 S ANGELINE ST
Case 1020878 - Case Resolved as of 05/21/2010	CITATION	1735 S ANGELINE ST
Case 1020565 - Application Added as of 09/15/2009	HZW	5659 CALIFORNIA AVE SW
Case 1014863 - Case Resolved as of 01/04/2010	CITATION	6535 11TH AVE NW
Case 1007565 - Application Added as of 02/21/2006	CONSTRUCT	3907 25TH AVE S
Case 1020772 - Case Opened as of 01/08/2010	HZW	10208 EVANSTON AVE N
Case 1021265 - Case Resolved as of 05/21/2010	CITATION	8022 FAUNTLEROY WAY SW

# Test Map

Violation found: Trees topped in Steep Slope and Potential Slide ECAs without a permit.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1007264>

Zoning violation

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020951>

Violation of the Seattle Building Code found: constructing a carport structure in the rear yard w/o a permit.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1003638>

Permit 6191827 was issued 2/2/09 for work originally started without a permit. this case will remain open until all required inspections have been requested and approved.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016035>

10/14/09 bg - Number of vehicles on site, 2 commercial trucks in the driveway, a car in front of the front entrance and a car at the rear of the property.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020878>

Observed a daycare operating on north side of 1st floor. To tech for research

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020565>

Outdoor storage case opened next door (the daughter) and this property is an extension of the problem.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014863>

TREE CUTTING PERMIT IS REQUIRED FOR CUTTING TREES IN ECA

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1007565>

salvage yard not allowed in L2 residential zone + light & glare violation

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020772>

12/3/09 Ej-Inspection shows outdoor junk storage such as but not limit to inoperable vehicle located in the drive way, broken windows and other miscellaneous items in

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021265>



# Test Map

-122.39563926	47.54920841
---------------	-------------

-122.3649073	47.68812929
--------------	-------------

-122.41449643	47.57366567
---------------	-------------

-122.3084348	47.56026216
--------------	-------------

-122.30904346	47.56027124
---------------	-------------

-122.38738827	47.55053314
---------------	-------------

-122.37109411	47.67704895
---------------	-------------

-122.301048	47.5689971
-------------	------------

-122.35031584	47.70319354
---------------	-------------

-122.39235332	47.53088177
---------------	-------------

# Test Map

Case 1015114 - Application Added as of 03/06/2008      CONSTRUCT      3779 S PERRY ST

Case 1022173 - Application Added as of 04/08/2010      CONSTRUCT      1321 33RD AVE S

Case 1009728 - Application Added as of 09/19/2006      CONSTRUCT      9281 31ST AVE SW

Case 1020862 - Application Added as of 12/24/2009      CONSTRUCT      1802 7TH AVE W

Case 1021553 - Case Resolved as of 03/03/2010      CITATION      3302 NE 60TH ST

Case 1018203 - Application Added as of 01/08/2009      CONSTRUCT      305 LAKESIDE AVE S

Case 1010117 - Application Added as of 10/20/2006      CONSTRUCT      3802 19TH AVE SW

Case 1022194 - Application Added as of 04/07/2010      CITATION      3802 19TH AVE SW

Case 1004518 - Application Added as of 02/16/2005      CONSTRUCT      1937 45TH AVE SW

# Test Map

the rear yard.

Trees not planted per Permit 743691 renewed by Permit 6105631. Permit 6105631 expired 1/13/08 without obtaining final inspection.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015114>

Work being performed including but not limited to interior remodel, creating habitable space out of a garage, reconfiguring roof & repairing a chimney requires permits (construction, electrical, furnace & plumbing) and inspections from DPD & King County. STOP WORK ORDER posted 4/5/10.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022173>

Addition on rear (west side) of house requires a permit from DPD. Stop Work Order posted 9/18/06.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1009728>

5 TO 10 FOOT RETAINING WALL BUILT AT EDGE OF PROPERTY REQUIRES PERMIT

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020862>

Big outdoor storage, a repeat offender. Including but not limited to piles of junk and trash in the driveway, 30 or 40 empty paint cans, hand tools, logs, and a pile of cut brush the size of a Volkswagen.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021553>

Occupying 301A, 301B, 305A, 305B, 309A & 309B Lakeside Ave S requires a Certificate of Occupancy.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018203>

Replacing decks and other work requires a permit and inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010117>

Violation of Land Use- Outdoor junk storage

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022194>

Violation found of the Seattle Building Code: replacing a

# Test Map

-122.28275515      47.51457885

-122.2907067      47.5916368

-122.37267265      47.51909905

-122.36599063      47.63493194

-122.29191041      47.67233117

-122.28654338      47.60002048

-122.35770746      47.56999763

-122.35770746      47.56999763

-122.38943962      47.58570756

# Test Map

Case 1004518 - Application Added as of 02/16/2005	CONSTRUCT	1937 45TH AVE SW
Case 1022362 - Application Added as of 04/29/2010	CITATION	2518 ROYAL CT E
Case 1018956 - Application Added as of 04/10/2009	HZW	5121 SW OLGA ST
Case 1020437 - Application Added as of 11/06/2009	HZW	5121 SW OLGA ST
Case 1021624 - Case Resolved as of 04/08/2010	CITATION	559 N 82ND ST
Case 1021332 - Citation Issued as of 04/01/2010	CITATION	1717 N 85TH ST
Case 1018418 - Case Resolved as of 02/26/2010	CITATION	4736 25TH AVE SW
Case 1022451 - Citation Issued as of 05/10/2010	CITATION	4736 25TH AVE SW
Case 1008629 - Case Opened as of 07/14/2006	CONSTRUCT	4767 SW EDDY ST
Case 1022282 - Application Added as of 04/21/2010	CONSTRUCT	5221 17TH AVE NE
Case 1021048 - Notice or Order Issued as of 04/16/2010	HZW	3034 NE 89TH ST

# Test Map

Violation found of the Seattle Building Code: replacing a deck requires a permit from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1004518>

A shed has been built in the required side yard.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022362>

Church/Snyogogue activity being run out of SFR

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018956>

Church/Snyogogue activity being run out of SFR

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020437>

Zoning violation

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021624>

junk storage & Home Occ violations, sf zone

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021332>

A sofa and miscellaneous furniture and junk at the rear of the property. photos taken

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018418>

5/6/10 ej- Inspection shows outdoor junk storage such as but not limited to vegetation rubbish, wood, open shed full of debris and other miscellaneous items.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022451>

Accessory structure built on top of terraced garage requires zoning approval and permits. Stop work Order posted 6/7/06.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1008629>

EXTERIOR STAIRWAY REQUIRES PERMIT--(THIS IS AN ARTIST STUDIO--NOT A DWELLING UNIT)

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022282>

Violations of Vacant Building Code.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=>

# Test Map

-122.2994993	47.64222891
--------------	-------------

-122.39828485	47.58036322
---------------	-------------

-122.39828485	47.58036322
---------------	-------------

-122.35014036	47.68822412
---------------	-------------

-122.33694485	47.69034251
---------------	-------------

-122.36391904	47.55997141
---------------	-------------

-122.36391904	47.55997141
---------------	-------------

-122.39413633	47.54566513
---------------	-------------

-122.30992386	47.66706076
---------------	-------------

-122.29450649	47.69340298
---------------	-------------

# Test Map

04/16/2010

Case 1022411 - Notification Issued as of 05/04/2010      VACANT      3034 NE 89TH ST

Case 1002934 - Application Added as of 07/22/2004      CONSTRUCT      11045 35TH AVE SW

Case 1019180 - Application Added as of 02/02/2010      HZW      5021 17TH AVE NE

Case 1008352 - Application Added as of 05/08/2006      CONSTRUCT      3804 E SUPERIOR ST

Case 1005755 - Application Added as of 07/11/2005      CONSTRUCT      7152 WOODSIDE PL SW

Case 1005735 - Notice or Order Issued as of  
04/07/2010      CONSTRUCT      3643 46TH AVE SW

Case 1022406 - Notice or Order Issued as of  
05/14/2010      HZW      521 N 105TH ST

Case 1015238 - Application Added as of 04/07/2008      CONSTRUCT      5317 S HUDSON ST

Case 1015410 - Application Added as of 04/07/2008      CONSTRUCT      5317 S HUDSON ST



# Test Map

	1021048
Violations of Vacant Building Code.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022411">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022411</a>
Violation found: grading and retaining walls without a permit.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1002934">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1002934</a>
Inspected property, observed violations of Housing Building and Maintenance Code.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019180">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019180</a>
Constructing a retaining wall and adding to the top of a retaining wall in an ECA 1 (Steep Slope) and ECA 2 (Potential Slide) requires a permit from DPD.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1008352">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1008352</a>
Retaining wall (over 4 feet tall in some places) being built requires a permit from DPD. Owner and contractor notified.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1005755">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1005755</a>
Constructing a second story addition to a detached garage and attaching the garage to house requires a permit from DPD. Stop Work Order posted 7/6/05.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1005735">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1005735</a>
Bedbugs violation	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022406">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022406</a>
Emergency slide repair work being performed to protect adjacent house from further damage requires building & grading permits and inspections from DPD. Installation of Temporary Erosion & Sedimentation Control (TESC) measures required. STOP WORK ORDER posted 3/21/08.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015238">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015238</a>
Side sewer work requires a permit and inspections from	

# Test Map

-122.29450649	47.69340298
---------------	-------------

-122.37647889	47.50329911
---------------	-------------

-122.30995854	47.66557171
---------------	-------------

-122.28559781	47.60322272
---------------	-------------

-122.38921898	47.53827876
---------------	-------------

-122.39126192	47.57077269
---------------	-------------

-122.35174344	47.7048658
---------------	------------

-122.2662735	47.55691394
--------------	-------------

-122.2662735	47.55691394
--------------	-------------

# Test Map

Case 1015410 - Application Added as of 04/07/2008      CONSTRUCT      5317 S HUDSON ST

Case 1015411 - Application Added as of 04/07/2008      CONSTRUCT      5317 S HUDSON ST

Case 1019158 - Application Added as of 12/01/2009      CONSTRUCT      5318 SW LANDER ST

Case 1021020 - Notice or Order Issued as of 01/08/2010      CONSTRUCT      10221 BELGROVE CT NW

Case 1018511 - Notification Issued as of 05/10/2010      VACANT      2755 E YESLER WAY

Case 1017019 - Application Added as of 01/21/2010      HZW      2755 E YESLER WAY

Case 1014356 - Application Added as of 11/13/2008      HZW      1301 N NORTHLAKE WAY

Case 1015449 - Application Added as of 05/21/2009      HZW      1301 N NORTHLAKE WAY

Case 1021252 - Application Added as of 02/24/2010      CITATION      4919 30TH AVE S

Case 1017848 - Application Added as of 11/14/2008      CONSTRUCT      5727 S RYAN ST

# Test Map

Side sewer work requires a permit and inspections from DPD. STOP WORK ORDER posted 3/21/08.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015410>

Vegetation removal in a Steep Slope Environmentally Critical Area requires a Tree & Vegetation Restoration Plan from DPD. STOP WORK ORDER posted 3/21/08.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015411>

Removing more than 1500 sq.ft. of vegetation (including 5 trees) in a Steep Slope & Potential Slide Environmentally Critical Area requires SEPA review, a repainting plan & inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019158>

PERMIT REQUIRED FOR TERRACED RETAINING WALL IN STEEP SLOPE ECA

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021020>

Secure; deterioration; outdoor & vehicle storage.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018511>

Secure; deterioration; outdoor & vehicle storage.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017019>

Pouring concrete on timber pier w/o authorization.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014356>

See case no. 1014356. In researching for that case, found that unauthorized expansion of City Dock took place between 1993-1999.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015449>

VIOLATIONS OF THE SEATTLE LAND USE AND ZONING CODE OBSERVED (VEHICLES IN REQUIRED FRONT YARD; MORE THAN 3 VEHICLES OUTDOORS, LUMBER AND METAL IN YARD).

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021252>

Temporary Erosion & Sedimentation Control (TESC) is

# Test Map

-122.2662735 47.55691394

-122.4010958 47.57971305

-122.38323881 47.70317844

-122.29642668 47.60142917

-122.29642668 47.60142917

-122.34213533 47.64788228

-122.34213533 47.64788228

-122.294587 47.55765956

-122.2600384 47.50944419

# Test Map

Case 1004058 - Application Added as of 12/03/2004	CONSTRUCT	7312 56TH AVE NE
Case 1018670 - Citation Issued as of 05/17/2010	CITATION	3717 SW THISTLE ST
Case 1004166 - Case Opened as of 06/15/2006	CONSTRUCT	4827 12TH AVE S
Case 1009104 - Notice or Order Issued as of 05/06/2010	CONSTRUCT	4827 12TH AVE S
Case 1022455 - Application Added as of 05/10/2010	HZW	3053 FAUNTLEROY AVE SW
Case 1022456 - Application Added as of 05/10/2010	CITATION	3053 FAUNTLEROY AVE SW
Case 1021952 - Application Added as of 04/20/2010	HZW	5219 COLUMBIA DR S
Case 1021954 - Application Added as of 04/16/2010	CITATION	5219 COLUMBIA DR S
Case 1017361 - Application Added as of 08/24/2009	CONSTRUCT	2409 29TH AVE W
Case 1022483 - Notice or Order Issued as of 05/12/2010	HZW	8606 35TH AVE NE

# Test Map

not per Application 6192360 (Raise existing single story residence and replace foundation) or code.

STOP WORK POSTED--BUILDING AND SITE  
DEVELOPMENT PERMITS NEEDED--ECA

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017848>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1004058>

Violation of Land Use- Outdoor junk storage

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018670>

Violation of the Seattle Building Code found: building addition without a permit. Stop Work Order posted 12/21/04.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1004166>

Construction of roofs and dormers requires a permit from DPD. Stop Work Order posted 7/25/06.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1009104>

unsafe stair treads & loose guardrail assembly; pictures in file.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022455>

Outdoor storage including vehicle, motorcycle, carpeting, tires, lumber, tarps, black plastic bags & other items, pictures in file.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022456>

Missing paint; open ditches in yard; pictures in file.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021952>

outdoor storage includes lumber, const. debris, suitcase, etc; pictures in file.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021954>

PERMIT IS REQUIRED FOR RETAINING WALL

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017361>

Outdoor storage includes couch, futon, pallet & pipe; pictures in file.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=>

# Test Map

-122.26767338	47.68158027
---------------	-------------

-122.38013893	47.52818114
---------------	-------------

-122.31733829	47.55936873
---------------	-------------

-122.31733829	47.55936873
---------------	-------------

-122.3742879	47.57583798
--------------	-------------

-122.3742879	47.57583798
--------------	-------------

-122.3052695	47.55532249
--------------	-------------

-122.3052695	47.55532249
--------------	-------------

-122.3944704	47.63986184
--------------	-------------

-122.29037824	47.69129406
---------------	-------------



# Test Map

05/12/2010

Case 1022399 - Notice or Order Issued as of 05/12/2010 HZW 8606 35TH AVE NE

Case 1020448 - Payment Processed as of 12/30/2009 TRAO 2712 60TH AVE SW

Case 1021245 - Case Opened as of 12/11/2009 HZW 1126 34TH AVE

Case 1010962 - Application Added as of 02/01/2007 CONSTRUCT 1341 N NORTHLAKE WAY

Case 1019461 - Application Added as of 09/18/2009 HZW 1341 N NORTHLAKE WAY

Case 1022264 - Application Added as of 04/19/2010 CITATION 7500 10TH AVE NW

Case 1010966 - Application Added as of 02/01/2007 CONSTRUCT 2533 WESTLAKE AVE N

Case 1014824 - Case Resolved as of 01/04/2010 CITATION 6531 11TH AVE NW

Case 1003235 - Application Added as of 08/25/2004 CONSTRUCT 2220 34TH AVE S

# Test Map

pictures in file.	1022483
Open to entry in 4 locations, pictures in file.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022399">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022399</a>
Application for a Tenant Relocation License. Total units:14; total units occupied:14. Demolition.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020448">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020448</a>
Violation of the Land Use & Zoning Code	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021245">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021245</a>
CONTINUATION OF PTS CASE #211177 IN LAW-- FAILING TO CONSTRUCT RETAINING WALL ACCORDING TO THE APPROVED PLANS FOR PERMIT #705410--FAILING TO OBTAIN REQUIRED INSPECTIONS	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010962">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010962</a>
Observed large boat shed in CW w/o DPD authorization.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019461">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019461</a>
Violation of Land Use Code observed.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022264">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022264</a>
CONTINUATION OF PTS CASE #234223--OBTAIN A PERMIT FOR RETAINING WALL BUILT IN ECA--MAKE ALL CORRECTIONS	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010966">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010966</a>
Junk and outdoor storage.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014824">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014824</a>
Violation found: building a retaining wall without a permit and never submitting Special Inspection reports or obtaining building inspections for Permit 691203.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1003235">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1003235</a>

# Test Map

-122.29037824	47.69129406
---------------	-------------

-122.40904779	47.57905178
---------------	-------------

-122.28899525	47.61243079
---------------	-------------

-122.34086416	47.64746509
---------------	-------------

-122.34086416	47.64746509
---------------	-------------

-122.36915169	47.68338933
---------------	-------------

-122.34428432	47.6430057
---------------	------------

-122.37108835	47.67693104
---------------	-------------

-122.28953765	47.58302563
---------------	-------------

# Test Map

Case 1017087 - Application Added as of 05/04/2009	CONSTRUCT	2220 34TH AVE S
Case 1017818 - Application Added as of 06/03/2009	CONSTRUCT	3528 S WEBSTER ST
Case 1018547 - Case Resolved as of 04/26/2010	CITATION	11029 53RD AVE S
Case 1022578 - Application Added as of 05/21/2010	CITATION	319 W KINNEAR PL
Case 1015349 - Case Resolved as of 05/18/2010	HZW	2540 34TH AVE S
Case 1015992 - Notification Issued as of 03/08/2010	VACANT	2540 34TH AVE S
Case 1015113 - Application Added as of 03/06/2008	CONSTRUCT	3759 S PERRY ST
Case 1013322 - Application Added as of 03/02/2010	HZW	7567 LAKE CITY WAY NE
Case 1007316 - Application Added as of 01/24/2006	CONSTRUCT	6312 SWIFT AVE S

# Test Map

PERMIT REQUIRED FOR ROCKERIES, RETAINING WALLS AND OTHER STRUCTURES ON STEEP SLOPE ECA

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017087>

Permit 6200255 was issued 11/7/08 for work originally started without a permit. This case will remain open until all required inspections have been requested and approved.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017818>

Inspection shows massive outdoor junk storage such as but not limited to luggage, paint cans, pile of miscellaneous items in front, side, back yards and driveway.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018547>

5/11/10 KB inspected property and Weeds violation exists

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022578>

Open to entry & weather with deterioration & outdoor storage.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015349>

Open to entry & weather with deterioration & outdoor storage.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015992>

Trees not planted per Permit 743690 renewed by Permit 6105634. Permit 6105634 expired 1/13/08 without obtaining final inspection.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015113>

Inspected property, observed violation of Land Use Code.PR

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1013322>

Temporaray Erosion & Sedimentation Control (TESC) measures required. Grading permit required for grading more than 100 cubic yards in the non-ECA area of the

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1007316>

# Test Map

-122.28953765	47.58302563
---------------	-------------

-122.28733855	47.53570037
---------------	-------------

-122.26779427	47.50191238
---------------	-------------

-122.36149958	47.62752501
---------------	-------------

-122.28952706	47.57983503
---------------	-------------

-122.28952706	47.57983503
---------------	-------------

-122.28351256	47.51467187
---------------	-------------

-122.31576491	47.6849117
---------------	------------

-122.30717488	47.54670479
---------------	-------------

# Test Map

Case 1016221 - Order of Director Issued as of 01/26/2010	UNFIT	1133 32ND AVE S
Case 1022508 - Application Added as of 05/14/2010	CITATION	6719 18TH AVE SW
Case 1022496 - Notice or Order Issued as of 05/13/2010	HZW	6719 18TH AVE SW
Case 1022438 - Notice or Order Issued as of 05/12/2010	HZW	4515 GREENWOOD AVE N
Case 1013440 - Application Added as of 04/15/2008	CONSTRUCT	6029 ATLAS PL SW
Case 1021937 - Notice or Order Issued as of 04/19/2010	CONSTRUCT	6053 ATLAS PL SW
Case 1015239 - Application Added as of 04/01/2010	HZW	13508 RIVIERA PL NE
Case 1013627 - Application Accepted as of 09/28/2007	TRAO	13734 RIVIERA PL NE
Case 1022200 - Application Added as of 04/15/2010	HZW	5601 RAINIER AVE S

# Test Map

site.	
abatement inspection request	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016221">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016221</a>
outdoor storage, pictures in file.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022508">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022508</a>
Open to entry, pictures in file.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022496">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022496</a>
Permit violation, eliminated landscaping south side	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022438">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022438</a>
MORE THAN 14 TREES WERE CUT--WORK IS NOT PER PLAN FOR PROJECT #3006057	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1013440">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1013440</a>
Installing drainage without a permit causing uncontrolled runoff from plastic sheeting to adversely stability of hillside requires permit & repair. Side Sewer permit requires review by DPD geotechnical staff & repairs must be performed under direction & observation of licensed geotechnical engineer.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021937">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021937</a>
Installation or repair of bulkhead w/o shoreline authorization.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015239">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015239</a>
Application for a Tenant Relocation License. Total units: 1; total units occupied: 1. Demolition.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1013627">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1013627</a>
04/07/10 - Wood debris on second story porch and a wooden pallet at the rear of the building. photos taken	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022200">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022200</a>



# Test Map

-122.29180146	47.59236116
---------------	-------------

-122.35752865	47.54227608
---------------	-------------

-122.35752865	47.54227608
---------------	-------------

-122.3557432	47.66203576
--------------	-------------

-122.39720764	47.5482485
---------------	------------

-122.39734147	47.54757135
---------------	-------------

-122.2807225	47.72663386
--------------	-------------

-122.28210655	47.72925656
---------------	-------------

-122.27831856	47.55180461
---------------	-------------

# Test Map

Case 1018025 - Application Added as of 06/04/2009	CONSTRUCT	10014 RAINIER AVE S
Case 1010874 - Application Added as of 01/23/2007	CONSTRUCT	10371 RAINIER AVE S
Case 1022569 - Application Added as of 05/20/2010	CONSTRUCT	6977 23RD AVE SW
Case 1008283 - Application Added as of 02/04/2010	CONSTRUCT	817 LAKE WASHINGTON BLVD S
Case 1018114 - Application Added as of 01/26/2010	CONSTRUCT	10623 57TH AVE S
Case 1013432 - Application Added as of 09/12/2007	HZW	11004 14TH AVE NE
Case 1022507 - Application Added as of 05/14/2010	CITATION	1542 NE NORTHGATE WAY
Case 1022489 - Notice or Order Issued as of 05/19/2010	HZW	1542 NE NORTHGATE WAY

# Test Map

Constructing an addition on the east side, enlarging each on the east side & enclosing the deck on the south side of the house & other construction requires plan review, permits & inspections from DPD. STOP WORK ORDER posted 12/9/08.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018025>

Temporary Erosion & Sedimentation Control (TESC) is not per Permit 6099428. Need to repair temporary construction entrance and clean S Taft St of mud.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010874>

Building a small shed (less than 100 sq.ft.) in the riparian corridor of Long fellow Creek and building a retaining wall next to the creek including placing concrete blocks in the creek, if allowed, requires approval from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022569>

Fence with trellis does not require a permit from DPD. Permits 724044 & 727390 need final inspections by a DPD Building Inspector. ADU requires a permit from DPD. Owner notified 4/27/06.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1008283>

Constructing a two story addition on the back side of a single family residence requires permits and inspections from DPD. STOP WORK ORDER posted 11/30/07.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018114>

Violation of Just Cause Eviction Ordinance.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1013432>

outdoor storage, pictures in file.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022507>

House & shed open to entry; pictures in file.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022489>

# Test Map

-122.24712647	47.51203577
---------------	-------------

-122.23828725	47.50985478
---------------	-------------

-122.36203688	47.53948826
---------------	-------------

-122.28946224	47.59518066
---------------	-------------

-122.26160897	47.50541868
---------------	-------------

-122.31349495	47.70872034
---------------	-------------

-122.31061363	47.70875025
---------------	-------------

-122.31061363	47.70875025
---------------	-------------

# Test Map

Case 1016122 - Application Added as of 04/13/2009	HZW	126 27TH AVE E
Case 1010813 - Application Added as of 01/16/2007	CONSTRUCT	4121 47TH AVE S
Case 1019844 - Application Added as of 11/06/2009	CONSTRUCT	3879 51ST AVE NE
Case 1012249 - Application Added as of 01/27/2009	CONSTRUCT	216 31ST AVE
Case 1017823 - Application Added as of 12/09/2009	CONSTRUCT	1939 E CRESCENT DR
Case 1020141 - Notice or Order Issued as of 04/12/2010	HZW	750 N 91ST ST
Case 1021140 - Notification Issued as of 04/12/2010	VACANT	750 N 91ST ST
Case 1018941 - Application Added as of 08/24/2009	CONSTRUCT	1119 NE RAVENNA BLVD
Case 1010978 - Application Added as of 02/02/2007	CONSTRUCT	2212 FAIRMOUNT AVE SW
Case 1006622 - Application Added as of 10/18/2005	CONSTRUCT	4033 34TH AVE SW

# Test Map

Violation of the Just Cause Eviction Ordinance.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016122>

Interior alterations and rear addition requires permit and inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010813>

REVISE PLANS FOR PERMIT #6170773 TO INCLUDE THE CONSTRUCTION OF ROCKERY TO REPLACE RAILROAD TIE WALL IN STEEP SLOPE ECA

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019844>

Permit 6150131 was issued 8/13/07 for work originally started without a permit. This case will remain open until all required inspections have been requested and approved.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1012249>

PERMIT REQUIRED FOR RETAINING WALL IN STEEP SLOPE ECA

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017823>

Unsecured window @ NW corner, deflected/open roof above rear entry door, pictures in file.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020141>

Unsecured window @ NW corner, deflected/open roof above rear entry door, pictures in file.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021140>

PERMITS ARE REQUIRED FOR ACCESSORY STRUCTURE

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018941>

CONTINUATION OF PTS CASE #222164--OBTAIN BUILDING PERMIT AND CALL FOR INSPECTION

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010978>

The unpermitted roof of the porch entry in the required north side yard must be removed and reinspected by DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1006622>

# Test Map

-122.2969705	47.61971072
--------------	-------------

-122.27477387	47.56579828
---------------	-------------

-122.27273106	47.65691121
---------------	-------------

-122.29239185	47.60375849
---------------	-------------

-122.30588495	47.63297605
---------------	-------------

-122.34776861	47.6950936
---------------	------------

-122.34776861	47.6950936
---------------	------------

-122.315435	47.6713161
-------------	------------

-122.38053206	47.58322522
---------------	-------------

-122.37535977	47.56692499
---------------	-------------

# Test Map

Case 1018108 - Application Added as of 12/18/2008	CONSTRUCT	3503 S GRAHAM ST
---	-----------	------------------

Case 1020907 - Application Added as of 10/20/2009	CONSTRUCT	2333 32ND AVE S
---	-----------	-----------------

Case 1013750 - Application Added as of 01/06/2009	CONSTRUCT	9635 50TH AVE S
---	-----------	-----------------

Case 1022049 - Application Added as of 04/01/2010	CONSTRUCT	3860 33RD AVE SW
---	-----------	------------------

Case 1015342 - Case Opened as of 01/12/2010	HZW	933 NW 97TH ST
---	-----	----------------

Case 1022417 - Application Added as of 05/04/2010	CITATION	2012 S EDMUNDS ST
---	----------	-------------------

Case 1015116 - Application Added as of 03/07/2008	CONSTRUCT	1817 E SPRUCE ST
---	-----------	------------------

Case 1007911 - Application Added as of 03/22/2006	CONSTRUCT	8425 9TH AVE SW
---	-----------	-----------------

Case 1022461 - Application Added as of 05/10/2010	CITATION	8324 18TH AVE NW
---	----------	------------------



# Test Map

Grading/filling approximately 300 cu.yds. and constructing retaining walls over 4' tall requires permits & inspections from DPD. STOP WORK ORDER posted 9/28/07.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018108>

Reconstructing a deck on the south side & front porch on the west side and making interior alterations to a single family residence requires permits & inspections from DPD. STOP WORK ORDER posted 10/19/09.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020907>

Permit 6165617 was issued 3/18/08 for work originally started without a permit. This case will remain open until all inspections have been called for and obtained.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1013750>

Permit 6244382 was issued 3/26/10 for work (2nd story deck) originally started without a permit. This case will remain open until all required inspections have been requested and obtained.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022049>

LU permit violation possible

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015342>

05/04/10 bg - Vegetation encroaching onto the sidewalk along S Columbian Way. photo taken

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022417>

Temporary Erosion & Sedimentation Control (TESC) is not per Permit 6064355.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015116>

Building an addition and remodeling a house requires a permit from DPD. Stop Work Order posted 3/21/06.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1007911>

Zoning violation.Storage of construction debris in the driveway.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022461>

# Test Map

-122.28782254	47.54585083
---------------	-------------

-122.29223437	47.58151574
---------------	-------------

-122.27125238	47.51590002
---------------	-------------

-122.37382715	47.56801747
---------------	-------------

-122.37018087	47.69996219
---------------	-------------

-122.30641	47.55996278
------------	-------------

-122.30822118	47.60339302
---------------	-------------

-122.34713273	47.5274351
---------------	------------

-122.37973737	47.68943051
---------------	-------------

# Test Map

Case 1021578 - Notice or Order Issued as of  
03/29/2010

HZW

7400 8TH AVE S

Case 1016772 - Application Accepted as of  
10/12/2009

ADVISORY

9550 INTERLAKE AVE N

Case 1022572 - Application Added as of 05/21/2010

HZW

3716 S OREGON ST

Case 1022315 - Application Added as of 04/30/2010

HZW

1001 LENORA ST

Case 1013728 - Payment Processed as of 12/14/2009

TRAO

304 E THOMAS ST

Case 1022068 - Application Added as of 05/10/2010

HZW

5030 26TH AVE S

Case 1022527 - Application Added as of 05/19/2010

HZW

9000 20TH AVE SW

Case 1007256 - Application Added as of 01/17/2006

CONSTRUCT

309 1ST AVE S

# Test Map

Non-water dependent cargo and non-water-dependent recycling uses are both prohibited in the UI Shoreline Environment. Workers on-site said that Cedar Grove has operated at this loaction for about 2 months, hauling compost to and from the site for distribution in Seattle. Wood waste appears to be processed on site within 200' of shoreline.

Condo conversion.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021578>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016772>

Tenant confirms water service has not been restored to his unit - owners does not answer, sent Fax to advise of EO and asked for a call back ASAP. PBarrett 5-21-10

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022572>

Violation of the Zoning Code

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022315>

Application for a Tenant Relocation License. Total units: 14; total units occupied: 14. Demolition.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1013728>

Open to entry via rear window, picture in file. No siding or protective cover on most parts of the structure. permit 6152461 - expired.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022068>

5/13/10 ej-Inspection shows housing code violations such as but not limited to missing outlet covers, missing smoke detectors, moisture & mold in the unit and other housing code violations.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022527>

MEZZANINE REMODEL NEEDS PERMIT

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1007256>

# Test Map

-122.32106689	47.53699621
---------------	-------------

-122.34043539	47.6993176
---------------	------------

-122.28528511	47.56303058
---------------	-------------

-122.33572599	47.61789063
---------------	-------------

-122.3274728	47.62099696
--------------	-------------

-122.29892558	47.55635852
---------------	-------------

-122.35887517	47.52265367
---------------	-------------

-122.33458819	47.59966398
---------------	-------------

# Test Map

Case 1022531 - Application Added as of 05/18/2010	HZW	5026 M L KING JR WAY S
---	-----	------------------------

Case 1022532 - Application Added as of 05/18/2010	CITATION	5026 M L KING JR WAY S
---	----------	------------------------

Case 1022181 - Notice or Order Issued as of 05/05/2010	CONSTRUCT	213 S MAIN ST
--	-----------	---------------

Case 1017988 - Application Added as of 12/04/2008	CONSTRUCT	3927 S BRANDON ST
---	-----------	-------------------

Case 1018685 - Application Added as of 03/09/2010	CONSTRUCT	2617 44TH AVE SW
---	-----------	------------------

Case 1019534 - Application Added as of 06/05/2009	TRAO	3402 15TH AVE W
---	------	-----------------

Case 1022278 - Application Added as of 04/21/2010	HZW	3402 15TH AVE W
---	-----	-----------------

Case 1009025 - Application Added as of 07/19/2006	CONSTRUCT	9757 60TH AVE S
---	-----------	-----------------

# Test Map

05/18/10 bg - Single family residence with seperate unit downstairs, outdoor storage of junk. photos taken

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022531>

05/18/10 bg - Single family residence with seperate unit downstairs. photos taken

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022532>

Loose brick at NE corner of building, along the public sidewalks & bulging bricks along alley requires a structural engineer's evaluation including recommendation for repair & overhead protection for sidewalk. Repair requires Pioneer Square Preservation Board approval and permit & inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022181>

Construction a roof hoverhang in a required side yard requires zoning approval and, if approved, a building permit OR removal. STOP WORK ORDER posted 12/3/08.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017988>

Permit 6210164 was issued 3/6/09 for work originally started without a permit. This case will remain open until all required inspections have been requested and approved.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018685>

Notice of Violation of Tenant Relocation Assistance Ordinance (SMC 22.210), failure to apply.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019534>

Deteriorated window frames, front wall & porch assemblies deflected & unsound, pictures in file.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022278>

Permits 6104099 & 6104096 issued 6/29/06 for work originally done without a permit. Grading and vegetation removal and construction of a retaining wall in an ECA 1 (Steep Slope) requires permit(s) from DPD. Stop Work

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1009025>

# Test Map

-122.29021571	47.5563171
---------------	------------

-122.29021571	47.5563171
---------------	------------

-122.33068945	47.59986421
---------------	-------------

-122.28230588	47.55316224
---------------	-------------

-122.38816383	47.5806149
---------------	------------

-122.37584581	47.6505078
---------------	------------

-122.37584581	47.6505078
---------------	------------

-122.25845408	47.51351116
---------------	-------------



# Test Map

Case 1010811 - Notice or Order Issued as of 03/25/2010	CONSTRUCT	6300 S PERRY ST
Case 1017395 - Application Added as of 09/23/2008	CONSTRUCT	5414 S BUDD CT
Case 1022227 - Application Added as of 04/29/2010	HZW	400 NW 100TH PL
Case 1021002 - Application Added as of 03/16/2010	CONSTRUCT	7520 EAST GREEN LAKE DR N
Case 1017822 - Notice or Order Issued as of 01/08/2010	CONSTRUCT	11502 6TH AVE NW
Case 1008497 - Application Added as of 05/23/2006	CONSTRUCT	9658 41ST AVE S
Case 1019855 - Application Added as of 11/04/2009	CITATION	2800 23RD AVE S
Case 1020863 - Notice or Order Issued as of 12/22/2009	HZW	5015 18TH AVE NE
Case 1020931 - Application Added as of 10/22/2009	HZW	5015 18TH AVE NE
Case 1019093 - Notice or Order Issued as of	HZW	14038 PALATINE AVE N

# Test Map

(Steep Slope) requires permit(s) from DPD. Stop Work Order posted 6/22/06.

Constructing an elevated walkway and decks from R-O-W to house requires a permit and all inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010811>

Disconnecting downspouts violates the conditions of Permit 672152 which requires flow control.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017395>

Housing violations.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022227>

EXISTING SIGNS MUST BE REMOVED--PORTABLE SIGNS ARE PROHIBITED AND OTHER SIGNS MUST NOT EXCEED 64 SQUARE INCHES

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021002>

IMMEDIATELY COVER ALL EXPOSED SOIL, SUBMIT EROSION CONTROL PLAN, AND INSTALL PERMANENT EROSION CONTROL MEASURES

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017822>

Permits required from DPD for remodel (and all required inspections).

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1008497>

07/02/09 bg - Zoning violation - Parking of vehicles in the required front yard, photos taken.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019855>

Violation of Land Use Code observed.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020863>

Violation of Just Cause Eviction Ordinance due to owner issuing two (2) deficient notices.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020931>

Rear house: illegal 2nd dwelling on sf lot

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=>

# Test Map

-122.25506089	47.51571748
---------------	-------------

-122.26446865	47.52990233
---------------	-------------

-122.3626153	47.70371109
--------------	-------------

-122.33134434	47.68282784
---------------	-------------

-122.36290683	47.71220126
---------------	-------------

-122.2811394	47.51616883
--------------	-------------

-122.30304326	47.57821496
---------------	-------------

-122.3086397	47.66534138
--------------	-------------

-122.3086397	47.66534138
--------------	-------------

-122.35635493	47.73162704
---------------	-------------

# Test Map

09/30/2009

Case 1022487 - Case Opened as of 05/13/2010	CITATION	4702 50TH AVE S
---	----------	-----------------

Case 1009800 - Application Added as of 09/22/2006	CONSTRUCT	1129 LAKE WASHINGTON BLVD S
---	-----------	--------------------------------

Case 1020949 - Case Resolved as of 04/06/2010	CITATION	1520 LAKE WASHINGTON BLVD S
---	----------	--------------------------------

Case 1007731 - Case Resolved as of 10/22/2009	CITATION	4722 SW RAYMOND ST
---	----------	--------------------

Case 1018475 - Case Resolved as of 05/21/2010	CITATION	9050 11TH AVE SW
---	----------	------------------

Case 1020641 - Case Opened as of 09/24/2009	HZW	4211 7TH AVE NE
---	-----	-----------------

Case 1022554 - Application Added as of 05/20/2010	HZW	1811 17TH AVE
---	-----	---------------

Case 1022311 - Application Added as of 04/23/2010	CITATION	600 E DENNY WAY
---	----------	-----------------

Case 1018339 - Payment Processed as of 04/10/2009	TRAO	5240 UNIVERSITY WAY NE
---	------	------------------------

# Test Map

	1019093
Int Insp 3/26/10 DG The compressor was not in operation on my inspection. I believe the owner has had the maintenance on the compressor. Noise barrier has not been constructed.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022487">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022487</a>
Height not per approved plan for Permit 752459. Stop Work Order posted 4/12/06.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1009800">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1009800</a>
Violation of the Land Use Code	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020949">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020949</a>
OBSERVED VIOLATION OF THE SEATTLE LAND USE AND ZONING CODE (PAPER BOXES, PLASTIC BAGS, AUTO TIRES AND OTHER MATERIALS IN YARDS). TOOK PHOTOS.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1007731">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1007731</a>
Inspection shows solid fence exceeds the allow height of 6'.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018475">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018475</a>
Violations of Housing and Building Code observed.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020641">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020641</a>
Minor Violation of the HBMC	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022554">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022554</a>
4/21/10 KB inspected property and LU violation exists - Junk Storage	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022311">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022311</a>
Application for a Tenant Relocation License. Total units:11; Total units occupied:11. Demolition.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018339">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018339</a>

# Test Map

-122.27044192	47.56043019
---------------	-------------

-122.28956329	47.59255796
---------------	-------------

-122.28891447	47.58818879
---------------	-------------

-122.3934723	47.54872713
--------------	-------------

-122.3487456	47.52132416
--------------	-------------

-122.32111503	47.65791231
---------------	-------------

-122.31046169	47.61804557
---------------	-------------

-122.32368781	47.61875332
---------------	-------------

-122.31271813	47.66760993
---------------	-------------

# Test Map

Case 1021751 - Case Resolved as of 04/23/2010	HZW	3015 NE 143RD ST
Case 1019509 - Application Added as of 02/18/2010	HZW	222 SW ROXBURY ST
Case 1016889 - Application Added as of 08/06/2008	CONSTRUCT	5642 32ND AVE SW
Case 1021054 - Application Accepted as of 12/04/2009	TRAO	4200 S OTHELLO ST
Case 1021154 - Application Added as of 04/05/2010	HZW	3300 RAINIER AVE S
Case 1018644 - Case Resolved as of 05/21/2010	HZW	8820 AURORA AVE N
Case 1009692 - Application Added as of 09/14/2006	CONSTRUCT	2001 20TH AVE S
Case 1005361 - Application Added as of 06/07/2005	CONSTRUCT	3867 RAINIER AVE S
Case 1022187 - Application Added as of 04/07/2010	CONSTRUCT	6116 34TH AVE NW
Case 1013925 - Application Added as of 10/24/2007	CONSTRUCT	2363 53RD AVE SW
Case 1019061 - Application Added as of 07/15/2009	CONSTRUCT	4700 S MEAD ST

# Test Map

Land Use Code Violation	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021751">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021751</a>
6/2/09 EJ- Observed multiple vehicles parked on vacant lot.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019509">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019509</a>
Remodeling a house and constructing decks requires permits and inspections from DPD. STOP WORK ORDER posted 8/6/08.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016889">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016889</a>
Application for Tenant Relocation License. Total units:11; total units occupied:9. Demolition.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021054">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021054</a>
11/17/09 bg - Junk storage, including pickup truck, furniture and garbage. photos taken	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021154">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021154</a>
Salvage yard in C1-65	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018644">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018644</a>
Building a structure in the front yard requires a permit from DPD.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1009692">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1009692</a>
No violation: approximately a 2-1/2' cut at property line and less than 25 cu. yds. grading does not require a permit from DPD.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1005361">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1005361</a>
INSPECTOR LEFT REPORT AT DOOR REQUESTING SPECIAL INSPECTIONS FINAL REPORT	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022187">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022187</a>
Removing two trees in a Potential Slide Environmentally Critical Area requires a Tree & Vegetation Replanting Plan.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1013925">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1013925</a>
Constructing a large addition on the north side of a	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=</a>



# Test Map

-122.2954874	47.73122084
-122.33857976	47.51746945
-122.37331787	47.55070537
-122.28039124	47.53770768
-122.29449543	47.57391191
-122.3436714	47.69325334
-122.30722335	47.58536791
-122.28966814	47.56810811
-122.40079485	47.67352114
-122.40019246	47.58273139
-122.27404486	47.55066173

# Test Map

Case 1021166 - Notice or Order Issued as of 05/04/2010	CONSTRUCT	3538 S HUDSON ST
--	-----------	------------------

Case 1022447 - Application Added as of 05/10/2010	CITATION	716 16TH AVE
---	----------	--------------

Case 1010987 - Application Added as of 02/05/2007	CONSTRUCT	5722 SW WINTHROP ST
---	-----------	---------------------

Case 1015751 - Application Added as of 01/27/2009	CONSTRUCT	3246 36TH AVE SW
---	-----------	------------------

Case 1017478 - Application Added as of 03/05/2010	HZW	4836 49TH AVE SW
---	-----	------------------

Case 1018530 - Notification Issued as of 03/05/2010	VACANT	4836 49TH AVE SW
---	--------	------------------

Case 1017506 - Application Added as of 10/03/2008	CONSTRUCT	1129 37TH AVE
---	-----------	---------------

# Test Map

house requires zoning approval and, if approved, permits and inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019061>

Permit 6238565 was issued 1/22/10 for work originally performed without a permit. This case will remain open until all required inspections have been requested, performed & approved.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021166>

Violation of the Land Use Code

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022447>

Retaining walls, a portion in Steep Slope ECA, require permit (or revision to Permit 6080723) including geotechnical and structural engineer design. Side yard easement agreement also required. STOP WORK ORDER posted 2/5/07.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010987>

Plan review w/ engineering needed for major renovation including large structural alterations & converting unheated to heated space requires new permit(s) & all required inspections from DPD. STOP WORK ORDER posted 5/1/08 & 7/24/08.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015751>

Inspection show rear door of the house open to entry.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017478>

Inspection show rear door of the house open to entry.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018530>

Excavation and placing concrete footing at south property line in a Steep Slope & Potential Slide ECA requires a permit & inspections from DPD. STOP WORK ORDER posted 10/2/08.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017506>

# Test Map

-122.28702621	47.55731735
---------------	-------------

-122.31124302	47.60858066
---------------	-------------

-122.40632536	47.57647947
---------------	-------------

-122.37673356	47.57416606
---------------	-------------

-122.39462036	47.55840298
---------------	-------------

-122.39462036	47.55840298
---------------	-------------

-122.28642241	47.61246164
---------------	-------------

# Test Map

Case 1018283 - Application Added as of 04/02/2009	CITATION	1542 MAGNOLIA WAY W
Case 1007814 - Application Added as of 10/15/2008	CONSTRUCT	3805 DELRIDGE WAY SW
Case 1013231 - Findings Issued as of 08/25/2008	ADVISORY	10021 7TH AVE NW
Case 1019464 - Application Added as of 07/22/2009	CONSTRUCT	807 26TH AVE S
Case 1015934 - Application Added as of 09/04/2009	HZW	603 NW MARKET ST
Case 1012180 - Application Added as of 05/25/2007	HZW	8221 30TH AVE NE
Case 1019814 - Application Added as of 08/24/2009	HZW	1321 SENECA ST
Case 1021869 - Notice or Order Issued as of 05/06/2010	CONSTRUCT	319 3RD AVE S
Case 1016970 - Application Added as of 08/20/2008	CONSTRUCT	111 12TH AVE

# Test Map

ORDER posted 10/2/08.

NS inspected the property on 1/20/09- inspection shows a Operating telecommunications buss.out of the home in a residential zone. 3 dish antennas are mounted on towers on top of the roof of the garage.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018283>

Adding decks, remodeling and building requires a permit from DPD. Stop Work Order posted 3/14/06.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1007814>

Condo Conversion.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1013231>

Permit 6217763 was issued 7/23/09 for work started without permit and inspections. This case will remain open until all required inspections have been requested and approved by DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019464>

LU use violations- see also 601 (case 1015933)

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015934>

Inspection conducted, violation of Weeds and Vegetation Ordinance found

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1012180>

Demolished building site is now being used as a parking lot without a permit.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019814>

Unsafe conditions noted in and around elevator shaft require repairs (and building permit and inspections from DPD).

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021869>

Application 6190586 was made 8/8/08 for grading more than 100 cu.yds. (at least 1,500 cu.yds. including adjacent properties) performed w/o permit & inspections

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016970>

# Test Map

-122.38984321      47.63360012

-122.36256341      47.56990831

-122.36471901      47.70304428

-122.2993355      47.59526269

-122.36374189      47.66834656

-122.29655214      47.6891959

-122.32318525      47.61181024

-122.33066049      47.59945633

-122.31711164      47.60204905

# Test Map

Case 1017225 - Application Added as of 03/17/2009      CONSTRUCT      2107 4TH AVE W

Case 1015299 - Application Added as of 04/15/2008      CONSTRUCT      5840 16TH AVE S

Case 1019134 - Application Added as of 08/18/2009      CONSTRUCT      6765 41ST AVE SW

Case 1021129 - Notice or Order Issued as of 04/14/2010      HZW      3540 WALLINGFORD AVE N

Case 1021281 - Notice or Order Issued as of 04/29/2010      HZW      12327 15TH AVE NE

Case 1022050 - Citation Issued as of 04/16/2010      CITATION      4511 51ST AVE S

Case 1020990 - Case Resolved as of 04/21/2010      HZW      6511 50TH AVE NE



# Test Map

adjacent properties) performed w/o permit & inspections from DPD. STOP WORK ORDER posted 8/6/08. Only work allowed: stabilize site and cover stockpiles.

REVISED PLANS MUST BE SUBMITTED--DECK ADDITION IS NOT BUILT PER PLAN--SECOND STORY DECK ALSO REQUIRES A PERMIT

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017225>

Excavation not per Permit 6151598. Cuts need to be stabilized per Site Inspector's instructions & Geotechnical Engineer needs to make recommendations for any further work under this permit. SDOT notified re undermining of public sidewalk at S Juneau St. See Permit 6151598 for interim follow-up inspections.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015299>

Tree cutting & vegetation removal on a site mapped as a Steep Slope Environment requires approval from DPD. STOP WORK ORDER posted 4/27/09. The only work allowed before a revegetation plan is approved by DPD is erosion control & slope stabilization under the direction of a geotechnical engineer.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019134>

cabinet shop use not established in Residential L2 zone

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021129>

Land Use Code Violation

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021281>

03/19/10 bg - Outdoor storage of junk including but not limited to wooden crates, buckets, tarps and bags of debris on the front porch. photos taken

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022050>

HBMC Violations

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=>

# Test Map

-122.36258233      47.63805804

-122.31208765      47.55004734

-122.38473796      47.54113477

-122.33609434      47.65040129

-122.31304342      47.71843494

-122.26975681      47.56259684

-122.27457309      47.67618317

# Test Map

Case 1017206 - Application Added as of 09/03/2008      CONSTRUCT      3318 BEACH DR SW

Case 1020567 - Application Added as of 04/07/2010      CITATION      3707 S PERRY ST

Case 1022579 - Application Added as of 05/21/2010      CITATION      301 W KINNEAR PL

Case 1022184 - Application Added as of 05/13/2010      CITATION      7408 44TH AVE SW

Case 1021180 - Case Resolved as of 04/28/2010      HZW      2250 15TH AVE W

Case 1016045 - Application Added as of 12/11/2009      CONSTRUCT      802 23RD AVE E

Case 1006397 - Application Added as of 07/06/2006      CONSTRUCT      4717 S BENNETT ST

Case 1010863 - Application Added as of 08/06/2008      CONSTRUCT      1024 S TRENTON ST

# Test Map

Minor structural changes to exterior & extending/creating new deck requires permit & inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020990>

9/14/09 ej- Inspection outdoor junk storage such as but not limited inoperable vehicles, cardboard boxes and other miscellaneous items. More than the allowed 3 vehicles on the property.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017206>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020567>

5/11/10 KB inspected property and Weeds violation exists

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022579>

Violation of Weeds & Vegetation Ord-

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022184>

A large amount of outdoor storage, including but not limited to, an inoperable hottub on top of the garage roof, salvaged construction materials stored beside the house and numerous items in the back yard.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021180>

**STOP WORK POSTED--PERMIT NEEDED FOR DECKS IN BACK YARD AND GARAGE ROOF**

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016045>

Construction requires a permit from DPD. Stop Work Order posted 9/23/05. All construction to stop (except weatherproofing) until permit obtained.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1006397>

Grading more than 25 cu. yds. in a Steep Slope Environmentally Critical Area requires permits and Dry Season Grading Extension Approval from DPD. Temporary Erosion & Sedimentation Control measures

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010863>

# Test Map

-122.41831211      47.57488798

-122.28548107      47.51464394

-122.3609083      47.62757024

-122.38832294      47.53672237

-122.37583907      47.64012888

-122.30216065      47.62610564

-122.27367847      47.5543137

-122.31903312      47.52496872

# Test Map

Case 1019720 - Case Resolved as of 05/21/2010	CITATION	4127 37TH AVE SW
---	----------	------------------

Case 1009453 - Application Added as of 08/23/2006	CONSTRUCT	1312 5TH AVE
---	-----------	--------------

Case 1022467 - Application Added as of 05/11/2010	HZW	3307 SW ANDOVER ST
---	-----	--------------------

Case 1021789 - Notice or Order Issued as of 05/04/2010	CONSTRUCT	332 17TH AVE
--	-----------	--------------

Case 1022249 - Application Added as of 04/20/2010	HZW	9218 18TH AVE SW
---	-----	------------------

Case 1009783 - Application Added as of 09/21/2006	CONSTRUCT	512 21ST AVE
---	-----------	--------------

Case 1022030 - Application Added as of 05/11/2010	CITATION	4316 30TH AVE SW
---	----------	------------------

Case 1021363 - Notice or Order Issued as of 01/26/2010	HZW	11038 LAKE CITY WAY NE
--	-----	------------------------

# Test Map

required. STOP WORK order issued 1/19/07.

Violation of the Land Use Code.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019720>

Removing a structural concrete floor, concrete wall, adding a structural beam to support a mezzanine, and adding a ramp requires a permit from DPD. Stop Work Order posted 8/23/06. (Application 6092387 has not been accepted by DPD as an application as of 8/23/06.)

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1009453>

Violation of Land Use- Fence over height requirement.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022467>

Addition to rear of & remodeling a single family residence requires permits & inspections from DPD. STOP WORK ORDER posted 2/16/10.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021789>

4/15/10 ej-Inspection shows outdoor junk storage, such as but not limited to, inoperable vehicles, tires, canopy, plywood and other miscellaneous items. Parking in the required front yard, more than the allowed 3 vehicles parked not in an enclosed area.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022249>

Work on 2nd story above garage and repair of interior fire damage requires a permit from DPD. Permit 6113954 issued 9/25/06 for some of the work performed without a permit.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1009783>

Violation of Land Use- Outdoor junk storage

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022030>

HBMC violation

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=>

# Test Map

-122.37905915	47.5656386
---------------	------------

-122.33388393	47.60931723
---------------	-------------

-122.37440662	47.56765276
---------------	-------------

-122.30981745	47.60529909
---------------	-------------

-122.35752616	47.52045937
---------------	-------------

-122.30474734	47.60662714
---------------	-------------

-122.3705607	47.56482151
--------------	-------------

-122.30032381	47.70949753
---------------	-------------



# Test Map

01/26/2010

Case 1022273 - Application Added as of 04/29/2010      HZW      4520 55TH AVE NE

Case 1021860 - Notice or Order Issued as of 04/30/2010      CONSTRUCT      1760 26TH AVE E

Case 1015505 - Payment Processed as of 06/17/2008      TRAO      4317 PHINNEY AVE N

Case 1020281 - Citation Issued as of 03/22/2010      CITATION      160 27TH AVE

Case 1019439 - Notification Issued as of 05/10/2010      VACANT      160 27TH AVE

Case 1019042 - Application Added as of 05/10/2010      HZW      160 27TH AVE

Case 1016938 - Application Added as of 04/30/2009      CONSTRUCT      770 31ST AVE

Case 1018954 - Citation Issued as of 02/04/2010      CITATION      922 N 84TH ST

Case 1016776 - Application Added as of 05/10/2010      HZW      157 27TH AVE

Case 1016777 - Notification Issued as of 05/10/2010      VACANT      157 27TH AVE

Case 1021889 - Case Resolved as of 05/06/2010      HZW      555 S CLOVERDALE ST

# Test Map

	1021363
Shoreline exemption and mitigation required for patio, barbeque, low wall and landscaping near shoreline	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022273">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022273</a>
PERMIT #6070618 MUST BE RE-ESTABLISHED	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021860">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021860</a>
Application for a Tenant Relocation License. Total units: 1; total units occupied: 1. Demolition.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015505">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015505</a>
vehicle stored in yard; pictures in file.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020281">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020281</a>
Secure; deterioration; 2 inop. veh.; outdoor storage.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019439">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019439</a>
Secure; deterioration; 2 inop. veh.; outdoor storage.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019042">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019042</a>
Constructing a carport requires a permit and inspections from DPD.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016938">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016938</a>
junk storage & pking violations	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018954">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018954</a>
Deterioration, open crawl spaces, veg. overgrowth	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016776">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016776</a>
Deterioration, open crawl spaces, veg. overgrowth	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016777">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016777</a>
hbmc violations-	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=</a>

# Test Map

-122.26841613	47.6618683
---------------	------------

-122.29926214	47.63567528
---------------	-------------

-122.35483769	47.65953608
---------------	-------------

-122.29754996	47.60303579
---------------	-------------

-122.29754996	47.60303579
---------------	-------------

-122.29754996	47.60303579
---------------	-------------

-122.29230479	47.60904929
---------------	-------------

-122.34609973	47.69003859
---------------	-------------

-122.29816396	47.60295161
---------------	-------------

-122.29816396	47.60295161
---------------	-------------

-122.32601694	47.5262784
---------------	------------

# Test Map

Case 1021016 - Notice or Order Issued as of 05/04/2010	CONSTRUCT	6400 M L KING JR WAY S
--	-----------	------------------------

Case 1021385 - Case Opened as of 04/06/2010	HZW	320 CEDAR ST
---	-----	--------------

Case 1022548 - Application Added as of 05/20/2010	CITATION	308 20TH AVE
---	----------	--------------

Case 1021965 - Case Resolved as of 05/05/2010	CITATION	5380 S WALLACE ST
---	----------	-------------------

Case 1012851 - Application Added as of 07/19/2007	TRAO	1909 25TH AVE S
---	------	-----------------

Case 1020791 - Application Added as of 10/07/2009	CONSTRUCT	5728 S BANGOR ST
---	-----------	------------------

Case 1007192 - Application Added as of 01/05/2006	CONSTRUCT	10054 65TH AVE S
---	-----------	------------------

Case 1022201 - Application Added as of 05/07/2010	CITATION	3018 S BRANDON ST
---	----------	-------------------

# Test Map

Creating additional height & changing roof and remodeling a 2-story restaurant requires permits and inspections from DPD. STOP WORK ORDER posted 10/30/09.

1021889

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021016>

Violation of the HBMC

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021385>

Violation of the Land Use Code

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022548>

VIOLATION OF THE SEATTLE LAND USE AND ZONING CODE OBSERVED ( VEHICLE IN FRON T YARD MORE THAN THREE VEHICLES OUTDOORS ON LOT, AUTO TIRES AND OTHER JUNK STORAGE IN YARDS.)

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021965>

Violation of the Tenant Relocation Assistance Ordinance

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1012851>

Constructing a detached accessory structure larger than 120 sq.ft. requires zoning review and, if approved, a permit and all required inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020791>

Grading permit required from DPD and Temporary Erosion & Sedimentation Control (TESC) needed. SDOT was contacted 1/3/06 regarding unpermitted work in alley. Stop Work Order posted 1/3/06.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1007192>

04/07/10 bg - 6 vehicles on the property, recreational vehicle parked in the front yard and two vehicles parked

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022201>

# Test Map

-122.28473324      47.54524234

-122.34858206      47.61758351

-122.30581994      47.60466132

-122.26437131      47.49757564

-122.30083283      47.58595911

-122.26001796      47.50626746

-122.25210523      47.51034707

-122.29276103      47.55373563

# Test Map

Case 1016039 - Application Added as of 06/03/2008	CONSTRUCT	7717 30TH AVE SW
---	-----------	------------------

Case 1018780 - Application Added as of 03/18/2010	CONSTRUCT	4443 48TH AVE SW
---	-----------	------------------

Case 1008544 - Application Added as of 08/15/2006	CONSTRUCT	4102 SW AUSTIN ST
---	-----------	-------------------

Case 1008385 - Application Added as of 05/10/2006	CONSTRUCT	3900 12TH AVE S
---	-----------	-----------------

Case 1010960 - Application Added as of 05/06/2010	CONSTRUCT	2806 19TH AVE S
---	-----------	-----------------

Case 1021110 - Application Added as of 11/10/2009	CONSTRUCT	1818 E YESLER WAY
---	-----------	-------------------

Case 1022494 - Notice or Order Issued as of 05/13/2010	HZW	4411 DAYTON AVE N
--	-----	-------------------

Case 1020644 - Application Added as of 04/29/2010	HZW	5033 37TH AVE S
---	-----	-----------------

# Test Map

in the required front yard. photos taken

Constructing an addition to a kitchen requires permits and inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016039>

Constructing an approximately 19' tall garage on the SW corner of the lot requires zoning approval and, if approved, permits & inspections from DPD. STOP WORK ORDER posted 3/18/09.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018780>

Building a retaining wall in an ECA 1 (Steep Slope) requires a permit from DPD. Stop Work Order posted 3/20/06.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1008544>

Vegetation & tree removal (7,200 sq.ft) and grading on an undeveloped site requires a permit from DPD. Temporary Erosion and Sedimentation Control (TESC) also required. There is a Street Use Permit for the work in the 12th Ave. S. R-O-W. Stop Work Order issued 5/10/06 for the work on private property without permits from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1008385>

Second floor addition requires a building permit and inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010960>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021110>

rear structure open to entry via door on North side , picture in file.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022494>

09/18/09 bg - HBMC violations. photos taken

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020644>



# Test Map

-122.37144318	47.53323213
---------------	-------------

-122.39375743	47.56346476
---------------	-------------

-122.38484682	47.53524537
---------------	-------------

-122.3169318	47.56880548
--------------	-------------

-122.30773416	47.57844527
---------------	-------------

-122.30807695	47.6018133
---------------	------------

-122.35230915	47.66055595
---------------	-------------

-122.2865078	47.55608592
--------------	-------------

# Test Map

Case 1021684 - Application Added as of 04/22/2010 HZW 5033 37TH AVE S

Case 1022338 - Application Added as of 05/04/2010 HZW 5033 37TH AVE S

Case 1021576 - Case Resolved as of 04/29/2010 HZW 5033 37TH AVE S

Case 1021770 - Application Added as of 02/11/2010 HZW 5033 37TH AVE S

Case 1020707 - Application Added as of 01/20/2010 CONSTRUCT 301 35TH AVE S

Case 1015093 - Citation Issued as of 01/21/2010 CITATION 405 31ST AVE E

Case 1022454 - Application Added as of 05/10/2010 CITATION 13016 42ND AVE NE

Case 1022546 - Application Added as of 05/20/2010 HZW 1139 33RD AVE E

Case 1018119 - Payment Processed as of 03/09/2009 TRAO 12053 35TH AVE NE

Case 1018039 - Application Added as of 01/07/2010 HZW 1303 NE BOAT ST

Case 1022244 - Application Added as of 04/19/2010 HZW 206 NW 39TH ST

# Test Map

01/29/10 bg - HBMC violations in Unit 105 & 108.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021684>

04/12/10 - HBMC violations Unit 113

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022338>

HBMC violations in Unit 308

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021576>

09/18/09 bg - HBMC violations. photos taken

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021770>

Permit 6228632 was issued 9/29/09 for work originally started without a permit. This case will remain open until all required inspections have been requested and approved.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020707>

junk storage in sf zone

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015093>

Weeds and Vegetation Ordinance Violation

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022454>

Multiple housing violations, including deck guardrails not to code and various electrical issues.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022546>

Application for a Tenant Relocation License. Total units: 3; total units occupied: 3. Demolition.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018119>

7 floating boat storage structures w/o permits

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018039>

Zoning violation. Parking in the required set back.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=>

# Test Map

-122.2865078 47.55608592

-122.2865078 47.55608592

-122.2865078 47.55608592

-122.2865078 47.55608592

-122.28790139 47.60010108

-122.29223991 47.62274916

-122.28259475 47.72351966

-122.28983962 47.62913637

-122.29202538 47.71691027

-122.31437784 47.65158911

-122.3594791 47.65437111

# Test Map

Case 1013023 - Application Added as of 08/03/2007	NOISE	1825 QUEEN ANNE AVE N
Case 1014770 - Application Added as of 01/25/2008	CONSTRUCT	5609 S AVON ST
Case 1021163 - Application Accepted as of 11/20/2009	TRAO	4202 E LYNN ST
Case 1021699 - Payment Processed as of 05/21/2010	TRAO	4202 E LYNN ST
Case 1011541 - Application Added as of 04/22/2009	CONSTRUCT	1717 5TH AVE N
Case 1014821 - Citation Issued as of 04/30/2010	CITATION	618 NW 58TH ST
Case 1016186 - Citation Issued as of 04/30/2010	CITATION	618 NW 58TH ST
Case 1021481 - Case Resolved as of 04/06/2010	HZW	618 NW 58TH ST
Case 1017499 - Payment Processed as of 12/30/2008	TRAO	2316 NW 95TH ST
Case 1006626 - Application Added as of 12/23/2009	CONSTRUCT	10229 RENTON AVE S

# Test Map

	1022244
Int Insp 6/21/07 DG Noise levels from the restaurant fans meet daytime level. Fans are in operation after 10 PM, they do not meet nighttime levels for noise.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1013023">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1013023</a>
Constructing a one story addition at the rear of a single family dwelling requires permit(s) and inspections from DPD.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014770">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014770</a>
Application for a Tenant Relocation License. Total units: 3; Total units occupied:3. Demolition.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021163">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021163</a>
Application for a Tenant Relocation License. Total units:3;total units occupied:3. Demolition.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021699">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021699</a>
STOP WORK POSTED--PERMIT REQUIRED FOR ROCKERY IN ECA	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1011541">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1011541</a>
A pile of vegetation in the yard that has been there for months.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014821">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014821</a>
Outdoor junk storage on the front porch of a vacant building.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016186">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016186</a>
Housing violations.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021481">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021481</a>
Application for a Tenant Relocation License. Total units: 1; total units occupied: 1. Demolition.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017499">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017499</a>
Constructing a deck more than 18" above grade, exterior stairs and remodeling a garage into habitable space requires permits and inspections from DPD.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1006626">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1006626</a>

# Test Map

-122.35731623	47.63555879
---------------	-------------

-122.26204505	47.5011223
---------------	------------

-122.27808368	47.63926165
---------------	-------------

-122.27808368	47.63926165
---------------	-------------

-122.34753723	47.63422241
---------------	-------------

-122.36486579	47.67107913
---------------	-------------

-122.36486579	47.67107913
---------------	-------------

-122.36486579	47.67107913
---------------	-------------

-122.38606381	47.69842947
---------------	-------------

-122.25814079	47.5089798
---------------	------------

# Test Map

Case 1020094 - Application Added as of 02/17/2010	HZW	5001 1ST AVE S
Case 1014308 - Application Added as of 08/05/2008	CONSTRUCT	2503 N NORTHLAKE WAY
Case 1014437 - Application Added as of 08/05/2008	CONSTRUCT	2503 N NORTHLAKE WAY
Case 1008095 - Application Added as of 06/21/2007	CONSTRUCT	4815 15TH AVE SW
Case 1012242 - Case Resolved as of 10/02/2009	HZW	3253 NE 98TH ST
Case 1016886 - Application Added as of 08/20/2008	CONSTRUCT	113 12TH AVE
Case 1021366 - Notice or Order Issued as of 01/04/2010	HZW	4742 20TH AVE NE
Case 1016887 - Application Added as of 08/20/2008	CONSTRUCT	115 12TH AVE



# Test Map

requires permits and inspections from DPD.

Electrical inspector Jessen has required that the owners of this site apply for a use permit before he signs off the electrical permits. The lot is being used as an illegal use at this time.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020094>

PERMITS REQUIRED FOR NEW SALES' OFFICE

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014308>

MUST OBTAIN CERTIFICATE OF OCCUPANCY (#6092153) OR CEASE OCCUPANCY

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014437>

GRADING PERMIT REQUIRED FOR EXCAVATING MORE THAN 100 CUBIC YARDS IN WILDLIFE HABITAT

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1008095>

KB inspected property and Housing Code violations exist.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1012242>

Application 6190487 made 8/8/08 for grading more than 100 cu.yds. (at least 1,500 cu.yds. including adjacent properties) performed w/o permit & inspections from DPD. STOP WORK ORDER posted 8/6/08. Only work allowed: stabilize site (currently 16'-17' cut 10' from west property line).

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016886>

Violations of Housing Building and Maintenance Code.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021366>

Application 6190587 made 8/8/08 for grading more than 100 cu.yds. (at least 1,500 cu.yds. including adjacent properties) performed w/o permit & inspections from

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016887>

# Test Map

-122.33474626	47.55716664
---------------	-------------

-122.32803779	47.65157553
---------------	-------------

-122.32803779	47.65157553
---------------	-------------

-122.35350832	47.55875034
---------------	-------------

-122.2916392	47.70001845
--------------	-------------

-122.31713253	47.60214335
---------------	-------------

-122.30622409	47.66430514
---------------	-------------

-122.31705182	47.60223738
---------------	-------------

# Test Map

Case 1016505 - Notification Issued as of 05/04/2009	VACANT	360 HAYES ST
Case 1017006 - Application Added as of 12/24/2009	HZW	305 VALLEY ST
Case 1010984 - Application Added as of 02/05/2007	CONSTRUCT	3906 S PILGRIM ST
Case 1019247 - Application Added as of 05/12/2009	CONSTRUCT	6355 BEACH DR SW
Case 1019081 - Case Resolved as of 03/15/2010	HZW	3714 S HOLLY ST
Case 1016969 - Application Added as of 08/20/2008	CONSTRUCT	109 12TH AVE
Case 1020085 - Case Resolved as of 04/27/2010	CITATION	5961 36TH AVE S

# Test Map

DPD. STOP WORK ORDER posted 8/6/08. Only work allowed: stabilize site (currently 16'-17' cut 10' from west property line).

Unsecured sheds; deterioration; veg. overgrowth

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016505>

Principle use parking lot by U-Park, addressed as 720 3rd Av N, 284-9797. 28 stalls with a pay box, entering on 3rd Av N.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017006>

CONTINUATION OF PTS CASE 233797--PERMIT REQUIRED FOR RETAINING WALL IN ECA STEEP SLOPE

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010984>

Installing an air conditioner/heat pump in a required side yard requires zoning review, a permit & inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019247>

Open, deflected & unsound accessory structure in rear yard of bldg. who's use is considered to be vacant; picture in file. Dimensions between structural posts are 19'.75 " x 10'.25" or 202 sq. ft.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019081>

Application 6190585 made 8/8/08 for grading more than 100 cu.yds. (at least 1,500 cu.yds. including adjacent properties) performed w/o permit & inspections from DPD. STOP WORK ORDER posted 8/6/08. Only work allowed: stabilize site and cover stockpiles.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016969>

07/14/09 bg - Two vehicles in the front yard, three vehicles and an recreational trailer in the rear yard. Junk storage on site, including but not limited to plastic containers, bags of garbage, clothing, shopping carts.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020085>

# Test Map

-122.35024503	47.63419933
---------------	-------------

-122.35122808	47.62614853
---------------	-------------

-122.28433923	47.51600872
---------------	-------------

-122.39875363	47.54536986
---------------	-------------

-122.28548213	47.54268556
---------------	-------------

-122.3173576	47.60195644
--------------	-------------

-122.28808834	47.54809473
---------------	-------------

# Test Map

Case 1018574 - Application Added as of 05/14/2010      HZW      9551 DAYTON AVE N

Case 1017690 - Application Added as of 02/18/2009      CONSTRUCT      5603 30TH AVE SW

Case 1007380 - Application Added as of 01/30/2006      CONSTRUCT      7333 32ND AVE SW

Case 1022218 - Notice or Order Issued as of 05/21/2010      CONSTRUCT      319 N 104TH ST

Case 1022543 - Application Added as of 05/20/2010      CITATION      5603 S BANGOR ST

Case 1022545 - Application Added as of 05/20/2010      CITATION      5603 S BANGOR ST

Case 1008956 - Application Added as of 10/06/2006      CONSTRUCT      10110 51ST AVE SW

# Test Map

containers, bags of garbage, clothing, shopping carts.

photos taken

2nd dwelling on sf lot

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018574>

Constructing a rockery in a Steep Slope and Potential Slide Environmentally Critical Area (ECA) requires permits and inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017690>

POSTED STOP WORK--NEW DECK, STAIRS, AND LANDING REQUIRE PERMIT

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1007380>

PERMIT REQUIRED FOR NEW GARAGE

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022218>

VIOLATION OF THE SEATTLE LAND USE AND ZONING CODE OBSERVED (PLASTIC BAGS & WOOD FURNITURE IN YARDS; VEHICLE IN REQUIRED FRONT YARD)

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022543>

VIOLATION OF THE SEATTLE LAND USE AND ZONING CODE OBSERVED (PLASTIC BAGS & WOOD FURNITURE IN YARDS; VEHICLE IN REQUIRED FRONT YARD)

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022545>

Gutting a house, replacing exterior walls, reframing a roof and other remodeling requires permits from DPD. IAP with full plans and engineering required for any first floor work per building inspector. Any other work will require full plan review. Case will remain open until all permits issued and ALL required inspections done. Stop Work Order posted 7/12/06.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1008956>

# Test Map

-122.35302201      47.69935873

-122.37128729      47.55180447

-122.37425859      47.53637297

-122.3543946      47.7042008

-122.26285279      47.50591562

-122.26285279      47.50591562

-122.39432083      47.51273462



# Test Map

Case 1015454 - Application Added as of 04/10/2008	CONSTRUCT	3556 SW ADMIRAL WAY
---	-----------	---------------------

Case 1022257 - Case Opened as of 05/21/2010	CITATION	7641 46TH AVE S
---	----------	-----------------

Case 1022575 - Application Added as of 05/21/2010	CITATION	1001 2ND AVE W
---	----------	----------------

Case 1017001 - Application Added as of 08/14/2008	CONSTRUCT	4422 S KENYON ST
---	-----------	------------------

Case 1015805 - Application Added as of 10/17/2008	CONSTRUCT	4709 9TH AVE NE
---	-----------	-----------------

Case 1019532 - Application Added as of 11/12/2009	CONSTRUCT	3206 PORTAGE BAY PL E
---	-----------	-----------------------

Case 1019435 - Application Added as of 11/30/2009	HZW	3206 PORTAGE BAY PL E
---	-----	-----------------------

Case 1010520 - Application Added as of 04/08/2009	CONSTRUCT	420 BLANCHARD ST
---	-----------	------------------

Case 1018840 - Application Added as of 03/26/2009	CONSTRUCT	9421 16TH AVE SW
---	-----------	------------------

# Test Map

Constructing a deck in the rear yard of a single family residence in a Steep Slope & Potential Slide ECA requires permits & inspections from DPD. STOP WORK ORDER posted 4/9/08.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015454>

04/16/10 bg - Tires, household debris on the south side of the house. photos taken

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022257>

5/11/10 KB inspected and Weed violation exists

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022575>

Retaining wall is not per Permit 6077396. Cuts at property line need to be stabilized and revised drawings need to be submitted to & approved by DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017001>

Remodeling basement, 1st floor, 2nd floor & making alterations to roof requires permits & inspections from DPD. STOP WORK ORDER posted 5/6/08.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015805>

TWO TREES HAVE BEEN REMOVED IN SHORELINE ECA--RESTORATION IS REQUIRED

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019532>

Bulkhead work w/o shoreline authorization. Observed freshly cut cedar stumps and trenching along southern property line.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019435>

Interior remodel including plumbing, electrical, mechanical and change of use requires a building permit and all inspections from DPD. Permit 6122971 issued 12/15/06. Application 6084351 must be issued before this case can be closed.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010520>

Permit 6211733 was obtained 3/25/09 for work originally started without a permit. Inspector will confirm work is

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=>

# Test Map

-122.3761952	47.57956732
--------------	-------------

-122.27567819	47.53352549
---------------	-------------

-122.359702	47.62795796
-------------	-------------

-122.27734045	47.53199673
---------------	-------------

-122.31878906	47.66348622
---------------	-------------

-122.31923136	47.65066832
---------------	-------------

-122.31923136	47.65066832
---------------	-------------

-122.3422326	47.61513285
--------------	-------------

-122.35559996	47.51849745
---------------	-------------

# Test Map

Case 1013140 - Application Added as of 04/02/2009	CONSTRUCT	710 20TH AVE
---	-----------	--------------

Case 1022471 - Application Added as of 05/11/2010	CONSTRUCT	5427 48TH AVE SW
---	-----------	------------------

Case 1015788 - Application Added as of 05/09/2008	CITATION	4157 39TH AVE SW
---	----------	------------------

Case 1010410 - Application Added as of 01/29/2007	CONSTRUCT	3400 37TH AVE SW
---	-----------	------------------

Case 1007568 - Notice or Order Issued as of 05/14/2010	CONSTRUCT	6017 SW ADMIRAL WAY
--	-----------	---------------------

Case 1019201 - Case Resolved as of 02/17/2010	CITATION	812 NE 67TH ST
---	----------	----------------

Case 1021531 - Notice or Order Issued as of 03/10/2010	CONSTRUCT	317 CORYELL CT E
--	-----------	------------------

# Test Map

started without a permit. Inspector will confirm work is occurring only on this property while conducting required inspections.

1018840

Permit 6141395 was issued 8/13/07 for repairing a fire damaged building without permits and inspections from DPD. This case will remain open until all required inspections have been requested and approved.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1013140>

Drainage installation requires a side sewer permit and inspections from DPD. Discharge from sump pump to alley may not be allowed (gravity discharge might be allowed).

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022471>

left a message for complainant as no violation observed

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015788>

Remodeling a non-conforming apartment building, adding a unit and performing electrical work requires permits and inspections from DPD. Plumbing work requires permit and inspections from Seattle-King Co. Health Department. Stop Work Order posted 11/29/06 and 12/7/06.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010410>

Two story addition on the rear of single family residence requires a permit from DPD. Stop Work Order posted 2/16/06.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1007568>

Building open to entry.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019201>

PERMIT REQUIRED FOR NEW DECKS AND OTHER NEW CONSTRUCTION

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021531>

# Test Map

-122.30606252 47.6083985

-122.39397523 47.55316571

-122.38184637 47.56484414

-122.37793731 47.57297334

-122.41022276 47.57570328

-122.31942613 47.67748554

-122.30814354 47.6210725

# Test Map

Case 1022392 - Application Added as of 04/30/2010	CONSTRUCT	304 ALASKAN WAY S
---	-----------	-------------------

Case 1022330 - Application Added as of 04/27/2010	CITATION	8446 46TH AVE S
---	----------	-----------------

Case 1015288 - Application Added as of 03/25/2008	CONSTRUCT	1514 ALKI AVE SW
---	-----------	------------------

Case 1020187 - Application Added as of 11/30/2009	CITATION	10347 WALLINGFORD AVE N
---	----------	----------------------------

Case 1019434 - Citation Issued as of 12/18/2009	CITATION	10347 WALLINGFORD AVE N
---	----------	----------------------------

Case 1022127 - Application Added as of 04/01/2010	CITATION	360 QUEEN ANNE DR
---	----------	-------------------

Case 1019503 - Application Added as of 02/19/2010	HZW	3216 22ND AVE W
---	-----	-----------------

Case 1021776 - Case Resolved as of 04/29/2010	CITATION	3011 S ANDOVER ST
---	----------	-------------------

# Test Map

Earthquake damage repair permit obtained - work never performed (no inspections or Special Inspections obtained for Permit 733386) to satisfy Hazard Correction Order BC 220648.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022392>

VIOLATION OF THE SEATTLE LAND USE AND ZONING CODE OBSERVED (FIVE VEHICLES PARKED ON LOT) TOOK PHOTOS.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022330>

Revision to Permit 6086211 required including revised engineering for changes to existing plan & glazing to meet prescriptive path for new windows not shown on permitted drawings.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015288>

Vegetation overgrowth encroaches & overhangs the street & unimproved section of the ROW as well. Pictures in file.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020187>

Outdoor storage of collapsed shed, carpeting, lumber, const. debris, furniture, garden equipment, mattresses, tires, car seats, buckets, couch, lawn mowers, chest, car battery & other miscellaneous items in driveway & throughout yard areas.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019434>

3/30/10 KB inspected property and Land Use violation exists, junk storage and vegetation overgrowth.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022127>

Unpermitted ADU.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019503>

02/10/10 bg - Junk storage, household & construction debris. photos taken

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021776>



# Test Map

-122.33514387	47.5997616
---------------	------------

-122.27444897	47.52654741
---------------	-------------

-122.39302914	47.59009035
---------------	-------------

-122.3361612	47.7045594
--------------	------------

-122.3361612	47.7045594
--------------	------------

-122.35006225	47.64302874
---------------	-------------

-122.38438176	47.6491005
---------------	------------

-122.29351109	47.56783104
---------------	-------------

# Test Map

Case 1020110 - Citation Issued as of 02/01/2010	CITATION	7954 39TH AVE S
Case 1005990 - Application Added as of 08/08/2005	CONSTRUCT	9165 45TH AVE SW
Case 1016450 - Application Added as of 07/02/2008	HZW	10652 RIVIERA PL NE
Case 1022198 - Application Added as of 05/10/2010	HZW	3820 22ND AVE SW
Case 1022344 - Application Added as of 04/27/2010	CITATION	1408 N 137TH ST
Case 1022402 - Application Added as of 05/03/2010	CONSTRUCT	1408 N 137TH ST
Case 1011144 - Notice or Order Issued as of 03/22/2010	CONSTRUCT	4801 23RD AVE SW
Case 1022574 - Application Added as of 05/21/2010	HZW	422 BELLEVUE AVE E
Case 1022304 - Application Added as of 04/22/2010	CITATION	656 NW 74TH ST
Case 1007422 - Notice or Order Issued as of 12/22/2009	CONSTRUCT	2207 12TH AVE S

# Test Map

07/29/09 bg - At least 5 vehicles on the property, photos taken.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020110>

Deck and hot tub require a permit from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1005990>

Aerial photos between 1999 & 2002 show covered moorage; no permits

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016450>

Deteriorated roof, garage & window frames.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022198>

sfr junk storage, parking & structure violations

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022344>

INSPECTOR HAD NO ACCESS TO REAR YARD BUT HE COULD SEE THAT THERE WAS WORK GOING ON IN THE BACK OF HOUSE--LEFT A REPORT REQUESTING THAT OWNER CALL HIM

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022402>

Remodeling and rebuilding a house requires permits and inspections from DPD. STOP WORK ORDER posted 2/15/07.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1011144>

5/11/10 KB inspected property and Junk Storage exists on-site, MR zone

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022574>

Weeds and vegetation violation. Vegetation encroaching into the sidewalk

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022304>

New door and other alterations require a permit from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1007422>

# Test Map

-122.28335147	47.52987184
---------------	-------------

-122.39040229	47.52158749
---------------	-------------

-122.2751207	47.70727073
--------------	-------------

-122.36081913	47.56949292
---------------	-------------

-122.34047323	47.72886463
---------------	-------------

-122.34047323	47.72886463
---------------	-------------

-122.36186185	47.55911664
---------------	-------------

-122.32633745	47.62264989
---------------	-------------

-122.36573061	47.68272601
---------------	-------------

-122.31758448	47.58344443
---------------	-------------

# Test Map

Case 1022298 - Application Added as of 05/13/2010	CONSTRUCT	5218 S PEARL ST
---	-----------	-----------------

Case 1004880 - Application Added as of 04/04/2005	CONSTRUCT	3925 S CLOVERDALE ST
---	-----------	----------------------

Case 1004882 - Application Added as of 04/04/2005	CONSTRUCT	3925 S CLOVERDALE ST
---	-----------	----------------------

Case 1004888 - Application Added as of 04/04/2005	CONSTRUCT	3925 S CLOVERDALE ST
---	-----------	----------------------

Case 1004883 - Application Added as of 04/04/2005	CONSTRUCT	3925 S CLOVERDALE ST
---	-----------	----------------------

Case 1017404 - Application Added as of 04/29/2009	CONSTRUCT	2354 30TH AVE S
---	-----------	-----------------

Case 1019253 - Application Added as of 01/20/2010	CONSTRUCT	7607 45TH AVE S
---	-----------	-----------------

# Test Map

Permit 6246823 was issued 4/22/10 for work originally started without a permit. This case will remain open until all required inspections have been requested & approved.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022298>

3925 D/Violation found: grading in an Potential Slide Enviromentally Critical Area (ECA) and Potential Wetland ECA requires a permit from DPD. Temporary erosion control required.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1004880>

3925 E/Violation found: grading in an Potential Slide Enviromentally Critical Area (ECA) and Potential Wetland ECA requires a permit from DPD. Temporary erosion control required.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1004882>

3925 G/Violation found: grading in an Potential Slide Enviromentally Critical Area (ECA) and Potential Wetland ECA requires a permit from DPD. Temporary erosion control required.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1004888>

3925 F/Violation found: grading in an Potential Slide Enviromentally Critical Area (ECA) and Potential Wetland ECA requires a permit from DPD. Temporary erosion control required.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1004883>

Permit 6194815 was issued 9/17/08 for work originally started without permit. This case will remain open until all required inspections have been requested and approved.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017404>

Constructing an addition to an accessory building/creating a detached dwelling unit requires permits and inspections from DPD. STOP WORK ORDER posted 4/28/09.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019253>

# Test Map

-122.26727305	47.55646267
---------------	-------------

-122.28249726	47.52579413
---------------	-------------

-122.28249726	47.52579413
---------------	-------------

-122.28249726	47.52579413
---------------	-------------

-122.28249726	47.52579413
---------------	-------------

-122.29385054	47.58138764
---------------	-------------

-122.2768735	47.53414308
--------------	-------------

# Test Map

Case 1012588 - Application Added as of 08/26/2008	CONSTRUCT	4201 16TH AVE SW
Case 1021300 - Application Added as of 12/09/2009	HZW	2209 E ROANOKE ST
Case 1021658 - Application Added as of 01/29/2010	HZW	2209 E ROANOKE ST
Case 1021659 - Application Added as of 03/24/2010	CITATION	2209 E ROANOKE ST
Case 1021616 - Notice or Order Issued as of 03/19/2010	HZW	3838 BEACH DR SW
Case 1020142 - Citation Issued as of 01/21/2010	CITATION	3838 BEACH DR SW
Case 1020129 - Application Added as of 12/30/2009	CONSTRUCT	3838 BEACH DR SW
Case 1009026 - Application Added as of 07/19/2006	CONSTRUCT	9752 59TH AVE S
Case 1009027 - Application Added as of 07/19/2006	CONSTRUCT	9758 59TH AVE S
Case 1009023 - Application Added as of 07/19/2006	CONSTRUCT	9753 60TH AVE S



# Test Map

Single Family Residence has been remodeled and other structures constructed without permits or inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1012588>

Multiple housing violations including, but not limited to, egress window issues with the basement windows, a missing handrail, and outdoor storage in the back yard.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021300>

Tenants in basement rooms without legal egress windows.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021658>

Multiple housing violations including, but not limited to, egress window issues with the basement windows, a missing handrail, and outdoor storage in the back yard.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021659>

Violation of HBMC

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021616>

Violation of Land Use- Outdoor junk storage

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020142>

Grading more than 100 cubic yards in the 200' Shoreline setback requires a permit and inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020129>

Grading and vegetation removal and construction of a retaining wall in an ECA 1 (Steep Slope) requires permit(s) from DPD. Stop Work Order posted 6/22/06.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1009026>

Grading and vegetation removal and construction of a retaining wall in an ECA 1 (Steep Slope) requires permit(s) from DPD. Stop Work Order posted 6/22/06.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1009027>

Grading and vegetation removal and construction of a retaining wall in an ECA 1 (Steep Slope) requires

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1009023>

# Test Map

-122.35497365 47.56622928

-122.30322978 47.64296853

-122.30322978 47.64296853

-122.30322978 47.64296853

-122.40891046 47.5690659

-122.40891046 47.5690659

-122.40891046 47.5690659

-122.25907383 47.51367692

-122.25907738 47.51351343

-122.25845416 47.51364557

# Test Map

Case 1021431 - Application Added as of 04/27/2010	HZW	2313 25TH AVE S
Case 1016267 - Notification Issued as of 09/04/2009	VACANT	6528 23RD AVE SW
Case 1015451 - Application Added as of 09/04/2009	HZW	6528 23RD AVE SW
Case 1020212 - Application Added as of 04/22/2010	HZW	930 N 83RD ST
Case 1011670 - Application Added as of 04/12/2007	CONSTRUCT	5033 41ST AVE SW
Case 1022348 - Application Added as of 04/28/2010	CITATION	2303 35TH AVE W
Case 1004116 - Application Added as of 12/13/2004	CONSTRUCT	2306 37TH AVE SW
Case 1004268 - Case Opened as of 08/30/2005	CONSTRUCT	6808 46TH AVE S
Case 1021943 - Application Added as of 03/08/2010	CONSTRUCT	1207 WESTLAKE AVE N
Case 1017955 - Citation Issued as of 04/16/2010	CITATION	316 27TH AVE

# Test Map

permit(s) from DPD. Stop Work Order posted 6/22/06.

12/15/09/Violation of the HBMC

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021431>

Bldg. secure with no deterioration; veg. overgrowth in yard area.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016267>

Bldg. secure with no deterioration; veg. overgrowth in yard area.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015451>

LU violation, garage door.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020212>

Enclosing a deck (adding roof and walls) requires permits and inspections from DPD and expired Permit 724620 requires remainder of inspections. STOP WORK ORDER posted 4/11/07.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1011670>

4/27/10 KB inspected unit and Weeds violation exists.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022348>

Violation of the Seattle Building and Land Use Codes found: spiral staircase built in sideyard without a permit.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1004116>

UNSUITABLE FILL ON BACK SLOPE--REMOVE UNSUITABLE MATERIAL AND APPLY IMMEDIATE EROSION CONTROL TO SITE--COVER EXPOSED SOIL WITH PLASTIC OF STRAW

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1004268>

PERMITS HAVE NOT BEEN ISSUED FOR THREE DEMOLISHED BUILDINGS

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021943>

zoning

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=>

# Test Map

-122.30054208      47.58247482

-122.36235601      47.54360541

-122.36235601      47.54360541

-122.34592356      47.68931542

-122.38445068      47.55650202

-122.4027557      47.63893822

-122.37735556      47.58272268

-122.27512175      47.54123103

-122.34140884      47.63002059

-122.29757009      47.60477398

# Test Map

Case 1004749 - Application Added as of 09/28/2009	CONSTRUCT	5049 RENTON AVE S
---	-----------	-------------------

Case 1022505 - Application Added as of 05/13/2010	CITATION	5049 RENTON AVE S
---	----------	-------------------

Case 1022568 - Application Added as of 05/20/2010	HZW	1627 33RD AVE
---	-----	---------------

Case 1006114 - Application Added as of 08/22/2005	CONSTRUCT	10036 RAINIER AVE S
---	-----------	---------------------

Case 1011259 - Application Added as of 10/12/2007	CONSTRUCT	5215 SW ADMIRAL WAY
---	-----------	---------------------

Case 1013445 - Application Added as of 09/13/2007	CONSTRUCT	4005 SW HOLLY ST
---	-----------	------------------

Case 1008884 - Application Added as of 01/26/2008	TRAO	668 W NICKERSON ST
---	------	--------------------

Case 1021742 - Notice or Order Issued as of 03/10/2010	HZW	9131 CALIFORNIA AVE SW
--	-----	------------------------

Case 1022553 - Application Added as of 05/20/2010	CITATION	1717 16TH AVE S
---	----------	-----------------

# Test Map

	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017955">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017955</a>
Violation of the Stormwater, Grading and Drainage Control Code (SGDCC) found: making a vertical cut greater than 10 feet along the south property line requires a grading permit from DPD. Stop Work Order posted 3/16/05.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1004749">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1004749</a>
04/15/10 bg - Vehicles on vacant lot, photos taken	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022505">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022505</a>
Possible Violation of the Land Use Code	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022568">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022568</a>
Approximately 5' rockery adjacent to private shared road and R-O-W requires permit from DPD.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1006114">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1006114</a>
Stream and buffer zone of stream not shown on application for Permit 6062245. Stop Work Order posted 3/1/07.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1011259">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1011259</a>
Building and electrical permits (and inspections) required from DPD for converting garage into living area and removing required off-street parking.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1013445">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1013445</a>
Issuance of a Notice of Violation for failure to apply for a Tenant Relocation License.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1008884">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1008884</a>
Violation of Land Use- Unpermitted catering business in SF zone	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021742">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021742</a>
05/19/10 bg - Outdoor storage of junk including but not limited to mattress, furniture. photos taken	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=</a>

# Test Map

-122.28801567	47.5555735
---------------	------------

-122.28801567	47.5555735
---------------	------------

-122.29059328	47.61602688
---------------	-------------

-122.24667136	47.51138726
---------------	-------------

-122.39971941	47.5790634
---------------	------------

-122.38349475	47.54282052
---------------	-------------

-122.36715674	47.65241456
---------------	-------------

-122.38787411	47.52190441
---------------	-------------

-122.31295197	47.58795143
---------------	-------------



# Test Map

Case 1009591 - Application Added as of 09/06/2006      CONSTRUCT      3033 SW SPOKANE ST

Case 1003876 - Application Added as of 11/05/2004      CONSTRUCT      1124 NEWPORT WAY

Case 1020098 - Application Added as of 07/29/2009      CONSTRUCT      1124 NEWPORT WAY

Case 1018855 - Case Resolved as of 04/29/2010      HZW      5214 DELRIDGE WAY SW

# Test Map

limited to mattress, furniture. photos taken

1022553

Remodeling accessory structure and constructing a retaining wall in a Potential Slide Environmentally Critical Area (ECA) requires permits from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1009591>

Violation of the Seattle Building Code found: 8 foot retaining wall built without permit in ECA 2 (potential slide).

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1003876>

Adding, replacing, re-routing, repairing sanitary and/or drainage lines requires permit(s) and inspections from DPD. STOP WORK ORDER posted 7/23/09.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020098>

Extensive water damage and lack of maintenance throughout the premises. The tenants are occupying three rooms which are illegal and uninhabitable. The owner was previously told not to rent the units out. The following was observed: merchandise for the business is being stored in the common living room area of the "house" and in the front entry; kitchen ceiling has fallen in, water is pooled on kitchen floor and water is leaking directly into the range/stove making it unusable; kitchen sink does not drain, cabinet undersink has open wall with black mold, rotten wood and exposed pipe; bathroom; sink works minimally but pea trap drains into bucket; toilet is flushed with a bucket with instructions on how to use; floors throughout premises whether covered or not, are dirty, unsanitary and deteriorating. stairs to sleeping rooms (SR's) are filthy and have no handrails; doors to SR's have been broken into and entire door assemblies

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018855>

# Test Map

-122.37224224

47.5717521

-122.28384415

47.61201152

-122.28384415

47.61201152

-122.362583

47.5545057

# Test Map

Case 1009074 - Application Added as of 04/29/2010      HZW      6400 8TH AVE NW

Case 1004547 - Application Added as of 02/22/2005      CONSTRUCT      6007 48TH AVE SW

Case 1008840 - Application Added as of 06/29/2006      CONSTRUCT      6014 LAKE SHORE DR S

Case 1003376 - Application Added as of 10/31/2007      CONSTRUCT      9419 6TH AVE SW

Case 1018162 - Application Added as of 01/05/2009      CONSTRUCT      4833 S ORCHARD ST

# Test Map

should be replaced. Sleeping rooms do not meet size standards, although the windows may meet minimum exit requirements. Electrical outlets are burnt, and have no faceplates; there are no smoke detectors; evidence of rodents entering through holes and walls; mold and damp evident throughout. Illegal and uninhabitable units.

Land Use Code Violation

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1009074>

Violation of the Seattle Building Code found: deck and interior remodel require a permit from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1004547>

Permit required for retaining walls and vegetation removal in ECA 1 (Steep Slope) AND to remove retaining walls and vegetation on adjacent Parks Department property (contact MaryLou Whiteford 684-7388). DO NOT ISSUE PERMIT FOR PARKS DEPARTMENT PROPERTY RESTORATION WITHOUT MaryLou Whiteford's written permission.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1008840>


REPAIR OF ROOF AND INTERIOR WALLS REQUIRES PERMIT

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1003376>


Substantially altering an existing institution (temple) including creating habitable space at lower level, creating a kitchen & assembly areas at main level, adding 2nd story assembly area with new stairwells & new structural work throughout requires plan review, permits & all required inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018162>

# Test Map




-122.36548548      47.67518475



-122.3941058      47.54823779

-122.25840169      47.5483638



-122.34331922      47.51849683

-122.27127703      47.53802524

# Test Map

Case 1002418 - Application Added as of 05/31/2004	CONSTRUCT	3537 S BRANDON ST
---	-----------	-------------------

Case 1021346 - Application Added as of 12/14/2009	CONSTRUCT	5927 SHAFFER AVE S
---	-----------	--------------------

Case 1022552 - Application Added as of 05/20/2010	CITATION	1116 24TH AVE
---	----------	---------------

Case 1021121 - Notice or Order Issued as of 05/14/2010	HZW	4626 S KENYON ST
--	-----	------------------

Case 1010181 - Application Added as of 10/26/2006	CONSTRUCT	2616 SW GENESEE ST
---	-----------	--------------------

Case 1022419 - Application Added as of 05/04/2010	CITATION	2016 S EDMUNDS ST
---	----------	-------------------

Case 1022542 - Application Added as of 05/20/2010	CITATION	317 33RD AVE E
---	----------	----------------

Case 1015747 - Notice or Order Issued as of 04/21/2010	CONSTRUCT	3523 ANTHONY PL S
--	-----------	-------------------

Case 1008762 - Application Added as of 03/09/2007	CONSTRUCT	6411 23RD AVE S
---	-----------	-----------------

# Test Map

Stop Work Order posted 5/25/04 for constructing a building over 120 sq. ft. without a permit.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1002418>

Constructing an addition requires permits & inspections from DPD. STOP WORK ORDER posted 4/9/09.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021346>

Violation of Land Use code

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022552>

VIOLATIONS OF THE SEATTLE HOUSING AND BUILDING MAINTENANCE CODE CONFIRMED VIOLATIONS OF THE SEATTLE HOUSING AND BUILDING MAINTENANCE CODE. (CUSTOMER REPORT FROM PUGET SOUND ENERGY SHOWS GAS LINE FOR RANGE WAS CAPPED DUE TO CARBON MONOXIDE.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021121>

Permit 6118163 issued 10/31/06 for work originally started without a permit.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010181>

05/04/10 bg - Vegetation overgrown onto the sidewalk along S Columbian Way, photos taken

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022419>

Tree limbs are hanging low over the sidewalk.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022542>

Permit 6180066 was issued on 10/17/08 for work originally started without a permit. This case will remain open until all required inspections have been requested & approved by DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015747>

As of 1/2/07 covered porch originally built without a permit was removed. All permit inspections required for

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=>



# Test Map

-122.28726759	47.55324239
---------------	-------------

-122.29503468	47.54900062
---------------	-------------

-122.30116972	47.61212211
---------------	-------------

-122.27408561	47.53176849
---------------	-------------

-122.36630117	47.56498406
---------------	-------------

-122.30634716	47.55979221
---------------	-------------

-122.29020693	47.62186396
---------------	-------------

-122.2985139	47.57105021
--------------	-------------

-122.30433415	47.54498204
---------------	-------------

# Test Map

Case 1014928 - Payment Processed as of 12/14/2009	TRAO	1030 NE 125TH ST
---	------	------------------

Case 1013121 - Application Added as of 11/17/2008	CONSTRUCT	411 21ST AVE
---	-----------	--------------

Case 1021434 - Case Opened as of 05/06/2010	HZW	11410 RENTON AVE S
---	-----	--------------------

Case 1021449 - Notice or Order Issued as of 02/08/2010	CONSTRUCT	11410 RENTON AVE S
--	-----------	--------------------

Case 1018536 - Application Added as of 02/23/2009	CONSTRUCT	8742 FAUNTLIEE CREST SW
---	-----------	-------------------------

Case 1015600 - Application Added as of 04/13/2009	HZW	4316 36TH AVE NE
---	-----	------------------

# Test Map

permit was removed. All permit inspections required for 6113674, 6112106 & 6094972 before this case can be closed.

[1008762](#)

Application for a Tenant Relocation License. Total units: 22; total units occupied: 22. Demolition.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014928>

Permit 6180127 was issued 5/7/08 for side sewer work originally started without permits and inspections from DPD. This case will remain open until all required inspections have been called for and obtained.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1013121>

"VIOLATION ALERT" VIOLATION OF THE SEATTLE LAND USE AND ZONING CODE CONFIRMED IN NC130 ZONE.(MARINE REPAIR,MINOR, USE ESTABLISHED 11/9/87 CHANGED TO "SALES & SERVICES HEAVY, ("CONSTRUCTION SERVICES") WITHOUT REQUIRED PERMIT.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021434>

Grading requires a permit & inspections from DPD. Site needs to be stabilized & Temporary Erosion & Sedimentation Control (TESC) installed immediately - both under the direction & recommendation of a geotechnical engineer.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021449>

Constructing a deck & stairs in a required side yard on a site mapped as a Steep Slope & Potential Slide Environmentally Critical Area (ECA) requires zoning review and, if approved, a permit & inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018536>

unsecured rear entry door; missing windows & siding; outdoor storage.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=>

# Test Map

-122.31667783 47.71968832

-122.30532439 47.60554556

-122.24956319 47.50087354

-122.24956319 47.50087354

-122.38664781 47.52417167

-122.2889816 47.66039796

# Test Map

Case 1016797 - Notification Issued as of 04/13/2009	VACANT	4316 36TH AVE NE
Case 1018692 - Payment Processed as of 08/28/2009	TRAO	13128 PALATINE AVE N
Case 1021155 - Application Added as of 12/10/2009	CONSTRUCT	2900 S MASSACHUSETTS ST
Case 1008476 - Application Added as of 05/05/2008	CONSTRUCT	531 31ST AVE S
Case 1018355 - Payment Processed as of 05/20/2010	TRAO	2270 LOTUS AVE SW
Case 1022443 - Application Added as of 05/07/2010	CITATION	3002 16TH AVE S
Case 1021044 - Application Added as of 11/04/2009	CONSTRUCT	2110 BEACON AVE S
Case 1021647 - Application Added as of 01/28/2010	CITATION	1953 25TH AVE E
Case 1015443 - Application Added as of 01/06/2009	CONSTRUCT	3420 59TH AVE SW

# Test Map

outdoor storage.	1015600
unsecured rear entry door; missing windows & siding; outdoor storage.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016797">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016797</a>
Application for a Tenant Relocation License. Total units: 3; total units occupied: 3. Demolition.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018692">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018692</a>
Rebuilding and enlarging an non-conforming garage requires a permit and inspections from DPD (if allowed to build over property line).	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021155">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021155</a>
Covered porch and retaining walls require a permit from DPD. Stop Work Order posted 5/17/06 and again on 5/24/06.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1008476">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1008476</a>
Application for a Tenant Relocation License. Total units:1; total units occupied:1. Demolition.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018355">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018355</a>
05/07/10 bg - Vegetation encroaching onto the sidewalk along 16th Ave S. photos taken	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022443">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022443</a>
Application 3010632 was accepted for review 10/14/09 for the removal of more than 1500 sq.ft. of trees & vegetation from a Steep Slope and Potential Slide Environmentally Critical Area (ECA).	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021044">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021044</a>
Outdoor junk storage. Piles of salvaged lumber, fencing material, many bags of gravel/stone etc.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021647">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021647</a>
Permit 6179262 was issued 11/25/08 for work originally started without a permit. This case will remain open until all required inspections have been requested and	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015443">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015443</a>

# Test Map

-122.2889816	47.66039796
--------------	-------------

-122.35728962	47.72489237
---------------	-------------

-122.29468367	47.58814995
---------------	-------------

-122.2929007	47.59702366
--------------	-------------

-122.37510184	47.58303146
---------------	-------------

-122.3117776	47.57665409
--------------	-------------

-122.3175665	47.58425716
--------------	-------------

-122.30084464	47.63731799
---------------	-------------

-122.40790782	47.57305019
---------------	-------------

# Test Map

Case 1021977 - Application Added as of 04/05/2010	CITATION	2822 HARVARD AVE E
---	----------	--------------------

Case 1021973 - Application Added as of 03/26/2010	CITATION	804 E HAMLIN ST
---	----------	-----------------

Case 1021335 - Case Resolved as of 05/07/2010	HZW	1411 E ALDER ST
---	-----	-----------------

Case 1007324 - Application Added as of 01/24/2006	CONSTRUCT	9001 21ST AVE SW
---	-----------	------------------

Case 1020970 - Application Added as of 10/28/2009	CITATION	3639 M L KING JR WAY S
---	----------	------------------------

Case 1017341 - Application Added as of 10/28/2009	NOISE	3639 M L KING JR WAY S
---	-------	------------------------

Case 1004678 - Application Added as of 03/09/2005	CONSTRUCT	529 19TH AVE
---	-----------	--------------

Case 1002492 - Application Added as of 06/08/2004	CONSTRUCT	3520 SW ROXBURY ST
---	-----------	--------------------

Case 1001712 - Application Added as of 03/10/2004	HZW	
---	-----	--



# Test Map

approved.

3/8/10 KB inspected property and Weeds violation exists. Vegetation overgrowth onto sidewalk ROW. Inoperable vehicles/junk storage in rear.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021977>

3/8/10 KB inspected property and Weeds violation exists. Vegetation overgrowth onto sidewalk ROW

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021973>

No outdoor storage of junk in the front yard of the property; west side yard: garbage, bags, plastic containers, and some kind of wooden structure, wood pieces in the side and rear yard.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021335>

ADDITION IN FRONT YARD REQUIRES PERMIT

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1007324>

6/21/08 JS looked up noise review in Hansen and found the application was not routed to Noise during plan review. I informed ACRS and mechanical contractor the equipment is not in compliance.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020970>

6/21/08 JS looked up noise review in Hansen and found the application was not routed to Noise during plan review. I informed ACRS and mechanical contractor the equipment is not in compliance.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017341>

Violation of the Seattle Building Code found: work being done on accessory structure requires permit.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1004678>

Violation of the Seattle Building Code: work without permit (structure or portion of structure in rear yard).

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1002492>

Alleged violation of the Just Cause Eviction Ordinance.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=>

# Test Map

-122.32180971 47.64634953

-122.32174777 47.64580723

-122.31360713 47.60416483

-122.36074207 47.5226741

-122.29732436 47.5708329

-122.29732436 47.5708329

-122.30800029 47.60704706

-122.37795636 47.51768388

# Test Map

Case 1001855 - Application Added as of 03/25/2004 HZW

Case 1002126 - Application Added as of 04/27/2004 TRAO

Case 1002074 - Application Added as of 04/21/2004 TRAO

Case 1002077 - Application Added as of 04/21/2004 TRAO

Case 1002267 - Application Added as of 05/13/2004 HZW

Case 1003021 - Application Added as of 08/03/2004 TRAO

Case 1003409 - Application Added as of 09/15/2004 TRAO

Case 1004047 - Application Added as of 12/01/2004 CITATION

Case 1004468 - Application Added as of 02/11/2005 HZW

Case 1004568 - Application Added as of 02/24/2005 HZW

# Test Map

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1001712>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1001855>

no displacement

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1002126>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1002074>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1002077>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1002267>

No Displacement Certificate

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1003021>

Issuance of an "Owner's Certification of Occupancy or No Displacement"

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1003409>


<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1004047>

Tenant called to complain about a roof leaking into the bedroom and kitchen through the electrical light fixtures.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1004468>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1004568>

# Test Map



# Test Map

Case 1004756 - Application Added as of 03/17/2005      TRAO

Case 1004757 - Application Added as of 03/17/2005      TRAO

Case 1004758 - Application Added as of 03/17/2005      TRAO

Case 1005907 - Application Added as of 07/28/2005      TRAO

Case 1006014 - Application Added as of 08/10/2005      TRAO

Case 1006692 - Application Added as of 10/27/2005      CONSTRUCT

Case 1006693 - Application Added as of 10/27/2005      CONSTRUCT

Case 1005963 - Application Added as of 08/04/2005      HZW

Case 1008731 - Application Added as of 06/16/2006      HZW

Case 1009658 - Application Added as of 09/12/2006      HZW

Case 1008208 - Application Added as of 04/21/2006      CONSTRUCT

# Test Map

No Displacement Certification

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1004756>

No Displacement Certification for TRAO

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1004757>

No Displacement Certification for TRAO

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1004758>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1005907>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1006014>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1006692>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1006693>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1005963>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1008731>

Violation of the Zoning Code

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1009658>

AKA 240768 PTS

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1008208>

# Test Map





# Test Map

Case 1007802 - Application Added as of 03/13/2006	HZW
Case 1011856 - Application Added as of 04/26/2007	ADVISORY
Case 1013338 - Application Added as of 08/30/2007	UNFIT
Case 1010572 - Application Added as of 12/15/2006	HZW
Case 1013127 - Application Added as of 08/14/2007	NOISE
Case 1013508 - Application Added as of 09/18/2007	ADVISORY
Case 1020553 - Application Added as of 09/14/2009	HZW
Case 1015677 - Application Added as of 04/29/2008	UNFIT
Case 1021153 - Application Added as of 11/18/2009	NOISE
Case 1022476 - Application Added as of 05/12/2010	HZW
Case 1022528 - Application Added as of 05/18/2010	ADVISORY

# Test Map

Weeds encroaching half of side walk at 2646 SW Holden ST.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1007802>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1011856>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1013338>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010572>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1013127>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1013508>

Violation of Just Cause Eviction Ordinance SMC due to owners' issuance of eight (8) deficient notices.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020553>

unfit building

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015677>


<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021153>

Violation of the Just Cause Eviction Ordinance

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022476>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022528>

# Test Map



# Test Map

Case 1017060 - Payment Processed as of 12/09/2008    TRAO    506 BELMONT AVE E

Case 1020262 - Application Added as of 05/13/2010    HZW    3238 NE 87TH ST

Case 1022369 - Case Opened as of 04/29/2010    HZW    4520 7TH AVE NE

Case 1009407 - Application Added as of 08/17/2006    HZW    909 N 143RD ST

Case 1022480 - Case Opened as of 05/14/2010    HZW    13739 LINDEN AVE N

Case 1022573 - Case Opened as of 05/21/2010    UNFIT    103 12TH AVE

Case 1016520 - Notice or Order Issued as of 01/21/2010    HZW    756 S KENYON ST

Case 1018723 - Application Added as of 03/12/2009    CONSTRUCT    3728 BEACH DR SW

Case 1015988 - Application Added as of 09/04/2009    HZW    6529 DELRIDGE WAY SW

Case 1016265 - Notification Issued as of 03/08/2010    VACANT    6529 DELRIDGE WAY SW

# Test Map

Application for a Tenant Relocation License. Total units:5; total units occupied:4.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017060>

Land Use Code Violation

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020262>

Violation of Land Use Code observed.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022369>

Violation of Mobile Home Park Ordinance section 22.904.410

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1009407>

Observed interior and exterior violations

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022480>

Voluntary abatement of commercial/multi-family structure

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022573>

"VIOLATION ALERT" VIOLATION OF THE SEATTLE LAND USE AND ZONING CODE CONFIRMED(SINGLE FAMILY RESIDENCE WITH DETACHED GARAGE & HABITABLE SPACE CONVERTED TO 4 DWELLING UNITS WITHOUT PERMIT & REQUIRED PARKING).

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016520>

Electrical work performed in Unit 6 requires a permit & inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018723>

Veg. overgrowth, junk storage, vehicle storage.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015988>

Veg. overgrowth, junk storage, vehicle storage.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016265>

# Test Map

-122.32374804	47.62349756
---------------	-------------

-122.29171438	47.69183791
---------------	-------------

-122.32043939	47.66197876
---------------	-------------

-122.34685662	47.73199228
---------------	-------------

-122.34833787	47.72924589
---------------	-------------

-122.31703134	47.60185037
---------------	-------------

-122.3230293	47.5321458
--------------	------------

-122.40992247	47.57029086
---------------	-------------

-122.36167128	47.54359247
---------------	-------------

-122.36167128	47.54359247
---------------	-------------

# Test Map

Case 1016266 - Application Added as of 09/04/2009	HZW	6529 DELRIDGE WAY SW
Case 1020195 - Notice or Order Issued as of 04/27/2010	CONSTRUCT	3724 CASCADIA AVE S
Case 1019259 - Application Added as of 04/19/2010	CONSTRUCT	10401 LAKE CITY WAY NE
Case 1002255 - Application Added as of 07/10/2009	CONSTRUCT	5605 DELRIDGE WAY SW
Case 1012412 - Application Added as of 07/10/2009	CONSTRUCT	5605 DELRIDGE WAY SW
Case 1002524 - Case Opened as of 06/10/2004	CONSTRUCT	1554 15TH AVE E
Case 1002257 - Application Added as of 05/12/2004	CONSTRUCT	3242 38TH AVE SW
Case 1002322 - Application Added as of 09/28/2004	CONSTRUCT	2100 FAIRMOUNT AVE SW

# Test Map

vehicle storage in front of garage .

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016266>

Remodeling a basement, converting a garage into a living area & rebuilding a deck in the rear yard requires zoning approval and, if approved, permits & inspections from DPD. STOP WORK ORDER posted 8/5/09.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020195>

Cutting four trees (2 - 18" diameter, 1 - 36 " diameter and 1 - 12" diameter) on a Steep Slope Environmentally Critical Area site requires a tree & revegetation plan.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019259>

Permit 6162636 was issued 4/7/08 for work originally started without a permit. This case will remain open until all required inspections have been requested & approved.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1002255>

Permit 6189866 was issued 11/21/08 for work originally started without a permit. This case will remain open until all required inspections have been requested and approved.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1012412>

Grading more than 100 cubic yards without a permit.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1002524>

Deck on front of house requires building permit. Okay for STFI with site plan per Berg.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1002257>

Violation found: work not per approved plans (grading/construction access on adjacent Park Dept. property w/o permit). Stop Work Order (SWO) posted at site on 5/14/04.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1002322>



# Test Map

-122.36167128	47.54359247
---------------	-------------

-122.28253802	47.56995485
---------------	-------------

-122.30207643	47.70452237
---------------	-------------

-122.36320432	47.55167627
---------------	-------------

-122.36320432	47.55167627
---------------	-------------

-122.31223328	47.63396542
---------------	-------------

-122.37998389	47.57434356
---------------	-------------

-122.37853039	47.58529951
---------------	-------------

# Test Map

Case 1007564 - Application Added as of 02/21/2006	CONSTRUCT	5911 49TH AVE SW
---	-----------	------------------

Case 1014519 - Application Added as of 12/28/2007	CONSTRUCT	5617 RAINIER AVE S
---	-----------	--------------------

Case 1021418 - Notice or Order Issued as of 03/16/2010	HZW	7310 RAINIER AVE S
--	-----	--------------------

Case 1021419 - Case Opened as of 04/15/2010	CITATION	7310 RAINIER AVE S
---	----------	--------------------

Case 1021527 - Case Opened as of 01/12/2010	CONSTRUCT	5615 ROOSEVELT WAY NE
---	-----------	-----------------------

Case 1020366 - Application Added as of 10/01/2009	HZW	8901 ROOSEVELT WAY NE
---	-----	-----------------------

Case 1002792 - Application Added as of 07/12/2004	CONSTRUCT	2042 33RD AVE S
---	-----------	-----------------

Case 1008307 - Application Added as of 05/02/2006	CONSTRUCT	1327 14TH AVE S
---	-----------	-----------------

# Test Map

TREE CUTTING PERMIT REQUIRED FOR AT LEAST 3 TREES CUT ON STEEP SLOPE--BLACKBERRY BUSHES ALSO REMOVED

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1007564>

Replacing an exterior staircase requires a permit and inspections from DPD. STOP WORK ORDER posted 12/27/07.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014519>

VIOLATION OF THE SEATTLE HOUSING AND BUILDING MAINTERNANCE CODE OBSERVED (EVIDENCE OF COACKROACH INFESTATION PROVIDED INOPERABLE HEATER IN LIVING ROOM AND OTHETR VIOLATIONS) TOOK PHOTOS.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021418>

VIOLATIONS OF THE SEATTLE LAND USE AND ZONING CODE (OBSERVED REFRIGERATOR, RANGE,AUTO TIRES TELEVISIONS, CARPER MATERIAL HOUSEHOLD GOODS IN YARDS AND ON EXTERIOR CORRIDORS ).. TOOK PHOTOS.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021419>

SIGN FACE MUST BE CHANGED TO ADVERTISE PRODUCTS OR SERVICES FOUND ON PREMISES OR SIGN MUST BE REMOVED

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021527>

zoning- outdoor storage

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020366>

Violation of the Seattle Building Code found: work without a permit. Stop Work Order placed 7/8/04.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1002792>

SEWER REPAIR REQUIRES PERMIT--REPAIR IS LEAKING SEWAGE ONTO STREET CREATING PUBLIC HEALTH HAZARD--INFORMED HEALTH

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1008307>

# Test Map

-122.39543556	47.54986832
---------------	-------------

-122.27808385	47.5513373
---------------	------------

-122.26964024	47.5366103
---------------	------------

-122.26964024	47.5366103
---------------	------------

-122.31764373	47.66982486
---------------	-------------

-122.31791793	47.69331119
---------------	-------------

-122.29059594	47.583889
---------------	-----------

-122.31512606	47.59070394
---------------	-------------

# Test Map

Case 1018467 - Application Added as of 04/30/2009      CONSTRUCT      9340 55TH AVE S

Case 1007603 - Application Added as of 02/23/2006      CONSTRUCT      5501 S CLOVERDALE ST

Case 1009813 - Application Added as of 12/26/2008      CONSTRUCT      5501 S CLOVERDALE ST

Case 1019364 - Citation Issued as of 05/18/2010      CITATION      2814 S GRAHAM ST

Case 1017072 - Application Added as of 05/28/2009      CONSTRUCT      4208 RAINIER AVE S

Case 1017394 - Application Added as of 09/22/2009      HZW      4208 RAINIER AVE S

Case 1022182 - Notice or Order Issued as of  
05/21/2010      CONSTRUCT      4208 RAINIER AVE S

Case 1014868 - Application Added as of 05/02/2008      CONSTRUCT      9805 BAYARD AVE NW

# Test Map

## DEPT

Zoning approval, plan review, permits & inspections required for remodel, large addition & additional dwelling units being constructed without permits. STOP WORK ORDER posted 2/11/09. Replacing all plumbing & mechanical requires permits & inspections too.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018467>

Violation found: retaining wall along east property line requires permit.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1007603>

Constructing a room under a deck requires permit from DPD. Stop Work Order posted 9/22/06. (see previous violation for retaining wall that has not been permitted)

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1009813>

05/19/09 - Four vehicles on the property, one is a motor home, junk including but not limited to tires, truck topper, plastic buckets and bricks on the property. photos taken. bg

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019364>

Occupying a building requires Certificates of Occupancy (C of O). Immediately discontinue use of Wedding Chapel/Banquet facility. All required inspections needed for Permits 6131105 & 6092215 OR retail and restaurant occupancies must be discontinued.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017072>

Letter is enroute re: use is not established for active and expired permits.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017394>

Work occurring not per Permits 6240114 and 6241624. Either revised permit drawings or revising the work to match the permitted drawings is required.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022182>

PERMIT REQUIRED FOR RETAINING WALLS IN ECA

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=>

# Test Map

-122.26374004      47.51779635

-122.26354684      47.52666185

-122.26354684      47.52666185

-122.29623926      47.5464544

-122.28781107      47.56514344

-122.28781107      47.56514344

-122.28781107      47.56514344

-122.38104119      47.70083955

# Test Map

Case 1022158 - Notice or Order Issued as of 04/20/2010	HZW	6357 36TH AVE SW
Case 1021835 - Application Added as of 04/01/2010	CITATION	7304 44TH AVE SW
Case 1022501 - Application Added as of 05/13/2010	CITATION	4318 SW WEBSTER ST
Case 1022120 - Notice or Order Issued as of 04/01/2010	HZW	4801 DELRIDGE WAY SW
Case 1018116 - Application Added as of 05/18/2009	CONSTRUCT	8420 10TH AVE SW
Case 1022141 - Application Added as of 04/26/2010	CONSTRUCT	10711 55TH AVE S
Case 1013410 - Application Added as of 10/09/2007	CONSTRUCT	8320 46TH AVE SW
Case 1011577 - Application Added as of 04/06/2009	HZW	6511 16TH AVE NE
Case 1019497 - Application Added as of 05/20/2010	HZW	466 NE 70TH ST
Case 1021785 - Notice or Order Issued as of	CONSTRUCT	2830 NW 56TH ST



# Test Map

	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014868">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014868</a>
house & garage unsecured; pictures in file.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022158">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022158</a>
Violation of Weeds & Vegetation ORd-	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021835">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021835</a>
Violation of weeds & Vegetation Ord-	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022501">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022501</a>
Violation of HBMC_	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022120">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022120</a>
Permit & inspections required for addition to accessory detached building in rear yard.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018116">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018116</a>
LARGE CONIFER CUT IN FRONT YARD--APPEARS TO BE EXCEPTIONAL TREE	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022141">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022141</a>
Stop Work for not installing Temporary Erosion & Sedimentation Control (TESC) & for starting project w/o a Pre-Construction Conference for Permits 6097009 & 6097012. STOP WORK ORDER posted 9/28/07.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1013410">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1013410</a>
LUC violation. The required off street parking has been removed.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1011577">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1011577</a>
Land Use Code Violation	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019497">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019497</a>
OBTAIN PERMIT TO FINAL PERMIT #6114087---CALL	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=</a>

# Test Map

-122.37809654	47.54488363
---------------	-------------

-122.38780313	47.53808707
---------------	-------------

-122.3882577	47.53599341
--------------	-------------

-122.3632411	47.5591453
--------------	------------

-122.34776304	47.52762785
---------------	-------------

-122.26517541	47.50442324
---------------	-------------

-122.39125802	47.5290496
---------------	------------

-122.31114926	47.67616344
---------------	-------------

-122.32319303	47.67953032
---------------	-------------

-122.39397197	47.66966355
---------------	-------------

# Test Map

02/22/2010

Case 1018295 - Application Added as of 04/23/2009      CONSTRUCT      1943 1ST AVE S

Case 1020282 - Case Opened as of 08/18/2009      CONSTRUCT      1943 1ST AVE S

Case 1022352 - Application Added as of 04/28/2010      HZW      200 5TH AVE S

Case 1022337 - Application Added as of 05/05/2010      CITATION      313 N 143RD ST

Case 1021862 - Notice or Order Issued as of 03/24/2010      CONSTRUCT      1980 HARVARD AVE E

Case 1020986 - Notice or Order Issued as of 03/30/2010      CONSTRUCT      7047 EAST MARGINAL WAY S

Case 1020097 - Case Opened as of 08/05/2009      CONSTRUCT      4522 BROOKLYN AVE NE

Case 1022225 - Application Added as of 05/07/2010      HZW      1414 SENECA ST

Case 1019457 - Application Added as of 10/12/2009      CONSTRUCT      5322 47TH AVE SW

# Test Map

FOR INSPECTIONS--OBTAIN CERTIFICATE OF OCCUPANCY	<a href="#">1021785</a>
NO SIGN PERMIT--ALSO ADVERTISES PRODUCTS NOT SOLD ON SITE	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018295">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018295</a>
ADVERTISING MUST BE REMOVED	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020282">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020282</a>
Inspection of property: violation of ISRD requirements for approval; New bracing installed on exterior of building over window/door on North side. DPD-CSC	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022352">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022352</a>
outdoor junk storage sfr	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022337">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022337</a>
PERMIT #6223748 DOES NOT COVER SCOPE OF WORK--NEED PERMIT FOR ADU	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021862">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021862</a>
Occupying a building without a Certificate of Occupancy (C of O). Allowed occupant load is 134 for entire building until C of O for Permit 6099705 has been issued.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020986">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020986</a>
PERMIT IS REQUIRED FOR SIGN--SIGN MUST ADVERTISE GOODS OR SERVICES PROVIDED ON SITE	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020097">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020097</a>
4/5/10 KB inspected unit and HBMC violations exist	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022225">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022225</a>
Permit 6219983 was issued 10/12/09 for work originally performed without a permit. This case will remain open until all required inspections have been requested, performed and approved by DPD.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019457">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019457</a>

# Test Map

-122.33469722	47.58462106
---------------	-------------

-122.33469722	47.58462106
---------------	-------------

-122.32737691	47.60071479
---------------	-------------

-122.35468485	47.73212616
---------------	-------------

-122.32211739	47.63825018
---------------	-------------

-122.3231203	47.53970366
--------------	-------------

-122.31385712	47.66197571
---------------	-------------

-122.32260174	47.61266509
---------------	-------------

-122.39199248	47.55405453
---------------	-------------

# Test Map

Case 1022217 - Application Added as of 04/13/2010	CITATION	11403 34TH AVE SW
---	----------	-------------------

Case 1006332 - Application Added as of 09/19/2005	CONSTRUCT	7202 S TAFT ST
---	-----------	----------------

Case 1010596 - Application Added as of 01/18/2007	CONSTRUCT	2926 E REPUBLICAN ST
---	-----------	----------------------

Case 1018036 - Application Added as of 02/02/2009	HZW	9363 BEACON AVE S
---	-----	-------------------

Case 1022039 - Application Added as of 04/19/2010	CITATION	3017 S BYRON ST
---	----------	-----------------

Case 1021915 - Application Added as of 04/19/2010	HZW	3017 S BYRON ST
---	-----	-----------------

Case 1020252 - Application Added as of 04/15/2010	HZW	113 22ND AVE
---	-----	--------------

Case 1001705 - Application Added as of 05/17/2007	HZW	502 MINOR AVE N
---	-----	-----------------

Case 1018740 - Application Added as of 03/13/2009	CONSTRUCT	515 MADISON ST
---	-----------	----------------

# Test Map

4/2/10 ej- Inspection shows some outdoor junk storage such as but limited to pile of concrete rubble and wood stack neatly. There is an open permit #6080476 expires on 8/8/10.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022217>

Grading and retaining wall in Steep Slope and Potential Slide Environmentally Critical Areas requires a permit from DPD. Grading in the R-O-W requires a permit from SDOT.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1006332>

Retaining wall failed along Dewey PI E and rear deck damaged. House posted limited entry (do not use rear deck) on 12/15/06. Deck requires removal or repair (with permit).

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010596>

Violation of SMC 22.206.260; Owner has failed to pay relocation assistance.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018036>

02/26/10 bg - Outdoor junk storage.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022039>

02/26/10 bg - EO - Inoperable heaters in the unit, number HBMC violations. photos taken

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021915>

Violations of the HBMC

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020252>

Violation of the Just Cause Eviction Ordinance

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1001705>

Electrical work in Simar's Salon requires an electrical permit & must be performed by a certified electrician. Work seen included unsafe non code compliant electrical

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018740>

# Test Map

-122.3758243	47.50117527
--------------	-------------

-122.24361574	47.51068004
---------------	-------------

-122.29387141	47.62385482
---------------	-------------

-122.27583247	47.51733739
---------------	-------------

-122.29389465	47.57409139
---------------	-------------

-122.29389465	47.57409139
---------------	-------------

-122.30398235	47.60212856
---------------	-------------

-122.33284592	47.62326986
---------------	-------------

-122.33078167	47.60681191
---------------	-------------



# Test Map

Case 1018839 - Notice or Order Issued as of 01/14/2010	CONSTRUCT	704 1ST AVE
Case 1022433 - Application Added as of 05/06/2010	HZW	1921 BROOK AVE SW
Case 1011572 - Application Added as of 09/24/2009	CITATION	325 16TH AVE
Case 1007782 - Case Opened as of 08/20/2008	CONSTRUCT	2920 12TH AVE S
Case 1002474 - Application Added as of 04/08/2005	CONSTRUCT	3821 CHILBERG PL SW
Case 1002487 - Application Added as of 05/05/2006	CONSTRUCT	10062 WATERS AVE S
Case 1017745 - Application Added as of 10/28/2008	CONSTRUCT	4167 38TH AVE S
Case 1022269 - Application Added as of 04/22/2010	CONSTRUCT	4224 34TH AVE S
Case 1003528 - Application Added as of 04/12/2007	CONSTRUCT	4212 34TH AVE S

# Test Map

line voltage splice made in wall. STOP WORK ORDER posted 3/12/09.

SIGN AND ELECTRICAL PERMITS ARE REQUIRED FOR SIGNS

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018839>

Light and glare from bulkhead lights on the side of the house.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022433>

OBSERVED ONGOING JUNK STORAGE VIOLATION. TOOK PHOTOS.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1011572>

Detached shed/garage/ADU on NE corner of property requires building, electrical and plumbing permits. Permit 6117670 was issued 1/29/07 & finalized 6/20/07 for addition to south side of house originally started w/o permit.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1007782>

Vegetation removal greater than 750 sq. ft. in an Environmentally Critical Area without a permit.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1002474>

.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1002487>

Pipes directing footing drains to the sidewalk must either be removed or permit & inspections obtained to drain to a City facility. Temporary Erosion & Sedimentation Control (TESC) not per code.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017745>

ONE OF THE CO-DOMINANT TREE TRUNKS HAS BEEN REMOVED

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022269>

Violation of the Seattle Building Code found: elevated walkway at rear of house & CMU retaining

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=>

# Test Map

-122.33407067	47.60284045
---------------	-------------

-122.37977499	47.58615555
---------------	-------------

-122.31215101	47.60509967
---------------	-------------

-122.31705196	47.57707329
---------------	-------------

-122.40768942	47.5695647
---------------	------------

-122.25040147	47.51101912
---------------	-------------

-122.28525599	47.5642822
---------------	------------

-122.29032808	47.56473619
---------------	-------------

-122.29035265	47.56506317
---------------	-------------

# Test Map

Case 1021802 - Application Added as of 02/19/2010      CONSTRUCT      1547 32ND AVE S

Case 1005741 - Application Added as of 07/07/2005      CITATION      135 NW 85TH ST

Case 1022430 - Application Added as of 05/06/2010      CITATION      1761 22ND AVE S

Case 1022431 - Case Opened as of 05/06/2010      HZW      1761 22ND AVE S

Case 1022401 - Notice or Order Issued as of 05/13/2010      HZW      1761 22ND AVE S

Case 1022432 - Case Opened as of 05/06/2010      HZW      1765 22ND AVE S

Case 1022400 - Notice or Order Issued as of 05/13/2010      HZW      1765 22ND AVE S

Case 1018526 - Notification Issued as of 03/05/2010      VACANT      8447 DELRIDGE WAY SW

# Test Map

walkway at rear of house & CMU retaining wall/foundation require permit(s).

1003528

Constructing keystone block retaining walls (some on top of existing retaining walls) on a site mapped as a Steep Slope & Potential Slide ECA requires a permit & inspections from DPD. STOP WORK ORDER posted 2/18/10.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021802>

VIOLATIONS OF THE OF THE SEATTLE HOUSING AND BUILDING MAINTENANCE CODE WERE OBSERVED.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1005741>

veg. overgrowth on both sidewalks on this corner lot, pictures in file..

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022430>

outdoor storage includes pick-up truck canopy, mattresses, black plastic bags cardboard & othe used or salvageable materials on the site & on the VACANT LOT, pictures in file..

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022431>

Garage & doors behind fence unsecured; pictures in file..

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022401>

Outdoor storage includes barrels, wiring, lumber, glass, shipping container, tires & other items, pictures in file.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022432>

Garage door, 2 large window openings on the South wall & holes in the South wall make this bldg. open to entry, pictures in file.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022400>

Rear entry door unsecured; deterioration, at least 5 vehicles stored on site; collapsed garage.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018526>

# Test Map

-122.29181232	47.5880769
---------------	------------

-122.35947152	47.69036526
---------------	-------------

-122.30425214	47.5874102
---------------	------------

-122.30425214	47.5874102
---------------	------------

-122.30425214	47.5874102
---------------	------------

-122.30409049	47.58718283
---------------	-------------

-122.30409049	47.58718283
---------------	-------------

-122.36077887	47.52681818
---------------	-------------

# Test Map

Case 1019501 - Citation Issued as of 03/05/2010	CITATION	8447 DELRIDGE WAY SW
---	----------	----------------------

Case 1018063 - Application Added as of 03/05/2010	HZW	8447 DELRIDGE WAY SW
---	-----	----------------------

Case 1022203 - Case Opened as of 04/16/2010	HZW	8001 BEACON AVE S
---	-----	-------------------

Case 1022131 - Application Added as of 04/01/2010	CITATION	8039 BEACON AVE S
---	----------	-------------------

Case 1021197 - Application Added as of 04/20/2010	CONSTRUCT	9025 CECIL AVE S
---	-----------	------------------

Case 1021432 - Application Added as of 01/08/2010	CONSTRUCT	9025 CECIL AVE S
---	-----------	------------------

# Test Map

Rear entry door unsecured; deterioration, at least 5 vehicles stored on site; collapsed garage.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019501>

Rear entry door unsecured; deterioration, at least 5 vehicles stored on site; collapsed garage.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018063>

"VIOLATION ALERT" VIOLATION OF THE SEATTLE LAND USE AND ZONING CODE CONFIRMED (ACCESS TO GARAGE PARKING ELIMINATED WITHOUT REQUIRED PERMIT; ADDITIONS TO RESIDENCE AND GARAGE WITHOUT REQUIRED PERMITS. TOOK PHOTOS.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022203>

VIOLATION OF THE SEATTLE LAND USE AND ZONING CODE OBSERVED(LUMBER AND OTHER MATERIALS IN YARD). REPAIR OF EXTERIOR WALL IN PROGRESS.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022131>

Grading more than 300 to 400cu.yds. & destroying more than 1500sq.ft.of trees and vegetation in a Steep Slope, Potential Slide & Wildlife Habitat Environmentally Critical Area (ECA) requires permits and inspections from DPD. STOP WORK ORDER posted 11/20/09. Site stabilization is the only work allowed until permits obtained. (property owner)

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021197>

Grading more than 300 to 400cu.yds. & destroying more than 1500sq.ft.of trees and vegetation in a Steep Slope, Potential Slide & Wildlife Habitat Environmentally Critical Area (ECA) requires permits and inspections from DPD. STOP WORK ORDER posted 11/20/09. Site stabilization is the only work allowed until permits obtained.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021432>



# Test Map

-122.36077887 47.52681818

-122.36077887 47.52681818

-122.28851503 47.5308535

-122.28834502 47.52985126

-122.28825109 47.52292076

-122.28825109 47.52292076

# Test Map

Case 1021717 - Notice or Order Issued as of 03/04/2010	CONSTRUCT	4753 UNIVERSITY VIEW PL NE
Case 1021534 - Notice or Order Issued as of 05/17/2010	CONSTRUCT	7516 25TH AVE NW
Case 1002711 - Application Added as of 08/05/2004	CITATION	3215 S DEARBORN ST
Case 1022373 - Application Added as of 05/03/2010	HZW	6506 3RD AVE NW
Case 1021465 - Case Resolved as of 05/03/2010	CITATION	8137 17TH AVE SW
Case 1022032 - Application Added as of 04/28/2010	CITATION	7511 13TH AVE SW
Case 1014557 - Application Added as of 06/10/2008	CONSTRUCT	2550 S EDDY ST
Case 1021444 - Citation Issued as of 04/21/2010	CITATION	1022 SW PORTLAND ST

# Test Map

is the only work allowed until permits obtained.  
(responsible party)

PROVIDE PLAN REVISIONS FOR CHANGES TO  
GARAGE

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021717>

DECK HAS NOT BEEN BUILT PER PLAN BECAUSE  
THE APPROVED PLAN FOR PERMIT #6073068  
SHOWS A LARGER FRONT YARD THAN ACTUALLY  
EXISTS--THE DECK AS SHOWN ON THE PLAN IS  
BUILT INTO THE FRONT YARD SETBACK--SUBMIT  
REVISED PLANS OR REMOVE THE DECK

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021534>

Observed (violation) vehicle parked in the front yard; tk  
photos.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1002711>

Outdoor junk storage. Pile of wood from construction  
stored in the front yard.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022373>

12/31/09 ej- Inspection shows outdoor junk storage such  
as but not limited to car parts, tires, inoperable vehicles  
and more than the allowed 3 vehicles not in an enclosed  
area.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021465>

3/17/10 ej- Inspection shows 4 vehicles parked on a  
single lot and possible inoperable.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022032>

Permit 6169409 was issued 2/6/08 for work originally  
performed without a permit. This case will remain open  
until all inspections have been called for and obtained.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014557>

Violation of Land Use- Outdoor junk storage

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021444>

# Test Map

-122.29280835      47.66332183

-122.38843752      47.68370758

-122.29080526      47.59554637

-122.36022744      47.67624687

-122.35669867      47.52896536

-122.35195154      47.5351507

-122.29790865      47.54552994

-122.34905941      47.53349505

# Test Map

Case 1022086 - Application Added as of 05/13/2010      HZW      3904 M L KING JR WAY S

Case 1022515 - Application Added as of 05/14/2010      CONSTRUCT      2925 FAIRVIEW AVE E

Case 1013656 - Findings Issued as of 09/22/2008      ADVISORY      717 BELMONT AVE E

Case 1008388 - Application Added as of 01/30/2007      HZW      2629 NW 54TH ST

Case 1017801 - Case Opened as of 02/10/2009      HZW      2629 NW 54TH ST

Case 1020499 - Application Added as of 02/02/2010      HZW      2223 NW 59TH ST

Case 1021524 - Citation Issued as of 05/06/2010      CITATION      4507 S HOLLY ST

Case 1018121 - Payment Processed as of 03/27/2009      TRAO      6510 34TH AVE SW

Case 1021609 - Notice or Order Issued as of  
04/19/2010      HZW      3614 S FINDLAY ST

# Test Map

01/13/10 - Parking area has potholes w/standing water.  
Entry gate, keys dont work. bg

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022086>

EMERGENCY REPAIR OF MARINA ROOF--NEW  
PILINGS--PERMIT REQUIRED

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022515>

Condo Conversion.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1013656>

Observed large boat/ship repair structure, with repair work inside. An owner of Barnacle Point, LLC, said that it would not be on the premises within approx. 2 weeks from today.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1008388>

Overwater coverage and fill near shoreline verified during an inspection and comparison with aerial photos from 2005.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017801>

HBMC Structural Engineer report & construction permit for structural deterioration on exit balconies.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020499>

VIOLATION OF THE SEATTLE LAND USE AND ZONING CODE OBSERVED. (TWO VENDING MACHINES ON FRONT PORCH FOR SALES TO SCHOOL CHILDREN, AUTO TIRES,LUMBER AND OTHER MATERIALS IN YARDS.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021524>

Failure to apply for a Tenant Relocation License pursuant to Seattle Municipal Code Chapter 22.210.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018121>

deterioration of structural & non-structural components of bldg.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021609>

# Test Map

-122.29649301 47.56871665

-122.32564408 47.6486773

-122.32456129 47.62540471

-122.39156846 47.66744388

-122.39156846 47.66744388

-122.38578017 47.6714317

-122.27609225 47.54228493

-122.37480547 47.54422446

-122.28754725 47.55220448

# Test Map

Case 1021610 - Application Added as of 01/25/2010	CITATION	3614 S FINDLAY ST
Case 1021961 - Notification Issued as of 03/25/2010	VACANT	3614 S FINDLAY ST
Case 1006627 - Application Added as of 10/19/2005	CONSTRUCT	5522 RENTON AVE S
Case 1020722 - Application Added as of 11/13/2009	HZW	4701 WOODLAND PARK AVE N
Case 1012497 - Application Added as of 06/19/2007	CONSTRUCT	4614 15TH AVE S
Case 1010555 - Application Added as of 12/05/2008	CONSTRUCT	4001 31ST AVE S
Case 1022346 - Application Added as of 04/29/2010	HZW	837 W FULTON ST
Case 1007259 - Application Added as of 01/18/2006	CONSTRUCT	10242 42ND AVE SW
Case 1003990 - Application Added as of 11/22/2004	CONSTRUCT	10041 ARROWSMITH AVE S
Case 1012679 - Application Added as of 03/25/2009	CONSTRUCT	10435 41ST AVE SW



# Test Map

Outdoor storage includes pallets, pipe, sports equipment, tarps, wrought iron, doors, bathtubs, glass, hot water tanks, barrels, buckets, toilet, tires & window frames, pictures in file.

deterioration of structural & non-structural components of bldg.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021610>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021961>

Constructing a rockery greater than 4' tall in a Steep Slope Environmentally Critical Area (ECA) requires a permit from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1006627>

Zoom Language Center School in SF zone without ACU Permit approval for an institution.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020722>

New footing & foundation alteration at SW corner of SFR requires permit & inspections from DPD. Immediate retention of undermined porch footing/walls must be provided.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1012497>

Landscaping requires installation per MUP 9901787. All required inspections (including final approval) needed for the 13 dwelling units built under MUP 9901787.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010555>

4/27/10 KB inspected property and LU violation (illegal unit) and HBMC violations exist.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022346>

ADDITION TO EXISTING HOUSE REQUIRES PERMIT

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1007259>

Tree cutting in ECA 2 (Potential Slide) and ECA 1 (steep slope) requires a permit from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1003990>

Greenhouse addition requires zoning & building code

# Test Map

-122.28754725 47.55220448

-122.28754725 47.55220448

-122.28497305 47.55210973

-122.34486029 47.66307937

-122.3131516 47.56121901

-122.29274621 47.56787382

-122.36914357 47.64566967

-122.38518448 47.51092391

-122.25046133 47.51166328

-122.38464268 47.5090439

# Test Map

Case 1013941 - Application Added as of 06/17/2009      CONSTRUCT      2827 S RAYMOND ST

Case 1008370 - Application Added as of 05/06/2010      CONSTRUCT      4017 22ND AVE SW

Case 1017119 - Application Added as of 12/07/2008      CONSTRUCT      6067 ATLAS PL SW

Case 1021935 - Notice or Order Issued as of  
03/08/2010      CONSTRUCT      6067 ATLAS PL SW

Case 1021303 - Notice or Order Issued as of  
04/29/2010      CONSTRUCT      5236 18TH AVE SW

Case 1020410 - Case Resolved as of 04/16/2010      CITATION      1614 24TH AVE

Case 1021132 - Notification Issued as of 05/10/2010      VACANT      1614 24TH AVE

# Test Map

review and permit(s) & inspections from DPD or removal.  
NOTE: addition had been removed for 11/27/07  
compliance inspection but was in place during 10/28/08  
compliance inspection.

Constructing 2 carport additions & other additions  
requires zoning approval &, if allowed, building permit &  
inspections from DPD or removal. If located in R-O-W,  
SDOT approval will also be required.

## PERMIT REQUIRED FOR NEW DECK

Ecology block wall and grading at south end of site not  
per Permit 6114086 & not per ECA Covenant (King Co.  
Recording No. 20030122000289).

Broken side sewer & uncontrolled runoff from plastic  
sheeting adversely affecting stability of hillside. Side  
Sewer permit requires review by DPD geotechnical staff  
& repairs must be performed under direction &  
observation of licensed geotechnical engineer.

Permit 6236046 was issued 1/11/10 to remove  
unpermitted structures & to allow reconfigured carport &  
covered patio. This case will remain open until all  
required inspections have been requested & approved.

2 inop. vehicles in front of garage & partially obstructing  
the public sidewalk; outdoor storage of lumber & building  
materials; pictures in file.

unsecured garage with missing roof & walls; unfinished  
remodel; recent photo's in file.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1012679>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1013941>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1008370>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017119>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021935>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021303>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020410>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=>

# Test Map

-122.29568836      47.54785888

-122.36148843      47.5677748

-122.39740061      47.54740034

-122.39740061      47.54740034

-122.3567807      47.55467237

-122.3011439      47.61576746

-122.3011439      47.61576746

# Test Map

Case 1002825 - Application Added as of 07/14/2004      CONSTRUCT      6412 49TH AVE SW

Case 1004685 - Application Added as of 03/10/2005      CONSTRUCT      6550 32ND AVE SW

Case 1003545 - Application Added as of 11/30/2006      CONSTRUCT      5558 S AVON ST

Case 1022248 - Application Added as of 04/19/2010      CITATION      9002 14TH AVE SW

Case 1008499 - Case Opened as of 06/15/2006      CONSTRUCT      4030 39TH AVE S

Case 1020412 - Application Added as of 02/09/2010      CITATION      3437 15TH AVE S

Case 1010038 - Application Accepted as of  
10/27/2009      ADVISORY      1501 1ST AVE N

Case 1016525 - Notice or Order Issued as of  
02/05/2010      CONSTRUCT      10049 35TH AVE SW

# Test Map

remodel; recent photo's in file.

1021132

Violation of the Seattle Sormwater, Grading and Drainage Control Code found: grading without a permit.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1002825>

Violation found: Temporary Erosion & Sedimentation Controls (TESC) not per approved plan. To be re-evaluated by Site Inspector on 3/4/05.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1004685>

Violation of the Seattle Building Code found: building a deck over 18" high without a permit.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1003545>

I advised Michael Griffin - via a note on the SR for 9006 14th Ave SW to check to make sure that this address has a vacant house or not. PBarrett.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022248>

Initial inspection by M. Griffin, appears vacant: outdoor storage includes plywood, mattress, lawn mower, tarps & chairs; veg. blocks sidewalk, pictures in file.

Side sewer permit and inspections from DPD required.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1008499>

07/23/09 bg - Through lot parking area on 15th and vehicle parked in rear yard - inoperable.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020412>

Condo Conversion.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010038>

Permit 6193477 was issued on 9/4/08 for work originally performed without a permit. This case will remain open until all required inspections are requested and approved.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016525>

# Test Map

-122.39491173      47.54543996

-122.37354951      47.54377321

-122.26266495      47.501508

-122.35245955      47.5226876

-122.28371256      47.56696869

-122.31368017      47.57198444

-122.3559204      47.63246738

-122.37661716      47.51226763



# Test Map

Case 1020944 - Case Resolved as of 05/06/2010      HZW      7301 AURORA AVE N

Case 1004905 - Application Added as of 06/14/2007      CONSTRUCT      4817 45TH AVE S

Case 1013228 - Application Added as of 09/17/2007      CONSTRUCT      4817 45TH AVE S

Case 1015450 - Application Added as of 04/10/2008      CONSTRUCT      9401 42ND AVE NE

Case 1012715 - Citation Issued as of 05/13/2009      CITATION      3902 13TH AVE S

Case 1021414 - Citation Issued as of 05/14/2010      CITATION      3902 13TH AVE S

Case 1022048 - Application Added as of 05/20/2010      CITATION      4935 44TH AVE S

Case 1010920 - Application Added as of 01/26/2007      CONSTRUCT      3811 55TH AVE SW

# Test Map

salvage yard not allowed in NC3-40 zone

Violation of the Seattle Building Code and State Environmental Policy Act (SEPA) found: removing trees & vegetation, constructing a gazebo in a Steep Slope Environmentally Critical Area (ECA) requires permit(s) from DPD.

Removing trees in a Steep Slope ECA requires approval from DPD.

Temporary Erosion & Sedimentation Control (TESC) is not per Permit 6136738.

Inspection shows inoperable vehicles (Z-car, Mustang) and outdoor junk storage such as but limited to bags of garbage, wood, tires , tv and monitors, metal rack, and other misc. items. Outdoor junk storage not allowed in single family zones.

Inspection shows inoperable vehicles (Z-car, Mustang) and outdoor junk storage such as but limited to bags of garbage, wood, tires , tv and monitors, metal rack, and other misc. items. Outdoor junk storage not allowed in single family zones.

03/19/10 bg - Vegetation overgrown onto the sidewalk and street, trees obstructing street signs - photos taken

Work being done beyond what is allowed by Permit 6105755. Second story and other work requires a permit and inspections from DPD. STOP WORK ORDER

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020944>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1004905>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1013228>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015450>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1012715>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021414>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022048>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010920>

# Test Map

-122.3447369 47.68196857

-122.27731917 47.5587997

-122.27731917 47.5587997

-122.28319084 47.69669279

-122.3157176 47.56877897

-122.3157176 47.56877897

-122.27852669 47.55716795

-122.40315831 47.56997896

# Test Map

Case 1022577 - Application Added as of 05/21/2010      CITATION      309 W KINNEAR PL

Case 1022143 - Application Added as of 04/30/2010      HZW      300 3RD AVE W

Case 1011299 - Application Added as of 12/29/2008      CONSTRUCT      3262 CALIFORNIA AVE SW

Case 1009934 - Application Added as of 03/24/2010      CONSTRUCT      1385 33RD AVE S

Case 1021819 - Payment Processed as of 05/20/2010      TRAO      1527 E HOWE ST

Case 1008403 - Application Added as of 05/12/2006      CONSTRUCT      4820 44TH AVE S

Case 1013621 - Application Added as of 12/18/2008      CONSTRUCT      5929 20TH AVE S

Case 1022395 - Application Added as of 04/30/2010      CITATION      5042 30TH AVE S

# Test Map

and inspections from DPD. STOP WORK ORDER posted 1/9/07.

5/11/10 KB inspected property and Weeds violation exists

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022577>

4/1/10 KB inspected property and Land Use Violation exists

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022143>

Several Nextel antennas (minor telecommunication utility) installed on roof without required permit(s) and inspections. STOP WORK ORDER posted 3/14/08 for additional antenna(s) installed.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1011299>

Deck on east side of house (and French doors to deck) require a building permit and inspections from DPD. STOP WORK ORDER posted 10/2/06.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1009934>

Application for a Tenant Relocation License. Total units:1; total units occupied:1. Demolition.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021819>

INSPECTOR LEFT CARD--SEVERAL TOPPED MAPLES ON ECA LOT REQUIRE TREE REMOVAL PERMIT

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1008403>

ENTIRE STEEP SLOPE HAS BEEN CLEARED AND GRADED AND THERE IS A PERMIT FOR ONE SITE ONLY--5923 20TH AVENUE S--THERE IS ONLY APPLICATION FOR 5929--STEEP SLOPE ECA EXTENDS ACROSS BOTH SITES

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1013621>

04/30/10 bg - Vegetation encroaching onto sidewalk

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022395>

# Test Map

-122.36110232	47.62751965
---------------	-------------

-122.36015898	47.62120384
---------------	-------------

-122.38647969	47.57381626
---------------	-------------

-122.29071401	47.59015635
---------------	-------------

-122.31235026	47.63587782
---------------	-------------

-122.27783764	47.55870743
---------------	-------------

-122.30766083	47.54902195
---------------	-------------

-122.29393085	47.555801
---------------	-----------

# Test Map

Case 1008089 - Application Added as of 04/10/2006      CONSTRUCT      1850 S LUCILE ST

Case 1016927 - Notice or Order Issued as of 08/19/2008      HZW      3320 RAINIER AVE S

Case 1019790 - Application Added as of 05/10/2010      HZW      5955 M L KING JR WAY S

Case 1022472 - Application Added as of 05/11/2010      CONSTRUCT      1521 10TH AVE

Case 1011456 - Application Added as of 03/23/2007      HZW      6338 14TH AVE NE

# Test Map

Retaining walls over 4' tall and more than 100 cu.yds. grading requires a permit from DPD. Grading and retaining walls are on adjacent R-O-W and Parks Dept. property, permission to build on this property is required from DOPAR and SDOT. (PASV required per Roger Moore)

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1008089>

"VIOLATION ALERT" VIOLATIONS OF THE SEATTLE LAND USE AND ZONING CODE OBSERVED. (ILLEGAL CHANGE OF USE FROM OFFICE AND RETAIL TO RESTAURANT AND SOMALI COMMUNITY SERVICES, "INSTITUTION" USE ). TOOK PHOTOS.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016927>

VIOLATION OF THE SEATTLE HOUSING AND BUILDING MAINTENANCE CODE OBSERVED (INOPERABLE SMOKE DETECTOR 1ST FLOOR BEDROOM, INOPERABLE OUTLET OVER KITCHEN COUNTER, BROKEN WALL 7CEILING COVERING IN BASEMENT, BARS ON BASEMENT SLEEPING ROOM. NO WATER OR EVIDENCE OF RODENTS IN BASEMENT.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019790>

APPLICATION FOR PROJECTING SIGN HAS BEEN DENIED BECAUSE BUSINESS DOES NOT HAVE ENOUGH FRONTAGE--SIGN HAS BEEN INSTALLED DESPITE THE DENIAL OF PERMIT--SIGN MUST BE REMOVED

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022472>

Failure to pay relocation assistance pursuant to SMC Section 22.206.260 subsection G. PTS Case No.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1011456>



# Test Map

-122.3085526

47.5536384

-122.29402676

47.57344752

-122.28695399

47.54819189

-122.31983987

47.61466248

-122.31343225

47.67545297

# Test Map

Case 1011457 - Application Added as of 03/23/2007	HZW	6338 14TH AVE NE
---	-----	------------------

Case 1011458 - Application Added as of 03/23/2007	HZW	6338 14TH AVE NE
---	-----	------------------

Case 1022065 - Notice or Order Issued as of 03/25/2010	CONSTRUCT	1011 PIKE ST
--	-----------	--------------

Case 1019423 - Application Added as of 06/01/2009	CONSTRUCT	1610 PALM AVE SW
---	-----------	------------------

Case 1007266 - Application Added as of 01/18/2006	CONSTRUCT	9053 36TH AVE S
---	-----------	-----------------

Case 1018828 - Citation Issued as of 02/02/2010	CITATION	13560 SHERMAN RD NW
---	----------	---------------------

Case 1007427 - Application Added as of 02/03/2006	CONSTRUCT	4813 44TH AVE S
---	-----------	-----------------

# Test Map

231934 converted to Hansen Case No.1011456. Case referred to law.

Failure to pay relocation assistance pursuant to SMC Section 22.206.260 subsection G. PTS Case No.

231935 converted to Hansen Case No.1011457. Case referred to law.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1011457>

Failure to pay relocation assistance pursuant to SMC Section 22.206.260 subsection G. PTS Case No.

231933 converted to Hansen Case No.1011458. Case referred to law.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1011458>

SIGNS ADVERTISING PRODUCTS NOT AVAILABLE ON THE PREMISES MUST BE REMOVED

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022065>

Addition, retaining wall, roofed decks, interior alterations, hot tub, water feature, cutting trees in an ECA, grading more than 25 cu.yds. & removal of parking require zoning review & if approved, all required permits & inspections from DPD. STOP WORK ORDER posted 5/26/09.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019423>

Violation of the State Environmental Policy Act (SEPA) and the Stormwater, Grading and Drainage Control Code (SGDCC) found: grading in Steep Slope and Potential Slide Environmentally Critical Areas (ECAs) requires a permit from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1007266>

NS inspected the property on 3/19/09-Inspections shows 2 RVs and a vehicle parked in the required yard.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018828>

EVIDENCE OF GRADING IN UNOPENED STREET

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=>

# Test Map

-122.31343225 47.67545297

-122.31343225 47.67545297

-122.3292887 47.61301188

-122.38363647 47.58881546

-122.28772468 47.52165862

-122.36125713 47.72845012

-122.27852273 47.55891206

# Test Map

Case 1020530 - Application Added as of 12/24/2009	CONSTRUCT	4255 S RAYMOND ST
---	-----------	-------------------

Case 1018836 - Application Added as of 03/26/2009	CONSTRUCT	2822 BOYER AVE E
---	-----------	------------------

Case 1022074 - Notice or Order Issued as of 03/25/2010	HZW	4725 36TH AVE NE
--	-----	------------------

Case 1020869 - Application Added as of 01/11/2010	HZW	4301 34TH AVE W
---	-----	-----------------

Case 1020870 - Application Added as of 10/14/2009	CITATION	4301 34TH AVE W
---	----------	-----------------

Case 1014514 - Application Added as of 12/27/2007	CONSTRUCT	3808 37TH AVE S
---	-----------	-----------------

Case 1021311 - Notice or Order Issued as of 02/19/2010	CONSTRUCT	1827 NE 58TH ST
--	-----------	-----------------

Case 1020184 - Case Resolved as of 05/21/2010	CITATION	5411 26TH AVE SW
---	----------	------------------

# Test Map

RIGHT OF WAY AT TOP OF ECA STEEP SLOPE--  
GRADING EXTENDS ON TO PRIVATE PROPERTY

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1007427>

Constructing an addition to a garage requires permit(s)  
and inspections from DPD. STOP WORK ORDER  
posted 9/9/09.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020530>

HOUSEBOAT IS BUILT PER PLAN--BUT THE  
LOCATION ON THE WEST SIDE APPEARS TO BE  
CLOSER TO THE THE PROPERTY LINE THAN WHAT  
IS SHOWN ON PLANS--HOUSEBOAT CAN BE MOVED

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018836>

Violation of Land Use Code observed.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022074>

Housing violaton.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020869>

NS inspected the property on 10/5/09-Inspection shows  
outdoor junk storage including but not limited to  
mattresses and bags of garbage stored outside right by  
the garbage bins.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020870>

Discharge over rockery and sidewalk not allowed. Permit  
and inspections required for discharge lines that must be  
underground and terminate in a public drain water  
conveyance.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014514>

STOP WORK POSTED--OWNER SAYS HE WILL GET  
PERMITS FOR THE ENTIRE SCOPE OF JOB

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021311>

Violation of Land Use- Parking of vehicles in required  
front yard, and outdoor junk storage.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020184>

# Test Map

-122.27849587	47.54801703
---------------	-------------

-122.31571829	47.64636247
---------------	-------------

-122.28948002	47.66340056
---------------	-------------

-122.40112748	47.65962994
---------------	-------------

-122.40112748	47.65962994
---------------	-------------

-122.28581138	47.56944368
---------------	-------------

-122.30736282	47.67066392
---------------	-------------

-122.36593183	47.55330977
---------------	-------------

# Test Map

Case 1004651 - Application Added as of 03/07/2005      CONSTRUCT      5434 23RD AVE SW

Case 1006914 - Notice or Order Issued as of 03/25/2010      CONSTRUCT      6733 HOLLY PL SW

Case 1021936 - Payment Processed as of 05/20/2010      TRAO      4149 BEACH DR SW

Case 1014117 - Application Added as of 07/21/2008      CONSTRUCT      4126 44TH AVE SW

Case 1014360 - Citation Issued as of 04/14/2009      CITATION      4528 13TH AVE S

Case 1018993 - Application Added as of 04/14/2009      HZW      4528 13TH AVE S

Case 1019269 - Application Added as of 05/14/2009      HZW      10644 RIVIERA PL NE

Case 1016385 - Application Added as of 03/12/2009      HZW      11540 RIVIERA PL NE

Case 1021695 - Notice or Order Issued as of 04/20/2010      HZW      12564 17TH AVE NE

Case 1022142 - Application Added as of 04/02/2010      HZW      3001 21ST AVE S



# Test Map

Violation found: grading more than 25 cubic yards and constructing a new retaining wall in a Steep Slope and Potential Slide ECA (Environmentally Critical Area) requires a permit from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1004651>

Constructing decks & additions, remodeling a garage and SFR requires permits and inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1006914>

Application for a Tenant Relocation License. Total units:2; total units occupied:2. Demolition.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021936>

Permit 6162333 was issued 11/29/07 for work originally started without permits & inspections. This case will remain open until all required inspections have been called for & obtained.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014117>

JR inspected the property and documented zoning violations.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014360>

JR inspected the property and documented zoning violations.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018993>

Application a violation of 23.90.002.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019269>

Extension of finger pier to shoreline & replacement of pier decking w/ PT wood

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016385>

HBMC Violations

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021695>

The use as a Bible Study Outreach Ministries is not the established use.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022142>

# Test Map

-122.36152107	47.55269479
---------------	-------------

-122.39103336	47.54214577
---------------	-------------

-122.40883688	47.56609372
---------------	-------------

-122.38777598	47.56571729
---------------	-------------

-122.31578305	47.56262048
---------------	-------------

-122.31578305	47.56262048
---------------	-------------

-122.27506667	47.70688093
---------------	-------------

-122.27740263	47.71443477
---------------	-------------

-122.31050982	47.72132205
---------------	-------------

-122.30567621	47.57684646
---------------	-------------

# Test Map

Case 1016428 - Application Added as of 12/29/2008	HZW	6530 15TH AVE NE
Case 1010990 - Application Added as of 02/06/2007	CONSTRUCT	3312 SW ADMIRAL WAY
Case 1021421 - Application Added as of 12/28/2009	CITATION	3920 27TH AVE S
Case 1005560 - Application Added as of 06/16/2005	CONSTRUCT	710 29TH AVE S
Case 1015824 - Application Added as of 06/10/2008	CONSTRUCT	4317 SW DAWSON ST
Case 1006637 - Application Added as of 10/20/2005	CONSTRUCT	5410 20TH AVE S
Case 1022413 - Application Added as of 05/11/2010	CITATION	4546 DELRIDGE WAY SW
Case 1022378 - Application Added as of 04/29/2010	CITATION	7308 44TH AVE SW

# Test Map

HBMC violations. No electrical service to residence

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016428>

Eaves in north side yard need to be cut back to what is allowed by Permit 6101655. Chimney/flue in north side yard setback, deck on top of roof and height are per approved plan.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010990>

original address incorrect; occupied group home with no violations, picture in file. Amended address has locked gates so access is limited to the alley, pictures in file of junk storage.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021421>

Violation found: constructing retaining wall not included in approved drawings for either Permit 741800 or 741249 and Temporary Erosion & Sedimentation Control (TESC) is not per permit.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1005560>

Converting a garage into habitable space requires zoning plan review and, if approved, permits & inspections from DPD. Permit 6065509 needs renewal & all req'd inspections. STOP WORK ORDER posted 5/7/08.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015824>

Enclosing a carport/garage requires a permit from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1006637>

Violation of Weeds & Vegetation Ord-

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022413>

4/27/10 ej-Vegetation overgrowing onto the sidewalk.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022378>

# Test Map

-122.31166222	47.67673131
---------------	-------------

-122.37456675	47.57600203
---------------	-------------

-122.29750272	47.56880853
---------------	-------------

-122.29466437	47.59626279
---------------	-------------

-122.38781538	47.55625492
---------------	-------------

-122.307056	47.55367236
-------------	-------------

-122.36265545	47.56153233
---------------	-------------

-122.38790515	47.53797912
---------------	-------------

# Test Map

Case 1022389 - Application Added as of 04/30/2010	CITATION	907 NW MARKET ST
---	----------	------------------

Case 1021708 - Notice or Order Issued as of 03/16/2010	HZW	918 2ND AVE W
--	-----	---------------

Case 1022161 - Application Added as of 04/05/2010	HZW	3624 28TH AVE W
---	-----	-----------------

Case 1021028 - Case Resolved as of 05/21/2010	CITATION	4607 SW THISTLE ST
---	----------	--------------------

Case 1022167 - Citation Issued as of 05/14/2010	CITATION	2160 S PEARL ST
---	----------	-----------------

Case 1019477 - Notice or Order Issued as of 02/09/2010	CONSTRUCT	6018 36TH AVE SW
--	-----------	------------------

Case 1016806 - Application Added as of 10/02/2009	HZW	1529 9TH AVE
---	-----	--------------

Case 1019997 - Case Resolved as of 05/21/2010	HZW	3612 LEARY WAY NW
---	-----	-------------------

Case 1020637 - Notice or Order Issued as of 12/29/2009	HZW	3612 LEARY WAY NW
--	-----	-------------------

# Test Map

Zoning violation.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022389>

3 built-in garages open to entry, pictures in file.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021708>

3/22/10 KB inspected property and HBMC violations exist

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022161>

10/30/09 ej- inspection shows outdoor storage such as but not limited to bags of garbage, inoperable vehicles and other miscellaneous items. Cars parked in the required front yard.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021028>

04/02/10 bg - Vegetation overgrown over the sidewalk along Beacon Ave S. photos taken.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022167>

Connecting the garage to the house to create rooftop deck requires zoning approval and, if approved, permit & inspections from DPD. STOP WORK ORDER posted 6/1/09.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019477>

NS inspected the property on 7/28/08- Inspection shows that the vacant property is being used as a parking lot. The use has not been established.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016806>

EO restore, lack of heat 1st & 2nd floors

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019997>

1.Built 1906 as single family, 2 story dwelling with 2 rms 1st fl & 3 rms on 2nd fl & 1 toilet per KC Archives.  
2.Current permit: #29914 finalized 10/24/68 to "Occupy existing dwelling as WAREHOUSE for insulation

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020637>

# Test Map

-122.36907318	47.6684143
---------------	------------

-122.35894158	47.62729828
---------------	-------------

-122.39251852	47.65304178
---------------	-------------

-122.39194452	47.52834881
---------------	-------------

-122.3037862	47.55552313
--------------	-------------

-122.3774121	47.54779859
--------------	-------------

-122.33223068	47.61323898
---------------	-------------

-122.35937894	47.65375648
---------------	-------------

-122.35937894	47.65375648
---------------	-------------



# Test Map

Case 1021642 - Application Added as of 01/27/2010	CITATION	114 PIKE ST
---	----------	-------------

Case 1015835 - Application Added as of 03/26/2009	CONSTRUCT	220 4TH AVE S
---	-----------	---------------

Case 1021628 - Application Added as of 01/27/2010	HZW	4212 36TH AVE S
---	-----	-----------------

Case 1011574 - Citation Issued as of 12/28/2009	CITATION	6515 16TH AVE NE
---	----------	------------------

Case 1015305 - Application Added as of 06/19/2009	HZW	6515 16TH AVE NE
---	-----	------------------

Case 1015371 - Citation Issued as of 03/26/2009	CITATION	6515 16TH AVE NE
---	----------	------------------

Case 1022460 - Application Added as of 05/10/2010	CITATION	7400 32ND AVE NW
---	----------	------------------

Case 1005022 - Application Added as of 04/25/2005	CONSTRUCT	3553 SW OCEAN VIEW DR
---	-----------	-----------------------

# Test Map

materials". 3. Property now used as duplex, Unit 101 on 1st floor & Unit 201 on 2nd and 3rd floors with numerous Housing code violations.

1/7/10 JS Received call contractor was making exterior construction noise last night. Issued a written warning to work within the permitted hours for construction stated in the Master Use Permit. Informed contractor the consequences of working outside the permitted hours would be large fines or a Stop Work Order. Contractor said he will bring project into noise compliance.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021642>

Permit 6180817 was issued 5/13/08 for remodeling a night club without permits. This case will remain open until all required inspections have been requested & approved.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015835>

01/26/10 bg - HBMC violations in Unit A. photos taken

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021628>

parking of vehicle in the required front yard which is not allowed

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1011574>

Ant infestation observed along with many HBMC violations.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015305>

old windows, scrap material and inoperable vehicle stored in rear yard.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015371>

Weeds and vegetation violation.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022460>

Violation of the Seattle Electrical Code: work requires a

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=>

# Test Map

-122.33954786	47.60934944
---------------	-------------

-122.32881261	47.60016714
---------------	-------------

-122.28702963	47.56499142
---------------	-------------

-122.31117179	47.67629612
---------------	-------------

-122.31117179	47.67629612
---------------	-------------

-122.31117179	47.67629612
---------------	-------------

-122.39812942	47.68249566
---------------	-------------

-122.37766026	47.50146773
---------------	-------------

# Test Map

Case 1020131 - Case Resolved as of 04/16/2010	CITATION	14004 3RD AVE NW
---	----------	------------------

Case 1005496 - Application Added as of 05/06/2010	CONSTRUCT	3657 44TH AVE SW
---	-----------	------------------

Case 1020370 - Application Added as of 08/24/2009	CONSTRUCT	2715 23RD AVE S
---	-----------	-----------------

Case 1020154 - Notice or Order Issued as of 02/05/2010	CONSTRUCT	9234 39TH AVE S
--	-----------	-----------------

Case 1015768 - Application Added as of 05/07/2008	CONSTRUCT	6532 DELRIDGE WAY SW
---	-----------	----------------------

Case 1012992 - Application Added as of 04/13/2009	HZW	6249 FLORA AVE S
---	-----	------------------

Case 1021445 - Application Added as of 12/30/2009	CONSTRUCT	8400 ISLAND DR S
---	-----------	------------------

Case 1022090 - Application Added as of 05/19/2010	CITATION	911 BELMONT AVE E
---	----------	-------------------

# Test Map

permit from DPD. Stop Work Order posted 4/22/05.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1005022>

Bldg. secure; veg. overgrowth in yard, overhanging & encroaching into the street blocking driver's view of the stop sign; pictures in file.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020131>

Violation found: structure larger than 120 sq. ft. in rear yard requires permit. Also, there were never any building inspections done for Permit 652078 (should re-establish permit and call for inspections).

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1005496>

Side sewer permit & inspections required for work being performed. A Registered Side Sewer Contractor must perform all work in the R-O-W. STOP WORK ORDER issued 8/21/09.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020370>

Permit 6224597 was issued 10/23/09 for work originally started without a permit. This case will remain open until all required inspections have been requested and approved by DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020154>

Shoring & Temporary Erosion & Sedimentation Control (TESC) not per Permit 6131864.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015768>

Violation of Land Use-

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1012992>

Installing two thousand square feet or more of new plus replaced impervious surface requires a grading permit and inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021445>

Pampas grass over the sidewalk.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=>

# Test Map

-122.3604835	47.73073471
--------------	-------------

-122.38844343	47.57037797
---------------	-------------

-122.30361202	47.57864057
---------------	-------------

-122.28338808	47.52043334
---------------	-------------

-122.36093835	47.54352172
---------------	-------------

-122.31986371	47.54603444
---------------	-------------

-122.26138468	47.52873195
---------------	-------------

-122.32584935	47.62673602
---------------	-------------

# Test Map

Case 1015766 - Application Added as of 05/07/2008	CONSTRUCT	4807 47TH AVE S
Case 1021879 - Citation Issued as of 04/21/2010	CITATION	1000 NE 105TH ST
Case 1013053 - Application Added as of 12/14/2007	CONSTRUCT	8348 27TH AVE NW
Case 1010885 - Application Added as of 01/24/2007	CONSTRUCT	4620 15TH AVE S
Case 1010875 - Application Added as of 01/24/2007	CONSTRUCT	4620 15TH AVE S
Case 1010859 - Application Added as of 07/02/2009	ADVISORY	3017 NE 140TH ST
Case 1010860 - Application Added as of 02/04/2010	ADVISORY	3021 NE 140TH ST
Case 1015767 - Application Added as of 05/07/2008	CONSTRUCT	4809 47TH AVE S
Case 1014689 - Application Added as of 09/18/2008	CONSTRUCT	2721 14TH AVE S

# Test Map

	1022090
Temporary Erosion & Sedimentation Control is not per Permit 6061866.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015766">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015766</a>
Land Use Code Violation	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021879">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021879</a>
PERMIT IS REQUIRED FOR RECONSTRUCTING DETACHED GARAGE (PREVIOUS GARAGE HAS BEEN DEMOLISHED)	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1013053">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1013053</a>
Deck requires permit and inspections from DPD.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010885">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010885</a>
Tiered keystone block retaining wall requires a permit and all required inspections from DPD. Temporary Erosion & Sedimentation Control (TESC) measures required including: covering ruts in sidewalk area w/gravel, covering bare soil in flat area w/ straw and covering piled soil w/ plastic.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010875">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010875</a>
Condo conversion	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010859">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010859</a>
Condo conversion	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010860">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010860</a>
Temporary Erosion & Sedimentation Control (TESC) not per Permit 6130989.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015767">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015767</a>
Retaining wall along alley and sidewalk is not per Permit 6139219. Revised plans need to be submitted to and	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014689">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014689</a>



# Test Map

-122.27470568	47.55909521
---------------	-------------

-122.3175063	47.70512149
--------------	-------------

-122.39061276	47.69043554
---------------	-------------

-122.31313181	47.56098965
---------------	-------------

-122.31313181	47.56098965
---------------	-------------

-122.29563539	47.72990468
---------------	-------------

-122.29546708	47.72991029
---------------	-------------

-122.27469136	47.55901109
---------------	-------------

-122.31486127	47.57884935
---------------	-------------

# Test Map

Case 1014886 - Application Added as of 02/11/2008      CONSTRUCT      4030 BEACH DR SW

Case 1018368 - Application Added as of 05/28/2009      HZW      3317 NE 135TH ST

Case 1011454 - Application Added as of 03/23/2007      TRAO      1019 CALIFORNIA LN SW

Case 1016898 - Application Added as of 03/23/2009      HZW      1306 NE 65TH ST

Case 1017074 - Application Added as of 03/23/2009      CITATION      1306 NE 65TH ST

Case 1019302 - Citation Issued as of 12/02/2009      CITATION      8610 DELRIDGE WAY SW

Case 1020133 - Application Added as of 12/01/2009      CITATION      8610 DELRIDGE WAY SW

Case 1022275 - Application Added as of 04/20/2010      CONSTRUCT      837 NE 59TH ST

# Test Map

approved by DPD prior to final approval of Permit 6139219.

1014689

Constructing a new foundation for garage with minor structural repairs & performing interior alterations requires permits and inspections from DPD. Constructing a retaining wall & a fountain in the R-O-W requires SDOT approval. STOP WORK ORDER posted 2/7/08.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014886>

Violation of City of Seattle Municipal Code Section 22.206.260 for failure to pay relocation assistance pursuant to an Emergency Order to Vacate and Close

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018368>

Application for a Tenant Relocation License. Total units: 2; Total units occupied: 2. Demolition.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1011454>

Observed numerous HBMC violations including no smoke detector and no cover on the service panel/fuse box

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016898>

Observed numerous HBMC violations including no smoke detector and no cover on the service panel/fuse box. Inoperable vehicles/auto parts in rear yard. Junk storage.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017074>

Bldg. secure with no VB violations. Minor outdoor stg. & veg. overgrowth.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019302>

Veg. overgrowth in all yard areas & overhanging & encroaching onto the public sidewalk, pictures in file..

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020133>

PERMIT REQUIRED FOR COVERED DECK IN REAR YARD

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022275>

# Test Map

-122.40923649	47.56764523
---------------	-------------

-122.29147513	47.72627524
---------------	-------------

-122.3873685	47.59385973
--------------	-------------

-122.31399214	47.67598127
---------------	-------------

-122.31399214	47.67598127
---------------	-------------

-122.36017746	47.52615373
---------------	-------------

-122.36017746	47.52615373
---------------	-------------

-122.31849972	47.67131518
---------------	-------------

# Test Map

Case 1021579 - Notice or Order Issued as of 01/22/2010	CONSTRUCT	4434 46TH AVE S
Case 1009086 - Application Added as of 07/25/2006	TRA0	10112 4TH AVE NW
Case 1016136 - Application Added as of 06/10/2008	CONSTRUCT	4136 21ST AVE SW
Case 1021301 - Application Added as of 12/09/2009	CITATION	3638 BEACH DR SW
Case 1021302 - Application Added as of 12/10/2009	CITATION	3638 BEACH DR SW
Case 1022054 - Application Added as of 03/22/2010	CONSTRUCT	5106 51ST AVE S
Case 1022197 - Application Added as of 04/07/2010	CONSTRUCT	5106 51ST AVE S
Case 1018722 - Application Added as of 03/12/2009	CONSTRUCT	3217 BEACON AVE S

# Test Map

Deck and addition/shed in side yard require zoning approval, permits and inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021579>

Application for a Tenant Relocation License

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1009086>

Grading (raising the grade approximately 8') not per Permit 6139007.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016136>

1/8/09 DG Just received complaint today. Not sure who had this on their desk. I called the complainant and left a message on their VM. I will do an inspection today.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021301>

1/8/09 DG Just received complaint today. Not sure who had this on their desk. I called the complainant and left a message on their VM. I will do an inspection today.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021302>

Cutting an exceptional tree requires approval from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022054>

Remdeling a SFR including (but not limited to) new bathrooms, kitchen, new plumbing & electrical systems, floor joist replacement, new roof sheeting, repair and renovation of N & E exterior decks requires permits & inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022197>

Structural Engineer's evaluation of water damaged floor structure required (Lucky Seafood). Floor repair and replacement of plaster/gypsum fire membrane at basement requires permit & inspections (Lucky Seafood). Repair/upgrade of hanging corroded electrical wiring requires permit & inspections (Lucky Seafood).

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018722>

Sign Permit 6127263 required inspections need to be

# Test Map

-122.27544656	47.56306595
---------------	-------------

-122.36154444	47.70289142
---------------	-------------

-122.35990919	47.56552881
---------------	-------------

-122.41153787	47.57166396
---------------	-------------

-122.41153787	47.57166396
---------------	-------------

-122.26958714	47.5560317
---------------	------------

-122.26958714	47.5560317
---------------	------------

-122.30928162	47.57450381
---------------	-------------

# Test Map

Case 1011419 - Application Added as of 05/06/2010      CONSTRUCT      4213 S BRANDON ST

Case 1017059 - Application Added as of 08/20/2008      HZW      2369 FAIRVIEW AVE E

Case 1020965 - Citation Issued as of 05/04/2010      CITATION      9841 44TH AVE SW

Case 1019073 - Application Added as of 05/19/2009      CONSTRUCT      2310 SW ALASKA ST

Case 1016489 - Application Added as of 01/06/2009      CONSTRUCT      4435 S CAMANO PL

Case 1015763 - Application Added as of 07/08/2008      UNFIT      1653 EDGEWOOD AVE SW

Case 1010888 - Application Accepted as of 08/21/2009      ADVISORY      7901 DELRIDGE WAY SW

Case 1012327 - Application Added as of 06/07/2007      CONSTRUCT      1621 12TH AVE



# Test Map

Sign Permit 6127263 required inspections need to be requested & approved (Galaxie).

Deck in required front yard needs a permit with land use review and all required inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1011419>

Unauthorized accessory float, floating home unit #7 (no floating home present)

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017059>

10/26/09 ej- Inspection shows storage shed built in the required front yard.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020965>

Removing vegetation on a site mapped as a Potential Slide Environmentally Critical Area requires a approval & inspections from DPD. Temporary Erosion & Sedimentation Control (TESC) is not per code. STOP WORK ORDER posted 4/17/09.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019073>

Permit 6189209 was issued 10/28/08 for work originally started without permits and inspections. This case will remain open until all required inspections have been requested and approved.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016489>

ABATEMENT INSPECTION REQUEST

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015763>

Condo Conversion.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010888>

A Certificate of Occupancy (C of O) has never been issued for Permit 737123. A new permit must be applied for & issued, all inspections approved & C of O obtained or assembly occupancy discontinued.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1012327>

# Test Map

-122.28009586	47.5532274
---------------	------------

-122.33005185	47.64173046
---------------	-------------

-122.38893472	47.51447294
---------------	-------------

-122.36195234	47.56132009
---------------	-------------

-122.2765376	47.52731988
--------------	-------------

-122.38373145	47.58825196
---------------	-------------

-122.36076205	47.53143808
---------------	-------------

-122.31725295	47.61590313
---------------	-------------

# Test Map

Case 1004973 - Application Added as of 04/22/2005      CONSTRUCT      2901 3RD AVE

Case 1021410 - Application Added as of 12/24/2009      HZW      4524 7TH AVE NE

Case 1018823 - Application Added as of 03/24/2009      CONSTRUCT      667 S KING ST

Case 1013141 - Application Added as of 06/09/2008      CONSTRUCT      1509 BROADWAY

Case 1022112 - Application Added as of 03/27/2010      CITATION      13550 AURORA AVE N

Case 1009443 - Application Added as of 12/05/2006      CONSTRUCT      419 LAKESIDE AVE S

Case 1022457 - Application Added as of 05/10/2010      CITATION      6708 DIVISION AVE NW

Case 1016312 - Application Added as of 01/21/2010      HZW      7919 8TH AVE S

# Test Map

Violation of the Seattle Building Code found: interior demo work on 5th floor south side of building and upcoming tenant improvements require a permit from DPD. Contractor and superintendent notified of allowed construction hours. Stop Work Order posted 4/21/05.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1004973>

Failure to pay emergency relocation assistance pursuant to SMC 22.206.260.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021410>

Installing vinyl windows in a building located in the International Special Review District (ISRD) requires approval from the ISRD Board. STOP WORK ORDER posted 3/19/09.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018823>

Building permit & inspections required from DPD to construct mezzanine, stage, rebuild stairs & change portion from storage to retail in Atlas Clothing Company (1515 Broadway).

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1013141>

3/17/10 JS

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022112>

Permit and inspections required for major interior demolition and remodel. Stop Work Order posted 8/21/06 and 10/24/06. This case will remain open until all required permits and inspections are obtained.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1009443>

Zoning violation.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022457>

VIOLATION ALERT Inspection shows outdoor storage such as but not limited to containers and vehicles of Independent Metals.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016312>

# Test Map

-122.35200139      47.61819997

-122.32044574      47.6620956

-122.32395629      47.59796508

-122.32120582      47.61440757

-122.3421428      47.72802807

-122.28714679      47.59842772

-122.36636048      47.67805546

-122.32307674      47.53137628

# Test Map

Case 1012493 - Application Added as of 06/19/2007	CONSTRUCT	4415 S ANGELINE ST
Case 1022397 - Application Added as of 05/06/2010	HZW	1411 S CONCORD ST
Case 1022421 - Application Added as of 05/04/2010	HZW	1411 S CONCORD ST
Case 1017684 - Application Added as of 02/03/2010	HZW	816 NW MARKET ST
Case 1020318 - Case Resolved as of 05/21/2010	CITATION	928 N 88TH ST
Case 1020578 - Citation Issued as of 01/13/2010	CITATION	3840 LINDEN AVE N
Case 1021549 - Application Added as of 01/13/2010	CITATION	10461 57TH AVE S
Case 1021399 - Case Resolved as of 04/15/2010	CITATION	7721 15TH AVE NE
Case 1007408 - Application Added as of 02/02/2006	CONSTRUCT	10601 31ST AVE SW
Case 1010412 - Application Added as of 11/30/2006	CONSTRUCT	5038 29TH AVE S

# Test Map

Building permit (w/ zoning approval) and inspections required by DPD for addition to single family residence in apparent required yard.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1012493>

4/28/10 ej-Inspection shows housing code violation such as but not limited to broken wall covering, outdoor junk storage, unsecured entry gate and other code violations.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022397>

4/28/10 ej-Inspection shows housing code violation such as but not limited to broken wall covering, outdoor junk storage, unsecured entry gate and other code violations.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022421>

sfr illegal use

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017684>

Junk storage outdoors- sfr

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020318>

junk storage, L-1 zone

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020578>

outdoor storage, pictures in file.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021549>

Violation of Land Use Code observed.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021399>

RETAINING WALL IN ECA REQUIRES PERMIT

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1007408>

Addition and remodel requires all permits and inspections from DPD. Stop Work Order posted 11/29/06. Per Bob Berg restoration of roof to original configuration will require permit(s) and inspections from

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010412>

# Test Map

-122.2775031	47.5591843
--------------	------------

-122.31434897	47.5236556
---------------	------------

-122.31434897	47.5236556
---------------	------------

-122.36706221	47.66890984
---------------	-------------

-122.34593968	47.69293065
---------------	-------------

-122.34827807	47.65397924
---------------	-------------

-122.26155754	47.50651968
---------------	-------------

-122.31243169	47.68555955
---------------	-------------

-122.37245507	47.50802654
---------------	-------------

-122.29543059	47.55623056
---------------	-------------



# Test Map

Case 1013734 - Application Added as of 10/10/2007      CONSTRUCT      3316 S GRAHAM ST

Case 1017677 - Application Added as of 05/05/2010      CONSTRUCT      9236 31ST AVE SW

Case 1010675 - Application Added as of 12/27/2006      CONSTRUCT      4229 S WILLOW ST

Case 1009918 - Application Added as of 10/05/2006      CONSTRUCT      5222 35TH AVE S

Case 1006469 - Application Added as of 10/03/2005      CONSTRUCT      9014 21ST AVE SW

Case 1022213 - Application Accepted as of 05/20/2010      TRAO      210 WALL ST

# Test Map

configuration will require permit(s) and inspections from DPD.

Grading/fill requires permit & inspections. Temporary Erosion & Sedimentation Control (TESC) required immediately. Foundation, structural, framing & insulation inspections required for Permit 6098353.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1013734>

Permit 6199610 issued 10/31/08 for SOME of the work performed w/o permits/inspections. This case will remain open until all permits (including turning garage into habitable space & removing parking) have been issued and all required inspections have been requested and approved.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017677>

Side sewer permit and inspections required for repair to sewer/storm piping. TESC (Temporary Erosion & Sedimentation Control) measures not adequate: clean sidewalk and gutter of all silt and soil and cover bare soil with plastic sheeting.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010675>

Temporary Erosion & Sedimentation Control (TESC) is not per approved plan for Permit 752528. No work to take place until dirt cleaned from street, parking strip and sidewalk AND bare soil in yards and planting strips covered with mulch AND site protected from water run-off.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1009918>

Grading more than 100 cubic yards requires a permit from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1006469>

Application for a Tenant Relocation License. Total units:272; total units occupied:244. Demolition.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=>

# Test Map

-122.28952303      47.54633446

-122.37210473      47.52001461

-122.27910823      47.54051079

-122.28911345      47.5543968

-122.36022663      47.52238086

-122.34789377      47.61573965

# Test Map

05/20/2010

Case 1019148 - Application Added as of 04/30/2009      CONSTRUCT      4700 OHIO AVE S

Case 1020667 - Application Added as of 04/30/2010      HZW      6053 3RD AVE NW

Case 1018369 - Case Resolved as of 05/21/2010      CITATION      9046 11TH AVE SW

Case 1021038 - Case Opened as of 11/10/2009      CONSTRUCT      2466 WESTLAKE AVE N

Case 1019145 - Application Added as of 07/02/2009      HZW      2466 WESTLAKE AVE N

Case 1021511 - Application Added as of 01/14/2010      HZW      2466 WESTLAKE AVE N

Case 1022503 - Application Added as of 05/14/2010      HZW      3208 CLAREMONT AVE S

Case 1004213 - Application Added as of 07/27/2009      CONSTRUCT      6032 44TH AVE SW

Case 1009657 - Application Added as of 09/12/2006      CONSTRUCT      6032 44TH AVE SW

# Test Map

units:272; total units occupied:244. Demolition.	<a href="#">1022213</a>
Performing electrical work, covering and energizing electrical work in Suite C requires permit(s), and all required inspections with final approval from DPD.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019148">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019148</a>
NS inspected the property on 9/21/09-Housing violation.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020667">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020667</a>
Inspection shows fence exceeds the allowed height (6) for solid fence.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018369">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018369</a>
REVISED PLANS FOR PERMIT #6117998 MUST BE SUBMITTED SHOWING THE ACTUAL SIZE OF FLOAT	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021038">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021038</a>
Unauthorized non-water-dependent commercial use over water in storage area of legally nonconforming covered moorage.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019145">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019145</a>
Grossruck floating structure. Use for the Record inspection NOV requirement. DPD project # 6193296.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021511">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021511</a>
04/29/10 bg - Outdoor junk storage, approx 11 vehicles. Property w/in Light Rail Station Area Overlay photos taken	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022503">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022503</a>
Violation of the Seattle Building Code found: work is not per Permit 694088. Permit needs to be re-established and revised to show work performed (including lot coverage calculations).	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1004213">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1004213</a>
Demolition requires a permit from DPD.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1009657">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1009657</a>

# Test Map

-122.33783784	47.56021678
---------------	-------------

-122.36104388	47.67387316
---------------	-------------

-122.3490084	47.52146097
--------------	-------------

-122.34179846	47.64121348
---------------	-------------

-122.34179846	47.64121348
---------------	-------------

-122.34179846	47.64121348
---------------	-------------

-122.29632679	47.57437781
---------------	-------------

-122.3882808	47.54753574
--------------	-------------

-122.3882808	47.54753574
--------------	-------------

# Test Map

Case 1020987 - Notice or Order Issued as of 01/26/2010	CONSTRUCT	901 OCCIDENTAL AVE S
--	-----------	----------------------

Case 1017355 - Case Opened as of 01/28/2010	CONSTRUCT	901 OCCIDENTAL AVE S
---	-----------	----------------------

Case 1021535 - Application Added as of 04/01/2010	HZW	3312 RAINIER AVE S
---	-----	--------------------

Case 1021571 - Notice or Order Issued as of 03/05/2010	CONSTRUCT	3312 RAINIER AVE S
--	-----------	--------------------

Case 1022169 - Application Added as of 04/06/2010	HZW	3312 RAINIER AVE S
---	-----	--------------------

Case 1020202 - Citation Issued as of 05/06/2010	CITATION	201 15TH AVE
---	----------	--------------

Case 1019867 - Case Resolved as of 05/06/2010	CITATION	3506 S ADAMS ST
---	----------	-----------------

Case 1010964 - Application Added as of 02/01/2007	CONSTRUCT	4704 S MEAD ST
---	-----------	----------------

# Test Map

CERTIFICATE OF APPROVAL HAS BEEN DENIED BY THE PIONEER SQUARE PRESERVATION BOARD-- SO SIGN MUST BE REMOVED FROM NORTH WALL OF BUILDING

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020987>

OFF-PREMISE ADVERTISING IS NOT ALLOWED-- SIGN MUST BE REMOVED

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017355>

01/12/10 bg - Outdoor storage of junk including but not limited to bed frame, wood/construction debris. photos taken

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021535>

Remodeling a commercial building (interior & exterior) requires permits and inspections from DPD. STOP WORK ORDER posted 1/19/10.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021571>

04/02/10 - Three businesses on site, CD sales, Car wash/detailing and a recording studio. Established use is for retail sales in the front section of the building - these businesses are in the rear. Property within Station Area Overlay District.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022169>

Violation of the Land Use & Zoning Code

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020202>

07/02/09 bg - 6 vehicles in the required front yard one in the sideyard along with a recreational vehicle that appears occupied. Junk storage on site. Photos taken

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019867>

CONTINUATION OF PTS CASE #2023902-- ADDITIONS ARE NOT PER PLAN FOR PERMITS #677642 AND #686488--NO FINAL APPROVAL AND NO CERTIFICATE OF OCCUPANCY

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010964>



# Test Map

-122.33367802	47.59485771
---------------	-------------

-122.33367802	47.59485771
---------------	-------------

-122.29432352	47.57365536
---------------	-------------

-122.29432352	47.57365536
---------------	-------------

-122.29432352	47.57365536
---------------	-------------

-122.31313281	47.60364908
---------------	-------------

-122.28939866	47.56570928
---------------	-------------

-122.27384326	47.55060289
---------------	-------------

# Test Map

Case 1020883 - Notice or Order Issued as of 01/13/2010	CONSTRUCT	2703 W MCGRAW ST
--	-----------	------------------

Case 1020509 - Application Added as of 09/04/2009	CONSTRUCT	2703 W MCGRAW ST
---	-----------	------------------

Case 1011939 - Application Accepted as of 04/15/2009	ADVISORY	3430 RENTON PL S
--	----------	------------------

Case 1014907 - Application Added as of 02/11/2008	CONSTRUCT	6224 51ST PL S
---	-----------	----------------

Case 1011925 - Application Added as of 11/05/2007	CONSTRUCT	5320 SW LANDER ST
---	-----------	-------------------

Case 1014929 - Payment Processed as of 05/13/2008	TRAO	1026 NE 125TH ST
---	------	------------------

Case 1011371 - Case Resolved as of 01/05/2010	CITATION	5508 20TH AVE S
---	----------	-----------------

Case 1015832 - Application Added as of 05/14/2008	CONSTRUCT	4237 RAINIER AVE S
---	-----------	--------------------

Case 1009633 - Application Added as of 09/11/2006	CONSTRUCT	4223 S JUNEAU ST
---	-----------	------------------

# Test Map

SECOND STORY ADDITION ON GARAGE REQUIRES A VALID PERMIT

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020883>

STFI PERMIT 6221789 IS SUSPENDED--PLANS MUST BE SUBMITTED

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020509>

Condo Conversion.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1011939>

Temporary Erosion & Sedimentation Control (TESC) is not per Permit 753398. Stockpiles need to be covered, silt fencing needs to be installed and dirt cleaned up from adjacent streets.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014907>

Permits 6138712 & 6138131 issued for work started w/o permit. Permit(s) & inspections still req'd for 1st & 2nd floor remodel. This case will remain open until all inspections called for & obtained.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1011925>

Application for a Tenant Relocation License. Total units: 11; total units occupied 11. Demolition.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014929>

Inspection shows outdoor junk storage such as but not limited to racks, bikes, bags, bathtub and other misc. items. Zoning violation

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1011371>

Grading adjacent to alley requires a permit with a proposed stabilization plan to DPD by 5/28/08. Emergency permitting needed for protection of alley per Bob Berg.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015832>

Permit 6112286 issued September 12, 2006, for work originally performed without a permit. This case will not

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1009633>

# Test Map

-122.39201464	47.63986368
---------------	-------------

-122.39201464	47.63986368
---------------	-------------

-122.29631083	47.57255374
---------------	-------------

-122.26764775	47.54682663
---------------	-------------

-122.40105416	47.57933538
---------------	-------------

-122.31699026	47.719756
---------------	-----------

-122.30687592	47.55314395
---------------	-------------

-122.28866231	47.56451109
---------------	-------------

-122.2797654	47.54955163
--------------	-------------

# Test Map

Case 1016037 - Application Added as of 06/03/2008	CONSTRUCT	503 31ST AVE
Case 1012502 - Application Added as of 06/19/2007	CONSTRUCT	503 31ST AVE
Case 1010708 - Application Added as of 01/02/2007	CONSTRUCT	9303 36TH AVE S
Case 1014309 - Application Added as of 03/20/2008	CONSTRUCT	3092 ALKI AVE SW
Case 1013190 - Application Added as of 08/20/2007	CONSTRUCT	9847 RAINIER AVE S
Case 1017653 - Citation Issued as of 01/20/2010	CITATION	10448 35TH AVE SW
Case 1017551 - Application Added as of 12/04/2009	HZW	3047 SW AVALON WAY
Case 1010325 - Notice or Order Issued as of 04/06/2010	CONSTRUCT	2901 23RD AVE S

# Test Map

be closed until the final inspection has been approved.

Constructing decks more than 18" above grade at both ends of a home requires permits & inspections from DPD. Permits 6128470, 6141844, 6143115 & 6148558 all require final approvals/inspections.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016037>

Interior remodel requires permit(s) and inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1012502>

Permit required for grading (adding fill) more than 25 cu.yds. in a Steep Slope ECA (Environmentally Critical Area). Stop Work Order posted 12/29/06.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010708>

Deck in rear yard requires zoning approval, permit & inspections and interior remodel with structural alterations requires permits & inspections from DPD. STOP WORK ORDER posted 11/30/07.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014309>

Grading and constructing retaining walls in Steep Slope and Potential Slide ECAs requires permit and inspections from DPD. STOP WORK ORDER posted 8/16/07.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1013190>

09/26/08 KB inspected property and Land Use violation exists-parking in yard, # of vehicles

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017653>

Housing violations: unit 301 several violations.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017551>

Permit 6120293 was issued 2/26/08 for work originally started without a permit. This case will remain open until all required inspections have been requested and approved.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010325>

# Test Map

-122.29296255	47.60633816
---------------	-------------

-122.29296255	47.60633816
---------------	-------------

-122.28742395	47.51958142
---------------	-------------

-122.4182814	47.57668243
--------------	-------------

-122.25139126	47.51345964
---------------	-------------

-122.37558927	47.50857194
---------------	-------------

-122.37163289	47.56559927
---------------	-------------

-122.30365524	47.57738238
---------------	-------------

# Test Map

Case 1022063 - Case Opened as of 03/26/2010	HZW	1420 E MADISON ST
---	-----	-------------------

Case 1010896 - Application Added as of 01/25/2007	HZW	2251 NW 59TH ST
---	-----	-----------------

Case 1017670 - Payment Processed as of 12/30/2008	TRAO	2429 8TH AVE N
---	------	----------------

Case 1020593 - Application Added as of 12/08/2009	CONSTRUCT	3017 16TH AVE S
---	-----------	-----------------

Case 1010139 - Case Closed as of 11/07/2006	HZW	1321 14TH AVE S
---	-----	-----------------

Case 1022485 - Application Added as of 05/14/2010	CITATION	6408 SHAFFER AVE S
---	----------	--------------------

Case 1022386 - Application Added as of 04/30/2010	CITATION	7315 JONES AVE NW
---	----------	-------------------

Case 1022388 - Application Added as of 04/30/2010	CITATION	8502 20TH AVE NW
---	----------	------------------

Case 1014711 - Payment Processed as of 03/26/2008	TRAO	304 W LEE ST
---	------	--------------

Case 1014075 - Payment Processed as of 12/23/2009	TRAO	1722 13TH AVE S
---	------	-----------------



# Test Map

approved.

Violation of the Land Use & Zoning Code

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022063>

Duplicate case

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010896>

Application for a Tenant Relocation License. Total units: 1; total units occupied: 1. Demolition.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017670>

Permit 6228008 (3013 16th Ave S) & Permit 6228011 (3017 16th Ave S) were issued 9/23/09 for work originally started without permits (rebuilding portions of shared garage). This case will remain open until all required inspections have been requested and approved.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020593>

Vegetation overgrowth onto sidewalk. Weed and Vegetation Ord. violation.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010139>

zoning-

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022485>

Zoning violation.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022386>

Weeds and vegetation encroaching into the sidewalk.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022388>

Application for a Tenant Relocation License. Total units: 1; Total units occupied: 1. Demolition.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014711>

Application for a Tenant Relocation License. Total units: 8; total units occupied: 0. Demolition.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=>

# Test Map

-122.31333866	47.61445207
---------------	-------------

-122.38679836	47.67144285
---------------	-------------

-122.34339892	47.6404612
---------------	------------

-122.31235485	47.57625856
---------------	-------------

-122.31527013	47.59086931
---------------	-------------

-122.29441912	47.54495485
---------------	-------------

-122.38673692	47.68184706
---------------	-------------

-122.38190348	47.69078574
---------------	-------------

-122.36089268	47.63146299
---------------	-------------

-122.31568295	47.58784234
---------------	-------------

# Test Map

Case 1009401 - Application Added as of 12/12/2006	CONSTRUCT	9105 FAUNTLEROY WAY SW
---	-----------	------------------------

Case 1022364 - Application Added as of 04/29/2010	CITATION	4755 35TH AVE SW
---	----------	------------------

Case 1010165 - Application Added as of 10/25/2006	CONSTRUCT	4350 12TH AVE S
---	-----------	-----------------

Case 1012163 - Payment Processed as of 12/14/2009	TRAO	2600 E CHERRY ST
---	------	------------------

Case 1021909 - Notice or Order Issued as of 05/20/2010	HZW	4746 DELRIDGE WAY SW
--	-----	----------------------

Case 1010986 - Application Added as of 08/04/2009	CONSTRUCT	4701 BEACH DR SW
---	-----------	------------------

Case 1011203 - Case Opened as of 12/21/2007	CONSTRUCT	121 LAKESIDE AVE
---	-----------	------------------

Case 1011992 - Application Added as of 10/15/2009	HZW	121 LAKESIDE AVE
---	-----	------------------

# Test Map

8; total units occupied: 0. Demolition.

1014075

Grading in an ECA 3 (Riparian Corridor) requires a permit from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1009401>

Violation of Weeds & Veg Ordinance

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022364>

Building an addition onto the side of a house requires permits (building and electrical) and inspections from DPD and a plumbing permit. Stop Work Order posted 10/24/06.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010165>

Application for a Tenant Relocation License. Total units: 9; total units occupied: 9. Demolition.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1012163>

Violation of HBMC-

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021909>

Permit 6112979 was applied for on 3/20/08 and issued 3/5/09 for work originally started without a permit. This case will remain open until all required inspections have been requested and approved.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010986>

Pouring 8"-12" of concrete over an existing PT slab (approx. 20' X 20') above a basement parking facility requires a building permit including a review of structural issues by DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1011203>

OBSERVED VIOLATIONS OF THE SEATTLE LAND USE AND ZONING CODE (CHANGE OF USE & CONFIGURATION FROM RETAIL PARKING TO AUTOMOTIVE RETAIL SERVICES).

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1011992>

# Test Map

-122.39364006	47.52272971
---------------	-------------

-122.3765616	47.55939936
--------------	-------------

-122.3169851	47.56381829
--------------	-------------

-122.29868693	47.60816496
---------------	-------------

-122.36251773	47.55974416
---------------	-------------

-122.40415028	47.56088879
---------------	-------------

-122.28543774	47.60238293
---------------	-------------

-122.28543774	47.60238293
---------------	-------------

# Test Map

Case 1020040 - Case Resolved as of 04/16/2010	HZW	1918 10TH AVE W
Case 1014990 - Application Added as of 06/22/2009	CONSTRUCT	2345 NE 104TH WAY
Case 1021435 - Notice or Order Issued as of 05/05/2010	HZW	3601 WALLINGFORD AVE N
Case 1021413 - Application Added as of 01/12/2010	HZW	7408 RAINIER AVE S
Case 1018179 - Citation Issued as of 05/21/2010	CITATION	12755 PHINNEY AVE N
Case 1020528 - Notice or Order Issued as of 02/09/2010	HZW	901 N NORTHLAKE WAY
Case 1013439 - Application Added as of 04/15/2008	CONSTRUCT	5968 BEACH DR SW
Case 1009708 - Application Added as of 01/27/2009	CONSTRUCT	5005 26TH AVE SW
Case 1011179 - Application Added as of 02/26/2009	CONSTRUCT	6343 35TH AVE SW
Case 1018933 - Case Resolved as of 11/30/2009	CITATION	1502 SW HENDERSON ST

# Test Map

Illegal third unit.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020040>

PERMIT IS REQUIRED FOR BOTH DECK AND  
RETAINING WALL OVER 4 FEET TALL--ECA

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014990>

HBMC violations-

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021435>

Violation of Just Cause Eviction Ordinance

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021413>

outdoor junk in sf zone

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018179>

N'lake Wharf configuration altered between 2005 & 2007  
w/o permits. Concrete floats

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020528>

MORE THAN 14 TREES HAVE BEEN REMOVED--NOT  
PER PLAN FOR PROJECT #3006060

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1013439>

Permit 6113680 issued 3/23/07 for work originally started  
without a permit. All required inspections must be  
requested and approved before this case can be closed.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1009708>

Permit 6130379 was issued 2/19/08 for work originally  
started without a permit. This case will remain open untill  
all required inspections have been requested and  
approved.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1011179>

Violation of Land Use- Outdoor junk storage

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018933>

# Test Map

-122.37001817 47.63654494

-122.30245399 47.70412069

-122.33658601 47.65063675

-122.2697573 47.53557039

-122.3544618 47.72302893

-122.34847551 47.6482231

-122.39735768 47.54836629

-122.3658617 47.55722984

-122.37737092 47.54507948

-122.35421438 47.52303196



# Test Map

Case 1015648 - Application Added as of 04/28/2008	CONSTRUCT	3400 S PARKLAND PL
Case 1022281 - Application Added as of 04/21/2010	CITATION	6915 ELLIS AVE S
Case 1014693 - Application Added as of 01/17/2008	CONSTRUCT	5413 FAUNTLEROY WAY SW
Case 1011376 - Application Added as of 03/21/2007	CONSTRUCT	1727 1ST AVE S
Case 1011538 - Payment Processed as of 05/20/2010	TRAO	311 12TH AVE E
Case 1020369 - Case Resolved as of 05/11/2010	CITATION	5232 PULLMAN AVE NE
Case 1022394 - Application Added as of 05/20/2010	CITATION	5032 30TH AVE S
Case 1009353 - Application Accepted as of 04/20/2010	ADVISORY	401 HARVARD AVE E
Case 1016481 - Application Added as of 08/28/2008	CONSTRUCT	3716 55TH AVE SW

# Test Map

Removing/replacing a retaining wall over 5' tall along in a Potential Slide ECA requires a permit and inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015648>

4/2/10-Inspection shows structures build in the required front & side yards.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022281>

The duplex (5411 Fauntleroy Way SW) must be converted to Single Family Residence (SFR) or permit obtained for Accessory Dwelling Unit (ADU) prior to sale of townhouses (5413A & 5413B Fauntleroy Way SW) per MUP 3006379. Permit 6108069 will not be finaled until this is done.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014693>

Electrical and construction work requires permits & inspections from DPD. INSPECTOR TOLD WORKERS TO STOP WORK UNTIL PERMITS ARE ISSUED.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1011376>

Application for Tenant Relocation License. Total units: 4; total units occupied: 2. Substantial rehabilitation.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1011538>

Observed violation of Land Use Code.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020369>

04/30/10 bg - Vegetation encroaching onto 30th Ave S. photos taken

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022394>

Condo conversion

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1009353>

Constructing a storage structure requires zoning approval, building & electrical permits & inspections from DPD. STOP WORK ORDER posted 7/7/08.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016481>

# Test Map

-122.28870877	47.594211
---------------	-----------

-122.32031584	47.54050862
---------------	-------------

-122.38216498	47.55342568
---------------	-------------

-122.33465828	47.58752201
---------------	-------------

-122.31701188	47.62155577
---------------	-------------

-122.27216143	47.67153042
---------------	-------------

-122.29377267	47.55618387
---------------	-------------

-122.32248202	47.62213019
---------------	-------------

-122.40246254	47.57058649
---------------	-------------

# Test Map

Case 1022156 - Application Added as of 04/02/2010	CITATION	1985 GILMAN DR W
Case 1009821 - Application Added as of 09/26/2006	CONSTRUCT	9032 22ND AVE SW
Case 1018041 - Application Added as of 12/11/2008	CONSTRUCT	5931 30TH AVE S
Case 1009328 - Application Added as of 11/06/2006	CONSTRUCT	1200 S BRADFORD ST
Case 1009326 - Application Added as of 11/06/2006	CONSTRUCT	3601 HAHN PL S
Case 1009327 - Application Added as of 11/06/2006	CONSTRUCT	1201 S COURT ST
Case 1021892 - Notice or Order Issued as of 03/04/2010	HZW	7556 12TH AVE NE
Case 1022108 - Case Resolved as of 04/23/2010	HZW	1151 19TH AVE E
Case 1022393 - Application Added as of 04/30/2010	HZW	1151 19TH AVE E
Case 1021871 - Application Added as of 02/26/2010	HZW	1151 19TH AVE E

# Test Map

4/1/10 KB inspected and Weeds violation exists

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022156>

Permit required for covered porch on east side of building (subject to zoning review) from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1009821>

TESC is not per Permits 6108706, 6110065, 6108707, 6117373 & 6095969. Approved plans not on site 12/10/08: unknown at this time if grade changes between properties are per permit.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018041>

Removing approximately 6,300 sq.ft. of vegetation in an ECA 1 (Steep Slope) and ECA 2 (Potential Slide) requires permits/approvals from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1009328>

Removing approximately 17,875 sq.ft. of vegetation in an ECA 1 (Steep Slope) requires permits/approvals from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1009326>

Removing approximately 21,125 sq.ft. of vegetation in an ECA 1 (Steep Slope) and ECA 2 (Potential Slide) requires permits/approvals from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1009327>

Land Use Code Violation

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021892>

The gas has been shut off and there is no heat.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022108>

Failure to pay emergency relocation assistance pursuant to SMC 22.206.260

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022393>

Missing handrails/guardrails, minor electrical issues and basement maintenance issues.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021871>

# Test Map

-122.37244942 47.63752941

-122.36176463 47.521873

-122.29400368 47.54852343

-122.31692146 47.56914729

-122.31697808 47.57144345

-122.31695266 47.57055121

-122.31495901 47.68475025

-122.30750433 47.63016532

-122.30750433 47.63016532

-122.30750433 47.63016532

# Test Map

Case 1020099 - Application Added as of 05/19/2010	HZW	1151 19TH AVE E
Case 1021224 - Notice or Order Issued as of 12/22/2009	CONSTRUCT	9717 PHINNEY AVE N
Case 1011382 - Payment Processed as of 02/19/2009	TRAO	2637 22ND AVE W
Case 1022078 - Application Added as of 03/24/2010	CONSTRUCT	3424 24TH AVE S
Case 1022522 - Application Added as of 05/18/2010	CITATION	3752 SW CLOVERDALE ST
Case 1020648 - Case Resolved as of 04/27/2010	HZW	1425 E YESLER WAY
Case 1020940 - Application Added as of 10/22/2009	CITATION	10231 37TH AVE SW
Case 1015928 - Application Added as of 05/22/2008	CONSTRUCT	1761 14TH AVE S
Case 1013062 - Application Added as of 08/07/2007	CONSTRUCT	5415 31ST AVE S

# Test Map

Missing handrails/guardrails, minor electrical issues and basement maintenance issues.

1021871

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020099>

THE MADRONE IS 29 INCHES IN DIAMETER AND IS AN EXCEPTIONAL TREE--BILL AMES WILL DO APPRAISAL

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021224>

Application for Tenant Relocation License. Total units: 1; total units occupied: 1. Demolition.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1011382>

VEGETATION REMOVAL ON SLOPE EAST OF HOUSE APPEARS TO EXCEED 1500 SQUARE FEET--RESTORATION IS REQUIRED

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022078>

Violation of Weeds & Vegetation Ord-

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022522>

Bldg. open to entry via various windows & the entry door to the lower unit at the rear & other windows in various locations throughout the bldg. A total of 6 windows & 1 unit entry door are unsecured, pictures in file.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020648>

VIOLATIONS OF THE SEATTLE LAND USE AND ZONING CODE OBSERVED9 VEHICLES IN FRONT YARD, MORE THAN THREE VEHICLES IN YARD VEHICLE MISSING TIRES.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020940>

Drainage piped directly onto sidewalk no allowed. Need to revise per DPD Inspector's instructions.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015928>

Cutting all of the trees on a vacant lot with an unmapped Steep Slope ECA requires review and approval by DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=>



# Test Map

-122.30750433      47.63016532

-122.35448478      47.70014354

-122.38491988      47.64404371

-122.30146743      47.57229978

-122.38151861      47.52636444

-122.31308865      47.60145497

-122.37853634      47.51104885

-122.31515761      47.58734753

-122.29305568      47.55298756

# Test Map

Case 1015769 - Application Added as of 05/07/2008	CONSTRUCT	6534 DELRIDGE WAY SW
Case 1017961 - Notification Issued as of 04/13/2009	VACANT	1605 NE 63RD ST
Case 1017962 - Application Added as of 11/12/2009	HZW	1605 NE 63RD ST
Case 1017874 - Application Added as of 01/07/2010	HZW	1605 NE 63RD ST
Case 1018552 - Application Added as of 10/23/2009	HZW	7701 RAINIER AVE S
Case 1008600 - Application Added as of 06/05/2006	CONSTRUCT	9235 36TH AVE S
Case 1010535 - Application Added as of 04/20/2007	CONSTRUCT	5636 18TH AVE SW
Case 1022491 - Application Added as of 05/17/2010	CITATION	3739 SW CLOVERDALE ST
Case 1012058 - Application Added as of 05/15/2007	CONSTRUCT	5425 25TH AVE SW
Case 1013540 - Case Resolved as of 09/25/2009	CITATION	5403 18TH AVE SW
Case 1022380 - Application Added as of 04/29/2010	CITATION	5403 18TH AVE SW

# Test Map

Steep Slope ECA requires review and approval by DPD.

1013062

Shoring & Temporary Erosion & Sedimentation Control (TESC) not per Permit 6131872.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015769>

Property open to entry.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017961>

Property open to entry.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017962>

Property open to entry.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017874>

Dump trucks and trailers on site, track hoe and construction debris. Photos taken.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018552>

Permit 753797 issued 4/13/06 for work previously done without a permit.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1008600>

FILLING OF WETLAND MUST STOP

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1010535>

Violation of Weeds & Vegetation-

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022491>

Constructing a 2nd story addition on the west side of a SFR requires permits and inspections from DPD. STOP WORK ORDER posted 5/15/07.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1012058>

JR inspected the property and observed weeds and junk storage violations.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1013540>

4/27/10 ej- Inspection shows vegetation overgrowth into

# Test Map

-122.36093942      47.5434384

-122.31044043      47.67454544

-122.31044043      47.67454544

-122.31044043      47.67454544

-122.270105093      47.5336300885

-122.28800068      47.52045996

-122.35674976      47.5508477

-122.38100508      47.52589128

-122.36458192      47.55294042

-122.35743583      47.55353804

-122.35743583      47.55353804

# Test Map

Case 1022380 - Application Added as of 04/29/2010	CITATION	5403 18TH AVE SW
Case 1016137 - Application Added as of 06/10/2008	CONSTRUCT	4138 21ST AVE SW
Case 1016135 - Application Added as of 06/10/2008	CONSTRUCT	4132 21ST AVE SW
Case 1012438 - Application Added as of 06/14/2007	CONSTRUCT	120 14TH AVE
Case 1017649 - Application Added as of 05/20/2009	HZW	6556 RAVENNA AVE NE
Case 1022251 - Notice or Order Issued as of 05/12/2010	CONSTRUCT	9668 RAINIER AVE S
Case 1022266 - Application Added as of 04/19/2010	CITATION	1734 13TH AVE S
Case 1020575 - Case Resolved as of 04/26/2010	CITATION	4009 CALIFORNIA AVE SW
Case 1022104 - Case Resolved as of 05/21/2010	CITATION	2419 S JUDKINS ST
Case 1013185 - Notice or Order Issued as of 02/16/2010	CONSTRUCT	815 29TH AVE S

# Test Map

4/27/10 ej- Inspection shows vegetation overgrowth into the street.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022380>

Grading (raising the grade approximately 8') and eco-block retaining wall not per Permit 6139004.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016137>

Grading (raising the grade approximately 8') and eco-block retaining wall not per Permit 6137253.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016135>

Building, mechanical, electrical & plumbing permits & inspections required for washers, dryers & water heaters added to each unit. Land use permit required for establishing additional unit.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1012438>

Land Use Code Violation

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017649>

Constructing decks on roof and on east side of house over the pier requires permit(s) & inspections from DPD if allowed. STOP WORK ORDER posted 4/14/10.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022251>

04/15/10 bg - Outdoor storage of junk, photos taken

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022266>

Violation of Land Use- Outdoor junk storage

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020575>

Extensive outdoor junk storage.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022104>

Constructing an addition in the required front yard requires, zoning approval, permits and inspections from DPD. Permit 726373 did not have all required

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1013185>

# Test Map

-122.35990721	47.56546138
---------------	-------------

-122.3599066	47.56560064
--------------	-------------

-122.31393519	47.60252055
---------------	-------------

-122.3036335	47.67752088
--------------	-------------

-122.25506103	47.51795776
---------------	-------------

-122.31548245	47.58746231
---------------	-------------

-122.38714559	47.56797908
---------------	-------------

-122.30030044	47.59183062
---------------	-------------

-122.29568629	47.5952667
---------------	------------

# Test Map

Case 1020396 - Application Added as of 01/29/2010      CONSTRUCT      3508 S GENESEE ST

Case 1020331 - Application Added as of 01/29/2010      CITATION      3508 S GENESEE ST

Case 1020334 - Application Added as of 03/22/2010      HZW      3508 S GENESEE ST

Case 1020630 - Notification Issued as of 03/08/2010      VACANT      3508 S GENESEE ST

Case 1022323 - Application Added as of 04/26/2010      CITATION      8123 48TH AVE S

Case 1021933 - Application Added as of 04/26/2010      CITATION      8123 48TH AVE S

Case 1020547 - Application Added as of 02/02/2010      UNFIT      502 BELMONT AVE E

Case 1018505 - Application Added as of 02/04/2010      HZW      502 BELMONT AVE E

Case 1018247 - Notice or Order Issued as of 12/30/2009      HZW      502 BELMONT AVE E

Case 1018537 - Notification Issued as of 05/20/2009      VACANT      502 BELMONT AVE E



# Test Map

inspections: needs renewal and remainder of required inspections. STOP WORK ORDER posted 8/17/07.

Construction (building deck/porch, replacing dormer & other exterior/interior modifications) requires permit(s) and inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020396>

Junk storage on all sides of this unfinished remodel, pictures in file.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020331>

Unfinished remodel; open ditches, missing siding, open to weather via upper windows, front door deteriorated & unsound, deteriorated & open garage, pictures in file.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020334>

Unfinished remodel; open ditches, missing siding, open to weather via upper windows, front door deteriorated & unsound, deteriorated & open garage, pictures in file.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020630>

vegetation overhanging & encroaching onto the public sidewalk; pictures in file.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022323>

outdoor storage; veg. overgrowth on sidewalk; pictures in file.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021933>

fire damaged single family residence

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020547>

Inspected vacant property, open to entry and weather.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018505>

Inspected vacant property, open to entry and weather.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018247>

Inspected vacant property, open to entry and weather.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=>

# Test Map

-122.28896788	47.56435993
---------------	-------------

-122.28896788	47.56435993
---------------	-------------

-122.28896788	47.56435993
---------------	-------------

-122.28896788	47.56435993
---------------	-------------

-122.27298885	47.52958848
---------------	-------------

-122.27298885	47.52958848
---------------	-------------

-122.32377096	47.62327949
---------------	-------------

-122.32377096	47.62327949
---------------	-------------

-122.32377096	47.62327949
---------------	-------------

-122.32377096	47.62327949
---------------	-------------

# Test Map

Case 1012814 - Application Added as of 10/08/2009	CITATION	2525 NE 82ND ST
Case 1017348 - Application Added as of 09/17/2008	CONSTRUCT	725 16TH AVE
Case 1014048 - Application Added as of 11/05/2007	CONSTRUCT	4436 RAINIER AVE S
Case 1015298 - Application Added as of 03/26/2008	CONSTRUCT	3021 SW HARBOR LN
Case 1018714 - Notice or Order Issued as of 05/04/2010	CONSTRUCT	3201 BEACON AVE S
Case 1018155 - Application Added as of 04/06/2009	CONSTRUCT	10248 66TH AVE S

# Test Map

	1018537
KB inspected property and Land Use violation exists-junk storage	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1012814">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1012814</a>
Temporary Erosion & Sedimentation Control (TESC) not per Permits 6166360, 6156893 & 6149107. Contractor instructed to not allow concrete washout into alley & storm drain.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017348">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017348</a>
New equipment and additional work requires approval and permit from DPD. STOP WORK ORDER issued 11/2/07.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014048">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014048</a>
Completely gutting a building, installing windows, replacing windows & doors, performing electrical & plumbing work requires permits & inspections. Any non-conforming elements including decks & stairs require proof of prior existence. Removing parking requires zoning review. STOP WORK ORDER posted 3/26/08.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015298">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015298</a>
Operating a restaurant requires a Certificate of Occupancy (no inspections were ever requested or approved for Permit 674953/Project 9401915). Permit 675150/Project 9401387 never received final approval. Both permits need to be re-established or new permits applied for, issued and all required inspections requested and approved.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018714">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018714</a>
Permit 6204750 was issued 1/26/09 for work originally performed without a permit. This case will remain open until all required inspections have been requested and	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018155">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018155</a>

# Test Map

-122.30046743	47.68826863
---------------	-------------

-122.31209896	47.60873328
---------------	-------------

-122.2875834	47.56313444
--------------	-------------

-122.3719804	47.57688901
--------------	-------------

-122.30940776	47.57491884
---------------	-------------

-122.25083566	47.50832132
---------------	-------------

# Test Map

Case 1015328 - Application Added as of 03/31/2008	CONSTRUCT	1502 33RD AVE S
Case 1022535 - Application Added as of 05/19/2010	CONSTRUCT	3444 36TH AVE W
Case 1015856 - Application Added as of 10/10/2008	CONSTRUCT	8733 29TH AVE NW
Case 1016352 - Application Added as of 10/10/2008	CONSTRUCT	8733 29TH AVE NW
Case 1013568 - Application Added as of 01/06/2009	CONSTRUCT	4740 51ST AVE SW
Case 1020656 - Citation Issued as of 04/30/2010	CITATION	4502 41ST AVE S
Case 1020860 - Application Added as of 03/26/2010	CITATION	3614 SW TRENTON ST
Case 1015217 - License Issued as of 09/15/2009	TRAO	321 W OLYMPIC PL
Case 1017511 - Application Added as of 10/03/2008	CONSTRUCT	3202 HUNTER BLVD S

# Test Map

approved.

Constructing a second story deck requires a permit and inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015328>

PERMIT REQUIRED FOR RETAINING WALL BUILT ON A STEEP SLOPE ECA

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022535>

INSPECTOR CONFIRMED THAT TREE STUMP WAS THE REMAINS OF DEAD MAPLE THAT HAD BEEN NOTED IN INSPECTION ON 8/30/07--REVEGETATION PLAN IS REQUIRED

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015856>

OBTAIN A PERMIT FOR RETAINING WALL IN ECA

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016352>

Permit 6163989 was issued 2/8/08 for work originally started without permits & inspections. This case will remain open until all required inspections have been requested and approved.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1013568>

09/08/09 bg - Outdoor storage, fence is leaning into right of way and sign advertising business in the front of the house.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020656>

Violation of Weeds & Vegetation

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020860>

Application for a Tenant Relocation License. Total units: 8; total units occupied: 8. Demolition.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015217>

Approval from DPD required to extend garage rooftop deck and guardrails towards alley. Revision (including zoning review) to Permit 6144074 required.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017511>

# Test Map

-122.29021449	47.58867482
---------------	-------------

-122.4033217	47.65178298
--------------	-------------

-122.39451033	47.69284339
---------------	-------------

-122.39451033	47.69284339
---------------	-------------

-122.39733317	47.55990901
---------------	-------------

-122.28145471	47.56268914
---------------	-------------

-122.37869405	47.5248846
---------------	------------

-122.36164446	47.62653374
---------------	-------------

-122.28453415	47.57507088
---------------	-------------



# Test Map

Case 1019469 - Application Accepted as of 05/20/2010	TRAO	1303 NE CAMPUS PKWY
--	------	---------------------

Case 1020830 - Notice or Order Issued as of 02/16/2010	CONSTRUCT	3446 22ND AVE W
--	-----------	-----------------

Case 1014712 - Payment Processed as of 03/27/2008	TRAO	2220 10TH AVE E
---	------	-----------------

Case 1013832 - Application Added as of 02/28/2008	CONSTRUCT	8411 48TH AVE S
---	-----------	-----------------

Case 1017409 - Payment Processed as of 05/20/2010	TRAO	8360 WABASH AVE S
---	------	-------------------

Case 1022333 - Application Added as of 04/27/2010	HZW	307 23RD AVE
---	-----	--------------

Case 1022334 - Application Added as of 04/27/2010	CITATION	307 23RD AVE
---	----------	--------------

Case 1014005 - Application Added as of 08/19/2008	CONSTRUCT	5307 BEACON AVE S
---	-----------	-------------------

Case 1020125 - Notice or Order Issued as of 04/20/2010	HZW	7323 14TH AVE NW
--	-----	------------------

# Test Map

zoning review) to Permit 6144074 required.

Application for a Tenant Relocation License. Total units: 47; total units occupied: 42. Demolition.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019469>

## STOCKPILED SOIL NEEDS EROSION CONTROL

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020830>

Application for a Tenant Relocation License. Total units: 3; total units occupied: 3. Demolition.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014712>

Detached ADU requires zoning approval, permits & inspections from DPD. Permit 6166111 issued 1/8/08 for a portion of the work performed without a permit. This case will remain open until all required permits have been obtained & all required inspections approved by DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1013832>

Application for a Tenant Relocation License. Total units:3; Total units occupied:3. Demolition.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017409>

no siding;

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022333>

junk in yard includes mattresses, electronic equipment, bed frame, carpeting, furniture & other items; pictures in file.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022334>

Permit 6162201 was issued 11/26/07 for work originally started without a permit. This case will remain open until all required inspections have been requested & obtained.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014005>

deteriorated front deck & wall; open to weather.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=>

# Test Map

-122.31411999      47.65574199

-122.38441681      47.65167853

-122.31974867      47.63909406

-122.27310543      47.52761671

-122.26790188      47.5282493

-122.30274095      47.6046111

-122.30274095      47.6046111

-122.30344774      47.55465638

-122.37387595      47.68216265

# Test Map

04/20/2010

Case 1022261 - Notification Issued as of 04/20/2010      VACANT      7323 14TH AVE NW

Case 1019627 - Citation Issued as of 05/06/2010      CITATION      11222 PHINNEY AVE N

Case 1013770 - Application Added as of 07/24/2008      HZW      1609 FAIRVIEW AVE E

Case 1022195 - Application Added as of 04/07/2010      CITATION      3700 SW ADMIRAL WAY

Case 1020158 - Notice or Order Issued as of 01/14/2010      CONSTRUCT      6607 58TH AVE NE

Case 1022490 - Application Added as of 05/18/2010      CITATION      5202 18TH AVE SW

Case 1013108 - Application Added as of 08/14/2008      CONSTRUCT      6010 SW ORLEANS ST

Case 1014520 - Application Added as of 12/28/2007      HZW      500 S RIVER ST

Case 1017664 - Application Added as of 10/21/2008      CONSTRUCT      10407 67TH AVE S

Case 1013889 - Application Added as of 01/14/2009      CONSTRUCT      7027 15TH AVE NW

# Test Map

deteriorated front deck & wall; open to weather.	1020125 <a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022261">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022261</a>
outdoor junk storage, sfr	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019627">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019627</a>
Observed large green barge	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1013770">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1013770</a>
Violation of Land Use- Outdoor junk storage	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022195">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022195</a>
ELEVATED WALKWAY AND THE NORTH SIDE ENTRY OVERHANG MUST BE BUILT PER PLAN BEFORE FINAL APPROVAL OF PERMIT #6126640	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020158">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020158</a>
Violation of Weeds & Vegetation Ord-	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022490">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022490</a>
Drainage issues in adjacent R-O-W have been transferred to SDOT.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1013108">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1013108</a>
Violation of Just Cause Eviction Ordinance.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014520">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014520</a>
Side Sewer Permit 6190819 to be re-opened & yard drains to be installed to collect surface flow discharging to the north.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017664">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017664</a>
PERMIT REQUIRED FOR REMODEL	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1013889">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1013889</a>

# Test Map

-122.37387595	47.68216265
---------------	-------------

-122.35387997	47.71121286
---------------	-------------

-122.32734978	47.63405404
---------------	-------------

-122.37789444	47.58132191
---------------	-------------

-122.26691894	47.67691346
---------------	-------------

-122.35668101	47.55554578
---------------	-------------

-122.40999084	47.57177359
---------------	-------------

-122.3280274	47.54413507
--------------	-------------

-122.25025155	47.50789738
---------------	-------------

-122.37711551	47.6803818
---------------	------------

# Test Map

Case 1021971 - Application Added as of 03/24/2010	CITATION	1624 S HOLGATE ST
Case 1021972 - Application Added as of 03/09/2010	CITATION	1630 S HOLGATE ST
Case 1021974 - Application Added as of 03/09/2010	CITATION	1636 S HOLGATE ST
Case 1022418 - Application Accepted as of 05/21/2010	TRAO	4163 42ND AVE NE
Case 1022359 - Application Accepted as of 05/20/2010	TRAO	5720 ROOSEVELT WAY NE
Case 1020464 - Notice or Order Issued as of 03/08/2010	HZW	1915 25TH AVE S
Case 1021484 - Notification Issued as of 03/08/2010	VACANT	1915 25TH AVE S
Case 1020889 - Case Resolved as of 03/04/2010	CITATION	3643 COURTLAND PL S
Case 1022488 - Application Added as of 05/13/2010	HZW	1207 26TH AVE E
Case 1022368 - Application Added as of 04/29/2010	CITATION	2031 S WASHINGTON ST
Case 1022478 - Application Added as of 05/11/2010	CONSTRUCT	941 26TH AVE S

# Test Map

02/10/10 bg - vegetation overgrown onto 16th Ave S and debris scattered on the property. photos taken

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021971>

02/10/10 bg - vegetation overgrown onto 16th Ave S and debris scattered on the property. photos taken

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021972>

02/10/10 bg - vegetation overgrown onto 16th Ave S and debris scattered on the property. photos taken

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021974>

Application for a Tenant Relocation License. Total units:1; total units occupied:1; Demolition.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022418>

Application for a Tenant Relocation License. Total units:2; total units occupied:2. Demolition.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022359>

Unfinished new construction, open to entry, pictures in file. Outdoor storage.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020464>

Unfinished new construction, open to entry, pictures in file. Outdoor storage.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021484>

10/16/09 bg - Damaged vehicle parked in the rear of the residence. photo taken

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020889>

Illegal unit in the basement.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022488>

Vacant lot. Trash, litter and homeless encampment debris.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022368>

Permit 6195765 was issued 9/25/08 for Side Sewer work originally started without a permit. None of the required inspections were requested or performed before the

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022478>



# Test Map

-122.31172832 47.58680918

-122.31171542 47.58665226

-122.31173604 47.58648632

-122.28301583 47.66028184

-122.31705908 47.67066615

-122.30062923 47.58586036

-122.30062923 47.58586036

-122.28745534 47.57025722

-122.2993236 47.6305349

-122.3050119 47.60063626

-122.29928236 47.59338705

# Test Map

Case 1021117 - Case Resolved as of 03/02/2010	HZW	617 QUEEN ANNE AVE N
---	-----	----------------------

Case 1011858 - Application Accepted as of 05/10/2010	ADVISORY	3855 34TH AVE W
--	----------	-----------------

Case 1013408 - Payment Processed as of 11/02/2007	TRAO	914 NW 52ND ST
---	------	----------------

Case 1011546 - Application Added as of 10/08/2007	CONSTRUCT	9819 61ST AVE S
---	-----------	-----------------

Case 1013741 - Application Added as of 08/21/2009	CONSTRUCT	5137 S BRIGHTON ST
---	-----------	--------------------

Case 1011680 - Application Added as of 04/12/2007	CONSTRUCT	3728 SW CAMBRIDGE ST
---	-----------	----------------------

Case 1011747 - Application Added as of 12/26/2008	CONSTRUCT	1037 S CLOVERDALE ST
---	-----------	----------------------

Case 1017284 - Payment Processed as of 05/20/2010	TRAO	1431 NW 62ND ST
---	------	-----------------

# Test Map

permit expired on 3/25/10. A new permit is needed along with all of the required inspections and approvals from DPD.

Stairway handrail is not code compliant.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021117>

Condo Conversion.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1011858>

Application for a Tenant Relocation License. Total units: 1; total units occupied: 1. Demolition.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1013408>

Permit 6145345 was issued on 7/3/07 for work originally started without a permit. This case will remain open until all required inspections are completed and approved.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1011546>

Permit 6160443 was issued 11/19/07 to take care of some of the permitting issues. Permit still needed for creating additional dwelling unit in house. This case will remain open until all required permits & inspections have been obtained.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1013741>

Constructing a retaining wall (>4' tall in some places) with a fence (>6' tall in some places) on top of the wall in a Steep Slope (ECA 1), Riparian Corridor (ECA 3), Wetlands (ECA 4) and Wildlife Habitat (ECA 9) requires permits, approval & inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1011680>

Building a detached garage requires permits and inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1011747>

Application for a Tenant Relocation License. Total

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=>

# Test Map

-122.35706666	47.62521587
---------------	-------------

-122.40141479	47.65555678
---------------	-------------

-122.36934021	47.66661414
---------------	-------------

-122.25731179	47.51280112
---------------	-------------

-122.26825141	47.54139734
---------------	-------------

-122.38053836	47.5194563
---------------	------------

-122.31864492	47.52628435
---------------	-------------

-122.37506639	47.67361831
---------------	-------------

# Test Map

Case 1012394 - Application Added as of 02/19/2008	CITATION	2519 NE 82ND ST
Case 1019106 - Application Added as of 04/27/2009	HZW	104 NW 101ST ST
Case 1022335 - Application Added as of 04/27/2010	HZW	10502 LAKE CITY WAY NE
Case 1022336 - Application Added as of 04/27/2010	CITATION	10502 LAKE CITY WAY NE
Case 1011498 - Application Added as of 03/29/2007	CONSTRUCT	8249 5TH AVE S
Case 1017181 - Citation Issued as of 02/18/2010	CITATION	9455 14TH AVE SW
Case 1012057 - Application Added as of 05/15/2007	CONSTRUCT	2344 30TH AVE S

# Test Map

units:2. Total units occupied:2. Demolition.	1017284
KB inspected property and Land Use violation exists-junk storage	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1012394">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1012394</a>
Violation of Just Cause Eviction Ordinance due to issuance of deficient termination of tenancy notices to all tenant households at 104 & 104 1/2 NW 101st St.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019106">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019106</a>
Open to weather via upper level windows	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022335">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022335</a>
outdoor storage, pictures in file.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022336">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022336</a>
Grading more than 500 cu.yds., possibly filling wetlands, removing more than 750 sq.ft. of vegetation (approximatley 10 acres), removing vegetation and grading in wetland and/or riparian corridor buffers and changing the use of property requires permits and all required inspections from DPD. Need to install TESC (Temporary Erosion & Sedimentation Control) immediately. STOP WORK ORDER issued 3/29/07.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1011498">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1011498</a>
Several vehicles are parked in the rear yard and required side yard of the property, junk is also stored in the front yard of the house.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017181">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017181</a>
Side sewer work requires a permit & inspections from DPD. A registered side sewer contractor is required for work in the R-O-W. STOP WORK ORDER issued 5/15/07.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1012057">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1012057</a>

# Test Map

-122.30068248	47.68830867
---------------	-------------

-122.3582403	47.70276582
--------------	-------------

-122.3012914	47.70492601
--------------	-------------

-122.3012914	47.70492601
--------------	-------------

-122.32882327	47.52849458
---------------	-------------

-122.35311097	47.51753027
---------------	-------------

-122.29377264	47.58159114
---------------	-------------

# Test Map

Case 1012123 - Application Added as of 04/28/2010	CONSTRUCT	118 NE 77TH ST
Case 1021815 - Application Added as of 02/22/2010	CONSTRUCT	1924 E SPRUCE ST
Case 1014927 - Payment Processed as of 05/20/2010	TRAO	12705 35TH AVE NE
Case 1018110 - Case Closed as of 03/01/2010	CITATION	846 S DONOVAN ST
Case 1021786 - Notice or Order Issued as of 02/22/2010	CONSTRUCT	4220 PASADENA PL NE
Case 1021023 - Application Added as of 04/20/2010	HZW	4422 CASCADIA AVE S
Case 1017710 - Application Added as of 11/12/2008	CONSTRUCT	3915 SW HINDS ST
Case 1012251 - Application Added as of 06/13/2007	CONSTRUCT	816 31ST AVE
Case 1021888 - Application Added as of 04/07/2010	CITATION	8850 9TH AVE SW
Case 1021331 - Notice or Order Issued as of 02/23/2010	HZW	2519 1ST AVE



# Test Map

## BASEMENT REMODEL REQUIRES PERMIT

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1012123>

Occupying a triplex requires a Certificate of Occupancy.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021815>

Application for a Tenant Relocation License. Total units: 1; total units occupied: 1. Demolition.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014927>

Inspection show outdoor junk storage in the alley behind the property.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018110>

OBTAIN PERMIT TO FINAL PERMIT #6075178--CALL FOR INSPECTIONS--OBTAIN A CERTIFICATE OF OCCUPANCY

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021786>

11/02/09 bg - Unit in the basement, flooding has caused mold and the floor to buckle. Illegal unit, tenants in adu and in the house - owner not living on site. photos taken

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021023>

Permit 6198647 was issued 10/23/08 for work originally started without a permit. This case will remain open until all required inspections have been requested and approved by DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017710>

External stairs in north side yard & 2nd story door need zoning approval, permit and inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1012251>

2/25/10 EJ- Inspection shows vegetation encroaching into the sidewalk, along 9th Ave SW.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021888>

hbmc violations

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021331>

# Test Map

-122.32736304	47.68525665
---------------	-------------

-122.30662686	47.60366187
---------------	-------------

-122.29122991	47.72137043
---------------	-------------

-122.32100889	47.52579225
---------------	-------------

-122.32162359	47.65816477
---------------	-------------

-122.28249096	47.5633919
---------------	------------

-122.38205953	47.57298155
---------------	-------------

-122.29234504	47.60980459
---------------	-------------

-122.34646101	47.52319438
---------------	-------------

-122.3495672	47.61491808
--------------	-------------

# Test Map

Case 1012658 - Application Added as of 07/03/2007	CONSTRUCT	5307 SW SHORE PL
Case 1012633 - Payment Processed as of 12/14/2009	TRAO	1515 STURGUS AVE S
Case 1017775 - Application Added as of 06/19/2009	HZW	2901 1ST AVE S
Case 1015271 - Application Added as of 01/08/2010	CONSTRUCT	2901 1ST AVE S
Case 1017575 - Application Added as of 01/08/2010	CONSTRUCT	2901 1ST AVE S
Case 1022317 - Notice or Order Issued as of 04/28/2010	HZW	8900 AURORA AVE N
Case 1012543 - Application Added as of 06/21/2007	CONSTRUCT	5410 M L KING JR WAY S
Case 1019621 - Payment Processed as of 03/08/2010	TRAO	4502 42ND AVE SW
Case 1020482 - Application Added as of 09/03/2009	NOISE	8329 8TH AVE NW

# Test Map

Remodeling and repairing foundation on a single family residence and garage requires permit(s) and inspections from DPD. STOP WORK ORDER posted 6/28/07.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1012658>

Application for a Tenant Relocation License. Total units: 1; total units occupied: 1. Demolition.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1012633>

Violation of the Zoning Code/Case #1017775

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017775>

Permit 6175318 was issued 3/28/08 for a portion of the interior alterations originally started without permits. This case will remain open until all required permits are issued, inspections requested and all approvals granted.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015271>

Permit 6199649 was issued 11/3/08 for a portion of the electrical work originally performed without a permit & inspections. This case will remain open until all required permits are issued, inspections requested & final approvals obtained.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017575>

LU violation: unused curb cuts must be removed

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022317>

Additions, alterations and second dwelling unit all require permits and inspections from DPD. STOP WORK ORDER issued 6/20/07.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1012543>

Application for a Tenant Relocation License. Total units: 4; total units occupied: 3; Demolition.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019621>

8/13/09 JS talked to owner and complainant about the situation. The owner has not used the furnace (power

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020482>

# Test Map

-122.39883249	47.55428057
---------------	-------------

-122.31191061	47.58946298
---------------	-------------

-122.33472186	47.57742423
---------------	-------------

-122.33472186	47.57742423
---------------	-------------

-122.33472186	47.57742423
---------------	-------------

-122.34368294	47.69365788
---------------	-------------

-122.28858585	47.55303654
---------------	-------------

-122.38516131	47.5627124
---------------	------------

-122.36653272	47.68990945
---------------	-------------

# Test Map

Case 1022146 - Application Added as of 04/02/2010	CITATION	303 NICKERSON ST
Case 1017862 - Application Added as of 02/24/2010	CONSTRUCT	4019 FAUNTLEROY WAY SW
Case 1022396 - Application Added as of 04/30/2010	CITATION	3048 20TH AVE S
Case 1020974 - Application Added as of 05/04/2010	CITATION	3020 23RD AVE S
Case 1022188 - Application Added as of 04/07/2010	CITATION	1930 45TH AVE SW
Case 1022033 - Notice or Order Issued as of 03/24/2010	HZW	4501 SW ADMIRAL WAY
Case 1022274 - Notice or Order Issued as of 05/03/2010	HZW	3100 PORTAGE BAY PL E
Case 1014263 - Application Added as of 03/26/2009	CONSTRUCT	1545 19TH AVE S
Case 1021906 - Notice or Order Issued as of	CONSTRUCT	13747 STONE AVE N

# Test Map

vent) during the times complainant has heard the noise. Complainant will locate the source of the noise and contact me.

4/1/10 KB inspected property and Weeds violation exists

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022146>

Permit 6201938 was issued 2/26/09 for work originally started without a permit. This case will remain open until all required inspections have been requested & approved by DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017862>

04/30/10 bg - Vegetation encroaching onto the sidewalk, photos taken.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022396>

10/23/09 bg - One vehicle appears inoperable, tarp over the vehicle, construction debris in side and rear yards. photos taken

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020974>

Violation of Land Use- Outdoor junk storage

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022188>

Violation of Housing & Building Maintenance Code (HBMC)

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022033>

Replaced common dock w/ new untreated cedar decking.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022274>

Permit 6174697 was issued 10/30/08 for extensive remodel originally started without a permit. This case will remain open until all required inspections have been requested and approved.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014263>

EXCEPTIONAL TREE HAS BEEN CUT

# Test Map

-122.35114255 47.64658195

-122.374054252 47.567229326

-122.30619823 47.57554225

-122.3030419 47.57602875

-122.38872925 47.58587858

-122.38954766 47.58101758

-122.31793961 47.64887435

-122.30869109 47.58870872

-122.34259311 47.72999311



# Test Map

03/11/2010

Case 1021493 - Application Added as of 05/10/2010      HZW      2416 S JUNEAU ST

Case 1018185 - Application Added as of 04/29/2009      CONSTRUCT      5633 30TH AVE SW

Case 1015750 - Application Added as of 01/14/2010      CONSTRUCT      403 32ND AVE

Case 1016853 - Application Added as of 04/20/2010      HZW      544 27TH AVE

Case 1018946 - Application Added as of 07/02/2009      NOISE      2345 42ND AVE SW

Case 1022520 - Application Added as of 05/18/2010      CITATION      4507 SW COLLEGE ST

Case 1022284 - Application Added as of 04/21/2010      CITATION      2126 ALKI AVE SW

Case 1018377 - Notice or Order Issued as of      CONSTRUCT      4044 33RD AVE W

# Test Map

Rear entry door unsecured, picture in file; deterioration.  
Tall veg. in yard areas only not on any ROW.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021906>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021493>

Permit 6205858 was issued 2/18/09 for work originally started without a permit. This case will remain open until all required inspections have been requested and approved.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018185>

Permit 6179553 was issued on 5/1/08 for work originally started without permits. This case will remain open until all required inspections have been requested & approved.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015750>

Inspection Scheduled 7/10/08.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016853>

Int Insp 5/5/08 DG I went to the Bartell store and found the condition just as the complainant described. I spoke to Tom of Bartells, he agreed that the noise was too loud. He would call the Bartell's maintenance contractor for mechanical.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018946>

Violation of Land Use- Outdoor junk storage.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022520>

Violation of Land Use- Outdoor junk storage. Unable to verify if the RV in the required yard. Conduct more research

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022284>

13 INCH CEDAR TREE ALONG SOUTH PROPERTY

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=>

# Test Map

-122.30063087      47.55022731

-122.37135902      47.55096569

-122.29185416      47.60533215

-122.29758336      47.60751717

-122.38551393      47.58204174

-122.38967629      47.58276218

-122.39848885      47.58499913

-122.39911121      47.65728211

# Test Map

03/04/2010

Case 1022544 - Application Added as of 05/20/2010      HZW      1008 W RUFFNER ST

Case 1018979 - Application Added as of 04/01/2010      HZW      4848 S LUCILE ST

Case 1022345 - Application Added as of 05/14/2010      UNFIT      5444 DELRIDGE WAY SW

Case 1022310 - Application Added as of 04/27/2010      CITATION      1801 19TH AVE

Case 1014661 - Payment Processed as of 04/21/2008      TRAO      1213 6TH AVE N

Case 1017285 - Application Added as of 09/11/2008      CONSTRUCT      1312 CALIFORNIA WAY SW

Case 1020877 - Application Added as of 10/15/2009      CONSTRUCT      1312 CALIFORNIA WAY SW

Case 1022207 - Citation Issued as of 05/12/2010      CITATION      1153 N 92ND ST

# Test Map

LINE HAS BEEN REMOVED--PLANS SHOW THAT TREE IS TO REMAIN--SUBMIT REVISED PLANS

1018377

3/18/10 kb inspected property and land use violation exists - junk storage, improper storage of a trailer in front yard.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022544>

"VIOLATION ALERT". VIOLATION OF THE SEATTLE LAND USE AND ZONING CODE CONFIRMED (REQUIRED OFF-STREET PARKING IN ATTACHED GARAGE REMOVED). UNABLE TO VERIFY IF VEHICLE IN DRIVEWAY IS INOPERABLE.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018979>

unfit, badly deteriorated single family residence

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022345>

Violation of the Land Use & Zoning Code

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022310>

Application for a Tenant Relocation License. Total units: 1; total units occupied: 1. Demolition.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014661>

Occuppying a duplex as a triplex, repair of 3rd floor atrium with minor structural repair/changes to deck (not changing existing footprint) & changes to drainage requires a permit & inspections from DPD. STOP WORK ORDER posted 9/8/08.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017285>

Altering drainage requires a permit and inspections from DPD. See related Case 1017285.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020877>

Land Use Code Violation

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022207>

# Test Map

-122.37065207	47.65237403
---------------	-------------

-122.27054416	47.55279775
---------------	-------------

-122.36244935	47.55240027
---------------	-------------

-122.30766696	47.61772162
---------------	-------------

-122.34528414	47.63020928
---------------	-------------

-122.38316766	47.59162028
---------------	-------------

-122.38316766	47.59162028
---------------	-------------

-122.343835019	47.6955468635
----------------	---------------

# Test Map

Case 1022500 - Application Added as of 05/17/2010	CITATION	5219 FAUNTLEROY WAY SW
Case 1015947 - Application Added as of 11/30/2009	CONSTRUCT	5111 S HUDSON ST
Case 1022510 - Application Added as of 05/14/2010	CITATION	3548 S HUDSON ST
Case 1021137 - Application Added as of 01/05/2010	CITATION	3528 S HUDSON ST
Case 1021152 - Case Resolved as of 05/11/2010	HZW	3206 S HUDSON ST
Case 1017880 - Payment Processed as of 02/20/2009	TRAO	2904 S JACKSON ST
Case 1021250 - Notice or Order Issued as of 12/22/2009	HZW	411 11TH AVE E
Case 1019838 - Payment Processed as of 09/14/2009	TRAO	1530 15TH AVE E

# Test Map

## Violation of Weeds & Vegetation Ord-

Permit 6183874 was issued on 6/10/08 for work originally started without a permit. This case will remain open until all inspections have been requested and approved.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022500>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015947>

04/30/10 bg - Vegetation encroaching onto the sidewalk. photos taken

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022510>

11/16/09 bg - Four vehicles on the property, one commercial vehicle and pick up bed toppers. photos taken

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021137>

Alley behind the business: an extremely large "mountain" of mattresses has accumulated at the NE end of the lot. There is other trash and debris associated with the various businesses on the lot - including two inoperable trucks in the rear under the mattresses; old spools, cardboard cartons and trash in the upper parking lot and old wet mattresses leaning against the front of the building (Mattrees Store) on ML King WY.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021152>

Application for a Tenant Relocation License. Total units: 2; total units occupied: 2. Demolition.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017880>

Violations of Housing Building and Maintenance Code observed. PR

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021250>

Application for a Tenant Relocation License. Total units: 1; total units occupied: 1. Demolition.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019838>



# Test Map

-122.38191448	47.55510225
---------------	-------------

-122.26922222	47.55689976
---------------	-------------

-122.28674255	47.55723765
---------------	-------------

-122.28744545	47.55725775
---------------	-------------

-122.29092333	47.5573879
---------------	------------

-122.294644492	47.5994483282
----------------	---------------

-122.3181412	47.62232914
--------------	-------------

-122.31217756	47.63323752
---------------	-------------

# Test Map

Case 1017606 - Application Added as of 06/03/2009	HZW	2102 2ND AVE
Case 1019971 - Application Added as of 07/16/2009	HZW	3706 38TH AVE SW
Case 1022416 - Application Added as of 05/04/2010	CITATION	2006 S EDMUNDS ST
Case 1022415 - Application Added as of 05/04/2010	CITATION	2000 S EDMUNDS ST
Case 1021436 - Application Added as of 12/29/2009	CONSTRUCT	2036 S COLUMBIAN WAY
Case 1017683 - Application Accepted as of 01/02/2009	TRAO	203 18TH AVE
Case 1021782 - Application Added as of 03/29/2010	CITATION	206 20TH AVE
Case 1019389 - Citation Issued as of 05/05/2010	CITATION	5543 S WALLACE ST
Case 1022216 - Application Added as of 05/14/2010	CITATION	10621 61ST AVE S

# Test Map

Violation of the Land Use & Zoning Code/Case  
#1017606

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017606>

Violation of land Use- Outdoor junk storage, and no violation on the location of the boat

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019971>

05/04/10 bg - Vegetation overgrown along S Edmunds St and S Columbian Way, photos taken

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022416>

04/30/10 bg - Vegetation overgrown along S Columbian Way, photos taken

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022415>

Permit 6235754 was issued 12/15/09 for work originally started without a permit. This case will remain open until all required inspections have been requested & approved.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021436>

Application for a Tenant Relocation License. Total units:3; total units occupied:2. Demolition.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017683>

Violation the Land Use Code

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021782>

05/26/09 - Six vehicles on the property, 3 in the front yard. The fourth vehicle parked at the garage has a broken window and a black tarp hanging off of it. The fifth vehicle is in the rear yard. The sixth vehicle is behind the boat in the rear yard. Junk & debris on the open porch and scattered around the yards. photos taken. bg

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019389>

outdoor storage including vehicle, grocery cart, tires, auto parts, tv, lawn mowers, bicycles mattresses & box springs; pictures in file.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022216>

# Test Map

-122.342953624	47.6128408067
----------------	---------------

-122.379959629	47.57094515
----------------	-------------

-122.30671257	47.55994901
---------------	-------------

-122.3069598	47.56003802
--------------	-------------

-122.3057235	47.56018659
--------------	-------------

-122.30921665	47.60370804
---------------	-------------

-122.30601318	47.60379719
---------------	-------------

-122.26245866	47.49721122
---------------	-------------

-122.25740846	47.5055098
---------------	------------

# Test Map

Case 1022193 - Notice or Order Issued as of 05/05/2010	HZW	10621 61ST AVE S
Case 1022441 - Application Added as of 05/07/2010	CITATION	5604 S BANGOR ST
Case 1015519 - Case Resolved as of 11/13/2009	CITATION	10455 59TH AVE S
Case 1015866 - Application Added as of 05/19/2008	CONSTRUCT	4716 51ST AVE SW
Case 1015868 - Application Added as of 05/19/2008	CONSTRUCT	4716 51ST AVE SW
Case 1020876 - Notice or Order Issued as of 02/02/2010	CONSTRUCT	9434 37TH AVE S
Case 1016480 - Application Added as of 07/17/2008	CONSTRUCT	4600 BEACH DR SW
Case 1021878 - Application Added as of 03/03/2010	HZW	4433 42ND AVE SW
Case 1022272 - Notice or Order Issued as of 05/20/2010	CONSTRUCT	4436 52ND AVE SW

# Test Map

springs; pictures in file.

Unsecured garage door; outdoor storage including vehicle, pictures in file.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022193>

05/05/10 bg - Inoperable vehicles in front yard, junk and vegetation overgrown onto the sidewalk. photos taken

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022441>

Inspection shows outdoor junk storage such as but not limited to inoperable vehicle, foam, broken toys and other miscellaneous items.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015519>

Constructing a rockery in a Steep Slope Environmentally Critical Area requires permits, approvals & inspections from DPD. STOP WORK ORDER posted 4/30/08.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015866>

Removing more than 750 sq.ft. of vegetation in a Steep Slope Environmentally Critical Area requires approval from DPD. STOP WORK ORDER posted 4/30/08.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015868>

Permit 6234683 was issued 12/2/09 for work originally started without a permit. This case will remain open until all required inspections have been requested and approved.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020876>

Permit 6187018 was issued 7/8/08 for work originally started without a permit. The is case will remain open until all required inspections have been performed.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016480>

2/25/10 EJ-Inspection shows Lady Di Pet Chaperone service operating out of a single family home in a NC2-40 zone.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021878>

Adding a 2nd story to a detached garage requires permits and inspections from DPD. STOP WORK

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=>

# Test Map

-122.25740846	47.5055098
---------------	------------

-122.26283864	47.50627743
---------------	-------------

-122.25971228	47.50662848
---------------	-------------

-122.397331	47.56062398
-------------	-------------

-122.397331	47.56062398
-------------	-------------

-122.285553971	47.5173457314
----------------	---------------

-122.40501913	47.56220439
---------------	-------------

-122.38574794	47.563731
---------------	-----------

-122.3985468	47.56371526
--------------	-------------

# Test Map

05/20/2010

Case 1020329 - Application Added as of 10/08/2009      CONSTRUCT      4425 51ST AVE SW

Case 1022179 - Eligibility Determined as of 05/14/2010      TRAO      4532 20TH AVE NE

Case 1022302 - Case Opened as of 04/30/2010      CONSTRUCT      2200 WESTERN AVE

Case 1018239 - Application Added as of 01/14/2009      CONSTRUCT      9743 RAINIER AVE S

Case 1018202 - Application Added as of 01/08/2009      CONSTRUCT      3810 AIRPORT WAY S

Case 1016005 - Notice or Order Issued as of 02/02/2010      CONSTRUCT      3810 37TH AVE SW

Case 1019572 - Citation Issued as of 04/27/2010      CITATION      2905 S ESTELLE ST

Case 1019735 - Application Added as of 05/17/2010      HZW      2905 S ESTELLE ST



# Test Map

permits and inspections from DPD. STOP WORK ORDER posted 5/20/10.

1022272

Permit 6228202 was issued 10/7/09 for work originally started without a permit. This case will remain open until all required inspections have been requested and approved.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020329>

Application for a Tenant Relocation License. Total units:2; total units occupied:2. Demolition.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022179>

PERMIT TO INSTALL SIGN HAS BEEN DENIED--SIGN HAS BEEN INSTALLED ANYWAY ON NORTH FACING WALL

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022302>

Landslide repair, if more than 25 cu.yds. grading, will need permit(s) & inspections from DPD. Connecting roof downspouts to combined sewer requires permits & inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018239>

Electrical work (including outlets, receptacles, lights and switches) requires a permit and inspections from DPD. STOP WORK ORDER posted 1/7/09.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018202>

Constructing a deck over a garage requires permits & inspections from DPD. STOP WORK ORDER posted 5/30/08.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016005>

VIOLATION OF THE SEATTLE LAND USE AND ZONING CODE OBSERVED(AUTO TIRES &14 VEHICLES PARKED OUTDOORS ON SF5000 LOT).

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019572>

"VIOLATION ALERT"VIOLATION OF THE SEATTLE LAND USE AND ZONING CODE

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019735>

# Test Map

-122.39787746	47.5640321
---------------	------------

-122.30618058	47.66222319
---------------	-------------

-122.34611001	47.61229821
---------------	-------------

-122.25379986	47.51526213
---------------	-------------

-122.32226769	47.56953549
---------------	-------------

-122.37848016	47.56954802
---------------	-------------

-122.29415548	47.5713979
---------------	------------

-122.29415548	47.5713979
---------------	------------

# Test Map

Case 1022372 - Application Added as of 04/29/2010	CITATION	4905 SW CHARLESTOWN ST
Case 1021167 - Notice or Order Issued as of 04/16/2010	HZW	6204 29TH AVE NE
Case 1022450 - Notice or Order Issued as of 05/11/2010	HZW	6200 15TH AVE NW
Case 1022550 - Application Added as of 05/20/2010	CITATION	2615 E PINE ST
Case 1021228 - Application Added as of 01/06/2010	HZW	3110 E OLIVE ST
Case 1021978 - Application Added as of 03/10/2010	CITATION	2920 E OLIVE ST
Case 1022150 - Application Added as of 04/29/2010	CITATION	3700 SW BARTON ST
Case 1022237 - Application Added as of 05/11/2010	CITATION	10017 46TH AVE S
Case 1022360 - Application Added as of 04/28/2010	CITATION	10202 40TH AVE SW

# Test Map

OBSERVED(STRUCTURAL ADDITIONS TO RESIDENCE WITHOUT REQUIRED BUILDING PERMIT ON SF5000 LOT).

4/27/10 ej Inspection shows vegetation encroaching into the alley and sidewalk along Charlestown St.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022372>

Land Use Code violation observed. PR

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021167>

LU violations: outdoor storage in NC zone prohibited & permit requires 5 parking stalls.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022450>

Violation of the Land Use Code

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022550>

Possible illegal unit/further info/research needed.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021228>

Violation of the Land Use & Zoning Code

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021978>

weeds

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022150>

VIOLATION OF THE SEATTLE LAND USE AND ZONING CODE OBSERVED (MATTRESS, APPLIANCES PLASTIC BAGS AND OTHER JUNK STORAGE IN YARDS).

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022237>

4/27/10 ej- Inspection shows more than the allowed 3 vehicles not in an enclosed area on a single family lot.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022360>

# Test Map

-122.39512549	47.57010165
---------------	-------------

-122.2960698	47.67421951
--------------	-------------

-122.37591204	47.67402832
---------------	-------------

-122.29801957	47.6151217
---------------	------------

-122.2918505	47.61660639
--------------	-------------

-122.2939249	47.61664543
--------------	-------------

-122.3796573	47.52125548
--------------	-------------

-122.27561039	47.5106068
---------------	------------

-122.38285095	47.51188
---------------	----------

# Test Map

Case 1022446 - Application Added as of 05/07/2010	CITATION	9261 31ST AVE SW
---	----------	------------------

Case 1019211 - Case Resolved as of 05/20/2010	CITATION	9304 32ND AVE SW
---	----------	------------------

Case 1021813 - Case Opened as of 05/03/2010	HZW	1112 N 98TH ST
---	-----	----------------

Case 1018232 - Payment Processed as of 05/20/2010	TRAO	2324 W CROCKETT ST
---	------	--------------------

Case 1021818 - Order of Director Issued as of 03/19/2010	UNFIT	120 10TH AVE E
--	-------	----------------

Case 1018141 - Application Added as of 12/31/2008	CONSTRUCT	1048 S TRENTON ST
---	-----------	-------------------

Case 1022525 - Application Added as of 05/17/2010	CITATION	1048 S TRENTON ST
---	----------	-------------------

Case 1021405 - Application Added as of 01/12/2010	CONSTRUCT	8839 36TH AVE S
---	-----------	-----------------

Case 1021430 - Application Added as of 01/12/2010	CONSTRUCT	8839 36TH AVE S
---	-----------	-----------------

# Test Map

5/6/10 ej- Inspection shows outdoor junk storage such as but not limited to mattresses, couches and other household items.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022446>

Inspection shows outdoor junk storage, such as but not limited, inoperable vehicle (flat tire), couch, appliance, wood and other miscellaneous items.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019211>

Zoning Violations: major veh repair w/out permit,(per# 6167644 for minor repair) & salvage yard prohibited in C2 zone; (2 buildings,as 1112 and 1124 N 98th St plus lot rented out)

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021813>

Application for a Tenant Relocation License. Total units:2; total units occupied:2. Demolition.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018232>

Unfit single family structure in multi family zone

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021818>

Remodeling a single family residence & creating a duplex in a SF zone requires zoning approval, permits & inspections from DPD. STOP WORK ORDER posted 12/30/08.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018141>

VIOLATION OF THE SEATTLE LAND USE AND ZONING CODE OBSERVED (INOPERABLE VEHICLE, AUTO TIRES, FENDERS AND OTHER MATERIALS IN A RESIDENTIAL ZONE. TOOK PHOTOS

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022525>

Grading more than 25 cu.yds. in Steep Slope & Potential Slide ECA requires permission from Parks and a permit & inspections from DPD.(owner)

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021405>

Grading more than 25 cu.yds. in Steep Slope & Potential

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=>

# Test Map

-122.37263505	47.51966406
---------------	-------------

-122.3741583	47.51965106
--------------	-------------

-122.34381842	47.70088102
---------------	-------------

-122.38736153	47.63787479
---------------	-------------

-122.31909935	47.61946004
---------------	-------------

-122.31814597	47.52506374
---------------	-------------

-122.31814597	47.52506374
---------------	-------------

-122.28893582	47.52334443
---------------	-------------

-122.28893582	47.52334443
---------------	-------------



# Test Map

Case 1021433 - Application Added as of 02/16/2010	CONSTRUCT	8839 36TH AVE S
---	-----------	-----------------

Case 1022290 - Application Added as of 04/23/2010	CITATION	9003 13TH AVE SW
---	----------	------------------

Case 1020759 - Application Added as of 12/30/2009	CONSTRUCT	4010 58TH PL SW
---	-----------	-----------------

Case 1020724 - Application Added as of 10/08/2009	CONSTRUCT	8638 31ST AVE SW
---	-----------	------------------

Case 1022509 - Application Added as of 05/14/2010	CITATION	8603 39TH AVE SW
---	----------	------------------

Case 1017212 - Application Added as of 02/18/2009	CONSTRUCT	8312 39TH AVE S
---	-----------	-----------------

Case 1018987 - Application Added as of 07/07/2009	HZW	7732 37TH AVE NE
---	-----	------------------

Case 1022407 - Application Added as of 05/17/2010	HZW	8038 35TH AVE NE
---	-----	------------------

# Test Map

Slide ECA requires permission from Parks and a permit & inspections from DPD. (responsible party)

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021430>

Constructing a structure larger than 120 sq.ft. requires permits and inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021433>

Violation of Weeds & Vegetation Ord-

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022290>

Repairing a rockery in a Steep Slope & Potential Slide Environmentally Critical Area (ECA) requires a Building & a Side Sewer Permit & all required inspections from DPD. STOP WORK ORDER posted 6/18/09. Need to install temporary drain, stabilize rockery material & install erosion control immediately.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020759>

Permit 6228706 was issued 10/7/09 for work originally started without a permit. This case will remain open until all required inspections have been requested and approved.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020724>

5/13/10 ej- Inspection shows vegetation encroaching onto the sidewalk along 39th Ave SW.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022509>

Building a retaining wall more than 4' tall (w/ intent to place fence on top) in a Steep Slope ECA requires permit & inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017212>

Fire damaged SFR open to entry & weather with minor fire debris on site. Motorcycles appear operable & are legally parked.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018987>

Open to entry via window near the Northeast corner of

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=>

# Test Map

-122.28893582	47.52334443
---------------	-------------

-122.35201731	47.52266686
---------------	-------------

-122.407692093	47.5684271866
----------------	---------------

-122.37230689	47.52552482
---------------	-------------

-122.38238703	47.52618087
---------------	-------------

-122.28342374	47.5288696
---------------	------------

-122.28823787	47.68574763
---------------	-------------

-122.29023979	47.68777478
---------------	-------------

# Test Map

Case 1022354 - Application Added as of 04/29/2010	HZW	714 HARVARD AVE E
---	-----	-------------------

Case 1014180 - Application Added as of 07/09/2008	CONSTRUCT	3015 S BRADFORD ST
---	-----------	--------------------

Case 1022027 - Application Added as of 04/19/2010	HZW	3961 S THISTLE ST
---	-----	-------------------

Case 1021711 - Notice or Order Issued as of 02/11/2010	HZW	2005 SW THISTLE ST
--	-----	--------------------

Case 1014059 - Application Added as of 04/11/2008	CONSTRUCT	5611 30TH AVE SW
---	-----------	------------------

Case 1020384 - Application Added as of 11/20/2009	HZW	7606 45TH AVE S
---	-----	-----------------

Case 1022133 - Application Added as of 04/01/2010	CITATION	7512 45TH AVE S
---	----------	-----------------

Case 1022140 - Notice or Order Issued as of 05/10/2010	HZW	7512 45TH AVE S
--	-----	-----------------

# Test Map

the rear wall, picture in file.

1022407

4/23/10 KB inspected property and HMBC violations exist

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022354>

Permit 6170898 was issued on 6/26/08 for work originally started without a permit. This case will remain open until all required inspections have been requested and approved.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014180>

VIOLATION OF THE SEATTLE HOUSING AND BUILDING MAINTENANCE CODE CONFIRMED BY PROP.MGR.(CLOGGED SEWER LINE AND RAW SEWERAGE IN BASEMENT).

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022027>

Violation of Land Use- Illegal dwelling unit

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021711>

THREE TREES REMOVED THAT ARE GREATER THAN 6 INCH CALIPER IN ECA--REVEGETATION PLAN REQUIRED

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014059>

OBSERVED VIOLATIONS OF THE SEATTLE HOUSING AND BUILDING MAINTENANCE CODE(LEAKING KITCHEN FAUCETT, DECAYED WOOD IN FRONT PORCH AND OTHER VIOLATIONS.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020384>

VIOLATIONS OF THE SEATTLE LAND USE AND ZONING CODE OBSERVED( SCRAP METAL IN YARD; RV IN REQUIRED FRONT YARD;) TOOK PHOTOS 7& LEFT DOOR HANGER.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022133>

VIOLATION OF THE SEATTLE LAND USE AND ZONING CODE CONFIRMED BY OWNER, JUMMY

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=>

# Test Map

-122.3221036	47.62547271
--------------	-------------

-122.29342264	47.56871579
---------------	-------------

-122.28158809	47.52771997
---------------	-------------

-122.35938767	47.52807548
---------------	-------------

-122.371359713	47.5515482108
----------------	---------------

-122.27624286	47.53410225
---------------	-------------

-122.27624243	47.5348223
---------------	------------

-122.27624243	47.5348223
---------------	------------

# Test Map

05/10/2010

Case 1021561 - Citation Issued as of 04/28/2010      CITATION      7055 18TH AVE SW

Case 1022023 - Application Added as of 03/18/2010      HZW      8540 23RD AVE NE

Case 1022025 - Application Added as of 04/21/2010      CITATION      8540 23RD AVE NE

Case 1022229 - Application Added as of 04/15/2010      CITATION      9025 12TH AVE NW

Case 1017489 - Application Added as of 02/01/2010      CONSTRUCT      103 NW 40TH ST

Case 1017522 - Application Added as of 02/18/2010      CITATION      6327 22ND AVE SW

Case 1021460 - Notice or Order Issued as of 02/22/2010      CONSTRUCT      6327 22ND AVE SW

Case 1022100 - Notice or Order Issued as of 03/29/2010      CONSTRUCT      6312 18TH AVE SW

Case 1021012 - Application Added as of 12/09/2009      HZW      6023 19TH AVE S

# Test Map

ZONING CODE CONFIRMED BY OWNER, JUMMY SUAREZ(OFF-STREET PARKING SPACE IN GARAGE ELIMINATED WITHOUT REQUIRED PERMIT).

1022140

1/14/10 EJ-Inspection shows outdoor junk storage such as but not limited to inoperable vehicle, pallets, car parts and other miscellaneous items.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021561>

Fire damage includes holes in roof, missing windows & doors, soffits, vertical corner support posts; open to entry & weather with outdoor storage.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022023>

Outdoor storage includes fire damaged sections of the building & it's contents in the yard including lumber, mattresses, tv, paint & gas cans, truck canopy, doors, furnace parts, utility tray & trailer.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022025>

TWO TRUCKS FILLED WITH JUNK ARE PARKED IN THE FRONT YARD--JUNK IS ALSO PILED IN FRONT YARD NEXT TO TRUCKS

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022229>

PERMITS NEEDED FOR NEW FOUNDATION WALLS

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017489>

09/12/08 KB inspected and HBMC code violation exists, Land Use violation exist (junk storage/inop)

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017522>

Constructing an addition to a single family residence requires permits & inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021460>

Enclosing a a 2nd story rear deck requires permits and inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022100>

"VIOLATION ALERT" VIOLATION OF THE SEATTLE

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=>



# Test Map

-122.35757916	47.53931864
---------------	-------------

-122.30392344	47.69096242
---------------	-------------

-122.30392344	47.69096242
---------------	-------------

-122.37172454	47.69505477
---------------	-------------

-122.357436986	47.6554334176
----------------	---------------

-122.36130629	47.54563915
---------------	-------------

-122.36130629	47.54563915
---------------	-------------

-122.35687137	47.54619689
---------------	-------------

-122.30914652	47.5481594
---------------	------------

# Test Map

Case 1022289 - Application Added as of 04/22/2010	HZW	934 N 104TH ST
Case 1022350 - Application Added as of 04/28/2010	CONSTRUCT	2514 NE 107TH ST
Case 1021529 - Application Added as of 01/08/2010	CONSTRUCT	2238 E CRESCENT DR
Case 1022157 - Application Added as of 04/06/2010	HZW	819 W GALER ST
Case 1017331 - Application Added as of 09/25/2008	CONSTRUCT	4317 SW FLETCHER ST
Case 1022088 - Application Added as of 04/19/2010	HZW	7520 RENTON AVE S
Case 1017388 - Application Added as of 09/22/2008	CONSTRUCT	3927 S LUCILE ST
Case 1022465 - Application Added as of 05/11/2010	CITATION	5644 40TH AVE SW

# Test Map

LAND USE AND ZONING CODE CONFIRMED  
(UNAUTHORIZED HABITABLE SPACES CREATED IN  
DETACHED GARAGE; DETACHED STRUCTURES ON  
PREMISES LESS THAN FIVE FEET FROM SINGLE  
FAMILY RESIDENCE.

Housing violations in unit #1, 6...

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021012>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022289>

DECK IN SIDEYARD HIGHER THAN 18 INCHES  
REQUIRES PERMIT

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022350>

PERMITS ARE REQUIRED FOR NEW ADDITION

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021529>

3/26/10 KB inspected property and HBMC violations  
exist

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022157>

Permit 6194761 was issued 9/16/08 for work originally  
started without a permit. This case will remain open until  
all required inspections have been requested and  
obtained.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017331>

03/16/10 bg - HBMC violations.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022088>

Constructing an addition in the front yard setback  
requires zoning approval, permits & inspections from  
DPD. STOP WORK ORDER posted 9/19/08.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017388>

Violation of Weeds & Vegetation Ord-

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022465>

# Test Map

-122.345782      47.70448376

-122.300867      47.70692189

-122.30189351      47.63293875

-122.36875019      47.63213386

-122.389141249      47.5188136323

-122.27963678      47.53467646

-122.282258383      47.5524968972

-122.38272633      47.55067232

# Test Map

Case 1015005 - Application Added as of 02/22/2008      CONSTRUCT      5412 30TH AVE SW

Case 1017763 - Application Added as of 01/05/2009      CONSTRUCT      5217 42ND AVE S

Case 1017680 - Application Added as of 10/22/2008      CONSTRUCT      5218 35TH AVE S

Case 1016978 - Application Added as of 08/13/2008      CONSTRUCT      5218 35TH AVE S

Case 1020286 - Application Added as of 10/06/2009      HZW      4701 ROOSEVELT WAY NE

Case 1017391 - Application Accepted as of  
12/26/2008      TRAO      1932 QUEEN ANNE AVE N

Case 1021562 - Payment Processed as of 05/20/2010      TRAO      2032 YALE AVE E

Case 1022155 - Application Added as of 04/02/2010      CITATION      1945 GILMAN DR W

# Test Map

Installing drainage from house, through alley & directed to Parks property to the east requires permits/approvals from SDOT, Parks Dept. & DPD or removal & restoration. Grading more than 25 cu.yds. & filling wetlands on Parks property requires permits & approvals from DPD and Parks.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015005>

Permit 6201936 was issued 12/31/08 for constructing a two story deck without a permit and inspections. This case will remain open until all required inspections have been requested & obtained from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017763>

Installing a drainage system requires a permit and inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017680>

Raising a house, constructing new foundation system, installing new structural beams/posts & complete remodel requires DPD plan review with engineering AND permits and inspections. STOP WORK ORDER issued 8/12/08 for 5218-1/2 35th Ave S.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016978>

Violation of Land Use Code observed. see attached notes

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020286>

Application for a Tenant Relocation License. Total units:10; Total units occupied:6. Demolition.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017391>

Application for a Tenant Relocation License. Total units: 12; total units occupied: 12. Substantial rehabilitation.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021562>

4/1/10 KB inspected and Weeds violation exists

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022155>

# Test Map

-122.37051007	47.55332036
---------------	-------------

-122.2809929	47.55462423
--------------	-------------

-122.28889849	47.55452495
---------------	-------------

-122.28889849	47.55452495
---------------	-------------

-122.31780654	47.66330181
---------------	-------------

-122.35665993	47.63705305
---------------	-------------

-122.32692322	47.63775439
---------------	-------------

-122.37242547	47.63724753
---------------	-------------

# Test Map

Case 1017570 - Notice or Order Issued as of 04/21/2010	CONSTRUCT	3562 SW ADMIRAL WAY
Case 1022366 - Application Added as of 04/29/2010	CITATION	3612 SW OTHELLO ST
Case 1017838 - Citation Issued as of 02/03/2010	CITATION	3033 S MYRTLE ST
Case 1021900 - Notice or Order Issued as of 05/12/2010	HZW	4748 23RD AVE SW
Case 1017073 - Case Closed as of 03/01/2010	HZW	910 N 35TH ST
Case 1021544 - Case Resolved as of 04/01/2010	CITATION	12724 23RD AVE NE
Case 1022279 - Application Added as of 04/21/2010	CITATION	1745 S SHELTON ST
Case 1020024 - Application Added as of 07/22/2009	CONSTRUCT	2371 FRANKLIN AVE E
Case 1019956 - Notice or Order Issued as of 12/22/2009	CONSTRUCT	2371 FRANKLIN AVE E
Case 1021916 - Case Resolved as of 05/10/2010	CITATION	3230 17TH AVE S



# Test Map

Remodeling a home requires permits and inspections from DPD. STOP WORK ORDER posted 10/9/08.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017570>

Violation of Weeds & Vegetation Ord-

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022366>

VIOLATIONS OF THE SEATTLE LAND USE AND ZONING CODE OBSERVED(VEHICLES IN REQUIRED FRONT YARD; AUTO SEAT, TIRES AND OTHER JUNK STORAGE IN YARDS)

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017838>

Violation of Land Use- Illegal duplex

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021900>

Land Use Code Violation

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017073>

Land Use Code Violation

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021544>

04/15/10 bg - Vehicles parked in required front yard, 4 vehicles and some have flat tires. Outdoor storage on the east side of the property. photos taken

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022279>

INSTALL TEMPORARY EROSION CONTROL, SWEEP ALLEY, STABILIZE BASE WITH ROCK,STRAW OR CONTAIN WITH SILT FENCE

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020024>

STOP WORK POSTED--LARGE CUT AT ALLEY W/O SHORING--PERMIT REQUIRED FOR REMODELING AND FOR RETAINING WALL

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019956>

Outdoor storage in rear yard & on planting strip.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021916>

# Test Map

-122.376245877	47.5797276918
----------------	---------------

-122.3789506	47.53701529
--------------	-------------

-122.29244943	47.53866829
---------------	-------------

-122.36133001	47.55974613
---------------	-------------

-122.346720987	47.6502899014
----------------	---------------

-122.30423794	47.7219058
---------------	------------

-122.308521335	47.557695186
----------------	--------------

-122.32496372	47.64179691
---------------	-------------

-122.32496372	47.64179691
---------------	-------------

-122.31099178	47.57419123
---------------	-------------

# Test Map

Case 1020832 - Notice or Order Issued as of  
02/16/2010

CONSTRUCT

3061 20TH AVE S

Case 1018898 - Payment Processed as of 05/22/2009

TRAO

3008 63RD AVE SW

Case 1020064 - Application Added as of 12/22/2009

CITATION

9652 BEACON AVE S

Case 1020140 - Application Added as of 08/06/2009

CONSTRUCT

7305 34TH AVE SW

Case 1020137 - Application Added as of 12/23/2009

HZW

1304 SW FLORIDA ST

Case 1022192 - Application Added as of 04/07/2010

CITATION

4034 21ST AVE SW

Case 1021293 - Case Opened as of 05/21/2010

CONSTRUCT

3016 ALKI AVE SW

Case 1021429 - Application Added as of 04/27/2010

HZW

2309 25TH AVE S

# Test Map

Constructing a deck approximately 10' above grade in the required front yard & creating habitable space out of garage requires zoning review and if approved, permits & inspections from DPD. STOP WORK ORDER posted 10/12/09.

1021916

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020832>

Application for a Tenant Relocation License. Total units: 3; total units occupied: 3. Demolition.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018898>

Junk storage in yard area, vegetation overgrowth on unpaved portion of ROW blocks clear sight for drivers exiting driveway to North; pictures in file.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020064>

Removing exceptional tree (48" diameter pine) on SF zoned lot less than 5000 sq.ft. (approximately 60% of tree on private property & remainder in R-O-W) does not require approval from DPD or SDOT.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020140>

Violation of Land use Code- Illegal use & outdoor junk storage in the vacant lot.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020137>

Violation of Land Use- Outdoor junk storage on vacant lot.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022192>

Permit 6230924 was issued 12/4/09 for work originally started without a permit. This case will remain open until all required inspections have been requested and approved.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021293>

Violation of the HBMC

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021429>

# Test Map

-122.30667749      47.57522306

-122.412770448      47.5779936669

-122.27395138      47.51553761

-122.37551652      47.53714841

-122.35295548      47.58464903

-122.359858675      47.5673379897

-122.41652933      47.57723555

-122.30059597      47.58259607

# Test Map

Case 1022453 - Application Added as of 05/10/2010	CITATION	8817 DELRIDGE WAY SW
Case 1021654 - Citation Issued as of 05/12/2010	CITATION	1541 VALENTINE PL S
Case 1021655 - Application Added as of 04/08/2010	HZW	1541 VALENTINE PL S
Case 1017928 - Application Added as of 05/21/2010	HZW	7814 STROUD AVE N
Case 1018187 - Notification Issued as of 04/12/2010	VACANT	7814 STROUD AVE N
Case 1020304 - Application Added as of 02/22/2010	UNFIT	7814 STROUD AVE N
Case 1015006 - Application Added as of 03/05/2008	CONSTRUCT	4727 23RD AVE SW
Case 1022529 - Application Accepted as of 05/21/2010	ADVISORY	2009 YALE AVE E
Case 1015117 - Application Added as of 10/14/2008	CONSTRUCT	1341 N 78TH ST
Case 1020342 - Notice or Order Issued as of 12/22/2009	CONSTRUCT	1633 MADRONA DR
Case 1016311 - Application Added as of 01/21/2010	HZW	8003 8TH AVE S

# Test Map

5/6/10 ej- Inspection shows outdoor junk storage such as but not limited to inoperable vehicle (flat tire) blue Ford Crown Vic.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022453>

01/25/10 bg - Outdoor junk storage - Garbage and debris in front, side and rear yards. photos taken

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021654>

01/25/10 bg - Outdoor junk storage - Garbage and debris in front, side and rear yards. photos taken

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021655>

Collapsed roof; unsound front porch assemblies; outdoor storage & veg. overgrowth.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017928>

Collapsed roof; unsound front porch assemblies; outdoor storage & veg. overgrowth.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018187>

unfit single family residence

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020304>

Removing trees & vegetation from Steep Slope & Potential Slide Environmentally Critical Areas requires approvals from DPD & mitigation.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015006>

8 unit non occupied building conversion from apartments to condominiums

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022529>

**BASEMENT REMODEL NEEDS PERMITS**

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015117>

**STOP WORK POSTED--PERMIT REQUIRED FOR FRONT PORCH**

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020342>

**VIOLATION ALERT** Inspection shows the Use has not been established for this parcel.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=>

# Test Map

-122.36068019 47.52412725

-122.30766655 47.58853746

-122.30766655 47.58853746

-122.33556962 47.68572007

-122.33556962 47.68572007

-122.33556962 47.68572007

-122.361767026 47.5602820819

-122.327443523 47.6371060218

-122.339944206 47.6853268014

-122.285044033 47.616223379

-122.323054951 47.5311275104



# Test Map

Case 1016923 - Application Added as of 07/01/2009	HZW	2656 42ND AVE SW
Case 1018996 - Application Added as of 04/15/2009	CONSTRUCT	2656 42ND AVE SW
Case 1014490 - Application Added as of 12/24/2007	CONSTRUCT	2240 PRESCOTT AVE SW
Case 1021823 - Application Added as of 02/22/2010	CONSTRUCT	3439 14TH AVE W
Case 1022297 - Application Added as of 04/22/2010	CONSTRUCT	4328 BAKER AVE NW
Case 1022409 - Application Added as of 05/13/2010	HZW	2110 S GRAND ST
Case 1020373 - Application Added as of 08/24/2009	HZW	4830 WEST MARGINAL WAY SW
Case 1021660 - Notice or Order Issued as of 05/21/2010	CONSTRUCT	3427 25TH AVE S
Case 1021771 - Case Resolved as of 04/22/2010	CITATION	2837 SW NEVADA ST

# Test Map

been established for this parcel.	1016311
KB inspected property and Land Use violation exists - "Use" is not established	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016923">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016923</a>
Construction, plumbing & gas piping permits must be issued (for work performed without permits) & have final approvals from DPD before any temporary use or any change of use permit can be issued.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018996">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018996</a>
Interior alterations including adding a bathroom requires permits & inspections from DPD. STOP WORK ORDER posted 12/12/07.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014490">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014490</a>
TWO TREES (REQUIRED TO BE RETAINED BY PERMIT #6164753) HAVE BEEN REMOVED--REVISED PLANS MUST BE SUBMITTED	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021823">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021823</a>
BUILDING, ELECTRICAL & PLUMBING PERMITS ARE NEEDED FOR THIS REMODEL	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022297">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022297</a>
Secure; deterioration, veg. overgrowth.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022409">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022409</a>
making case # for Nov prep- inspection to take place this week	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020373">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020373</a>
Permit 6239717 was issued 3/29/10 & Permit 6249568 was issued 5/20/10 for work originally started without a permit. This case will remain open until all required inspections have been requested & approved.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021660">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021660</a>
Violation of Land Use- Outdoor junk storage & parking in required front yard.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=</a>

# Test Map

-122.384850328	47.5794989101
----------------	---------------

-122.384850328	47.5794989101
----------------	---------------

-122.378504105	47.58274473
----------------	-------------

-122.375407244	47.6515464632
----------------	---------------

-122.359250178	47.6597963424
----------------	---------------

-122.30419914	47.58704491
---------------	-------------

-122.35134933	47.55893176
---------------	-------------

-122.30091995	47.57228856
---------------	-------------

-122.36977419	47.56522861
---------------	-------------

# Test Map

Case 1021830 - Notice or Order Issued as of 03/05/2010	CONSTRUCT	11002 EXETER AVE NE
--	-----------	---------------------

Case 1021428 - Notice or Order Issued as of 05/10/2010	HZW	8017 MERIDIAN AVE N
--	-----	---------------------

Case 1021716 - Notification Issued as of 05/10/2010	VACANT	8017 MERIDIAN AVE N
---	--------	---------------------

Case 1015862 - Application Added as of 01/27/2010	CONSTRUCT	2535 DEXTER AVE N
---	-----------	-------------------

Case 1016479 - Application Added as of 07/10/2008	CONSTRUCT	3956 SW AUSTIN ST
---	-----------	-------------------

Case 1016527 - Application Added as of 07/10/2008	CONSTRUCT	3956 SW AUSTIN ST
---	-----------	-------------------

Case 1022010 - Application Added as of 03/15/2010	CONSTRUCT	3027 S EDMUNDS ST
---	-----------	-------------------

# Test Map

required front yard.

## BUILDING PERMIT REQUIRED FOR REMOVING VEGETATION, GRADING AND CONSTRUCTING RETAINING WALLS IN ECA (KNOWN SLIDE)

Open to entry in 3 locations, pictures in file. Appears to be at least six inches of water in the basement & it seems to be coming through the floors. Exterior North wall "bay window push-out" leaking through wall & floor. Various deteriorated assemblies, see Warning.

Open to entry in 3 locations, pictures in file. Appears to be at least six inches of water in the basement & it seems to be coming through the floors. Exterior North wall "bay window push-out" leaking through wall & floor. Various deteriorated assemblies, see Warning.

## TREES HAVE BEEN TOPPED IN STEEP SLOPE ECA--REVEGETATION REQUIRED

Constructing a rockery on the north side of the site in a Steep Slope ECA requires a permit & inspections from DPD. STOP WORK ORDER posted 7/7/08.

Removing 2 trees and vegetation in a Steep Slope Environmentally Critical Area (ECA) requires a revegetation plan & approval from DPD.

Large portion of tree (one trunk of many) removed on a vacant lot mapped as a Steep Slope Environmentally Critical Area (ECA) without approval from DPD. A restoration plan is required.

1021771

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021830>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021428>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021716>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015862>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016479>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016527>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022010>

# Test Map

-122.27751678      47.70959957

-122.33342372      47.6874257

-122.33342372      47.6874257

-122.34594011      47.643016186

-122.384427782      47.5352819626

-122.384427782      47.5352819626

-122.293109237      47.5585932886

# Test Map

Case 1021306 - Findings Issued as of 01/08/2010	ADVISORY	1200 OLYMPIC WAY W
Case 1017392 - Application Added as of 01/27/2009	CONSTRUCT	5017 30TH AVE S
Case 1021635 - Application Added as of 03/15/2010	CITATION	506 N 75TH ST
Case 1021636 - Application Added as of 03/15/2010	HZW	506 N 75TH ST
Case 1022470 - Application Added as of 05/11/2010	CITATION	8411 39TH AVE SW
Case 1022322 - Application Added as of 04/26/2010	CITATION	124 12TH AVE
Case 1021893 - Application Added as of 04/21/2010	CITATION	7336 28TH AVE NW
Case 1021911 - Application Added as of 03/04/2010	HZW	8509 14TH AVE NW
Case 1021899 - Application Added as of 03/03/2010	HZW	8815 RENTON AVE S
Case 1021939 - Application Added as of 03/08/2010	HZW	8448 37TH AVE S

# Test Map

condo conversion

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021306>

Permit 6194415 was issued 9/26/08 for work originally started without a permit. This case will remain open until all required inspections have been requested and approved.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017392>

Secure; outdoor storage; deterioration.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021635>

Secure; deterioration includes what appears to be a collapsed upper balcony roof assembly.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021636>

5/6/10 ej-Inspection shows vegetation encroaching onto the sidewalk, tree limbs hanging lower than 8ft.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022470>

Violation of the Land Use Code

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022322>

NS inspected the property on 2/25/10-Inspections shows outdoor junk storage including but not limited to clothing, garbage and more misc.items being stored in the yard.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021893>

Housing violations.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021911>

zoning-

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021899>

Illegal basement dwelling unit.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021939>



# Test Map

-122.36861617	47.63010848
---------------	-------------

-122.29448062	47.5566615
---------------	------------

-122.35201243	47.68346244
---------------	-------------

-122.35201243	47.68346244
---------------	-------------

-122.38225267	47.52799264
---------------	-------------

-122.3163103	47.60250943
--------------	-------------

-122.39270751	47.68242473
---------------	-------------

-122.37439266	47.69101383
---------------	-------------

-122.27661694	47.52346319
---------------	-------------

-122.28567863	47.52643731
---------------	-------------

# Test Map

Case 1022007 - Application Added as of 03/11/2010	HZW	1145 19TH AVE E
Case 1017349 - Case Resolved as of 05/06/2010	HZW	9205 3RD AVE SW
Case 1022555 - Application Added as of 05/20/2010	CITATION	5115 17TH AVE S
Case 1020245 - Citation Issued as of 12/24/2009	CITATION	4156 15TH AVE S
Case 1021355 - Application Added as of 12/22/2009	HZW	2818 BOYER AVE E
Case 1022390 - Application Added as of 04/30/2010	CONSTRUCT	926 N 96TH ST
Case 1020835 - Application Added as of 10/12/2009	ADVISORY	7506 32ND AVE NW
Case 1020585 - Application Added as of 09/18/2009	CONSTRUCT	7745 18TH AVE SW
Case 1022347 - Application Added as of 04/28/2010	CITATION	141 NW 74TH ST
Case 1021895 - Application Added as of 03/02/2010	CONSTRUCT	5404 S ORCAS ST

# Test Map

Failure to pay relocation assistance pursuant to Seattle Municipal Code Section 22.206.260.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022007>

zoning- illegal use. VIOLATION ALERT. See notes below.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017349>

05/19/10 - Outdoor junk storage, photos taken

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022555>

08/11/09 bg - Construction debris, carpeting and household debris all over the backyard. photos taken

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020245>

Observed repair of accessory float @ end of pier. In-water work occurring within work window. Told owner to apply for shoreline exemption. Also: P/T wood decking observed on a separate new float w/o permit. New float was observed on shoreward side of same floating home.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021355>

FILL HAS BEEN ADDED OVER ROOTS OF EXCEPTIONAL TREE--FILL MUST BE REMOVED

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022390>

observed household items and tire on planting strip and same in driveway- :tv, wood, misc materials

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020835>

Permit 6227560 was issued 9/18/09 for work originally started without a permit. This case will remain open until all required inspections have been requested & approved by DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020585>

Violation of the Home Occupation standards. Loud noise from the basement of the property.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022347>

Remodeling a single family residence including adding

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=>

# Test Map

-122.30776153	47.63003564
---------------	-------------

-122.33911412	47.5206557161
---------------	---------------

-122.310778556	47.556225993
----------------	--------------

-122.313143734	47.5655898999
----------------	---------------

-122.316951165	47.6458805295
----------------	---------------

-122.34588222	47.69889123
---------------	-------------

-122.39801021	47.68335118
---------------	-------------

-122.35809518	47.53234918
---------------	-------------

-122.359795408	47.6823483578
----------------	---------------

-122.26568883	47.55129727
---------------	-------------

# Test Map

Case 1021983 - Notice or Order Issued as of 05/06/2010	HZW	401 NE 40TH ST
Case 1021997 - Application Added as of 03/10/2010	CITATION	4816 S KENYON ST
Case 1021709 - Notice or Order Issued as of 02/09/2010	HZW	846 NE 88TH ST
Case 1017508 - Application Added as of 10/03/2008	CONSTRUCT	719 M L KING JR WAY
Case 1019182 - Payment Processed as of 08/07/2009	TRAO	7036 25TH AVE NW
Case 1020945 - Application Added as of 10/23/2009	CONSTRUCT	4536 15TH AVE S
Case 1020688 - Application Added as of 01/13/2010	HZW	1409 NW 59TH ST
Case 1021809 - Application Added as of 02/25/2010	HZW	114 NW 59TH ST

# Test Map

2nd story dormers (new dwelling space), creating new dwelling space in basement, new systems throughout with new windows & insulation requires permits & inspections from DPD. Plans required. STOP WORK ORDER posted 3/2/10.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021895>

Violation of Housing Building and Maintenance Code observed.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021983>

Outdoor storage and possibly too many chickens.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021997>

Land Use Code Violation

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021709>

Recently constructed rear addition and deck over 18" above grade currently under construction require permits and inspections from DPD. STOP WORK ORDER posted 10/2/08.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017508>

Application for a Tenant Relocation License. Total units: 1; Total units occupied: 1. Demolition.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019182>

Constructing a retaining wall over 4' tall (footing to top) requires a permit & inspections. Paving over front yard may require drainage review.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020945>

NS inspected the property on 9/21/09-Inspection shows a play house stored in the req.front yard.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020688>

Illegal unit.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021809>

# Test Map

-122.32400701      47.65538968

-122.27186466      47.53179411

-122.31824898      47.69237886

-122.296520214      47.6086342136

-122.388401746      47.68062765

-122.31318341      47.5624026

-122.37412134      47.67145721

-122.35837348      47.67186088

# Test Map

Case 1017586 - Payment Processed as of 05/20/2010	TRAO	138 NE 60TH ST
Case 1019729 - Application Added as of 12/08/2009	CITATION	1302 S HANFORD ST
Case 1019730 - Application Added as of 03/17/2010	HZW	1302 S HANFORD ST
Case 1022129 - Application Added as of 04/01/2010	CITATION	5940 35TH AVE SW
Case 1022196 - Application Added as of 04/07/2010	CITATION	4043 20TH AVE SW
Case 1022199 - Application Added as of 04/07/2010	CONSTRUCT	3530 S BENNETT ST
Case 1022287 - Application Added as of 04/21/2010	CONSTRUCT	13747 ASHWORTH AVE N
Case 1022239 - Application Added as of 04/19/2010	HZW	4622 S BRIGHTON ST



# Test Map

Application for a Tenant Relocation License. Total units:1; total units occupied:1; Demolition.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017586>

VIOLATIONS OF THE SEATTLE LAND USE AND ZONING CODE OBSERVED(PAINT CANS, PLASTIC CONTAINERS, SCRAP WOOD, PLASTIC BAGS IN YARD AND CARPORT; ALSO CARPORT IS LOCATED IN REQUIRED EAST SIDE YARD).

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019729>

"VIOLATION ALERT". VIOLATION OF THE SEATTLE LAND USE AND ZONING CODE CONFIRMED (CARPORT ADDED TO EAST WALL OF RESIDENTIAL STRUCTURE WITHOUT A BUILDING PERMIT; BUILDING PERMIT # 585145 FOR ALTERATIONS EXPIRED 8/2/79).

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019730>

Violation of Land Use- Numbers of chickens (9) in SF5000 lot and number of vehicles (4) on property.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022129>

Violation of Weeds & Vegetation Ord-

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022196>

Demolishing a portion of a shared garage requires a permit and inspections from DPD. STOP WORK ORDER posted 4/6/10.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022199>

PERMIT IS REQUIRED TO RAISE GARAGE APPROXIMATELY 4 FEET

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022287>

VIOLATION OF THE SEATTLE HOUSING AND BUILDING MAINTENANCE CODE OBSERVED(STANDING WATER IN REAR YARD, MISSING PEEP-HOLES AND OTHER VIOLATIONS).

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022239>

# Test Map

-122.326483492 47.6724402152

-122.315749758 47.5752732717

-122.315749758 47.5752732717

-122.3759928 47.54889631

-122.35937804 47.56705044

-122.28798418 47.55445661

-122.33990466 47.73002159

-122.27445797 47.54176974

# Test Map

Case 1022241 - Application Added as of 04/15/2010	CITATION	4622 S BRIGHTON ST
---	----------	--------------------

Case 1022363 - Application Added as of 04/29/2010	CITATION	4054 48TH AVE SW
---	----------	------------------

Case 1022292 - Application Added as of 04/21/2010	CITATION	2116 SW TRENTON ST
---	----------	--------------------

Case 1022221 - Application Added as of 04/13/2010	CONSTRUCT	3826 45TH AVE S
---	-----------	-----------------

Case 1022259 - Citation Issued as of 05/13/2010	CITATION	5246 39TH AVE S
---	----------	-----------------

Case 1022276 - Application Added as of 04/26/2010	CITATION	10728 LINDEN AVE N
---	----------	--------------------

Case 1020548 - Case Opened as of 02/02/2010	UNFIT	8733 GREENWOOD AVE N
---	-------	----------------------

# Test Map

MISSING PEEP-HOLES AND OTHER VIOLATIONS).

VIOLATIONS OF THE SEATTLE LAND USE AND ZONING CODE OBSERVED VEHICLE PARKED IN FRONT YARD, SCRAP WOOD , GAS CONTAINERS, TIRES AND OTHER MATERIALS IN YARDS). TOOK PHOTOS.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022241>

4/27/10 ej- Inspection shows more than the than allowed 3 vehicles not in an enclosed area on single family lot. Outdoor junk storage such as but not limited to inoperable bus.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022363>

Violation of Weeds & Vegetation Ord-

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022292>

Constructing a retaining wall more than 4' tall requires a permit and inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022221>

04/16/10 bg - Two vehicles parked in required front yard, 3 vehicles on the property appear to have not been moved recently. photos taken

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022259>

Violation of Land Use Code observed.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022276>

unfit commercial structure and accessory structure- VIOLATION ALERT-building meets unfit criteria, however owner is insistent on repair. New occupancy would be a change of use. Also, facade of building that is cantilevered has settled and has deteriorated beams and mudsill. Photos available if necessary. According to owner, building has been gutted.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020548>

# Test Map

-122.27445797      47.54176974

-122.39319022      47.56686642

-122.36135468      47.52488666

-122.27657251      47.56915286

-122.28322674      47.55432826

-122.34706561      47.70739694

-122.35564424      47.69340368

# Test Map

Case 1020030 - Application Added as of 09/24/2009	HZW	8733 GREENWOOD AVE N
---	-----	----------------------

Case 1022079 - Application Added as of 05/13/2010	CITATION	357 NW 90TH ST
---	----------	----------------

Case 1018721 - Application Added as of 07/29/2009	CONSTRUCT	3939 S WARSAW ST
---	-----------	------------------

Case 1021089 - Notice or Order Issued as of 12/22/2009	HZW	4536 LATONA AVE NE
--	-----	--------------------

Case 1022342 - Application Added as of 04/27/2010	CONSTRUCT	1419 N 40TH ST
---	-----------	----------------

Case 1017990 - Application Added as of 12/04/2008	CONSTRUCT	11637 BEACON AVE S
---	-----------	--------------------

Case 1015310 - Application Added as of 02/03/2010	CONSTRUCT	2625 41ST AVE SW
---	-----------	------------------

Case 1021611 - Notice or Order Issued as of 04/14/2010	CONSTRUCT	3423 SOUND VIEW DR W
--	-----------	----------------------

Case 1021613 - Case Opened as of 04/14/2010	CONSTRUCT	3423 SOUND VIEW DR W
---	-----------	----------------------

# Test Map

owner, building has been gutted.

Violations of Land Use Code.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020030>

Zoning violation.Bags of garbage,garbage bins,and more misc.items stored in the req.yard.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022079>

Permit 6215398 was issued 5/6/09 for work originally started without a permit. Permit 6207349 was issued 7/7/09. This case will remain open until all required inspections have been requested & approved by DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018721>

Violation of Land Use Code.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021089>

**BUILDING AND OTHER PERMITS ARE REQUIRED FOR REMODEL**

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022342>

Repairing/reconstructing the east side (front) of a single family residence requires permit(s) & inspections from DPD. STOP WORK ORDER issued 12/3/08.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017990>

Permit 6175839 was issued on 4/1/08 for work originally started without permits & inspections. This case will remain open until all required inspections have been requested and approved.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015310>

**GRADING PERMIT IS NEEDED FOR GRADING MORE THAN 25 CUBIC YARDS OF MATERIAL ON A STEEP SLOPE ECA**

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021611>

**RESTORATION IS REQUIRED FOR VEGETATION REMOVAL IN ECA**

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021613>

# Test Map

-122.35564424      47.69340368

-122.36312065      47.69408836

-122.281767349      47.5429739613

-122.32483316      47.6624851221

-122.340143681      47.6554942083

-122.264665367      47.4985778238

-122.384257746      47.5803850629

-122.418097517      47.6511315517

-122.418097517      47.6511315517



# Test Map

Case 1014495 - Application Added as of 06/27/2008      CONSTRUCT      1563 S DAWSON ST

Case 1022081 - Application Added as of 05/17/2010      CITATION      8739 12TH AVE NW

Case 1022154 - Application Added as of 04/02/2010      CITATION      1977 GILMAN DR W

Case 1022563 - Application Added as of 05/20/2010      CITATION      304 21ST AVE

Case 1021064 - Case Resolved as of 05/21/2010      HZW      9406 LAKE CITY WAY NE

Case 1018120 - Application Added as of 06/23/2009      CONSTRUCT      4121 SW 109TH ST

Case 1018769 - Application Added as of 08/26/2009      CONSTRUCT      3213 S EDMUNDS ST

Case 1021678 - Notice or Order Issued as of 05/18/2010      HZW      1107 N 50TH ST

Case 1021144 - Citation Issued as of 05/11/2010      CITATION      1107 N 50TH ST

# Test Map

Major remodel including basement demolished to studs with new framing requires building, plumbing & electrical permits and inspections from DPD and King County.

1021613

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014495>

Zoning violation. An inoperable gray van parked on property.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022081>

4/1/10 KB inspected and Weeds violation exists

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022154>

Violation of the Land Use Code

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022563>

Land Use Code Violation

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021064>

Permit 6204405 was issued 6/18/09 for work originally started without a permit. This case will remain open until all required inspections have been requested and obtained.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018120>

Permit 6210889 was issued on 3/25/09 for work originally started without a permit. This case will remain open until all required inspections have been requested and obtained.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018769>

canopy over 120sf not allowed

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021678>

junk & parking violations in sf zone

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021144>

# Test Map

-122.310745906 47.5554647182

-122.37169394 47.69320524

-122.37242262 47.63738449

-122.3048345 47.60453904

-122.30542799 47.69696655

-122.384011659 47.5052323256

-122.290842858 47.5584667489

-122.34414541 47.66480475

-122.34414541 47.66480475

# Test Map

Case 1022547 - Application Added as of 05/20/2010	CITATION	9503 7TH AVE NW
Case 1021870 - Application Added as of 02/25/2010	HZW	3614 2ND AVE NW
Case 1018484 - Application Added as of 02/13/2009	CONSTRUCT	3507 S PORTLAND ST
Case 1021456 - Application Added as of 12/30/2009	CONSTRUCT	3119 WALNUT AVE SW
Case 1018981 - Payment Processed as of 07/10/2009	TRAO	1505 17TH AVE S
Case 1022124 - Application Added as of 04/01/2010	CONSTRUCT	11035 5TH AVE NE
Case 1022435 - Citation Issued as of 05/21/2010	CITATION	3836 RENTON AVE S
Case 1021105 - Notice or Order Issued as of 05/19/2010	CONSTRUCT	5750 27TH AVE NE
Case 1022299 - Application Added as of 04/22/2010	CONSTRUCT	4833 PULLMAN AVE NE
Case 1022325 - Application Added as of 04/27/2010	CITATION	10015 SAND POINT WAY NE

# Test Map

5/11/10 KB inspected property and LU violation exists -  
junk storage and inop vehicles

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022547>

LU violations, use not permitted

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021870>

Completely remodeling a house (down to the studs)  
requires permits & inspections including zoning review  
for the porch extension from DPD. STOP WORK  
ORDER posted 2/12/09.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018484>

Remodeling and making repairs to a single family  
residence requires permits & inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021456>

Application for a Tenant Relocation License. Total units:  
1; total units occupied: 1. Demolition.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018981>

Construction Stormwater Control (CSC) measures  
including covering stockpiles to City standards required.  
CSC not per Permit 6208703. NOV issued 3/22/10 with  
an assessed penalty.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022124>

05/05/10 bg - Five vehicles parked on the property.  
photos taken.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022435>

STOP WORK POSTED--PERMIT REQUIRED FOR 2ND  
STORY ADDITION

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021105>

REMODEL AND ADDITION OF ADU REQUIRES A  
FULL SET OF PLANS WITH ENGINEERING

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022299>

Land Use Code Violation

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022325>

# Test Map

-122.36497179	47.69804351
---------------	-------------

-122.358429956	47.6537225342
----------------	---------------

-122.287715995	47.5328873132
----------------	---------------

-122.383783067	47.5758709023
----------------	---------------

-122.310664188	47.5899124802
----------------	---------------

-122.325318565	47.7099088963
----------------	---------------

-122.294423826	47.5687277378
----------------	---------------

-122.298209324	47.6715029247
----------------	---------------

-122.27411714	47.66907494
---------------	-------------

-122.27807847	47.70160334
---------------	-------------

# Test Map

Case 1020020 - Application Added as of 07/21/2009	HZW	7303 38TH AVE NE
---	-----	------------------

Case 1022205 - Notice or Order Issued as of 05/06/2010	HZW	10733 62ND AVE S
--	-----	------------------

Case 1015344 - Application Added as of 04/29/2009	CONSTRUCT	9430 21ST AVE SW
---	-----------	------------------

Case 1017671 - Eligibility Determined as of 01/07/2009	TRAO	4111 DELRIDGE WAY SW
--	------	----------------------

Case 1018088 - Application Added as of 12/17/2008	CONSTRUCT	1309 16TH AVE S
---	-----------	-----------------

Case 1021026 - Application Added as of 04/20/2010	HZW	4412 NE 60TH ST
---	-----	-----------------

Case 1022123 - Citation Issued as of 04/01/2010	CITATION	4412 NE 60TH ST
---	----------	-----------------

Case 1020880 - Citation Issued as of 10/16/2009	CITATION	6258 33RD AVE NE
---	----------	------------------

# Test Map

Violation of Just Cause Eviction Ordinance due to issuance of deficient notice to terminate tenancy.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020020>

"VIOLATION ALERT" VIOLATION OF THE SEATTLE LAND USE AND ZONING CODE CONFIRMED (PARKING SPACE IN GARAGE WAS ELIMINATED WITHOUT REQUIRED BUILDING PERMIT. TOOK PHOTOS .

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022205>

Permit 6174615 was issued on 3/25/08 for work originally started without a permit. This case will remain open until all required inspections have been requested and approved.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015344>

Application for a Tenant Relocation License. Total units: 2; total units occupied: 2. Demolition.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017671>

Removing trees & vegetation and grading more than 25 cubic yards on an undeveloped site mapped Steep Slope and Potential Slide Environmentally Critical Areas requires approvals & permits from DPD. STOP WORK ORDER posted 12/10/08 (Only installation of TESC measures allowed.)

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018088>

Violation of Land Use Code observed.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021026>

Violation of Land Use Code observed.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022123>

8/4/09 JS talked to business owner about the complaint. They said the owner is out of touch but they turned the fan on a little early due to the heatwave. 8/7/09 JS the

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020880>



# Test Map

-122.288030737	47.6814178739
----------------	---------------

-122.255948785	47.5034442576
----------------	---------------

-122.36025719	47.518278313
---------------	--------------

-122.363618734	47.5661528682
----------------	---------------

-122.312819446	47.5913902652
----------------	---------------

-122.280173125	47.6723970851
----------------	---------------

-122.280173125	47.6723970851
----------------	---------------

-122.291925	47.6756359
-------------	------------

# Test Map

Case 1020570 - Notice or Order Issued as of 01/08/2010	HZW	2325 42ND AVE SW
Case 1021327 - Case Resolved as of 03/04/2010	HZW	140 NE 55TH ST
Case 1018881 - Application Added as of 03/31/2009	CONSTRUCT	7433 48TH AVE S
Case 1018762 - Application Added as of 02/19/2010	CITATION	7743 19TH AVE NW
Case 1018678 - Application Added as of 09/16/2009	CONSTRUCT	7743 19TH AVE NW
Case 1019769 - Case Resolved as of 05/17/2010	CITATION	2016 14TH AVE S
Case 1022374 - Application Added as of 05/13/2010	CITATION	6215 S RYAN ST
Case 1017007 - Notice or Order Issued as of	HZW	431 EASTLAKE AVE E

# Test Map

fan on a little early due to the heatwave. 8/7/09 JS the complainant said it has always been noisy but that she can't ignore it any longer. She said over the past few years a number of people have moved out because of the noise. 8/12/09 JS we need to meet with the owner to measure any equipment that needs to operate before 7:00 a.m.

Violation of Land use- Operating preschool without establishing the use permit

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020570>

HBMC Violation

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021327>

Remodeling a house requires permit(s) and inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018881>

NS inspected the property on 3/10/09- land use violation. Inspection shows a deck built with out a permit which is in the required rear yard and a 16 ft high lattice on an existing deck attached to the house.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018762>

PERMIT REQUIRED FOR ASSESSORY STRUCTURE IN REAR YARD

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018678>

Violation of Land Use Code.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019769>

VIOLATION OF THE SEATTLE LAND USE AND ZONING CODE OBSERVED(AT LEAST 4 VEHICLES PARKED OUTDOORS ON THE LOT) TOOK PHOTOS.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022374>

Illegal use. No use permit for artist work/live units.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=>

# Test Map

-122.38541884      47.58219989

-122.32648663      47.66880207

-122.272869772      47.5349244986

-122.381403947      47.686296677

-122.381403947      47.686296677

-122.314388509      47.5849905732

-122.255243177      47.509482335

-122.32953335      47.62296609

# Test Map

02/19/2010

Case 1022236 - Application Added as of 05/05/2010      CITATION      10321 61ST AVE S

Case 1021759 - Application Added as of 02/10/2010      CITATION      1827 S LANE ST

Case 1021142 - Application Added as of 11/17/2009      CONSTRUCT      10641 MARINE VIEW DR  
SW

Case 1020601 - Application Added as of 10/15/2009      HZW      11038 RIVIERA PL NE

Case 1017938 - Application Added as of 02/01/2010      CONSTRUCT      11753 LAKESIDE AVE NE

Case 1016198 - Application Added as of 09/30/2008      CONSTRUCT      6007 PALATINE AVE N

Case 1020079 - Case Resolved as of 12/30/2009      CITATION      933 S DORIS ST

Case 1018888 - Notification Issued as of 03/08/2010      VACANT      3243 BELVIDERE AVE SW

Case 1018496 - Application Added as of 03/08/2010      HZW      3243 BELVIDERE AVE SW

# Test Map

	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017007">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017007</a>
VIOLATION OF THE SEATTLE LAND USE AND ZONING CODE OBSERVED.(DOOR SCREEN NEXT TO SOUTH WALL).	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022236">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022236</a>
"VIOLATION ALERT" VIOLATION OF THE SEATTLE LAND USE AND ZONING CODE CONFIRMED (SHED BUILT ON VACANT SF 5000 LOT WITHOUT PRINCIPAL USE STRUCTURE.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021759">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021759</a>
Removing 2 trees (possibly "exceptional") on a site mapped as a Steep Slope Environmentally Critical Area (ECA) requires approval from DPD.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021142">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021142</a>
Location of shoreline incorrect on plans. Affects ECA setback and pending issued permits.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020601">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020601</a>
STOP WORK POSTED--PERMIT REQUIRED FOR 2 STORY ADDITION AND REMODEL	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017938">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017938</a>
SIDE SEWER PERMIT REQUIRED	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016198">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1016198</a>
7/24/09 ej- Inspection shows vegetation encroaching onto the sidewalk.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020079">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020079</a>
Secure; no rear access; outdoor storage; veg. overgrowth; deterioration.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018888">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018888</a>
Secure; no rear access; outdoor storage; veg. overgrowth; deterioration.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018496">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018496</a>

# Test Map

-122.25793171	47.50793653
---------------	-------------

-122.30778607	47.59641986
---------------	-------------

-122.38801639	47.5068792
---------------	------------

-122.27648839	47.71072069
---------------	-------------

-122.27940741	47.71435649
---------------	-------------

-122.356724941	47.6726851931
----------------	---------------

-122.319525013	47.5496270096
----------------	---------------

-122.379554737	47.5743453739
----------------	---------------

-122.379554737	47.5743453739
----------------	---------------

# Test Map

Case 1018523 - Case Resolved as of 07/14/2009	CITATION	2510 NE 140TH ST
Case 1021009 - Citation Issued as of 05/07/2010	CITATION	14006 COURTLAND PL N
Case 1022267 - Application Added as of 04/19/2010	CITATION	5914 8TH AVE NW
Case 1021600 - Application Added as of 02/17/2010	CONSTRUCT	849 NW 60TH ST
Case 1020269 - Payment Processed as of 10/23/2009	TRAO	5920 24TH AVE NW
Case 1022316 - Case Opened as of 04/30/2010	HZW	12200 AURORA AVE N
Case 1021891 - Notice or Order Issued as of 04/02/2010	HZW	12055 PHINNEY AVE N
Case 1019531 - Application Added as of 04/22/2010	CITATION	12561 ROOSEVELT WAY NE
Case 1022111 - Application Added as of 03/26/2010	HZW	6514 S HAZEL ST
Case 1019184 - Notice or Order Issued as of 02/05/2010	CONSTRUCT	10037 39TH AVE SW



# Test Map

## Land Use Code Violation

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018523>

junk in sf zone

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021009>

Weeds and vegetation encroaching into the sidewalk

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022267>

EXCEPTIONAL MONKEY PUZZLE TREE (DIAMETER GREATER THAN 22 INCHES IN SF LOT LARGER THAN 5000 SQUARE FEET) HAS BEEN REMOVED

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021600>

Application for a Tenant Relocation License. Total units:2; total units occupied:2. Change of use.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020269>

LU: Use changed from storage to rehearsal studio without permit

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022316>

LU sf zone violations:Illegal basement dwelling unit; tent canopy over 120sf, business use of detached garage & elim off st pking.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021891>

## Land Use Code Violation

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019531>

03/26/10 bg - No permit record for seperate dwelling unit in the basement.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022111>

Permit 6230166 was issued 10/14/09 for work originally performed without a permit. This case will remain open until all required inspections have been requested and approved by DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019184>

# Test Map

-122.30146726	47.730380752
---------------	--------------

-122.33772286	47.73073394
---------------	-------------

-122.36589472	47.6720508
---------------	------------

-122.36832903	47.67215703
---------------	-------------

-122.38725691	47.67214939
---------------	-------------

-122.34449288	47.71766385
---------------	-------------

-122.35453763	47.71761295
---------------	-------------

-122.32016171	47.72077531
---------------	-------------

-122.251684804	47.505627576
----------------	--------------

-122.382095121	47.512636122
----------------	--------------

# Test Map

Case 1022493 - Application Added as of 05/14/2010	HZW	143 NW 85TH ST
Case 1018623 - Application Added as of 11/16/2009	HZW	1520 11TH AVE
Case 1015230 - Case Opened as of 07/30/2008	HZW	1520 11TH AVE
Case 1019160 - Application Added as of 06/26/2009	CONSTRUCT	5355 SW PRITCHARD ST
Case 1019714 - Application Added as of 06/22/2009	CONSTRUCT	7738 20TH AVE SW
Case 1021762 - Application Added as of 02/17/2010	HZW	327 NW 76TH ST
Case 1019581 - Application Added as of 12/18/2009	CONSTRUCT	11223 DAYTON AVE N
Case 1019488 - Case Resolved as of 12/09/2009	CITATION	11223 DAYTON AVE N
Case 1020171 - Citation Issued as of 05/14/2010	CITATION	8156 12TH AVE SW

# Test Map

Zoning violation.Outdoor junk storage including but not limited to wood, empty cans, bags of garbage and more misc. items stored on property.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022493>

Complainant states a lounge and musical venue is in use on the property. Cmplnt has recorded video's and high decibel noise readings that show disturbances for the nearby residential uses.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018623>

Violation of the Just Cause Eviction Ordinance due to owner's failure to provide a just cause for terminating tenancy.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015230>

Removing 4 trees in a Steep Slope & Potential Slide Environmentally Critical Area requires a replanting plan & inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019160>

Permit 6217417 was issued 5/29/09 for work originally started without a permit. This case will remain open until all required inspections have been requested and approved.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019714>

Illegal unit.Verified someone living in the garage.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021762>

OVERFRAMING OF EXISTING GARAGE AND NEW BAY WINDOW REQUIRE PERMIT

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019581>

Land Use Code Violation

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019488>

7/31/09 ej- Inspection shows parking in the required front yard and rear yard abutting street.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020171>

# Test Map

-122.359795083	47.690413867
----------------	--------------

-122.317766958	47.6146686375
----------------	---------------

-122.317766958	47.6146686375
----------------	---------------

-122.399871998	47.5797357294
----------------	---------------

-122.358785614	47.532563307
----------------	--------------

-122.36192812	47.68382233
---------------	-------------

-122.353127379	47.7112655453
----------------	---------------

-122.353127379	47.7112655453
----------------	---------------

-122.35028482	47.52850258
---------------	-------------

# Test Map

Case 1019754 - Notice or Order Issued as of 12/22/2009	CONSTRUCT	14344 MERIDIAN AVE N
Case 1019611 - Application Added as of 03/04/2010	UNFIT	4519 S KENYON ST
Case 1018313 - Notice or Order Issued as of 03/05/2010	CONSTRUCT	5446 32ND AVE SW
Case 1020833 - Application Added as of 10/12/2009	TRAO	2020 NE 65TH ST
Case 1020834 - Application Added as of 10/12/2009	TRAO	2028 NE 65TH ST
Case 1022246 - Application Added as of 04/16/2010	CITATION	625 MALDEN AVE E
Case 1022514 - Application Added as of 05/18/2010	CITATION	700 RAINIER AVE S
Case 1021372 - Notice or Order Issued as of 04/27/2010	HZW	2625 BOYLSTON AVE E
Case 1021294 - Notice or Order Issued as of 04/12/2010	CONSTRUCT	9409 44TH AVE SW
Case 1021186 - Case Resolved as of 04/15/2010	CITATION	556 S CLOVERDALE ST

# Test Map

Large fir tree (45" diameter 2' tall stump next to driveway) cut without DPD approval.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019754>

unfit single family residence

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019611>

Grading (adding fill) more than 100 cu.yds. on a site mapped ECA 1, ECA 2 & ECA 9 requires a permit & inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018313>

Notice of Violation of Tenant Relocation Assistance Ordinance (SMC Chp 22.210)

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020833>

Notice of Violation of Tenant Relocation Assistance Ordinance (SMC Chp 22.210)

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020834>

zoning-

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022246>

05/11/10 bg - Vegetation encroaching onto the sidewalk/street side, photos taken

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022514>

zoning violations\_

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021372>

Constructing a deck more than 18" above grade in a Steep Slope & Potential Slide Environmentally Critical Area (ECA) requires zoning approval & permit and inspections from DPD. STOP WORK ORDER posted 12/2/09.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021294>

11/20/09 EJ- Inspection shows outdoor junk storage such as but not limited wood, tires, inoperable vehicles,

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021186>

# Test Map

-122.33397654 47.73362495

-122.27512733 47.53137334

-122.373297481 47.552398098

-122.305557578 47.6759628795

-122.305375598 47.6759833387

-122.313868957 47.6250114198

-122.31126306 47.59650617

-122.32377186 47.64400071

-122.38978244 47.5178236

-122.32584557 47.52665003



# Test Map

Case 1021353 - Notice or Order Issued as of 05/04/2010	CONSTRUCT	4850 BEACON AVE S
--	-----------	-------------------

Case 1021919 - Application Added as of 03/04/2010	HZW	1430 NW 64TH ST
---	-----	-----------------

Case 1019277 - Application Added as of 05/15/2009	HZW	2119 NW 65TH ST
---	-----	-----------------

Case 1018796 - Application Added as of 05/15/2009	CITATION	2119 NW 65TH ST
---	----------	-----------------

Case 1017486 - Application Added as of 11/04/2008	HZW	14328 RIVIERA PL NE
---	-----	---------------------

Case 1022536 - Application Added as of 05/19/2010	CITATION	5303 16TH AVE S
---	----------	-----------------

Case 1017125 - Application Added as of 08/28/2008	CONSTRUCT	8440 46TH AVE SW
---	-----------	------------------

Case 1018014 - Application Added as of 03/13/2009	CONSTRUCT	3215 SW BRANDON ST
---	-----------	--------------------

# Test Map

metal and other miscellaneous items.

Building sheds and covered structures (with refrigeration equipment?) requires permits & inspections from DPD.  
STOP WORK ORDER posted 12/15/09.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021353>

Housing violatoinis

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021919>

NS inspected the property on 3/16/09-Inspection shows outdoor junk storage including but not limited to an inoperable trailer parked in the required side yard and more misc. junk items.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019277>

NS inspected the property on 3/16/09-Inspection shows outdoor junk storage including but not limited to an inoperable trailer parked in the required side yard and more misc. junk items.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018796>

Construction w/ new materials over water w/o shoreline exemption review. Possible expansion of pier.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017486>

05/19/10 bg - Vegetation encroaching into the alley, photos taken

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022536>

Creating a parking pad by modifying a tiered rockery over 4' tall in a Potential Slide ECA requires zoning approval and permit & inspections from DPD. STOP WORK ORDER posted 8/27/08 (okay to put temporary stairs in west side yard before permit issued).

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017125>

Permit Number 6207231 was issued 2/3/09 for work originally started without a permit. This case will remain open until all required inspections have been requested

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018014>

# Test Map

-122.30391889      47.55941965

-122.37510418      47.67545304

-122.38414108      47.67580636

-122.38414108      47.67580636

-122.28314386      47.732638

-122.312599466      47.5545931416

-122.391189466      47.5274804461

-122.374451203      47.5536211669

# Test Map

Case 1020468 - Application Added as of 04/01/2010	HZW	12504 NORTH PARK AVE N
---	-----	------------------------

Case 1022523 - Application Added as of 05/17/2010	TRAO	1731 S HORTON ST
---	------	------------------

Case 1021240 - Notice or Order Issued as of 03/08/2010	HZW	10426 WATERS AVE S
--	-----	--------------------

Case 1021482 - Notification Issued as of 03/08/2010	VACANT	10426 WATERS AVE S
---	--------	--------------------

Case 1021325 - Application Added as of 12/11/2009	CONSTRUCT	3609 SW HOLDEN ST
---	-----------	-------------------

Case 1022564 - Application Added as of 05/20/2010	CITATION	2825 NW 68TH ST
---	----------	-----------------

Case 1022084 - Application Added as of 03/25/2010	HZW	3200 NW 68TH ST
---	-----	-----------------

Case 1014526 - Application Added as of 12/28/2007	CONSTRUCT	11440 35TH AVE SW
---	-----------	-------------------

Case 1014607 - Application Added as of 01/11/2010	HZW	107 NW 50TH ST
---	-----	----------------

# Test Map

open until all required inspections have been requested and obtained.

LU violation Duplex in sf

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020468>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022523>

Deflected & collapsing roof & rear wall, pictures in file.  
Unfit bldg. Owner to get demo permit ASAP.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021240>

Deflected & collapsing roof & rear wall, pictures in file.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021482>

Permit 6235245 was issued 12/9/09 for electrical work to install a hot tub originally performed without a permit. This case will remain open until all required inspections have been requested & approvals obtained from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021325>

Zoning violation.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022564>

Light and glare violation.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022084>

Grading more than 25 cubic yards in a Steep Slope Environmentally Critical Area (ECA) and creating a grade change greater than 3 feet requires a permit and inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014526>

open to weather; deterioration; vegetation overgrowth

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014607>

# Test Map

-122.349224045	47.7197498829
----------------	---------------

-122.30989596	47.57392687
---------------	-------------

-122.24900952	47.50753536
---------------	-------------

-122.24900952	47.50753536
---------------	-------------

-122.37848485	47.53324726
---------------	-------------

-122.39425988	47.67785065
---------------	-------------

-122.3986672	47.67838069
--------------	-------------

-122.375881151	47.5000583056
----------------	---------------

-122.357588429	47.6648417795
----------------	---------------

# Test Map

Case 1014984 - Notification Issued as of 04/12/2010	VACANT	107 NW 50TH ST
Case 1019187 - Application Added as of 05/15/2009	TRAO	1928 43RD AVE E
Case 1014908 - Application Added as of 05/19/2010	HZW	1703 NW 62ND ST
Case 1022343 - Application Added as of 05/05/2010	CITATION	3628 PALATINE AVE N
Case 1021349 - Notice or Order Issued as of 03/04/2010	CONSTRUCT	6250 33RD AVE NE
Case 1021361 - Case Resolved as of 05/21/2010	CITATION	330 NW 75TH ST
Case 1021258 - Application Added as of 12/04/2009	CONSTRUCT	541 26TH AVE
Case 1018812 - Payment Processed as of 05/22/2009	TRAO	3044 31ST AVE W
Case 1018146 - Application Added as of 04/26/2010	HZW	4212 PASADENA PL NE
Case 1019639 - Application Added as of 07/17/2009	UNFIT	1619 26TH AVE

# Test Map

open to weather; deterioration; vegetation overgrowth	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014984">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014984</a>
Application for a Tenant Relocation License. Total units: 14; Total units occupied: 13. Demolition.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019187">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019187</a>
illegal dwelling unit in basement of sfr permit# 65279 (1945)	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014908">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1014908</a>
LU: outdoor junk storage vac lot in L2	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022343">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022343</a>
BUILDING HAS BEEN CHANGED TO A MIXED USE--3 RESIDENTIAL UNITS AND 2 OFFICES--NEED TO GET CHANGE OF USE PERMIT	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021349">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021349</a>
ZONING VIOLATION	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021361">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021361</a>
Converting a garage into living area & remodeling a basement into 2 bedrooms & a bathroom require permit & inspections from DPD. STOP WORK ORDER posted 12/1/09.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021258">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021258</a>
Notice of Violation of Tenant Relocation Assistance Ordinance (SMC, Chp. 22.210).	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018812">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018812</a>
Inspected property, observed violation of Land Use Code.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018146">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018146</a>
unfit building	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019639">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019639</a>



# Test Map

-122.357588429	47.6648417795
----------------	---------------

-122.276877364	47.6368228635
----------------	---------------

-122.379123512	47.6736377849
----------------	---------------

-122.356294654	47.6535697532
----------------	---------------

-122.291912238	47.6755221108
----------------	---------------

-122.36206094	47.68350354
---------------	-------------

-122.29918021	47.60743326
---------------	-------------

-122.396611089	47.6482172491
----------------	---------------

-122.321600627	47.6579409986
----------------	---------------

-122.29929941	47.61592578
---------------	-------------

# Test Map

Case 1020156 - Application Added as of 08/05/2009	CONSTRUCT	9232 39TH AVE S
---	-----------	-----------------

Case 1020529 - Application Added as of 10/14/2009	CONSTRUCT	5923 S CARVER ST
---	-----------	------------------

Case 1021326 - Notice or Order Issued as of 05/14/2010	CONSTRUCT	4831 S KENYON ST
--	-----------	------------------

Case 1021415 - Application Added as of 12/29/2009	HZW	3256 S FERDINAND ST
---	-----	---------------------

Case 1021416 - Notice or Order Issued as of 12/29/2009	HZW	3256 S FERDINAND ST
--	-----	---------------------

Case 1021417 - Application Added as of 12/29/2009	CITATION	3256 S FERDINAND ST
---	----------	---------------------

Case 1021401 - Application Added as of 12/22/2009	CONSTRUCT	7902 DUNCAN AVE S
---	-----------	-------------------

# Test Map

Constructing retaining walls/installing drainage on east side of site in ECA 1 (Steep Slope) requires permits and inspections from DPD. Permit & inspections required to keep or remove retaining walls.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020156>

Permit 6226761 was issued 9/30/09 for work originally started without a permit. This case will remain open until all required inspections have been requested and approved by DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020529>

Constructing additions to a single family residence requires permits and inspections from DPD. STOP WORK ORDER posted 12/8/09.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021326>

VIOLATION OF THE SEATTLE HOUSING AND BUILDING MAINTERNANCE CODE OBSERVED EXPOSED WIRING ON LAUNDRY ROOM JUNCTION BOX, INTERIOR LOCKS ON EXTERIOR DOOR, UNGROUNDED OUTLETS IN SEVERAL ROOMS). TOOK PHOTOS.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021415>

"VIOLATION ALERT" VIOLATION OF THE SEATTLE LAND USE AND ZONING CODE OBSERVED(OFF-STREET PARKING IN DETACHED GARAGE WAS ELIMINATED WITHOUT REQUIRED PERMIT)

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021416>

VIOLATION OF THE SEATTLE LAND USE AND ZONING CODE OBSERVED (PORTION OF CARPORT ADDITION ON WEST WALL IS IN SIDE YARD; VEHICLE PARKED IN REQUIRED FRONT YARD).TOOK PHOTOS.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021417>

Furnace and hot water tank require permits &

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=>

# Test Map

-122.28336893	47.52055056
---------------	-------------

-122.25880256	47.51822419
---------------	-------------

-122.271382	47.53138832
-------------	-------------

-122.28907399	47.55806855
---------------	-------------

-122.28907399	47.55806855
---------------	-------------

-122.28907399	47.55806855
---------------	-------------

-122.26734696	47.53150082
---------------	-------------

# Test Map

Case 1022019 - Application Added as of 04/12/2010	CONSTRUCT	1301 32ND AVE S
---	-----------	-----------------

Case 1022377 - Application Added as of 05/20/2010	CITATION	2817 NW 71ST ST
---	----------	-----------------

Case 1018300 - Payment Processed as of 04/03/2009	TRAO	902 N 72ND ST
---	------	---------------

Case 1020139 - Case Resolved as of 03/03/2010	CITATION	739 N 73RD ST
---	----------	---------------

Case 1022270 - Application Added as of 04/20/2010	CITATION	9006 14TH AVE SW
---	----------	------------------

Case 1021199 - Notice or Order Issued as of 01/14/2010	HZW	622 SW OTHELLO ST
--	-----	-------------------

Case 1015010 - Application Added as of 02/22/2008	CONSTRUCT	7331 36TH AVE SW
---	-----------	------------------

Case 1019624 - Application Added as of 06/15/2009	CITATION	5913 32ND AVE S
---	----------	-----------------

# Test Map

inspections from DPD and King County. STOP WORK ORDER posted 12/22/09.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021401>

Constructing a deck on the front of a single family residence requires a permit & inspections from DPD. STOP WORK ORDER posted 3/15/10.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022019>

Zoning violation.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022377>

Application for a Tenant Relocation License. Total units:3; total units occupied:3. Demolition.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018300>

outdoor junk in sf5000

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020139>

Outdoor storage includes vehicle, boat on trailer, auto parts, lumber, tires, & other items.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022270>

Violation of land use- Illegal duplex

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021199>

Installing drainage line without a permit (appears to be 2" force line into a perf section that drip drains onto sidewalk) and crossing the property line with an unapproved discharge point.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015010>

VIOLATION OF THE SEATTLE LAND USE AND ZONING CODE OBSERVED VEHICLE PARKED IN REQUIRED FRONT YARD LIC # FINAL OK TO CONSTRUCT SINGLE FAMILY RESIDENCE WITH BASEMENT GARAGE WAS 3/21/09 UNDER PERMIT # 523568.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019624>

# Test Map

-122.29156679	47.59199192
---------------	-------------

-122.39379484	47.6800845
---------------	------------

-122.34667517	47.68118076
---------------	-------------

-122.3481492	47.68158706
--------------	-------------

-122.352552751	47.5225628959
----------------	---------------

-122.344127264	47.5371723259
----------------	---------------

-122.378648844	47.5358909485
----------------	---------------

-122.291813274	47.549344759
----------------	--------------

# Test Map

Case 1015186 - Application Added as of 01/05/2009	CONSTRUCT	3550 SW ADMIRAL WAY
---	-----------	---------------------

Case 1015346 - Application Added as of 04/01/2008	CONSTRUCT	3059 SW HANFORD ST
---	-----------	--------------------

Case 1017431 - Application Added as of 05/20/2009	HZW	4614 S ORCHARD ST
---	-----	-------------------

Case 1018327 - Application Added as of 06/15/2009	HZW	2226 NW 58TH ST
---	-----	-----------------

Case 1019948 - Notice or Order Issued as of 05/04/2010	CONSTRUCT	4064 LETITIA AVE S
--	-----------	--------------------

Case 1020253 - Application Added as of 12/11/2009	CONSTRUCT	411 S DAWSON ST
---	-----------	-----------------

Case 1017601 - Application Added as of 08/06/2009	CONSTRUCT	4717 BEACH DR SW
---	-----------	------------------

Case 1015933 - Application Added as of 09/04/2009	HZW	601 NW MARKET ST
---	-----	------------------



# Test Map

523568.

Permit 6173782 was issued 11/21/08 for work performed without permits & inspections. This case will remain open until all required inspections have been requested & approved. STOP WORK ORDERS posted 4/28/08 and 9/8/08.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015186>

Demolishing and rebuilding a garage requires permits and inspections from DPD. STOP WORK ORDER posted 3/27/08.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1015346>

Failue to pay relocation assistance pursuant to an Emergency Order of the Director. Emergency Closure Relocation Assistance as required by SMC 22.206.260.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017431>

Housing violatoins

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018327>

Permit 6222039 was issued 4/14/10 for work originally performed without a permit. This case will remain open until all required inspections have been requested, performed and approved by DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019948>

Permit 6221649 was issued 9/18/09 for work originally started without a permit. This case will remain open until all required inspections have been requested and approved. Certificate of Occupancy required.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020253>

Remodeling a single family residence requires permits and inspections from DPD. STOP WORK ORDER posted 10/14/08.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1017601>

NOV to Discontinue salv yard & major veh repair &

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=>

# Test Map

-122.376206769	47.5794394911
----------------	---------------

-122.374189123	47.5757173263
----------------	---------------

-122.274556226	47.5384265542
----------------	---------------

-122.3859858	47.6711348837
--------------	---------------

-122.28964654	47.56642722
---------------	-------------

-122.32908622	47.55538488
---------------	-------------

-122.403707019	47.5604233776
----------------	---------------

-122.363573411	47.6684872161
----------------	---------------

# Test Map

Case 1022459 - Application Added as of 05/10/2010	CITATION	2908 HARRIS PL S
---	----------	------------------

Case 1019854 - Case Resolved as of 04/16/2010	CITATION	2908 HARRIS PL S
---	----------	------------------

Case 1021141 - Notice or Order Issued as of 03/08/2010	HZW	5119 CLOVERDALE PL S
--	-----	----------------------

Case 1021483 - Notification Issued as of 03/08/2010	VACANT	5119 CLOVERDALE PL S
---	--------	----------------------

Case 1021450 - Application Added as of 12/30/2009	CITATION	8107 8TH AVE NW
---	----------	-----------------

Case 1021488 - Application Added as of 03/09/2010	CITATION	7938 34TH AVE SW
---	----------	------------------

Case 1022351 - Application Added as of 04/28/2010	CONSTRUCT	7439 CORLISS AVE N
---	-----------	--------------------

Case 1020477 - Application Added as of 12/29/2009	CONSTRUCT	1910 S STEVENS ST
---	-----------	-------------------

Case 1018102 - Application Added as of 12/18/2008	CONSTRUCT	155 28TH AVE
---	-----------	--------------

# Test Map

building expansion over 990sq ft- see permit BN18855 & plans.

1015933

outdoor storage includes inop. veh. in carport, lumber, garden equipment, furniture, appliancesbicycle, fabric, cooler & all items in carport, pictures in file.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022459>

07/02/09 bg - Vegetation overgrowing onto the sidewalk, inoperable van in the driveway and parked in required front yard. Junk and debris on site and in the carport. photos taken.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1019854>

Open to weather via various windows on both the East & West walls; plywood siding lacks paint or protective cover; pictures in file.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021141>

Open to weather via various windows on both the East & West walls; plywood siding lacks paint or protective cover; pictures in file.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021483>

Weeds and vegetation encroaching into the sidewalk

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021450>

1/5/2010 EJ-Inspection shows outdoor junk storage such as but not limited to inoperable vehicle, plastic buckets and other household items.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1021488>

PERMIT REQUIRED FOR ACCESSORY STUCTURE LARGER THAN 120 SQUARE FEET

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022351>

Completely gutting & remodeling a single family residence requires permits and inspections from DPD. STOP WORK ORDER posted 4/14/09.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1020477>

Permit 6198462 was issued 11/3/08 for work originally

# Test Map

-122.30199745	47.57720645
---------------	-------------

-122.30199745	47.57720645
---------------	-------------

-122.26915092	47.52637328
---------------	-------------

-122.26915092	47.52637328
---------------	-------------

-122.36632038	47.68794991
---------------	-------------

-122.37498038	47.53075348
---------------	-------------

-122.33069053	47.68389031
---------------	-------------

-122.307416707	47.577208754
----------------	--------------

-122.296266362	47.6032876672
----------------	---------------

# Test Map

Case 1022365 - Application Added as of 04/29/2010	CITATION	1430 39TH AVE E
Case 1022498 - Application Added as of 05/17/2010	CITATION	3043 SW AVALON WAY
Case 1022387 - Application Added as of 04/30/2010	CITATION	2833 NW 71ST ST
Case 1022414 - Application Added as of 05/10/2010	HZW	6721 MARY AVE NW
Case 1022440 - Application Added as of 05/07/2010	CITATION	3103 16TH AVE S
Case 1022558 - Application Added as of 05/20/2010	CITATION	5945 S EASTWOOD DR
Case 1022549 - Application Added as of 05/20/2010	CITATION	9511 7TH AVE NW
Case 1022477 - Application Added as of 05/11/2010	CITATION	909 17TH AVE
Case 1022526 - Notice or Order Issued as of 05/20/2010	HZW	8451 37TH AVE S

# Test Map

started without permits. This case will remain open until all required inspections have been requested and obtained.

A large hedge is growing over the sidewalk.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1018102>

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022365>

Violation of Weeds & Vegetation Ord-

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022498>

Zoning violation.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022387>

Zoning violation.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022414>

05/05/10 - Three vehicles on the property, appear inoperable. photos taken

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022440>

VIOLATION OF THE SEATTLE WEEDS AND VEGETATION ORDINANCE OBSERVED (OVERGROWTH OVERHANGING AND OBSTRUCTING PUBLIC USE OF THE STREET ALONG 61ST AVENUE S.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022558>

5/11/10 KB inspected property and LU violation exists - inoperable vehicle

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022549>

Violation of the Land Use Code

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022477>

VIOLATION OF THE SEATTLE HOUSING AND BUILDING MAINTENANCE CODE OBSERVED

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022526>

# Test Map

-122.28243014	47.63198194
---------------	-------------

-122.37156678	47.56577455
---------------	-------------

-122.39447558	47.68006426
---------------	-------------

-122.376334	47.67848988
-------------	-------------

-122.3123413	47.57580832
--------------	-------------

-122.25755775	47.50348663
---------------	-------------

-122.36505837	47.69826647
---------------	-------------

-122.31046876	47.61070652
---------------	-------------

-122.28627278	47.52644279
---------------	-------------



# Test Map

Case 1022448 - Application Added as of 05/11/2010	CONSTRUCT	4721 FAUNTLEROY WAY SW
Case 1022486 - Application Added as of 05/12/2010	CONSTRUCT	4721 FAUNTLEROY WAY SW
Case 1022518 - Application Added as of 05/18/2010	CITATION	2327 45TH AVE SW
Case 1022262 - Application Added as of 05/20/2010	CITATION	3121 16TH AVE S
Case 1022551 - Application Added as of 05/20/2010	CITATION	424 S MAIN ST
Case 1022519 - Notice or Order Issued as of 05/20/2010	CONSTRUCT	3002 S MOUNT BAKER BLVD
Case 1022561 - Application Added as of 05/20/2010	CITATION	949 23RD AVE
Case 1022253 - Application Added as of 04/20/2010	HZW	9222 DELRIDGE WAY SW
Case 1022405 - Notice or Order Issued as of	HZW	1774 22ND AVE S

# Test Map

(MISSING WALL COVERING ON EXTERIOR AND INTERIOR BATHROOM WALL, NO WATER SUPPLIED TO BATHTUB HOLE BEHIND WASHING MACHINE DECAYED WOOD IN

Remodeling a commercial building requires permits & inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022448>

Signs advertising new business on site: "West Seattle Produce Company" require permits and inspections from DPD.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022486>

Violation of Land Use- Outdoor junk storage

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022518>

04/15/10 bg - Vegetation encroaching onto the sidewalk, photos taken

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022262>

Violation of Land Use Code

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022551>

Permit 6249367 was issued 5/19/10 for work originally started without a permit. This case will remain open until all required inspections have been requested and approved.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022519>

VIOLATION OF LAND USE CODE

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022561>

4/15/10 ej- Inspection shows outdoor junk storage such as but not limited to inoperable vehicles and parking in the required set back.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022253>

Open to entry via doors on North & West walls with open

# Test Map

-122.38206244 47.56035945

-122.38206244 47.56035945

-122.38960194 47.58217033

-122.31233682 47.5752993

-122.32844423 47.60029364

-122.29389709 47.57699357

-122.30301143 47.61151012

-122.35744362 47.52034153

-122.30346977 47.5870153

# Test Map

05/13/2010

Case 1022571 - Application Added as of 05/21/2010      HZW      314 W GARFIELD ST

Case 1022320 - Application Added as of 04/26/2010      CONSTRUCT      3182 NE 84TH ST

Case 1022293 - Notice or Order Issued as of 05/14/2010      HZW      907 N 83RD ST

Case 1022305 - Application Added as of 04/22/2010      CITATION      7612 8TH AVE NW

Case 1022384 - Application Added as of 05/14/2010      CITATION      3534 S HOLDEN ST

Case 1022341 - Application Added as of 04/27/2010      CONSTRUCT      1403 DEXTER AVE N

Case 1022539 - Application Added as of 05/19/2010      CITATION      2002 18TH AVE S

Case 1022484 - Application Added as of 05/12/2010      HZW      8609 ROOSEVELT WAY NE

Case 1022565 - Application Added as of 05/20/2010      CONSTRUCT      4525 S MEAD ST

Case 1022530 - Application Added as of 05/18/2010      HZW      3915 S EDMUNDS ST

# Test Map

window on S. wall, pictures in file.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022405>

5/20/10 KB inspected property and HBMC violations exist

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022571>

DURING PASV INSPECTION INSPECTOR OBSERVED THAT VERY LARGE DOUGLAS FIR HAD BEEN RECENTLY CUT DOWN

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022320>

HBMC violations

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022293>

Weeds and vegetation violation. Vegetation encroaching into the sidewalk.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022305>

04/28/10 bg - Broken tree limb in road right of way, 2 vehicles in front yard with flat tires. photos taken

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022384>

PERMIT REQUIRED FOR REMODEL (SLAB HAS BEEN REMOVED IN SEVERAL PLACES FOR NEW PLUMBING)

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022341>

05/19/10 bg - Vegetation encroaching onto the sidewalk, junk storage. photos taken

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022539>

Land Use Code Violation

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022484>

Constructing a garage in the rear yard requires a permit & inspections from DPD. STOP WORK ORDER posted 5/19/10.

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022565>

05/14/10 bg - Violation of HBMC. photos taken

<http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=>

# Test Map

-122.3617583	47.63369585
--------------	-------------

-122.29157741	47.68962239
---------------	-------------

-122.34676186	47.68890745
---------------	-------------

-122.36575241	47.68441799
---------------	-------------

-122.2866887	47.53393802
--------------	-------------

-122.34261925	47.63163456
---------------	-------------

-122.30914943	47.58535024
---------------	-------------

-122.31783364	47.69158604
---------------	-------------

-122.27601969	47.55024955
---------------	-------------

-122.28259334	47.55843898
---------------	-------------

# Test Map

Case 1022556 - Application Added as of 05/20/2010	HZW	3915 S EDMUNDS ST
---	-----	-------------------

Case 1022559 - Application Added as of 05/20/2010	CITATION	2451 S FERDINAND ST
---	----------	---------------------

Case 1022492 - Application Added as of 05/18/2010	CITATION	1805 S STATE ST
---	----------	-----------------

Case 1022567 - Application Added as of 05/20/2010	CITATION	1634 S LANE ST
---	----------	----------------

Case 1022495 - Application Added as of 05/19/2010	CITATION	3716 NE 57TH ST
---	----------	-----------------

Case 1022534 - Application Added as of 05/19/2010	CITATION	1432 NW 63RD ST
---	----------	-----------------

Case 1022570 - Application Added as of 05/21/2010	CITATION	619 MALDEN AVE E
---	----------	------------------

Case 1022391 - Application Added as of 04/30/2010	HZW	8627 ISLAND DR S
---	-----	------------------

Case 1022367 - Application Added as of 04/29/2010	CITATION	7618 8TH AVE NW
---	----------	-----------------

# Test Map

	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022530">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022530</a>
05/14/10 bg - Violation of HBMC. photos taken	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022556">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022556</a>
05/19/10 bg - Vegetation encroaching onto the sidewalk. photo taken	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022559">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022559</a>
05/12/10 bg - Outdoor junk storage, furniture, bags of garbage. photos taken	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022492">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022492</a>
Violation of the Weed & Veg Ordinance.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022567">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022567</a>
Violations of the Land Use Code observed.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022495">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022495</a>
Zoning violation.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022534">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022534</a>
A minor amount of vegetation growing over the sidewalk.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022570">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022570</a>
Open to entry with structural deterioration.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022391">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022391</a>
Weeds and vegetation encroaching into the sidewalk.	<a href="http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022367">http://web1.seattle.gov/dpd/PermitStatus/project.aspx?id=1022367</a>



# Test Map

-122.28259334	47.55843898
---------------	-------------

-122.3013179	47.5583593
--------------	------------

-122.30921553	47.58760609
---------------	-------------

-122.31002954	47.59682841
---------------	-------------

-122.28720783	47.67055142
---------------	-------------

-122.37511289	47.67474768
---------------	-------------

-122.31387316	47.62481949
---------------	-------------

-122.26142968	47.5260381
---------------	------------

-122.36576639	47.68456528
---------------	-------------